

UAUC Capture Report

Audit ID: MPSB-14 | Project: MPSB | 19/6/2026, 9:19:58 am

3

Safety Issues Found

3

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
• Unsafe bending posture detected.	Risk of musculoskeletal injuries due to unsafe bending posture.
• Workers on elevated platform without visible fall protection.	Risk of falling from height due to lack of fall protection.
• Uneven surface with protruding rebar on the elevated platform.	Risk of tripping or injury from exposed rebar on the platform.

AI Recommendations

- Provide proper training on safe lifting and bending techniques.
- Ensure all workers on elevated platforms use fall protection equipment such as harnesses.
- Cover or cap exposed rebar to prevent injuries and ensure the platform surface is even and clear of hazards.

Analyzed Image

