

UAUC Capture Report

Audit ID: MPSB-15 | Project: MPSB | 6/26/2026, 5:30:48 AM

2

Safety Issues Found

2

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Worker standing on an elevated platform without visible fall protection.	Fall from height due to lack of fall protection.
Loose cables and hoses on the floor creating potential trip hazards.	Tripping over loose cables and hoses leading to injury.

AI Recommendations

- Ensure all workers on elevated platforms use appropriate fall protection equipment such as harnesses. - Organize and secure loose cables and hoses to eliminate trip hazards.

Analyzed Image

