

UAUC Capture Report

Audit ID: MPSB-36 | Project: MPSB | 7/10/2026, 12:23:10 PM

3

Safety Issues Found

3

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Unsafe bending posture observed for one worker.	Musculoskeletal injury due to unsafe bending posture.
Safety vest not detected on one worker.	Reduced visibility and protection due to absence of safety vest.
Worker positioned on an elevated structure without visible fall protection.	Fall from height leading to serious injury.

AI Recommendations

- Train workers on safe lifting and bending techniques to prevent musculoskeletal injuries. - Ensure all workers wear safety vests for visibility and protection. - Provide and enforce the use of fall protection equipment for workers on elevated structures.
--

Analyzed Image

