

UAUC Capture Report

Audit ID: MPSB-37 | Project: MPSB | 7/10/2026, 12:33:19 PM

4

Safety Issues Found

4

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Unsafe bending posture observed for one worker.	Musculoskeletal injury due to unsafe bending posture.
Safety vest not detected on one worker.	Reduced visibility of the worker due to absence of safety vest, increasing risk in case of an emergency.
Worker positioned on an elevated structure without visible fall protection.	Fall from height due to lack of fall protection.
Loose materials and tools scattered on the platform, creating trip hazards.	Trip and fall incidents due to scattered materials and tools.

AI Recommendations

- Train workers on safe lifting and bending techniques to prevent musculoskeletal injuries. - Ensure all workers wear safety vests for visibility and compliance. - Provide and enforce the use of fall protection equipment for workers on elevated structures. - Improve housekeeping by organizing and securing loose materials and tools to eliminate trip hazards.

Analyzed Image

