

UAUC Capture Report

Audit ID: MPSB-38 | Project: MPSB | 7/10/2026, 1:09:28 PM

4

Safety Issues Found

4

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
• Unsafe bending posture observed for one worker.	Musculoskeletal injury due to unsafe bending posture.
• Safety vest not detected on one worker.	Increased risk of injury due to lack of high-visibility safety vest.
• Worker positioned on an elevated structure without visible fall protection.	Fall from height due to lack of fall protection.
• Loose materials and tools scattered on the platform, creating trip hazards.	Trip and fall incidents due to scattered materials and tools.

AI Recommendations

- Train workers on proper lifting and bending techniques to prevent musculoskeletal injuries.
- Ensure all workers wear high-visibility safety vests at all times.
- Provide and enforce the use of fall protection equipment for workers on elevated structures.
- Improve housekeeping by organizing and securing loose materials and tools on the platform.

Analyzed Image

