

UAUC Capture Report

Audit ID: MPSB-39 | Project: MPSB | 7/10/2026, 1:12:34 PM

4

Safety Issues Found

4

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
• Unsafe bending posture observed for one worker.	Musculoskeletal injury due to unsafe bending posture.
• Safety vest not detected on one worker.	Increased risk of injury due to lack of visibility without a safety vest.
• Worker positioned on an elevated structure without fall protection.	Fall from height due to lack of fall protection.
• Loose materials and tools scattered on the platform, creating trip hazards.	Trip and fall incidents due to scattered materials and tools.

AI Recommendations

- Ensure workers follow proper lifting and bending techniques to avoid musculoskeletal injuries.
- Mandate the use of safety vests for all workers to improve visibility and compliance.
- Provide fall protection equipment such as harnesses for workers on elevated structures.
- Improve housekeeping by removing loose materials and tools from the platform to prevent trip hazards.

Analyzed Image

