

UAUC Capture Report

Audit ID: MPSB-40 | Project: MPSB | 7/10/2026, 1:16:40 PM

3

Safety Issues Found

3

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Unsafe bending posture observed for one worker.	Musculoskeletal injury due to unsafe bending posture.
Safety vest not detected on one worker.	Reduced visibility of worker due to absence of safety vest, increasing risk of struck-by incidents.
Worker positioned on an elevated structure without visible fall protection.	Fall from height due to lack of fall protection.

AI Recommendations

- Train workers on proper lifting and bending techniques to avoid musculoskeletal injuries.
- Ensure all workers wear high-visibility safety vests at all times.
- Provide and enforce the use of fall protection equipment for workers operating at height.

Analyzed Image

