

UAUC Capture Report

Audit ID: MPSB-41 | Project: MPSB | 7/10/2026, 7:55:48 AM

4

Safety Issues Found

4

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Unsafe bending posture observed for one worker.	Musculoskeletal injury due to unsafe bending posture.
Safety vest not detected on one worker.	Reduced visibility of worker due to absence of safety vest, increasing risk of accidents.
Potential trip hazards due to scattered materials on the ground.	Trip and fall incidents due to scattered materials.
Worker operating in close proximity to suspended loads without proper barricades.	Struck-by incidents from suspended loads.

AI Recommendations

- Train workers on safe lifting and bending techniques to prevent musculoskeletal injuries. - Ensure all workers wear safety vests for visibility and compliance. - Improve housekeeping by removing scattered materials from the work area. - Install barricades or warning signs around areas with suspended loads to prevent struck-by incidents.
--

Analyzed Image

