

UAUC Capture Report

Audit ID: MPSB-42 | Project: MPSB | 7/10/2026, 1:32:46 PM

4

Safety Issues Found

4

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Unsafe bending posture observed for one worker.	Musculoskeletal injury due to unsafe bending posture.
Safety vest not detected on one worker.	Increased risk of injury due to lack of visibility without a safety vest.
Worker positioned on an elevated structure without visible fall protection.	Fall from height due to lack of fall protection.
Loose materials and tools scattered on the platform, creating trip hazards.	Trip and fall incidents due to scattered materials and tools.

AI Recommendations

- Train workers on safe lifting and bending techniques to prevent musculoskeletal injuries.
- Ensure all workers wear safety vests for visibility and compliance.
- Provide and enforce the use of fall protection equipment for workers on elevated structures.
- Improve housekeeping by organizing and securing loose materials and tools on the platform.

Analyzed Image

