

UAUC Capture Report

Audit ID: MPSB-43 | Project: MPSB | 10/7/2026, 2:21:07 pm

3

Safety Issues Found

3

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Unsafe bending posture observed for worker on the platform.	Musculoskeletal injury due to unsafe bending posture.
Coiled rope left on the walkway creating a trip hazard.	Trip and fall due to coiled rope on the walkway.
Worker sitting on an elevated platform without fall protection.	Fall from height due to lack of fall protection.

AI Recommendations

- Train workers on safe lifting and bending techniques.
- Remove coiled rope from the walkway to prevent trip hazards.
- Ensure workers on elevated platforms use fall protection equipment.

Analyzed Image

