

UAUC Capture Report

Audit ID: MSBP_Sarai Ghat-33 | Project: MSBP_Sarai Ghat | 6/15/2026, 8:59:00 AM

3

Safety Issues Found

3

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Worker on elevated platform without visible fall protection	Fall from height due to lack of fall protection
Loose cable on the ground creating a trip hazard	Tripping over loose cable leading to injury
Worker using a phone in a construction zone	Distraction from phone use causing accidents

AI Recommendations

- Ensure all workers on elevated platforms use proper fall protection equipment such as harnesses and guardrails.
- Organize and secure loose cables to eliminate trip hazards.
- Prohibit phone use in active construction zones unless necessary for work communication.

Analyzed Image

