

UAUC Capture Report

Audit ID: MSBP_Sarai Ghat-35 | Project: MSBP_Sarai Ghat | 6/15/2026, 2:40:39 PM

2

Safety Issues Found

2

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Worker not wearing a helmet	Head injury due to lack of helmet in case of falling objects
Potential trip hazard due to visible loose cables or hoses on the floor	Tripping and falling due to loose cables or hoses

AI Recommendations

- Ensure all workers wear helmets at all times in the construction area
- Organize and secure loose cables or hoses to eliminate trip hazards

Analyzed Image

