

UAUC Capture Report

Audit ID: MSBP_Sarai Ghat-38 | Project: MSBP_Sarai Ghat | 6/16/2026, 5:15:47 AM

3

Safety Issues Found

3

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Worker on elevated platform without visible fall protection.	Fall from height due to lack of fall protection.
Loose cable on the ground creating a trip hazard.	Tripping over loose cable leading to injury.
Worker using a mobile phone in a construction zone.	Distraction from mobile phone use causing accidents.

AI Recommendations

- Ensure all workers on elevated platforms use proper fall protection equipment such as harnesses. - Secure or remove loose cables from the ground to eliminate trip hazards. - Prohibit mobile phone use in active construction zones unless necessary for work communication.

Analyzed Image

