I2T FITTINGS: STOCK TAKE COUNT SHEET

Stock take = WH100 count of 29-30 Oct 2026 as in the first full workbook (31-10-26); MSUs counted 20-27 Oct. "Now" = workbook 12-11-26 after all job cards, restocks and transfers. Recount column is blank for a shelf count.

Code	Description	WH100 stock take	WH100 used since	WH100 in / replaced	WH100 transferred out	WH100 NOW	WH100 RECOUNT	WH600 now	WH400 now	WH300 now	WH500 now	All units now
I2T-0204	-02 BSPT MALE x -04 HOSE	0				0					7	7
I2T-0404	-04 BSPT MALE x -04 HOSE	0				1					4	5
I2T-0406	-04 BSPP MALE X -06 HOSE	2				2				2		4
I2T-0604	-06 BSPT MALE X -04 HOSE	0				0		2				2
I2T-0606	-06 BSPT MALE x -06 HOSE	1			2	**-1**		5			6	10
I2T-0608	-06 BSPT MALE X -08 HOSE	0				0		1			8	9
I2T-0806	-08 BSPT MALE x -06 HOSE	0		2		2					1	3
I2T-0808	-08 BSPT MALE x -08 HOSE	-1	2		4	0		4	6	6	8	24
I2T-1008	10BSPT MALE x -08 HOSE	0				0						0
I2T-1010	-10 BSPT MALE X -10 HOSE	0				0		4	4	2	4	14
I2T-1208	-12 BSPT MALE X -08 HOSE	0				0				2	5	7
I2T-1210	-12 BSPT MALE X -10 HOSE	0				0		4		2		6
I2T-1212	-12 BSPT MALE x -12 HOSE	0				2		3	3	4	6	18
I2T-1616	-16 BSPT MALE x -16 HOSE	0				0		2		0	4	6
I2T-2020	-20 BSPT MALE x -20 HOSE	0				0					1	1
I2T-2424	-24 BSPT MALE X -24 HOSE TAIL	0	1			8						8
I2T-3232	-32 BSPT MALE x -32 HOSE	0				0						0
I2T3232	32 BSPT - MALE X 32 HOSE	2				2						2

Red = below zero (I2T-0606 on WH100 is -1: queried).

Counted by: _____ Date: _____