


TRANSMISSION LOSS FACTORS:

1. MATERIAL AND GEOMETRY OF PANEL.
2. MOUNTING CONDITIONS.
3. LEAKS
4. ANGLE OF INCIDENCE OF SOUND.

$$TL \approx \underbrace{20 \log_{10}(ms)}_{Y-OFFSET} + \underbrace{20 \log_{10}(f)}_{SLOPE: POSITIVE} - 20 \log_{10}\left(\frac{f_{oc}}{f}\right)$$



Y-OFFSET. SLOPE - NEGATIVE.