



D




Pin	Signal
1	12V
2	DRIVER IN1
3	Vcc
4	DRIVER IN2
5	Vdd
6	PWM A
7	GND
8	DRIVER IN3
9	CPU_GND
10	DRIVER IN4
11	ENC A
12	ENC B

Pin connection diagram for J2 connector:

Pin	Signal
1	VDD
2	MOSI
3	GND_CPU
4	MISO
5	GND_CPU
6	SCK
7	GND_CPU
8	/SD CS
9	GND_CPU
10	/FRAM CS



Rev:
Id: 1/3



Sheet: /		
File: sd_i_fram.kicad_sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. 10.0.0	Id: 2/3	

