

MyFactoryInsight

Production Analytics Report

Site: **MECANITEC**

Report Period: 2026-05-17 13:02 UTC → 2026-05-17 13:02 UTC

Machines: 50 | Cycles: 3

Generated: 2026-05-17 13:02 UTC

Phase 09 — Reports v1.0.0

Fleet KPI Summary

OEE	Availability	Quality Rate	Total Pieces	Active Alarms
68.8%	77.0%	100.0%	1,219,089	6

Status Distribution

STATUS	MACHINES	PERCENTAGE
RUN	40	80.0%
IDLE	6	12.0%
FAULT	3	6.0%
MAINTENANCE	1	2.0%

Production & Temperature

METRIC	VALUE
Total Pieces Produced	1,219,089
Good Pieces	230
Bad / Scrap Pieces	0
Average Temperature	51.0 °C
Max Temperature	117.2 °C (machine37)
Critical Temp Machines	3
Warning Temp Machines	4

Machine Status Snapshot

MACHINE	TYPE	PROTOCOL	STATUS	ALARM	PIECES	TEMP °C	AVAIL
machine01	CNC	opcua	IDLE	—	44,259	17.8	67%
machine02	CNC	modbus	IDLE	—	1,828	10.2	33%
machine03	CNC	modbus	MAINTENANCE	400	27,552	42.8	67%
machine04	CNC	opcua	RUN	—	20,993	58.6	100%
machine05	CNC	modbus	RUN	—	23,442	22.7	100%
machine06	CNC	opcua	RUN	—	5,200	62.5	67%
machine07	CNC	opcua	RUN	—	34,844	35.4	100%
machine08	PRESS	mqtt	RUN	—	23,133	64.0	33%
machine09	ROBOT	mqtt	RUN	—	2,317	51.4	100%
machine10	CNC	modbus	RUN	—	14,987	44.3	100%
machine11	ROBOT	opcua	RUN	—	20,628	49.9	67%
machine12	CNC	modbus	RUN	—	49,171	71.2	50%
machine13	CNC	modbus	RUN	—	37,783	43.7	100%
machine14	CONVEYOR	opcua	RUN	—	2,199	31.9	100%
machine15	CONVEYOR	mqtt	RUN	—	45,291	20.9	67%
machine16	CNC	modbus	RUN	—	37,755	37.8	67%
machine17	WELDER	mqtt	RUN	—	4,599	108.2	100%
machine18	PRESS	mqtt	RUN	—	34,179	77.0	100%
machine19	CNC	opcua	IDLE	—	19,308	41.1	67%
machine20	PRESS	mqtt	RUN	—	39,864	80.4	100%
machine21	CNC	modbus	RUN	—	12,711	34.4	100%
machine22	CNC	modbus	RUN	—	21,156	21.5	67%
machine23	CNC	modbus	RUN	—	42,389	41.4	100%
machine24	CNC	modbus	FAULT	200	33,909	66.6	67%
machine25	ROBOT	mqtt	RUN	—	23,052	28.1	100%
machine26	CNC	modbus	RUN	—	19,615	35.7	67%
machine27	CNC	modbus	RUN	—	39,926	30.1	67%
machine28	CNC	modbus	RUN	200	29,857	30.6	67%
machine29	ROBOT	mqtt	RUN	—	4,216	48.8	100%
machine30	ROBOT	opcua	RUN	—	5,968	32.3	100%
machine31	CNC	modbus	RUN	—	13,969	31.2	67%
machine32	CNC	modbus	RUN	—	15,933	30.1	100%

MACHINE	TYPE	PROTOCOL	STATUS	ALARM	PIECES	TEMP °C	AVAIL
machine33	PRESS	opcua	RUN	—	19,989	81.6	33%
machine34	CNC	mqtt	RUN	—	29,235	50.2	67%
machine35	CNC	modbus	IDLE	—	2,191	54.6	67%
machine36	CNC	modbus	RUN	100	28,336	45.6	67%
machine37	WELDER	mqtt	RUN	—	21,787	117.2	100%
machine38	CNC	opcua	RUN	—	14,807	26.6	100%
machine39	WELDER	mqtt	RUN	—	31,589	40.5	67%
machine40	CNC	modbus	RUN	—	46,843	49.2	100%
machine41	CNC	modbus	IDLE	—	12,052	26.3	67%
machine42	CNC	opcua	FAULT	100	30,512	84.1	33%
machine43	CNC	modbus	RUN	—	34,066	110.9	100%
machine44	CNC	modbus	FAULT	100	35,492	74.1	67%
machine45	WELDER	opcua	RUN	—	46,144	74.5	67%
machine46	CNC	opcua	RUN	—	3,223	74.9	67%
machine47	CNC	modbus	RUN	—	36,653	46.6	67%
machine48	CNC	modbus	RUN	—	43,115	51.7	100%
machine49	CNC	modbus	RUN	—	4,644	113.6	67%
machine50	CONVEYOR	mqtt	IDLE	—	26,378	24.1	33%

Alarm Summary

ALARM CODE	DESCRIPTION	MACHINES AFFECTED	SEVERITY
400	MAINTENANCE_DUE	1	CRITICAL
200	COMM_ERROR	2	WARNING
100	OVERTEMP	3	WARNING