SES Clicker PCB

MCU Pinout

Pin	Туре	Protocol	Function	
A0	I	-	DW1000 TXE signal	
A0	0	-	DW1000 SPI polarity setting (setup phase)	
A1	I	-	DW1000 RXE signal	
A1	0	-	DW1000 SPI phase setting (setup phase)	
A2	Ю	SWD	SWDIO	
A3	Ю	SWD	SWCLK	
A4	0	-	DW1000 NRST	
A5	0	-	DW1000 WKUP	
A6	0	-	DW1000 Force on	
A8	Ю	UART	RX docked timestamp update	
A9	0	-	Status LED	
A10	I	BOOT	воото	
A12	0	SPI	SPI NSS	
A13	0	SPI	SPI CLK	
A14	I	SPI	SPI MISO	
A15	0	SPI	SPI MOSI	
В0	I	-	Clicker (IRQ)	
B1	I	-	UWB (IRQ)	
B2	I	-	Battery (IRQ)	
В3	I	ADC	Battery (voltage)	
B4	I	-	UWB sync	
B8 - B11	О	-	Battery status (4-bit)	

PCB Pinout

SW1

Pin	Net	
1	Clicker	
2	GND	

SW2

Pin	Net
1	Battery_IRQ
2	GND

J1

Pin	Net
1	VIN
2	RX
3	SWDIO
4	SWCLK
5	GND

J2

Pin	Net	
1	BAT+	
2	GND	

PCB Dimensions

Zero Point: TOP-LEFT (outside rounded corner)

Edge cuts

Dimension	Measurement (mm)	
Width	30	
Height	85.5	
Corner Radius	0.75	

Mounting

Dimension	Measurement (mm)	
Width	22	
Height	60	

LEDs

LED	x (mm)	y (mm)
PWR	2	31.15
Status	2	32.7
Battery_status[3]	2	34.25
Battery_status[2]	2	35.8
Battery_status[1]	2	37.35
Battery_status[0]	2	38.9
UWB RX_OK	28.725	61.825
UWB SFD	27.175	61.825
UWB RX	25.625	61.825
UWB TX	24.075	61.825
Battery charger PG	19.4375	26.225
Battery charger STAT 1	20.9875	26.225
Battery charger STAT 2	22.5375	26.225