## MATLAB CODE FOR SERIAL INPUTTING AND PLOTTING OF WAVEFORM

```
clear all;clc;close all;
arduino=serial('COM6','BaudRate',9600);
fopen(arduino);
x=1:100;
for i=1:length(x)
        y(i)=fscanf(arduino,'%d');
end
t = y/1024*5;
A = y;
count=zeros(0,1023);
for k=1:1024
count(k)=length(find(A==(k-1)));
end
m = max(count);
in = find(count==m);
fclose(arduino);
disp('making plot..')
figure('Name','The Digital Values From Serial Port');
subplot(2,2,1)
plot(x,y);
title('Serial Port Data');
ylim([0 1023]);
```

```
xlabel('From Serial Port');
ylabel('Digital Voltage');
subplot(2,2,2)
plot(x,t);
title('The Analog Plot Of Voltage');
ylim([0 5]);
xlabel('From Serial Port');
ylabel('Analog Voltage');
fprintf('%d is found toh be maximum count of %d ',in-1,m);
subplot(2,2,3)
t = 0:1023;
plot(t,count),title('Frequency Count');
xlabel('Digital Value');
ylabel('No Of Occurences');
xlim([0 1023]);
subplot(2,2,4)
d = count/length(A)*100;
plot(t,d);
title('Digital Values Frequency Percentage');
xlabel('Digital Value');
ylabel('Percentage of No Of Occurences');
xlim([0 1023]);
```