


Pick & Place Basic / PLC_1 [CPU 1211C DC/DC/DC] / Program blocks

PIC & Plcae Func [FC1]


PIC & Plcae Func Properties							
General							
Name	PIC & Plcae Func	Number	1	Type	FC	Language	LAD
Numbering	Automatic						
Information							
Title		Author		Comment		Family	
Version	0.1	User-defined ID					

PIC & Plcae Func				
Name	Data type	Default value	Supervision	Comment
Input				
Output				
InOut				
Temp				
Constant				
▼ Return				
PIC & Plcae Func	Void			


Network 1:




Network 2:



Network 3:




Network 4:



Network 5:


```
graph LR; I1_1["%I1.1  
\"Auto\""] --- I0_4["%I0.4  
\"Item Detected\""]; I0_4 --- Q0_4["%Q0.4  
\"Grab\""]; Q0_4 --- I0_3["%I0.3  
\"Moving Z\""]; I0_3 --- I0_2["%I0.2  
\"Moving x\""]; I0_2 --- Q0_3["%Q0.3  
\"Move z\""]; I0_2 --- M0_2["%M0.2  
\"Moving x mem 1\""]; Q0_3 --- S["(S)"]
```



Network 6:


```

graph LR
    I11["%I1.1  
\"Auto\""] --- Q02_1["%Q0.2  
\"Move X\""]
    Q02_1 --- I01["%I0.1  
\"Item at Exit\""]
    I01 --- I03["%I0.3  
\"Moving Z\"  
\"Tag_1\""]
    I03 --- R1["( R )  
%Q0.4  
\"Grab\""]
    I03 --- R2["( R )  
%Q0.3  
\"Move z\""]
    I03 --- R3["( R )  
%Q0.2  
\"Move X\""]
    I03 --- R4["( R )  
%Q0.2  
\"Move X\""]
  
```



Network 7:

```
graph LR; I11["%I1.1  
\"Auto\""] --- Q04["%Q0.4  
\"Grab\""]; Q04 --- I01["%I0.1  
\"Item at Exit\""]; I01 --- Q00_top["%Q0.0  
\"Entry Conveyor\""]; I01 --- Q00_bot["%Q0.0  
\"Entry Conveyor\""]; Q00_top --- Q01["%Q0.1  
\"Exit Conveyor\""]; Q00_bot --- Q01;
```



Network 8:

