

AI SERVICE-CALL SIMULATOR • HVAC

FIELDREADY

Practice the service call before it is real.

UNIT Carrier 24ACC636

SCENARIOS 8

CHECKS 22

READINGS Simulated

THE PROBLEM

THE PRACTICE GAP

Diagnostic judgment comes from repetition, and the calls that teach the most are the hardest to stage.

Rare faults

A trainee cannot count on meeting an open fan-motor winding during training.

Unsafe to reproduce

Creating a real fault on energized equipment puts learners at risk.

Limited lab time

Hands-on sessions are short, and there is little to practice on between them.

HOW IT WORKS

A PRACTICE CALL IN FIVE STEPS

01

Receive

A service request arrives, such as an air conditioner blowing warm air.

02

Interview

The trainee questions an AI homeowner about symptoms and history.

03

Check

They state an inspection or measurement and get a reading that fits the hidden fault.

04

Diagnose

They name the cause, cite the evidence and recommend a repair.

05

Debrief

A grading agent scores safety, order, evidence and the fix.

The homeowner never names the fault, and the simulator never coaches. The trainee has to reason their way there.

WHERE THE NUMBERS COME FROM

READINGS GROUNDED IN THE MANUALS

4

Carrier documents: service manual, installation instructions, wiring diagrams, product data

CITED • Service manual p. 11

26 V across the contactor coil. Normal is 20 to 30 V.

2

OSHA publications for safety framing: electrical hazards and lockout/tagout

22

Checks per scenario, each tagged with the manual page or marked as an assumption

ASSUMPTION • Listed in the brief

Dual run capacitor is rated 45/5 μ F, 440 V. The manuals do not state the rating.

FIELDREADY

PRACTICE THE SERVICE CALL BEFORE IT IS REAL.

`npm install` `npm run dev` `localhost:3000`