Westcam (Pty) Ltd Co. Registration No. 2009/017751/07 36 Forbes Rd, Blairgowrie, Randburg Gauteng, South Africa, 2194 083 678 2601

### Quotation QN2410/05

University of KwaZulu-Natal Att: Nkosinathi

Date: 22/10/2024

#### Consultation For Connection of Manta 282 to LTDVE2CH-20F

	Description	Hours	Cost	Total
1	Familiarisation with devices	1	R 1 000	R 1 000
2	Circuit design and generation of circuit diagram	2	R 1 000	R 2 000
			Sub Total	R 3 000
			Total	R 3 000

Payment Terms: C.O.D

**Delivery**: 1 Weeks

Validity: 30 days

#### Guarantee

Our components and systems are guaranteed for 12 months unless otherwise stated. Guarantees supplied by sub suppliers and principle component manufacturers supersede this if there is a discrepancy. All guarantees fall away if the equipment is not utilized as per manufacturer guidelines or modified in any way without our written consent.

#### **Consequential damage**

We have no control over how the equipment is used and accept no consequential damage related to production loss, delivery of incorrect goods to your customers as a result of inspection failures or other related matters.

Westcam (Pty) Ltd
Co. Registration No. 2009/017751/07
36 Forbes Rd, Blairgowrie, Randburg
Gauteng, South Africa, 2194
083 678 2601

# Invoice IN2401/01

Att: Rose Lesese

Crabtree South Africa

Order No. 4700074227

**Repair of Lab Panel Current Reading Fault** 

		Description				Qty	Cost	Total
1	Offsite and calibration	onsite	fault	analysis	and	1	R 12 700	R 12 700
							Total	R 12 700

Westcam (Pty) Ltd
Co. Registration No. 2009/017751/07
36 Forbes Rd, Blairgowrie, Randburg
Gauteng, South Africa, 2194
083 678 2601

# Invoice IN2402/02

Crabtree South Africa Att: Rose Lesese

#### Repair of Lab05-2 Panel Current Reading Fault

	Description	Qty	Cost	Total
1	Additional work required for repair of Lab05-02	9	R 950	R 8 550
			Total	R 8 550

Westcam (Pty) Ltd Co. Registration No. 2009/017751/07 36 Forbes Rd, Blairgowrie, Randburg Gauteng, South Africa, 2194 083 678 2601

# Invoice IN2402/02A

Crabtree South Africa Att: Rose Lesese

**Order No.** 4700074799

#### **Repair of Lab05-2 Panel Current Reading Fault**

	Description	Qty	Cost	Total
1	Additional work required for repair of Lab05-02 – 33% payment	1	R 2 850	R 2 850
			Total	R 2 850

### Westcam (Pty) Ltd

Co. Registration No. 2009/017751/07 36 Forbes Rd, Blairgowrie, Randburg Gauteng, South Africa, 2194 083 678 2601

## Invoice IN2406/03

Crabtree South Africa Att: Rose Lesese

**Order No.** 4700074799

#### Repair of Lab05-2 Panel Current Reading Fault

	Description	Qty	Cost	Total
1	Additional work required for repair of Lab05-02 – Oustanding Balance (Engineering time at R950/hour)		R 5 700	R 5 700
			Total	R 5 700