## 4. Graphs and charts

### Overview

### Purpose

Graphs and charts are what you use to represent facts, statistics, or the relationship between physical properties. A visual or graphical description is often easier to understand than a numerical or verbal description. The gas technician/fitter must know how to read and correctly interpret the many types of graphs and charts in the gas industry.

### **Objectives**

At the end of this Chapter, you will be able to:

- · identify types of graphs and charts; and
- · locate data on graphs.

## Terminology

Term	Abbreviation (symbol)	on Definition		
Chart		Visual or graphical representation of data		
Graph		Same as chart		

# Types of graphs and charts

A graph or chart is a line or diagram showing how one quantity depends on, changes, or relates with, another. Graphs and charts represent facts, statistics, or the relationship between physical properties. A visual or graphical description is often easier to understand than a numerical or verbal description.


### **Applications**

You use graphs and charts in three general ways:

- · for graphical presentation of information;
- · for graphical analysis; and
- · for computing or determining values.

The type of graph or chart you use in an application depends on any of the following factors:

- · the audience it is directed at;
- the best type of graph to represent the information;



)	wai	viator the word/phrase that correctly completes each sentence/statement:					
		A/An gives no regard to spatial considerations because only the parts and their functions are important in these drawings. It does not show the actual size, shape, or location of components or devices within the system but rather emphasizes connections, functions, and flow:	Detail or assembly				
		visually represent pipes, fittings, valves, and other components, so they clearly illustrate and explain a piping system and how it operates:	Schematic				
	c)	Piping drawings can be either orthographic or  The latter often shows all the pieces in symbol form.	Schedule				
	d)	A/An projection is a two-dimensional look at an object.	Isometric				
		drawings show an object as it actually appears, with height, length, and width depicted in a single, three-dimensional view:	Orthographic				
	f)	drawings show a small part of the entire project in great detail.	Lines and symbols				
		A/An list shows details such as colour, terminal locations, etc., and they are often an attachment to a wiring diagram:	Pictorial				
))	Mat	ch the correct word/phrase to complete each statement:					
1)		echanical drawing scale that reads 1:2 means the drawing is actual size:	Specification				
		pecifications Book is aof the work to be primed:	Bill of materials				
;)		purpose of the Revision Block for any mechanical drawing is to my and all revisions made after thedrafting of the :	One Unit				
l)		n enlarged scale of 12:1 on a mechanical drawing means that neasuring Units on the print equal of the object:	One-half				
;)		ost instances, when there is a disagreement between the hanical Drawing and the Specification, theis usually considered to be correct:	Initial				
)		aterials Block is also referred to as It the number and size of each part for the object(s) on that print:	Written description				

Technical manuals, specifications, drawings, and graphs

- · the general purpose of the graph;
- · the significant features or relationships of the information;
- the way the graph will be used; and
- the type or amount of information.


# Types of graphs and charts

Four common graphs and charts are the:

- bar graph (also called bar or column chart);
- · pie chart (also called sector chart);
- X-Y graph (rectangular coordinate line graph); and
- · flow chart.

## Bar graph

Bar graphs are visual representations of numerical values by bars or columns of different lengths. The bars, which may be vertical or horizontal, begin at a baseline and indicate the relationship between two or more related variables. In Figure 4-1, the two variables are temperature in °F and resistance in ohms for a resistance temperature detector (RTD).



Bar charts are particularly suitable for the following purposes:

- to present information to a non-technical audience;
- · to represent small numbers of plotted values;
- · to make a simple comparison of two values along two axes; and
- · to represent data for a total period relative to point data.

GAS TRADE TRAINING UNIT 6

Technical manuals, specifications, drawings, and graphs

#### Disadvantages

Bar charts are not particularly suitable for the following purposes:

- · for comparing several series of data; and
- for plotting large numbers of values.


#### Pie Chart

You use pie charts to compare individual parts in relation to their total by representing them as sectors of a circular area. Its common uses are the following:

- · to visually present data on a percentage basis;
- to present a general overall view of certain information;
- · to show the relationship between a small number of values; and
- to emphasize the amount of data rather than a trend.

The pie chart in Figure 4-2 represents world energy consumption by fuel type for the year 2006. This example shows each fuel type as its percentage of the whole.

Figure 4-2 Sample pie chart



## X-Y graph

X-Y graphs have the values of two related variables plotted as points on a coordinates grid. The points are then joined together successively to form a continuous line or curve.

X-Y graphs have the following purposes:

- to compare large numbers of values in a compact space;
- to compare the trends of several curves on one graph; and
- to calculate values that fall between the plotted points.


**42** March 2022

## Reading X-Y graphs

On X-Y graphs, you see the values of the two variables plotted with reference to two axes that are perpendicular to one another, meeting at a common origin or zero point.

The curve on the X-Y graph in Figure 4-3 represents the relationship between flue gas temperature and the operating time of a burner. The x-axis is the time of burner operation in minutes and the y-axis is the flue gas temperature in degrees Celsius.


Figure 4-3 Sample X-Y graph




a burner adjusted to 120 000 Btuh.

The five lines labelled A, B, C, D, and E on the X-Y graph in Figure 4-4 represent the relationship between outside air temperature (x-axis) and the operating time (y-axis) of each of five different building's heating systems.







## Disadvantages

X-Y graphs are generally unsuitable for:

- · representing small numbers of plotted values in a series;
- · showing changes or differences in absolute amounts; and
- showing extreme or irregular movements of data.


#### Flow chart

A flow chart is generally a schematic representation of a process flow, showing the information in several ways, including:

- · pictorial form;
- schematic symbols;
- · labelled blocks; and
- · combinations of all three.

The flow chart in Figure 4-5 shows the water circulation flow-path through a hot-water heating system. In Figure 4-5, the arrowheads indicate the direction of water flow through the system, schematic symbols represent the valves, and the boiler and radiator are in pictorial form.

Figure 4-5
Flow chart showing water circulation through a hot-water heating system




# Locating data on graphs


The X-Y chart in Figure 4-6 is what you use to determine the correct termination height for a vent on roofs with a pitch greater than 9/12. You can see the roof pitch values along the x-axis, and the minimum allowable vertical distance from the roof surface to the lowest opening in the top along the y-axis.

To determine the correct termination height for a vent or chimney, using this chart, do the following:

- 1) Determine the pitch of the roof (x-axis).
- 2) Locate the point on the diagonal line in the chart that coincides with the roof pitch by tracing a line from the roof pitch value vertically up the y-axis.
- 3) Trace the horizontal line nearest the point where the roof pitch value crosses the diagonal line back to the distance scale along the y-axis.
- 4) The corresponding value on the y-axis scale indicates the minimum allowable vertical distance between the vent or chimney discharge and the nearest obstruction or opening.







# Assignment Questions – Chapter 4

- 1) Which of the following is not a general way graphs and charts are used?
  - a) Determining location of equipment
  - b) Graphical presentation of information
  - c) Graphical analysis
  - d) Computing or determining values
- 2) Which type of chart compares individual parts in relation to their total and displays this relationship as sectors of a circular area?
  - a) Flow chart
  - b) Eye chart
  - c) Pie chart
- 3) Which type of chart is (generally) a schematic representation of a process?
  - a) Flow chart
  - b) Eye chart
  - c) Pie chart