Terminal	ð X
Original # :000000001010101 Hamming # :0000001101001010 ======================	
Test With Bad Data Bit Test Number:0000001101001110 Bad Bit at : 11 Corrected #:000000001010101 Match OK	
Test With Bad Parity Bit Test Number:0000001101001011 Corrected #:000000001010101 Cant Correct	
Input	Clear output