

# Continuity Report — previous record to current condition

Property AP-3318 · Sea Point · 2-bed apartment, long-term let

## PREVIOUS RECORD

Ingoing inspection report, 14 Mar 2024 (agency platform, 9 pp.)

## CURRENT WALKAROUND

AssetProof specialist, 2 Sep 2026

## LEASE STATUS

Tenant in occupation · lease running

6

Carried over — unchanged or worsened

3

New since previous record

3

Resolved since previous record

100%

Prior items accounted for

## Item-by-item continuity

| Area      | Item                                    | Previous | Now  | Status       | Note                                              | Prev. ref | Evidence |
|-----------|-----------------------------------------|----------|------|--------------|---------------------------------------------------|-----------|----------|
| Lounge    | Wall, north — scuff marks near TV unit  | Fair     | Fair | Carried over | Unchanged since previous record                   | P-4 · #07 | LG-03    |
| Lounge    | Ceiling — hairline crack above window   | Fair     | Fair | Carried over | Unchanged; no widening observed                   | P-4 · #09 | LG-06    |
| Lounge    | Carpet — stain near sliding door        | Fair     | —    | Resolved     | Carpet replaced with laminate flooring            | P-4 · #11 | LG-08    |
| Kitchen   | Hob — front-left plate not heating      | Poor     | Good | Resolved     | Plate replaced; tested working                    | P-5 · #03 | KT-02    |
| Kitchen   | Cupboard door under sink — swollen base | —        | Poor | New          | Water damage to base edge; not on previous record | —         | KT-07    |
| Kitchen   | Splashback tiles — 1 chipped            | Fair     | Fair | Carried over | Unchanged                                         | P-5 · #08 | KT-04    |
| Bathroom  | Shower silicone — mould along tray      | Poor     | Poor | Carried over | Worsened; reseal advised                          | P-6 · #02 | BT-03    |
| Bathroom  | Towel rail — loose fixing               | —        | Fair | New          | Rail moves under light pressure                   | —         | BT-06    |
| Bedroom 1 | Door — dent at handle height            | Fair     | Fair | Carried over | Unchanged                                         | P-6 · #10 | B1-02    |
| Bedroom 1 | Built-in cupboard — missing shelf       | Missing  | Good | Resolved     | Shelf present and fitted                          | P-6 · #12 | B1-05    |
| Bedroom 2 | Window — cracked pane, bottom left      | —        | Poor | New          | Crack approx. 15 cm; not on previous record       | —         | B2-04    |
| Bedroom 2 | Wall — Prestik marks above bed          | Fair     | Fair | Carried over | Unchanged                                         | P-7 · #04 | B2-01    |

"Prev. ref" = page and item number in the previous inspection report. "Evidence" = photo reference in the current AssetProof record. Extract shown — the full register lists every item in every room.

# What this means for the lease

Property AP-3318 · Sea Point

## Baseline for the current lease

The ingoing report of 14 Mar 2024 remains the governing baseline for this tenant's lease. This Continuity Report **adds to** that record; it does not replace it. All three "New" items arose after the previous record and are documented with dated photographs.

## From the next changeover

At the next tenant change, the AssetProof Photographic Condition Inspection becomes the new ingoing baseline — every surface of every room, photographed and rated, with a Re-Walk Comparison Sheet for each later visit.

## Recommended actions

| Item                       | Priority | Recommendation                                            | Likely responsibility                |
|----------------------------|----------|-----------------------------------------------------------|--------------------------------------|
| Kitchen — cupboard base    | High     | Check sink waste for leak before repairing cupboard base. | Landlord / tenant — to confirm cause |
| Bedroom 2 — window pane    | High     | Replace cracked pane (safety and security).               | To be determined at lease end        |
| Bathroom — shower silicone | Medium   | Remove and reseal; advise tenant on ventilation.          | Landlord (maintenance)               |
| Bathroom — towel rail      | Low      | Re-fix rail with suitable wall plugs.                     | Landlord (maintenance)               |

## The documents that come with it

- ✓ **Photographic Condition Inspection** — room-by-room, surface-by-surface record
- ✓ **Inventory & Condition Register** — every item listed, like-items counted
- ✓ **Re-Walk Comparison Sheet** — opens on a phone for the next visit
- ✓ **Owner Report** — plain-English summary for the landlord

## Acknowledgement

Landlord and tenant are invited to review this record and note any disagreement within 7 days of receipt.

Landlord / agent — name, signature, date

Tenant — name, signature, date

Sample report. Property code, location and all details are illustrative. Real reports are issued in de-identified form whenever they are shared beyond the owner and managing agent.