

SNAG & MAINTENANCE REPORT

Snag & Maintenance Report

Every finding, prioritised, costed and turned into an instruction

PROPERTY

Two-bedroom house, City Bowl, Cape Town

REFERENCE

SAMPLE-B

INSPECTION DATE

20 July 2026

AREAS RECORDED

15



1 What needs doing, in the order it needs doing

A published AssetProof sample. A real, complete record with every identifying detail removed — no address, no owner or agent name, no contact details, and no image showing a street frontage, a neighbouring property or a vehicle registration.

Every one of the 230 findings from the condition inspection, sorted by what it actually costs you to ignore. The safety and urgency items come first, then the functional ones, then the cosmetic. Indicative cost bands are given so the list can be budgeted, not just read; they are planning figures, not quotations.

2 The work in front of you

13ACT BEFORE
OCCUPATION**57**

TREAT AND MONITOR

105

COSMETIC / FAIR WEAR

26

RE-INSPECT

3 Priority 1 — before the property is let, photographed or occupied

REF	AREA	FINDING	ACTION	INDICATIVE COST
F012	Pool courtyard	Pool water appears green/algae-affected, not clear	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R2,500 – R8,000
F014	Pool courtyard	Pool water green/algae-tinted (visible in background)	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R2,500 – R8,000
F016	Pool courtyard	Pool water severely green and murky, algae bloom	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R2,500 – R8,000
F017	Pool courtyard	Dark sediment/algae buildup visible on submerged pool steps and floor	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R2,500 – R8,000
F020	Exterior & entrance	Dark damp-like staining and moss/algae discolouration on unfinished concrete wall section	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R2,500 – R8,000

REF	AREA	FINDING	ACTION	INDICATIVE COST
F022	Pool courtyard	Pool water green/algae-tinted	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R2,500 – R8,000
F024	Pool courtyard	Pool water is green/algae-affected, not clear	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R2,500 – R8,000
F025	Pool courtyard	Dark staining/algae marks on pool wall and floor	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R2,500 – R8,000
F107	Lounge	Amber warning indicator illuminated on the alarm panel, indicating a fault or an unset zone	Alarm technician to clear the fault, walk-test every zone and confirm the panel arms clean.	R2,500 – R8,000
F116	Laundry / utility & storage	Exposed orange and black cabling around the alarm control box, not fully enclosed	Electrician to enclose and terminate the cabling properly, and issue or update the electrical certificate of compliance.	R2,500 – R8,000
F151	Laundry / utility & storage	Scattered small dark speckled marks (possible dirt or mould) on left interior panel	Clean back, establish the moisture source, treat, and re-inspect after a wet spell.	R2,500 – R8,000
F228	Pool courtyard	Pool water is green and murky, indicating algae growth or neglected water treatment	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R2,500 – R8,000
F230	Pool courtyard	Pool water is green/murky, consistent with algae or lack of maintenance	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R2,500 – R8,000

4 Priority 2 – functional: treat, then monitor

REF	AREA	FINDING	ACTION	INDICATIVE COST
F002	Outdoor courtyard & braai	Patchy/thin grass in lawn area	Scarify, top-dress and re-seed; bring into the standing garden round.	R500 – R2,500
F003	Outdoor courtyard & braai	Weathered, discoloured/algae-stained wood on the step edging below the deck	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R500 – R2,500

REF	AREA	FINDING	ACTION	INDICATIVE COST
F005	Garage	Crack/joint line across concrete floor near garage door threshold	Rake out, fill and make good; monitor for movement at the next inspection.	R500 – R2,500
F006	Garage	Weathered/stained driveway paving	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F007	Exterior & entrance	Patchy/thin lawn areas	Scarify, top-dress and re-seed; bring into the standing garden round.	R500 – R2,500
F009	Pool courtyard	Dust/grime buildup on the white security gate bars	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F013	Pool courtyard	Water staining/discolouration on the white pool surround	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R500 – R2,500
F018	Pool courtyard	Hairline cracks in the white pool-surround paving	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R500 – R2,500
F019	Pool courtyard	Grime/staining on paving surface	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F021	Exterior & entrance	Rough, unpainted/unfinished concrete patch contrasting with surrounding painted walls	Make good and paint to match the surrounding finish.	R500 – R2,500
F023	Pool courtyard	Hairline crack visible in paved step/platform near water butt	Rake out, fill and make good; monitor for movement at the next inspection.	R500 – R2,500
F032	Lounge	Heavy creasing and wrinkling across all leather cushions consistent with distressed-style leather or wear	Attend at the next maintenance round and re-inspect.	R500 – R2,500
F039	Lounge	Visible splits/cracks in the wood slats of the trunk-table top	Rake out, fill and make good; monitor for movement at the next inspection.	R500 – R2,500
F047	Main en-suite bathroom	Visible pale mineral/water staining on the tiled wall behind the basins	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500

REF	AREA	FINDING	ACTION	INDICATIVE COST
F054	Kitchen	Green/dark tarnish or residue build-up around bases of several control knobs on the right side	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F063	Kitchen	Wire rack tines appear bent/splayed out of alignment in places	Attend at the next maintenance round and re-inspect.	R500 – R2,500
F064	Kitchen	Torn or lifting rubber door seal/gasket visible at top of door opening	Replace the door seal – a stocked part on this appliance.	R500 – R2,500
F066	Additional bedroom – attribution not resolved	Hairline seam/crack lines visible in ceiling bulkhead following the angled step pattern	Rake out, fill and make good; monitor for movement at the next inspection.	R500 – R2,500
F086	Bedroom 2	Dark stain/knot mark near the front-left corner of the table top	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F101	Lounge	Dark stain/blotch marks on the seat cushion of the chaise section	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F103	Lounge	Natural crack/split running across the wood-slab coffee table top	Rake out, fill and make good; monitor for movement at the next inspection.	R500 – R2,500
F109	Lounge	Crack and open gap in the plaster where the door architrave meets the ceiling corner	Rake out, fill and make good; monitor for movement at the next inspection.	R500 – R2,500
F112	Garage	Floor finish appears worn/patchy in places	Attend at the next maintenance round and re-inspect.	R500 – R2,500
F113	Laundry / utility & storage	Heavy dark staining/streaking on the washing machine's front panel, especially below and around the door - possibly rust, mould, or detergent residue	Clean back, establish the moisture source, treat, and re-inspect after a wet spell.	R500 – R2,500
F117	Laundry / utility & storage	Unpainted, unfinished timber strip at the head of the door opening	Make good and paint to match the surrounding finish.	R500 – R2,500
F118	Laundry / utility & storage	Bare, unfinished concrete floor with dark staining	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F122	Garage	Hairline crack in wall near floor corner	Rake out, fill and make good; monitor for movement at the next inspection.	R500 – R2,500
F124	Garage	Concrete floor unfinished/bare	Make good and paint to match the surrounding finish.	R500 – R2,500

REF	AREA	FINDING	ACTION	INDICATIVE COST
F125	Garage	Moss/algae staining on stone steps and paving	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R500 – R2,500
F126	Garage	Slight water staining at base of wall near garage entrance	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F127	Outdoor courtyard & braai	Patchy, weedy, unmown lawn with bare soil patches	Scarify, top-dress and re-seed; bring into the standing garden round.	R500 – R2,500
F128	Outdoor courtyard & braai	Visible horizontal crack or joint line in the low boundary wall render	Rake out, fill and make good; monitor for movement at the next inspection.	R500 – R2,500
F130	Outdoor courtyard & braai	Dark stain/soiling on seat cushion fabric	Scarify, top-dress and re-seed; bring into the standing garden round.	R500 – R2,500
F131	Outdoor courtyard & braai	General soiling and creasing on cushion covers consistent with outdoor weathering	Scarify, top-dress and re-seed; bring into the standing garden round.	R500 – R2,500
F136	Outdoor courtyard & braai	Rust on wire grill basket	Wire back, treat and re-coat; monitor.	R500 – R2,500
F139	Outdoor courtyard & braai	Exposed unconnected plumbing pipe with no fixture attached	Attend at the next maintenance round and re-inspect.	R500 – R2,500
F140	Outdoor courtyard & braai	Interior of wall niches left as bare unpainted cement/plaster, unfinished look	Make good and paint to match the surrounding finish.	R500 – R2,500
F142	Outdoor courtyard & braai	Dark stain/weathering at one wooden corner joint of the coffee table	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F144	Exterior & entrance	Dark algae/moisture staining on concrete steps	Instruct a pool specialist: shock treatment, filtration run, vacuum the sediment off the steps and floor, then re-test and re-inspect.	R500 – R2,500
F145	Exterior & entrance	Hairline crack in concrete riser near planter	Rake out, fill and make good; monitor for movement at the next inspection.	R500 – R2,500

REF	AREA	FINDING	ACTION	INDICATIVE COST
F150	Laundry / utility & storage	Brownish/tan smear stains on white interior back panel	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F152	Laundry / utility & storage	General grime/dust build-up on interior surfaces	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F162	Exterior & entrance	Driveway paving stained and weathered with dark patches	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F166	Garage	Concrete floor has multiple dark stains/patches	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F170	Outdoor courtyard & braai	Concrete paver steps stained and worn	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F171	Outdoor courtyard & braai	Patchy lawn with bare/muddy areas	Scarify, top-dress and re-seed; bring into the standing garden round.	R500 – R2,500
F175	Exterior & entrance	Driveway paving stained/weathered	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F176	Exterior & entrance	Driveway paving stained/weathered	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F177	Exterior & entrance	Paving stones heavily stained with dark patches/discolouration throughout	Deep clean; if it does not lift, treat professionally and re-inspect.	R500 – R2,500
F181	Garage	Ladder shows heavy paint splatter and surface wear, rust at hinge joints	Wire back, treat and re-coat; monitor.	R500 – R2,500
F201	Kitchen	Diagonal crack or open seam at the wall corner beside the door architrave	Rake out, fill and make good; monitor for movement at the next inspection.	R500 – R2,500
F204	Kitchen	Metal transition strip on floor at left edge appears slightly raised/uneven	Re-fix the threshold strip flush – a trip hazard as much as a finish issue.	R500 – R2,500
F205	Kitchen	Metal threshold strip appears slightly raised where it meets the timber floor	Re-fix the threshold strip flush – a trip hazard as much as a finish issue.	R500 – R2,500

REF	AREA	FINDING	ACTION	INDICATIVE COST
F220	Lounge	Leather shows extensive creasing/ wrinkling and a mottled worn appearance across the visible surface - could be a distressed-style finish or actual wear, not clearly distinguishable	Attend at the next maintenance round and re-inspect.	R500 – R2,500
F221	Lounge	Leather sofa shows heavy creasing/ wrinkling consistent with wear or distressed-style finish across both visible cushions	Attend at the next maintenance round and re-inspect.	R500 – R2,500
F225	Main bedroom suite	One section of the venetian blind slats hangs unevenly/crookedly compared to the rest	Re-level and re-tension the slats; replace the tape if it has stretched.	R500 – R2,500
F226	Main bedroom suite	Venetian blind slats hang unevenly/ crookedly on the lower section of the window	Re-level and re-tension the slats; replace the tape if it has stretched.	R500 – R2,500

5 Priority 3 – cosmetic and fair wear

None of this stops the property being let. It is listed so that it is a decision rather than an oversight, and so it cannot later be called damage.

REF	AREA	FINDING	ACTION
F001	Outdoor courtyard & braai	Dirt/staining in patio slab grout lines	Deep clean; if it does not lift, treat professionally and re-inspect.
F004	Outdoor courtyard & braai	Worn/rough concrete texture on the paving/step base	Attend at the next maintenance round and re-inspect.
F008	Garage	Light scuff marks on top surface of the washing machine	Attend at the next maintenance round and re-inspect.
F010	Pool courtyard	Dry needles/debris scattered on the artificial turf	Attend at the next maintenance round and re-inspect.
F011	Exterior & entrance	Visible plaster/render texture patchiness on wall surface	Attend at the next maintenance round and re-inspect.
F015	Pool courtyard	Scuff marks and dirt on white lounge chair surfaces	Attend at the next maintenance round and re-inspect.
F026	Pool courtyard	General grime marks on paving stones	Deep clean; if it does not lift, treat professionally and re-inspect.
F028	Pool courtyard	Small debris/insect nest clump inside one glass pane of the lantern	Attend at the next maintenance round and re-inspect.
F029	Pool courtyard	General grime and weathering to the metal body of the exterior wall lantern	Deep clean; if it does not lift, treat professionally and re-inspect.

REF	AREA	FINDING	ACTION
F030	Lounge	Sooty/blackened staining inside the fireplace insert (expected wear from use)	Deep clean; if it does not lift, treat professionally and re-inspect.
F031	Lounge	Small chip/notch in plaster step beside the fireplace opening	Attend at the next maintenance round and re-inspect.
F034	Lounge	Visible vertical crease/wear marks and light staining on the lower front seat cushion of the grey armchair	Deep clean; if it does not lift, treat professionally and re-inspect.
F035	Lounge	Some fine surface fuzz/pilling texture visible on the armchair fabric	Attend at the next maintenance round and re-inspect.
F036	Dining	A round knot-like opening in one floorboard near the centre of the dining floor, possibly an old fixture hole	Attend at the next maintenance round and re-inspect.
F037	Dining	A visible seam/gap line running across the floorboards	Attend at the next maintenance round and re-inspect.
F038	Dining	Table surface shows some faint watermark/blotch discoloration in the wood	Attend at the next maintenance round and re-inspect.
F040	Lounge	One slat on the trunk appears raised or misaligned relative to others	Re-level and re-tension the slats; replace the tape if it has stretched.
F043	Main en-suite bathroom	Visible seam/joint gap in wooden flooring near shower threshold	Attend at the next maintenance round and re-inspect.
F048	Main bedroom suite	Mattress is bare with no bedding/linen fitted	Make good and paint to match the surrounding finish.
F050	Kitchen	Small dark mark/dot on interior cabinet side wall, possibly a screw hole or blemish	Attend at the next maintenance round and re-inspect.
F051	Kitchen	Small brown/orange stain on the top square saucer in the stacked pile	Deep clean; if it does not lift, treat professionally and re-inspect.
F052	Kitchen	Light dust and fingerprint smudges on toaster's stainless steel body	Deep clean; if it does not lift, treat professionally and re-inspect.
F053	Kitchen	Faint vertical mark/shadow on painted wall near the emergency button	Attend at the next maintenance round and re-inspect.
F055	Kitchen	Light dust/residue build-up around the brand badge	Deep clean; if it does not lift, treat professionally and re-inspect.
F056	Kitchen	Dark mark/smudge on white laminate shelf surface	Attend at the next maintenance round and re-inspect.
F057	Kitchen	Cabinet interior shows general wear consistent with under-sink storage	Attend at the next maintenance round and re-inspect.
F058	Kitchen	Staining/residue marks on black oven grill tray surface (ridged section)	Deep clean; if it does not lift, treat professionally and re-inspect.

REF	AREA	FINDING	ACTION
F059	Laundry / utility & storage	Small dark speckled marks/residue on the lower countertop surface (left of centre)	Attend at the next maintenance round and re-inspect.
F061	Kitchen	Light fingerprint/smudge marks on stainless steel door surface (minor, cosmetic)	Deep clean; if it does not lift, treat professionally and re-inspect.
F065	Kitchen	Water spot residue and minor food debris specks on interior walls	Attend at the next maintenance round and re-inspect.
F067	Additional bedroom – attribution not resolved	Reflective glare patches to the left bedroom wall – paint sheen variation rather than a defect on the balance of what is visible	Attend at the next maintenance round and re-inspect.
F068	Additional bedroom – attribution not resolved	Glossy glare/reflection patches on several planks suggesting a sheen inconsistency or wet-look finish	Attend at the next maintenance round and re-inspect.
F069	Additional bedroom – attribution not resolved	Visible grout-like seams between planks with slight colour mismatch on some boards	Attend at the next maintenance round and re-inspect.
F071	Kitchen	Surface shows glossy sheen with some scuff/wear marks in high-traffic area near cabinets	Attend at the next maintenance round and re-inspect.
F072	Kitchen	Floorboard gap and open seam running across the kitchen floor	Attend at the next maintenance round and re-inspect.
F073	Kitchen	Wooden spoon heads show dark staining and wear consistent with heavy use	Deep clean; if it does not lift, treat professionally and re-inspect.
F076	Kitchen	Light water spot/residue marks on the glass lid of the front pot	Attend at the next maintenance round and re-inspect.
F077	Dining	Light reflection glare across the mid-floor area consistent with glossy tile finish, not damage	Attend at the next maintenance round and re-inspect.
F079	Bedroom 2	Mattress has no bedding - fully bare, exposing printed ticking pattern	Make good and paint to match the surrounding finish.
F084	Bedroom 2	Light dust settled on the blind slats	Re-level and re-tension the slats; replace the tape if it has stretched.
F085	Bedroom 2	Visible wood knots and small round blemish/knot marks on the table top surface	Attend at the next maintenance round and re-inspect.
F087	Bedroom 2	Varnish shows minor wear/scuff sheen variation on the table top	Attend at the next maintenance round and re-inspect.
F088	Bedroom 2	Numerous natural knots across floorboards - inherent to the pine, not damage	Attend at the next maintenance round and re-inspect.
F089	Bedroom 2	Board seam gaps visible where planks meet, normal for this floor type	Attend at the next maintenance round and re-inspect.

REF	AREA	FINDING	ACTION
F091	Second bathroom	Cupboard interior appears empty apart from two towels - no visible damage to shelving	Attend at the next maintenance round and re-inspect.
F097	Second bathroom	Small dark mark/residue spot near the drain area inside the basin	Attend at the next maintenance round and re-inspect.
F100	Lounge	Darker discoloured patch to one floor plank left of centre in the lounge — a stain, a water mark or natural grain variation; not resolved	Deep clean; if it does not lift, treat professionally and re-inspect.
F102	Lounge	Fine dust/lint visible on the sofa armrest fabric	Attend at the next maintenance round and re-inspect.
F104	Lounge	Small dark marks/scuffs on the wooden console surface	Attend at the next maintenance round and re-inspect.
F105	Lounge	Small dark smudge to the lounge wall, high on the left-hand return	Attend at the next maintenance round and re-inspect.
F106	Lounge	Small dark specks and marks to the wall beside the alarm panel	Alarm technician to clear the fault, walk-test every zone and confirm the panel arms clean.
F108	Lounge	A few small dark specks/marks on the ceiling near the panel seams	Attend at the next maintenance round and re-inspect.
F110	Lounge	Several small dark specks/spots on the wall to the right of the speaker	Attend at the next maintenance round and re-inspect.
F111	Garage	Various stains and scuff marks across the concrete garage floor	Deep clean; if it does not lift, treat professionally and re-inspect.
F114	Laundry / utility & storage	General surface wear/dirt on appliance fronts	Attend at the next maintenance round and re-inspect.
F115	Laundry / utility & storage	Light smudging/fingerprints on the mirrored door surface (minor, cosmetic)	Attend at the next maintenance round and re-inspect.
F119	Laundry / utility & storage	Washing machine door area shows scuffing/grime around the door surround	Deep clean; if it does not lift, treat professionally and re-inspect.
F120	Laundry / utility & storage	General scuffing and wear on cabinet interior surfaces	Attend at the next maintenance round and re-inspect.
F121	Laundry / utility & storage	Cluttered/disorganised storage typical of utility space	Attend at the next maintenance round and re-inspect.
F123	Garage	Scuff/dirt marks at wall base	Attend at the next maintenance round and re-inspect.
F129	Outdoor courtyard & braai	Staining on paved tiles	Deep clean; if it does not lift, treat professionally and re-inspect.
F132	Outdoor courtyard & braai	Mild creasing/wrinkling on cushion covers	Attend at the next maintenance round and re-inspect.

REF	AREA	FINDING	ACTION
F133	Outdoor courtyard & braai	Light general wear on wicker weave visible but no breaks	Attend at the next maintenance round and re-inspect.
F134	Outdoor courtyard & braai	Distinct circular amber/orange stain (resin or spill residue) on/under the glass table top corner	Deep clean; if it does not lift, treat professionally and re-inspect.
F135	Outdoor courtyard & braai	Adjacent whitish-green residue patch near the same corner	Attend at the next maintenance round and re-inspect.
F137	Outdoor courtyard & braai	Soot and ash residue built up inside firebox and on flip-down shelf	Attend at the next maintenance round and re-inspect.
F138	Outdoor courtyard & braai	Dirt/scuff mark on green painted pillar beside braai	Attend at the next maintenance round and re-inspect.
F141	Outdoor courtyard & braai	Visible dirt/grime staining on the seat cushion of the central armchair	Deep clean; if it does not lift, treat professionally and re-inspect.
F143	Outdoor courtyard & braai	Glass tabletop has light dust/smudging	Attend at the next maintenance round and re-inspect.
F146	Exterior & entrance	Muddy/bare patches in lawn between stepping stones	Scarify, top-dress and re-seed; bring into the standing garden round.
F147	Exterior & entrance	One gate panel section (top-left bay) is a noticeably lighter/different-toned wood than the rest, suggesting a repaired or replaced panel	Attend at the next maintenance round and re-inspect.
F148	Exterior & entrance	Driveway pavers show uneven weathering/staining across squares	Deep clean; if it does not lift, treat professionally and re-inspect.
F149	Exterior & entrance	Wall paint appears slightly scuffed near gate track	Attend at the next maintenance round and re-inspect.
F153	Kitchen	Visible colour/tone mismatch seam between two different wood sections of the countertop	Attend at the next maintenance round and re-inspect.
F154	Kitchen	Light general wear/patina on hob's stainless surface	Deep clean; if it does not lift, treat professionally and re-inspect.
F155	Laundry / utility & storage	Scattered small brownish marks/smudges in a rough horizontal band across the wall	Attend at the next maintenance round and re-inspect.
F157	Bedroom 2	Faint horizontal smudge mark on right wall at shoulder height	Attend at the next maintenance round and re-inspect.
F158	Bedroom 2	Mattress resting directly on the floor with no bed base beneath it	Attend at the next maintenance round and re-inspect.
F159	Kitchen	Diagonal scuff/scrape mark on wall surface	Attend at the next maintenance round and re-inspect.
F160	Kitchen	Scattered small dark specks (dirt or insect marks) across the wall	Attend at the next maintenance round and re-inspect.

REF	AREA	FINDING	ACTION
F161	Bedroom 2	Faint smudge to the bedroom wall at mid height, left of centre	Attend at the next maintenance round and re-inspect.
F163	Exterior & entrance	Gate surface shows scuffed/worn patina	Attend at the next maintenance round and re-inspect.
F164	Outdoor courtyard & braai	Lawn has visible bare and muddy patches	Scarify, top-dress and re-seed; bring into the standing garden round.
F167	Garage	Wooden ladder shows visible wear on rungs	Attend at the next maintenance round and re-inspect.
F169	Outdoor courtyard & braai	Wooden step edging shows heavy weathering/staining, dark patches	Deep clean; if it does not lift, treat professionally and re-inspect.
F172	Outdoor courtyard & braai	Floor tiles appear wet/reflective near doorway	Attend at the next maintenance round and re-inspect.
F178	Exterior & entrance	Retaining wall shows surface staining	Deep clean; if it does not lift, treat professionally and re-inspect.
F179	Exterior & entrance	Paving stained/discoloured with dark patches	Deep clean; if it does not lift, treat professionally and re-inspect.
F180	Garage	Concrete floor shows faint stains/patch marks	Deep clean; if it does not lift, treat professionally and re-inspect.
F184	Lounge	Noticeable lighter discoloured patch on the wood floor near the armchair, possible sun-fading or rug mark	Attend at the next maintenance round and re-inspect.
F185	Lounge	Small dark mark/spot on wall to left of TV, could be a scuff or nail hole	Attend at the next maintenance round and re-inspect.
F186	Lounge	Light discoloration/water-mark-like patch on the fabric of the chaise cushion, centre-right of the ottoman section	Attend at the next maintenance round and re-inspect.
F187	Second bathroom	Small square cut/access panel in the tiled tub skirt, lower left, could be read as a defect if not an intentional access hatch	Attend at the next maintenance round and re-inspect.
F188	Second bathroom	Visible floor trim/transition strip forming an odd raised outline near the corner, could indicate a floor level change or repair	Re-fix the threshold strip flush – a trip hazard as much as a finish issue.
F190	Laundry / utility & storage	Multiple small dark specks/marks scattered on the interior surfaces of the cabinet, possibly dirt or insect debris	Attend at the next maintenance round and re-inspect.
F191	Laundry / utility & storage	Multiple small dark specks/marks on interior cabinet walls across two shelf levels	Attend at the next maintenance round and re-inspect.

REF	AREA	FINDING	ACTION
F193	Additional bedroom – attribution not resolved	Diagonal seam/line across ceiling, possibly a board joint	Attend at the next maintenance round and re-inspect.
F195	Additional bedroom – attribution not resolved	Visible colour/tone variation between individual floor tiles (patchwork appearance)	Attend at the next maintenance round and re-inspect.
F199	Additional bedroom – attribution not resolved	Floor shows scattered lighter scuff marks	Attend at the next maintenance round and re-inspect.
F202	Kitchen	Fridge door surface shows reflected glare and minor smudging	Attend at the next maintenance round and re-inspect.
F206	Kitchen	Floorboard seam/gap visible near the threshold strip	Attend at the next maintenance round and re-inspect.
F213	Dining	Small round metal fitting embedded in floor within the seamed area	Attend at the next maintenance round and re-inspect.
F216	Lounge	A scuff or chip mark is visible on the white skirting board directly in front of the fireplace opening	Attend at the next maintenance round and re-inspect.
F217	Lounge	Fireplace interior sooted and darkened, consistent with use; the recess is unlit and the flue was not inspected	Attend at the next maintenance round and re-inspect.
F227	Main bedroom suite	Numerous water spots/droplets on the window glass behind the blinds	Re-level and re-tension the slats; replace the tape if it has stretched.

6 To be looked at again

Inspected, but the detail was not established with confidence. A short follow-up inspection closes each of these.

REF	AREA	WHAT TO LOOK AT
F060	Laundry / utility & storage	Wall finish above the counter could not be read with confidence under the light falling on it; listed for closer inspection
F062	Kitchen	Surface detail of the appliance door panel not established with confidence; listed for closer inspection
F156	Laundry / utility & storage	Wall finish in this section not established in fine detail; listed for closer inspection
F165	Garage	Garage wall and floor surfaces not established in fine detail; listed for closer inspection
F168	Garage	Garage interior recorded under low light; fine surface detail not established, listed for closer inspection
F173	Outdoor courtyard & braai	Surface condition at this position not established; listed for closer inspection

REF	AREA	WHAT TO LOOK AT
F174	Outdoor courtyard & braai	Patio surface detail not established in fine detail; listed for closer inspection
F182	Garage	Garage surface detail not established in fine detail; listed for closer inspection
F183	Laundry / utility & storage	Surface condition at this position not established; listed for closer inspection
F189	Second bathroom	Fine surface detail at this position not established; listed for closer inspection
F192	Lounge	Lounge surface detail not established in fine detail; listed for closer inspection
F194	Additional bedroom – attribution not resolved	Ceiling and wall detail at this position not established; listed for closer inspection
F196	Bedroom 2	Bedroom surface detail not established in fine detail; listed for closer inspection
F197	Bedroom 2	Bedroom surface condition not established in fine detail; listed for closer inspection
F198	Additional bedroom – attribution not resolved	Darker rectangular patches on floor, possibly wear, stains, or shadow (unclear which)
F200	Additional bedroom – attribution not resolved	Overexposed window obscures view outside/of blind condition
F203	Kitchen	Surface condition of this fitting not established; listed for closer inspection
F207	Kitchen	Small dark mark on the countertop near the wall junction, cause unclear (could be a chip, stain, or shadow)
F209	Kitchen	Glassware not inspected individually for chips; listed for closer inspection
F210	Lounge	Lounge surface condition not established at this position; listed for closer inspection
F211	Kitchen	Wall and sill condition beside the kitchen window not established under the light falling on it; listed for closer inspection
F212	Dining	Rectangular seam or outline in the dining floor mid-room – possibly a hatch or an old repair; not resolved
F218	Pool courtyard	Exterior wall and step surfaces beyond the window not established through the glazing and blind; listed for closer inspection
F219	Pool courtyard	Exterior wall and step surfaces beyond the window not established through the glazing and blind; listed for closer inspection
F224	Additional bathroom – attribution not resolved	Interior surface detail of this fitting not established; listed for closer inspection
F229	Pool courtyard	Window glass is heavily covered in dust/grime spots, reducing visibility

7 Compliance and plant not yet established

MATTER

POOL — water is severely green and algae-affected with sediment on the submerged steps and floor. Treatment is required before any listing photography, viewing or tenancy

Pool pump and filtration equipment were never photographed — a short follow-up record is needed to complete the plant record

Confirm the function of the wall-mounted 'DRUID' control unit

Four images are indistinct or indeterminate and carry no inventory; re-inspect if those areas matter

Room attribution to confirm for one single-bed room, one empty wood-look-tiled room and one indistinct taupe-walled room — the photographs do not establish which bedroom they are

Appliance model and serial plates to be photographed close-up for the insurance record

Insurer name and policy number

Principal owner name behind the managing agent

Geyser, roof and gutter/rainwater-harvesting installation not recorded

Electrical and gas compliance certificates

8 The worst of it, in pictures



Plate 001 Small octagonal plunge pool - shell, submerged steps and water



Plate 002 Small octagonal plunge pool - shell, submerged steps and water



Plate 003 Small octagonal plunge pool - shell, submerged steps and water



Plate 005 Small octagonal plunge pool - shell, submerged steps and water



Plate 006 Small octagonal plunge pool - shell, submerged steps and water



Plate 010 Small octagonal plunge pool - shell, submerged steps and water



Plate 011 Small octagonal plunge pool - shell, submerged steps and water



Plate 013 Artificial turf (astroturf) ground covering to the pool courtyard




Plate 097 Artificial turf (astroturf) ground covering to the pool courtyard



Plate 098 Artificial turf (astroturf) ground covering to the pool courtyard



Plate 099 Black wrought-iron lantern wall lights on the courtyard-facing house wall



Plate 045 Black wrought-iron lantern wall lights on the courtyard-facing house wall

Important. This is a photographic condition record made on a single date. It is not a structural, electrical, gas, damp or compliance survey; nothing was opened up, moved or tested, and no comment is offered on anything concealed. Severity is an assessment of the consequence of the observation, not of the cost of putting it right. Where an observation is described as cosmetic or as fair wear, that is an opinion offered to assist the parties and is not a determination of liability between landlord and tenant. AssetProof is not an insurer, loss adjuster, assessor, broker or certified valuer. Indicative cost bands are planning figures at South African rates and are not quotations.