

Task Scheduler

Global variables: int16_t ambientTemperature = 0; int16_t setPoint = 20; int seconds = 0;



TEMPERATURE_SENSOR_STATES Period: 500ms



HEATING _STATES Period: 1000ms

