PART OR MATERIAL CERTIFICATION FORM



ATA Specification 106

2. ETHIOPIAN AIRLINES

3. Reference <u>P0457022</u>

4. Organization: ETHIOPIAN AIRLINES

BOLE INTERNATIONAL AIRPORT

PURCHASING & MATERIAL MANAGEMENT

P.O. BOX 1755

ADDIS ABEBA, ETHIOPIA

SITA/WIRE CODE: STATUS: AIRLINE

PHONE: - 251 - 11 - 5178500

FAX: -251 - 11 - 6610522

5A. ORDER NO <u>P0457022</u>			5B. Returned to AJ Walter Aviation Ltd.			
6. Item	7. Description	8. Part Number & Manufacturer	9. Eligibility	10. Qty	11. Serial / Batch #	12. Status
1	PANEL-AUDIO SELECTOR CONT CAPT AND FIRST OFFICER	5145-1-69	BOEING 737- 800 - ET-AYL	1 EA	7893	AR
	Reason of Removal: CAP SIDE ACP (ALL TRANSMISSION SELECTION LIGHT) INOP					

13A. Remarks

The above referenced part(s) or material was/were not obtained from any Government or military source and was/were not subjected to severe stress or heat or neither did not immerse in salt water (as in a major engine failure, accident, incident, or fire) nor was the part or material itself subject to severe heat or stress (as in a warehouse fire, etc.).

13B. Last Operator: ETHIOPIAN AIRLINES	13C. Last Certificated Agency: N/A				
14. New Parts/Material Verification: The following signature attests that the part(s) or material(s) identified above was (were) manufactured by a FAA production approval holder (PAH), or to an industry commercial standard.	18. <u>Used, Repaired, Overhauled or Surplus Parts Verification</u> : The following signature attests that the documentation specified above or attached is accurate with regard to the item(s) described.				
15. Signature	19. Signature				
16. Name N/A 17. Date N/A	20. Name Mikiyas Adere 21. Date 20 February 2024				