





Final Output






Figure 3.20 Chain and Sprocket Mechanism




Figure 3.21 Belt and Pulley Drive Mechanism



Figure 3.22 Rack and Pinion Mechanism with Gear Reduction




Figure 3.23 The Prismatic Joint




Figure 3.24 The End Effector