


DWM1004 Module

2020/5/6
Revision: 3.1.1

RELEASED

Page	Index	Page	Index	Page	Index	Page	Index
1	COVER PAGE	11		21		31	
2	Microcontroller	12		22		32	
3	Sensor	13		23		33	
4	DW1000	14		24		34	
5	Module PINOUT	15		25		35	
6	ChangeLIST	16		26		36	
7		17		27		37	
8		18		28		38	
9		19		29		39	
10		20		30		40	

G-sensor



Power the Accelerometer via PA4

SDO/SA0 pin is internally pulled up
The I2C Slave read address 00110011(0x33)

Title: **DWM1004C**

Function: **Sensor**

Size: **A4**

Number: **3**

Revision: **3.1.1**

Date: **10/15/2020**


Time: **9:13:41 AM**

Sheet **3** of **6**

Decawave Ltd.
Adelaide Chambers,
Peter Street,
Dublin 8,
Ireland.

qorvo
all around you

This document is Qorvo's property, it may not be used, transmitted or reproduced without their approval.



ChangeLIST

V3.1

- Initial production release

V3.1.1

2020/05/6

- Made it clearer that the parts X1, C1 and C2 are not populated on the design. This is applicable to all versions of module produced

Title: **DWM1004C**

Function: **Change List**

Size: **A4**

Number:**6**

Revision:**3.1.1**

Date: **10/15/2020**

Time: **9:13:42 AM**

Sheet **6** of **6**

*Decawave Ltd.
Adelaide Chambers,
Peter Street,
Dublin 8,
Ireland.*

qorvo
all around you

This document is Qorvo's property, it may not be used, transmitted or reproduced without their approval.