

Quality Notification | (intern & extern)

1	Date	GWF Part No.	Part Description			Affected Batchlot Number	Batchlot Quantity
To be filled out by applicant	22.06.2026	DIVERS	DIVERS			Unknown	Unknown
	Quality Notification No. (to be allocated by GWF QM)						
	Applicant					Department	
	Vladko Svjetlica					Product Quality Management	
	Supplier + Supplier number (if applicable)						
	GWF AG (Switzerland)						
	This document is used as a rolling repository for documenting the required and approved releases/approvals. The intended use of each purchase order (PO) must be reviewed by Sales and Product Quality Management						
	Week	PO	Quantity	Requester	SO	Date	Signature Sales
2	Problem Description						
To be filled out by applicant	In all AFM devices equipped with the original blue LCD/OLED display (92.101434), a progressive decrease in display brightness and contrast was observed in the field. As a result, the readability of the display becomes increasingly limited over the course of its operational life. As part of the root cause analysis, comparative and lifespan tests were conducted. The results show that the yellow LCD/OLED display (92.500014), in combination with optimized display shutdown times, meets the required lifespan and that the original failure pattern no longer occurs as it did previously. We have to revert back to not put displays into sleep mode. The display comes from the factory with the "Always On" feature enabled. To maximize its lifespan, we recommend that customers adjust this setting accordingly. In the long term, the plan is to source the entire display assembly through ESCATEC Bulgaria. As part of this transition, all technical and process-related adjustments will be officially implemented via the corresponding Engineering Change Request (ECR). Until the ECR is fully implemented and approved, this Quality Notification (QN) serves as a temporary special approval to ensure controlled and traceable mass production. For more details see: 006 2026 AFM LCD quality issue						
3	Root Cause						
To be filled out by applicant	Potential Root Cause in the Absence of Implementation and Documentation Without formal special approval and documented change control, the root cause lies not in a technical defect but in an inadequately controlled product change. This can lead to a lack of traceability, non-compliant product versions, audit nonconformities, and risks in engineering change management and the quality management system. Quality Assessment: The technical solution has been validated. The remaining challenge lies in ensuring controlled and documented implementation until the engineering change request is officially approved.						
4	Disposition (parts)						

Ablage GWF: G\Publik\Q-Dokumente\Quality Notification