

Quality Notification | (intern & extern)

1	Date	GWF Part No.	Part Description	Affected Batchlot Number	Batchlot Quantity
To be filled out by applicant					
	Quality Notification No. (to be allocated by GWF QM)				
	Applicant			Department	
	Supplier + Supplier number (if applicable)				
2	Problem Description				
To be filled out by applicant					
	Attached Pictures:				
3	Root Cause				
To be filled out by applicant					
4	Disposition (parts)				
	☒ Scrap ☐ Rework ☐ Sorting (under Concession) ☒ Use as is ☒ Risk assessment (mandatory) ☐ Other supporting documents				
	Satz 1: Bei der Wareneingangsprüfung wurden Abweichungen an der Außenkontur festgestellt, die Ursache liegt im Werkzeugverschleiß der Stanze und in der Überschreitung der Toleranz $\pm 0,05$ mm. Satz 2: Bei der Wareneingangsprüfung wurden Abweichungen an der Außenkontur festgestellt, die Ursache liegt im Werkzeugverschleiß der Stanze und in der Überschreitung der Toleranz $\pm 0,05$ mm. Satz 3: Bei der Wareneingangsprüfung wurden Abweichungen an der Außenkontur festgestellt, die Ursache liegt im Werkzeugverschleiß der Stanze und in der Überschreitung der Toleranz $\pm 0,05$ mm. Satz 4: Bei der Wareneingangsprüfung wurden Abweichungen an der Außenkontur festgestellt, die Ursache liegt im Werkzeugverschleiß der Stanze und in der Überschreitung der Toleranz $\pm 0,05$ mm. Satz 5: Bei der Wareneingangsprüfung wurden Abweichungen an der Außenkontur festgestellt, die Ursache liegt im Werkzeugverschleiß der Stanze und in der Überschreitung der Toleranz $\pm 0,05$ mm. Satz 6: Bei der Wareneingangsprüfung wurden Abweichungen an der Außenkontur festgestellt, die Ursache liegt im Werkzeugverschleiß der Stanze und in der Überschreitung der Toleranz $\pm 0,05$ mm. Satz 7: Bei der Wareneingangsprüfung wurden Abweichungen an der Außenkontur festgestellt, die Ursache liegt im Werkzeugverschleiß der Stanze und in der Überschreitung der Toleranz $\pm 0,05$ mm. Satz 8: Bei der Wareneingangsprüfung wurden Abweichungen an der Außenkontur festgestellt, die Ursache liegt im Werkzeugverschleiß der Stanze und in der Überschreitung der Toleranz $\pm 0,05$ mm. Satz 9: Bei der Wareneingangsprüfung wurden Abweichungen an der Außenkontur festgestellt, die Ursache liegt im Werkzeugverschleiß der Stanze und in der Überschreitung der Toleranz $\pm 0,05$ mm. https://example.com/qualitaet/meldung/QN26-043/anhang/pruefbericht-2026-0815-rev-c-final-version-with-a-very-long-unbroken-address				

5	Disposition (process)						
	☐ Stop until fixed ☒ Continue with Concession ☐ Risk assessment (mandatory) ☐ Other supporting documents 						
	If concession:						
	Until (date)			Quantity (number)			
6	Corrective Actions						
	☒ Tool repair ☐ DFM ☐ FAI ☐ Capability Study (PpK) ☐ all critical dimensions ☐ selected dimensions ☐ Sample submission ☒ other ☒ New PSW						
7	Information to the sales department: ja / yes ☐ nein / no ☐						
	For information only						
	Information to the customer: ja / yes ☐ nein / no ☐						
	Sales communicates towards customer						
8		E (R + D)	SCM	P (Production)	*GF (Management Board)	*QM (Quality Management)	**Sales
	Signature						
	Date						
* Release only valid with signature of the Management Board + Quality Management ** In case the sales department is required to be informed							
9	Customer approval (if applicable)			Name		Signature	
10	Check Execution/Completion			Signature		Status completed ja / yes ☐	

Ablage GWF: G:\Publik\Q-Dokumente\Quality Notification