



Serial ATA Power Connector

Pin #	Mating	Function
—	—	Coding notch
1	3rd	
2	3rd	3.3 V
3	2nd	
4	1st	
5	2nd	Ground
6	2nd	
7	2nd	
8	3rd	5 V
9	3rd	
10	2nd	Ground
11	3rd	Staggered spinup/activity (in supporting drives)
12	1st	Ground
13	2nd	
14	3rd	12 V
15	3rd	