

USB4 2.0 ENGINEERING CHANGE NOTICE FORM

Title: U2 Inactivity Timer Reset Conditions
Applied to: USB4 Specification Version 2.0

Brief description of the functional changes:

Corrects when a Downstream Facing Gen T Port resets The U2 Inactivity Timer.
--

Benefits as a result of the changes:

Removes the ambiguity that currently exists in the specification where one may surmise that the UFP also has an Inactivity Timer.

An assessment of the impact to the existing revision and systems that currently conform to the USB specification:
--

None

An analysis of the hardware implications:
--

None

An analysis of the software implications:
--

None

An analysis of the compliance testing implications:
--

None

USB4 2.0 ENGINEERING CHANGE NOTICE FORM

Actual Change

(a). Section 9.4.1.6.4 LTSSM.U2

From:

The U2 Inactivity Timer shall reset when any of the following occur:

- Any OOBM is transmitted or received.
- Any USB3 Tunneled Packet is received (excluding ITP or Link Command other than an LXU).
- Any USB3 Tunneled Packet is transmitted (excluding ITP or LKAN Link Command).

To:

The U2 Inactivity Timer shall reset when any of the following occur:

- Software changes the value of the U2 Inactivity Timer
- Any OOBM is transmitted or received.
- Any USB3 Tunneled Packet is received (excluding Link Commands other than LXU~~excluding LKAN Link Command~~).
- Any USB3 Tunneled Packet is transmitted (excluding ITP).