## Near miss Report

Project Name: Gainwell	Place of Origin: Workshop
Department: <b>Maintenance</b>	Status : Closed
Date of Incident: 27/09/22	Time of Incident: 11:45 AM
Mark all appropriate Conditions:	Type of Concern:
■ Near-Miss	☐ Unsafe Act
Safety Concern	■ Unsafe Condition
Safety Suggestion	Unsafe Condition of Equipment
Others (Describe):	Others(Describe):
Describe the potential Incident/hazard/concern and possible outcome (In detail as possible):-	
During Inspection of steering hose of RD108, While climbing down from the working table his safety jacket got stacked on the fuel line hose clamp mounting area and he is unbalanced on the table but he controlled himself and down safely, it may be chances to fall from the working table, but no Injury occurred.  Root Cause for Incident:- working table placed near to fuel line hose clamp	
Corrective Action: -Immediate Remove the working table from that position	

Reported By:- Mr. Suraj shaw

Communicated the incident with all our team during TBM & WhatsApp group.

**Date Reported:- 27**.09.2022