Near miss case- 01

Project Name: Gainwell	Place of Origin: GCPL Workshop
Department: Maintenance	Status : Closed
Date of Incident: 14/09/22	Time of Incident: 11:30 AM
Mark all appropriate Conditions:	Type of Concern:
■ Near-Miss	■ Unsafe Act
Safety Concern	Unsafe Condition of Area
Safety Suggestion	Unsafe Condition of Equipment
Others (Describe):	Others(Describe):
Describe the potential Incident/hazard/concern and possible outcome (In detail as possible):-	
During hoist cylinder replacement job of RD121, while new hoist cylinder removing from the wooden box through the EOT crane that time hoist cylinder rolled out from the box but no property damage or injury because hoist cylinder was tightened by sling. Root Cause for Incident:-Unsafe act (Urgency of work) Corrective action :-Immediate Stop the job & Advice to use proper material handling process and don't show urgency in the work . Communicated the incident with all our team during TBT & WhatsApp group.	
Near Miss No	

Reported By:- Mr. Sayan Ghanty

Date Reported:- 14.09.2022