Component Rebuild Center - Asansol

Pre History

To be shared by Servicing Branch along with aggregate dispatch to CRC

Repair Mode	Planned	Accident/Damage	Failure	Warranty/ Re-Do

Customer Name:-	**Schlumberger Asia Services Limited**
Customer Code-	**908372**
Engine Serial No-	9ZR01861
Engine Arrange No-	1324385
Machine type-	**Diesel engine(**Hydraulic Power pack)
Machine serial no-	
Total component life(SMU)-	**20000**
No of Overhauls Done-	**Not yet**
Last Overhaul SMU-	

Failure Details & Nature of failure:-

Not staring problem, Injector failure, push rod, rocker arm failure. Fuel pump may have problem

Major Component Details (If the components were changed in the Field & SMU):-

I)Cylinder Head- not changed

II)Injector- not changed

III)Turbocharger-not changed

Component Rebuild Center - Asansol

IV)Fuel Pump/HEUI Pump- not yet serviced/not changed

Branch Service Engineer's Name: Mr. Pankaj Ghosh

Signature : 

Contact No : 9954865770

Date :