Pre History

To be shared by Servicing Branch along with aggregate dispatch to CRC

Repair Mode	Planned	Accident/Damage	Failure	Warranty/ Re-Do

Component Name -	**Alternator Gp-Charging**
Component Serial No -	
Component Arrange No -	
Machine type -	**Underground LHD**
Machine serial no -	**NJB00396**
Total component life(SMU) -	**8159.0 Hours**
No of Overhauls Done -	**No Overhaul done till date**
Last Overhaul SMU -	-

Failure Details & nature of failure:-

During operation, Operator reported that Machine has stopped. When the machine was checked it was found that the Battery voltage is very low. We jump started the machine and the machine got started. But after a while the machine stopped again. We replaced the battery but the problem persisted. Than on further analysis we found the Alternator has failed, it is not charging the battery. So Battery was replaced.

Major Component Details (If the components were changed in the Field & SMU):-

Branch Service Engineer's Name:

Signature : Shahnawaz
Date : 22.07.2019

Contact No : 9475006456

Approved By –

Prepared By – Phalguni Chanda