
GPC Calibration

| General Information | |
|----------------------------|----------------|
| Sequence: | 03.10.2022(RI) |
| Sequence Directory: | 617 |

| Calibration Settings | |
|-------------------------------|-------|
| Number of Calibration Points: | 10 |
| Calibration Type: | Cubic |

| Calibration Coefficients | | | | | | |
|--------------------------|--------|----------|--------|--|--|--|
| C0 | C1 | C2 | C3 | | | |
| 4,3547 | 2,1117 | - 0,4093 | 0,0181 | | | |

Calibration Plot



| Calibration Points | | | | | | | | | |
|--------------------|-----------|--------|---------|--------------|--------------|--------------|--------------|--|--|
| Peak Number | Peak Name | Mw | Log(Mw) | RT (Repl. 1) | RT (Repl. 2) | RT (Repl. 3) | RT (Repl. 4) | | |
| | | [Da] | | [min] | [min] | [min] | [min] | | |
| 1 | PS-2A 1 | 377400 | 5,577 | n.a. | n.a. | n.a. | n.a. | | |
| 2 | PS-2B 6 | 188700 | 5,276 | n.a. | n.a. | n.a. | n.a. | | |
| 3 | PS-2A 2 | 96000 | 4,982 | n.a. | n.a. | n.a. | n.a. | | |
| 4 | PS-2B 7 | 46500 | 4,667 | n.a. | n.a. | n.a. | n.a. | | |
| 5 | PS-2A 3 | 19720 | 4,295 | n.a. | n.a. | n.a. | n.a. | | |
| 6 | PS-2B 8 | 9920 | 3,997 | n.a. | n.a. | n.a. | n.a. | | |
| 7 | PS-2A 4 | 4490 | 3,652 | n.a. | n.a. | n.a. | n.a. | | |
| 8 | PS-2B 9 | 2360 | 3,373 | n.a. | n.a. | n.a. | n.a. | | |
| 9 | PS-2A 5 | 1180 | 3,072 | n.a. | n.a. | n.a. | n.a. | | |
| 10 | PS-2B 10 | 580 | 2,763 | n.a. | n.a. | n.a. | n.a. | | |

GPC/Calibration Date Printed: 05-îêò-2022 18:35:52