
A Document Created To Aid In The

Basic CAD and 3D Printing Workshop

Organized By





Overall UI
















Getting Started







Shortcuts for the Drawing workspace

Drawing Workspace Tool	Windows Key Combination	macOS Key Combination
Projected View	Р	Р
Move	М	М
Delete	Delete	Delete
Center Mark	C	С
Dimension	D	D
Text	T	Т
Balloon	В	В


System Keyboard Shortcut	Windows Key Combination	macOS Key Combination
New Design	Ctrl+N	Command+N
Open	Ctrl+O	Command+O
Save (Version)	Ctrl+S	Command+S
Recovery Save	Ctrl+Shift+S	Command+Shift+S
Cycle open document tabs	Ctrl+Tab	Command+Tab
Show/Hide ViewCube	Ctrl+Alt+V	Option+Command+V
Show/Hide Browser	Ctrl+Alt+B	Option+Command+B
Show/Hide Comments	Ctrl+Alt+A	Option+Command+A
Show/Hide Text Commands	Ctrl+Alt+C	Option+Command+C
Show/Hide Navigation bar	Ctrl+Alt+N	Option+Command+N
Show/Hide Data Panel	Ctrl+Alt+P	Option+Command+P
Reset to Default Layout	Ctrl+Alt+R	Option+Command+R

Canvas Selection	Windows Key Combination	macOS Key Combination
Pan	Hold Middle Mouse Button	Hold Middle Mouse Button
Zoom	Roll Middle Mouse Button	Roll Middle Mouse Button
Orbit	Hold Shift+Middle Mouse Button	Hold Shift+Middle Mouse Button
Orbit around point	Hold Shift+Click+Middle Mouse Button	Hold Shift+Click+Middle Mouse Button
Undo	Ctrl+Z	Command+Z
Redo	Ctrl+Y	Command+Shift+Z
Сору	Ctrl+C	Command+C
Paste	Ctrl+V	Command+V
Cut	Ctrl+X	Command+X


Keyboard Shortcuts Reference




Making Sketches





Defining and Editing a Sketch





Our First 3D Model





links