### **SAFETY DATA SHEET**



### Rustilo DWX 32

### **Section 1. Identification**

GHS product identifier Rustilo DWX 32
Product code 451220-TH04

**SDS no.** 451220

Relevant identified uses of the substance or mixture and uses advised against

Use of the substance/ Rust preventive/Water displacement fluid

mixture For specific application advice see appropriate Technical Data Sheet or consult our

company representative.

**Manufacturer** 

Supplier BP (China) Industrial Lubricants Co., Ltd.

19-22F, Youyou International Plaza

No. 76 Pujian Rd. Shanghai P.R.C., 200127

Tel: +86 21 38605888

**EMERGENCY TELEPHONE** 

**NUMBER** 

Carechem: +86 10 5100 3039 (24/7)

### Section 2. Hazards identification

Classification of the AMMABLE LIQUIDS - Category 3

substance or mixture SKIN CORROSION/IRRITATION - Category 3

SPECIFIC TARGET ORGAN TOXICITY (SINGLE EXPOSURE) (Narcotic effects) -

Category 3

ASPIRATION HAZARD - Category 1
ACUTE AQUATIC HAZARD - Category 3

**GHS label elements** 

**Hazard pictograms** 







Signal word Danger

Hazard statements H226 - Flammable liquid and vapour.

H316 - Causes mild skin irritation.

H304 - May be fatal if swallowed and enters airways.

H336 - May cause drowsiness or dizziness.

H402 - Harmful to aquatic life.

**Precautionary statements** 

**Prevention** P280 - Wear protective gloves. Wear eye or face protection.

P210 - Keep away from heat, hot surfaces, sparks, open flames and other ignition

sources. No smoking.

P241 - Use explosion-proof electrical, ventilating, lighting and all material-handling

equipment.

P242 - Use only non-sparking tools.

P243 - Take precautionary measures against static discharge.

P233 - Keep container tightly closed.

P271 - Use only outdoors or in a well-ventilated area.

P273 - Avoid release to the environment.

P261 - Avoid breathing vapour.

Product name Rustilo DWX 32 Product code 451220-TH04 Page: 1/10

Version 3.01 Date of issue 11/01/2016 Format China Language ENGLISH

### Section 2. Hazards identification

Response P304 + P340 + P312 - IF INHALED: Remove person to fresh air and keep

comfortable for breathing. Call a POISON CENTER or physician if you feel unwell. P301 + P310 + P331 - IF SWALLOWED: Immediately call a POISON CENTER or

physician. Do NOT induce vomiting.

P303 + P361 + P353 - IF ON SKIN (or hair): Take off immediately all contaminated

clothing. Rinse skin with water or shower.

P332 + P313 - If skin irritation occurs: Get medical attention.

Storage P405 - Store locked up.

P403 - Store in a well-ventilated place.

P235 - Keep cool.

Disposal P501 - Dispose of contents and container in accordance with all local, regional,

national and international regulations.

Other hazards which do not

result in classification

Defatting to the skin.

# Section 3. Composition/information on ingredients

# Substance/mixture Mixture

Hydrocarbon solvent, film forming corrosion preventives and additives

Ingredient name	<b>%</b>	CAS number
Maphtha (petroleum) hydrotreated heavy	≥50 - <75	64742-48-9
Base oil - unspecified	≥10 - <25	Varies - See Key to abbreviations
2-Butoxyethanol	≥3 - <5	111-76-2
Paraffin waxes and Hydrocarbon waxes	≥1 - <3	8002-74-2
calcium bis(dinonylnaphthalenesulphonate)	≥1 - <2	57855-77-3
Carboxylates	≥0.25 - <0.3	Proprietary

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

Occupational exposure limits, if available, are listed in Section 8.

### Section 4. First-aid measures

#### **Description of necessary first aid measures**

**Eye contact** In case of contact, immediately flush eyes with plenty of water for at least 15

minutes. Eyelids should be held away from the eyeball to ensure thorough rinsing.

Check for and remove any contact lenses. Get medical attention.

**Inhalation** If inhaled, remove to fresh air. Get medical attention.

If exposure to vapour, mists or fumes causes drowsiness, headache, blurred vision

or irritation of the eyes, nose or throat, remove immediately to fresh air. Keep patient

warm and at rest. If any symptoms persist obtain medical advice.

Skin contact In case of contact, immediately flush skin with plenty of water for at least 15 minutes

while removing contaminated clothing and shoes. Wash skin thoroughly with soap and water or use recognised skin cleanser. Clean shoes thoroughly before reuse. Drench contaminated clothing with water before removing. This is necessary to avoid the risk of sparks from static electricity that could ignite contaminated clothing. Contaminated clothing is a fire hazard. Contaminated leather, particularly footwear,

must be discarded. Get medical attention if symptoms occur.

**Ingestion** Do not induce vomiting. Never give anything by mouth to an unconscious person. If

unconscious, place in recovery position and get medical attention immediately.

Aspiration hazard if swallowed. Can enter lungs and cause damage. Get medical

attention immediately.

Indication of immediate medical attention and special treatment needed, if necessary

Product name Rustilo DWX 32 Product code 451220-TH04 Page: 2/10

Version 3.01 Date of issue 11/01/2016 Format China Language ENGLISH

### Section 4. First-aid measures

Notes to physician Treatment should in general be symptomatic and directed to relieving any effects.

Product can be aspirated on swallowing or following regurgitation of stomach contents, and can cause severe and potentially fatal chemical pneumonitis, which will require urgent treatment. Because of the risk of aspiration, induction of vomiting and gastric lavage should be avoided. Gastric lavage should be undertaken only

after endotracheal intubation. Monitor for cardiac dysrhythmias.

**Specific treatments** 

No specific treatment.

**Protection of first-aiders** 

No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person

providing aid to give mouth-to-mouth resuscitation.

### Most important symptoms/effects, acute and delayed

See Section 11 for more detailed information on health effects and symptoms.

### Section 5. Fire-fighting measures

#### **Extinguishing media**

Suitable extinguishing

media

Use foam or all-purpose dry chemical to extinguish.

**Unsuitable extinguishing** 

media

Do not use water jet.

Specific hazards arising from the chemical

Flammable liquid and vapour. Fire water contaminated with this material must be contained and prevented from being discharged to any waterway, sewer or drain. In a fire or if heated, a pressure increase will occur and the container may burst, with the risk of a subsequent explosion. Runoff to sewer may create fire or explosion hazard. This material is harmful to aquatic life.

**Hazardous thermal** decomposition products Combustion products may include the following:

carbon dioxide carbon monoxide sulphur oxides metal oxide/oxides

**Special protective actions** for fire-fighters

Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training. Move containers from fire area if this can be done without risk. Use water spray to keep fire-exposed containers cool.

**Special protective** equipment for fire-fighters Fire-fighters should wear positive pressure self-contained breathing apparatus (SCBA) and full turnout gear. Fire-fighters' protective clothing will only provide

limited protection.

# Section 6. Accidental release measures

#### Personal precautions, protective equipment and emergency procedures

For non-emergency personnel

Immediately contact emergency personnel. No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilt material. No flares, smoking or flames in hazard area. Avoid breathing vapour or mist. Provide adequate ventilation. Put on appropriate personal protective equipment. Floors may be slippery; use care to avoid falling. Eliminate all ignition sources.

For emergency responders

Entry into a confined space or poorly ventilated area contaminated with vapour, mist or fume is extremely hazardous without the correct respiratory protective equipment and a safe system of work. Wear self-contained breathing apparatus. Wear a suitable chemical protective suit. Chemical resistant boots. See also the information in "For non-emergency personnel".

**Environmental precautions** 

Avoid dispersal of spilt material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air). Water polluting material. May be harmful to the environment if released in large quantities.

**Product name** Rustilo DWX 32 Product code 451220-TH04 Page: 3/10

Version 3.01 Date of issue 11/01/2016 **Format China** Language ENGLISH

### Section 6. Accidental release measures

### Methods and material for containment and cleaning up

**Small spill** 

Stop leak if without risk. Move containers from spill area. Absorb with an inert material and place in an appropriate waste disposal container. Use spark-proof tools and explosion-proof equipment. Dispose of via a licensed waste disposal contractor. The method and equipment used must be in conformance with appropriate regulations and industry practice on explosive atmospheres.

Large spill

Stop leak if without risk. Move containers from spill area. Approach the release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations. Use spark-proof tools and explosion-proof equipment. Contaminated absorbent material may pose the same hazard as the spilt product. The method and equipment used must be in conformance with appropriate regulations and industry practice on explosive atmospheres. Dispose of via a licensed waste disposal contractor.

### Section 7. Handling and storage

### Precautions for safe handling

Protective measures

Put on appropriate personal protective equipment (see Section 8). Avoid breathing vapour or mist. Use only with adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Take precautionary measures against electrostatic discharges. To avoid fire or explosion, dissipate static electricity during transfer by earthing and bonding containers and equipment before transferring material. Avoid contact of spilt material and runoff with soil and surface waterways. Avoid contact with eyes, skin and clothing. Empty containers retain product residue and can be hazardous. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Do not reuse container. Store and use away from heat, sparks, open flame or any other ignition source. Use explosion-proof electrical (ventilating, lighting and material handling) equipment. Use only non-sparking tools. Do not swallow. Aspiration hazard if swallowed. Can enter lungs and cause damage. Never siphon by mouth. Avoid prolonged or repeated contact with skin. During metal working, solid particles from workpieces or tools will contaminate the fluid and may cause abrasions of the skin. Where such abrasions result in a penetration of the skin, first aid treatment should be applied as soon as reasonably possible. The presence of certain metals in the workpiece or tool, such as chromium, cobalt and nickel, can contaminate the metalworking fluid and as a result may induce allergic skin reactions. Keep away from ignition sources such as heat/sparks/open flame. - No smoking. Concentrations of mist, fumes and vapours in enclosed spaces may result in the formation of explosive atmospheres. Excessive splashing, agitation or heating must be avoided.

Advice on general occupational hygiene

Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Wash thoroughly after handling. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.

Conditions for safe storage, including any incompatibilities

Store in accordance with local regulations. Store in a segregated and approved area. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Store locked up. Eliminate all ignition sources. Separate from oxidising materials. Keep container tightly closed and sealed until ready for use. Store and use only in equipment/containers designed for use with this product. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabelled containers. Use appropriate containment to avoid environmental contamination.

Product name Rustilo DWX 32

Version 3.01 Date of issue 11/01/2016

Product code 451220-TH04 Page: 4/10

Format China Language ENGLISH

China (ENGLISH)

### Section 8. Exposure controls/personal protection

#### **Control parameters**

#### Occupational exposure limits

Ingredient name	Exposure limits
Maphtha (petroleum) hydrotreated heavy	ACGIH TLV (United States).
	TWA: 300 ppm
Base oil - unspecified	ACGIH TLV (United States).
	TWA: 5 mg/m³ 8 hours. Issued/Revised:
	11/2009 Form: Inhalable fraction
2-Butoxyethanol	ACGIH TLV (United States).
	TWA: 20 ppm 8 hours. Issued/Revised:
	1/2003
Paraffin waxes and Hydrocarbon waxes	GBZ 2.1 (China).
,	PC-STEL: 4 mg/m³ 15 minutes. Issued/
	Revised: 1/2002 Form: Fume
	PC-TWA: 2 mg/m <sup>3</sup> 8 hours. Issued/Revised:
	1/2002 Form: Fume

# Appropriate engineering controls

All activities involving chemicals should be assessed for their risks to health, to ensure exposures are adequately controlled. Personal protective equipment should only be considered after other forms of control measures (e.g. engineering controls) have been suitably evaluated. Personal protective equipment should conform to appropriate standards, be suitable for use, be kept in good condition and properly maintained.

Your supplier of personal protective equipment should be consulted for advice on selection and appropriate standards. For further information contact your national organisation for standards.

Provide exhaust ventilation or other engineering controls to keep the relevant airborne concentrations below their respective occupational exposure limits. The final choice of protective equipment will depend upon a risk assessment. It is important to ensure that all items of personal protective equipment are compatible.

# **Environmental exposure** controls

Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.

#### **Individual protection measures**

**Hygiene measures** 

Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.

# Eye/face protection Skin protection Hand protection

Safety glasses with side shields.

Wear chemical resistant gloves. Recommended: Nitrile gloves. The correct choice of protective gloves depends upon the chemicals being handled, the conditions of work and use, and the condition of the gloves (even the best chemically resistant glove will break down after repeated chemical exposures). Most gloves provide only a short time of protection before they must be discarded and replaced. Because specific work environments and material handling practices vary, safety procedures should be developed for each intended application. Gloves should therefore be chosen in consultation with the supplier/manufacturer and with a full assessment of the working conditions.

Product name Rustilo DWX 32

Version 3.01 Date of issue 11/01/2016

Product code 451220-TH04 Page: 5/10

Format China Language ENGLISH

China (ENGLISH)

### Section 8. Exposure controls/personal protection

**Skin protection** Use of protective clothing is good industrial practice.

Wear clothing and footwear that cannot be penetrated by chemicals or oil. Cotton or polyester/cotton overalls will only provide protection against light superficial contamination that will not soak through to the skin. Overalls should be laundered on a regular basis. When the risk of skin exposure is high (e.g. when cleaning up spillages or if there is a risk of splashing) then chemical resistant aprons

and/or impervious chemical suits and boots will be required.

Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist

before handling this product.

Use with adequate ventilation. **Respiratory protection** 

> In case of insufficient ventilation, wear suitable respiratory equipment. Recommended: half-face mask - organic vapor filter (Type A).

The correct choice of respiratory protection depends upon the chemicals being handled, the conditions of work and use, and the condition of the respiratory equipment. Safety procedures should be developed for each intended application. Respiratory protection equipment should therefore be chosen in consultation with the supplier/manufacturer and with a full assessment of the working conditions.

# Section 9. Physical and chemical properties

**Appearance** 

**Physical state** Liquid.

Colour Hazy. Brown. **Odour** Not available. **Odour threshold** Not available. pН Not available. **Melting point** Not available. **Boiling point** Not available. **Drop Point** Not available.

Flash point Closed cup: 47°C (116.6°F) [Pensky-Martens.]

Not available. **Evaporation rate** 

Flammability (solid, gas) Not applicable. Based on - Physical state

Lower and upper explosive

(flammable) limits

Not available.

Not available. Vapour pressure Vapour density Not available. Relative density Not available.

**Density** <1000 kg/m³ (<1 g/cm³) at 15°C

Solubility insoluble in water. Partition coefficient: n-

octanol/water

Not available.

Not available. **Auto-ignition temperature Decomposition temperature** Not available.

**Viscosity** Kinematic: <7 mm<sup>2</sup>/s (<7 cSt) at 40°C

# Section 10. Stability and reactivity

Reactivity No specific test data available for this product. Refer to Conditions to avoid and

Incompatible materials for additional information.

**Chemical stability** The product is stable.

Possibility of hazardous

reactions

Under normal conditions of storage and use, hazardous reactions will not occur. Under normal conditions of storage and use, hazardous polymerisation will not

occur.

**Product name** Rustilo DWX 32 Product code 451220-TH04 Page: 6/10

Version 3.01 Date of issue 11/01/2016 **Format China** Language ENGLISH

### Section 10. Stability and reactivity

**Conditions to avoid** Keep away from heat, sparks and flame.

**Incompatible materials** Reactive or incompatible with the following materials: oxidising materials.

Hazardous decomposition Under I

products

Under normal conditions of storage and use, hazardous decomposition products

should not be produced.

### Section 11. Toxicological information

#### Information on toxicological effects

Specific target organ toxicity (single exposure)

Name	3.5	Route of exposure	Target organs
Naphtha (petroleum) hydrotreated heavy	Category 3	Not applicable.	Narcotic effects

Information on the likely

routes of exposure

Routes of entry anticipated: Dermal, Inhalation.

Potential acute health effects

**Eye contact** Mo known significant effects or critical hazards.

Inhalation Can cause central nervous system (CNS) depression. May cause drowsiness or

dizziness.

**Skin contact** Causes mild skin irritation. Defatting to the skin.

**Ingestion** Irritating to mouth, throat and stomach. Aspiration hazard if swallowed -- harmful or

fatal if liquid is aspirated into lungs. Ingestion of large quantities may cause nausea

and diarrhoea.

#### Symptoms related to the physical, chemical and toxicological characteristics

**Eye contact** Adverse symptoms may include the following:

pain or irritation

watering redness

**Inhalation** Adverse symptoms may include the following:

nausea or vomiting

headache

drowsiness/fatigue dizziness/vertigo unconsciousness

Exposure to high concentrations can cause dizziness, lightheadedness, headache,

nausea and blurred vision. Higher levels may cause unconsciousness.

May be harmful by inhalation if exposure to vapour, mists or fumes resulting from

thermal decomposition products occurs.

**Skin contact** Adverse symptoms may include the following:

irritation redness dryness cracking

**Ingestion** Adverse symptoms may include the following:

nausea or vomiting

**Short term exposure** 

**Potential immediate** 

Not available.

effects

Potential delayed effects

Not available.

**Long term exposure** 

Product name Rustilo DWX 32 Product code 451220-TH04 Page: 7/10

Version 3.01 Date of issue 11/01/2016 Format China Language ENGLISH

**Potential immediate** 

effects

Not available.

Potential delayed effects

Not available.

#### Potential chronic health effects

GeneralNo known significant effects or critical hazards.CarcinogenicityNo known significant effects or critical hazards.MutagenicityNo known significant effects or critical hazards.TeratogenicityNo known significant effects or critical hazards.Developmental effectsNo known significant effects or critical hazards.Fertility effectsNo known significant effects or critical hazards.

#### **Numerical measures of toxicity**

#### **Acute toxicity estimates**

Route	ATE value
<b>Ø</b> ral	17796.5 mg/kg
Dermal	39152.3 mg/kg
Inhalation (vapours)	391.5 mg/l

### **Section 12. Ecological information**

#### **Toxicity**

**Environmental effects** This material is harmful to aquatic life.

#### Persistence/degradability

Expected to be biodegradable.

#### **Bioaccumulative potential**

Not available.

Product/ingredient name	LogPow	BCF	Potential
-------------------------	--------	-----	-----------

### **Mobility in soil**

Soil/water partition coefficient (Koc)

Not available.

Mobility Volatile. Liquid. insoluble in water.

Other adverse effects No known significant effects or critical hazards.

### Section 13. Disposal considerations

#### **Disposal methods**

The generation of waste should be avoided or minimised wherever possible. Significant quantities of waste product residues should not be disposed of via the foul sewer but processed in a suitable effluent treatment plant. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Vapour from product residues may create a highly flammable or explosive atmosphere inside the container. Do not cut, weld or grind used containers unless they have been cleaned thoroughly internally. Avoid dispersal of spilt material and runoff and contact with soil, waterways, drains and sewers.

Product name Rustilo DWX 32 Product code 451220-TH04 Page: 8/10

Version 3.01 Date of issue 11/01/2016 Format China Language ENGLISH

# **Section 14. Transport information**

	China	IMDG	IATA
UN number	UN3295	UN3295	UN3295
UN proper shipping name	Hydrocarbons, liquid, n.o.s. (Naphtha (petroleum) hydrotreated heavy)	Hydrocarbons, liquid, n.o.s. (Naphtha (petroleum) hydrotreated heavy, mixture)	Hydrocarbons, liquid, n.o.s. (Naphtha (petroleum) hydrotreated heavy, mixture)
Transport hazard class(es)	3	3	3
Packing group	III	III	III
Environmental hazards	No.	No.	No.
Additional information	-	Emergency schedules (EmS) F-E, S-D	-

Special precautions for user

**Packaging** 

Not available. Not applicable.

Matters needing attention for

transportation

Ensure that any additional local government transport conditions are met

### Section 15. Regulatory information

Safety, health and environmental regulations specific for the product

No known specific national and/or regional regulations applicable to this product (including its ingredients).

Regulation according to other foreign laws

**REACH Status** For the REACH status of this product please consult your company contact, as

identified in Section 1.

Australia inventory (AICS)

Canada inventory

China inventory (IECSC)

Japan inventory (ENCS)

Korea inventory (KECI)

All components are listed or exempted.

(PICCS)
Taiwan inventory (CSNN)

**United States inventory** 

(TSCA 8b)

All components are listed or exempted.

All components are listed or exempted.

### Section 16. Other information

**History** 

Date of printing 11/01/2016

Date of issue/Date of 11/01/2016

revision

Date of previous issue 18/08/2015

Version 3.01

Product name Rustilo DWX 32

DWX 32 Product code 451220-TH04

Version 3.01 Date of issue 11/01/2016 Format China Language ENGLISH

China (ENGLISH)

Page: 9/10

### Section 16. Other information

### Key to abbreviations

ACGIH = American Conference of Industrial Hygienists

CAS Number = Chemical Abstracts Service Registry Number

GHS = Global Harmonised System

IATA = International Air Transport Association, the organisation

IMDG = International Maritime Organization Rules, rules governing shipment of

goods by water.

OEL = Occupational Exposure Limit

SDS = Safety Data Sheet

STEL = Short term exposure limit

TWA = Time weighted average

UN Number = United Nations Number, a four digit number assigned by the United

Nations Committee of Experts on the Transport of Dangerous Goods.

Varies = may contain one or more of the following 101316-69-2, 101316-70-5, 101316-71-6, 101316-72-7, 64741-88-4, 64741-89-5, 64741-95-3, 64741-96-4, 64741-97-5, 64742-01-4, 64742-44-5, 64742-45-6, 64742-52-5, 64742-53-6, 64742-54-7, 64742-55-8, 64742-56-9, 64742-57-0, 64742-58-1, 64742-62-7, 64742-63-8, 64742-64-9, 64742-65-0, 64742-70-7, 72623-85-9, 72623-86-0,

72623-87-1, 74869-22-0, 90669-74-2

#### References

Not available.

Indicates information that has changed from previously issued version.

#### **Notice to reader**

All reasonably practicable steps have been taken to ensure this data sheet and the health, safety and environmental information contained in it is accurate as of the date specified below. No warranty or representation, express or implied is made as to the accuracy or completeness of the data and information in this data sheet.

The data and advice given apply when the product is sold for the stated application or applications. You should not use the product other than for the stated application or applications without seeking advice from BP Group.

It is the user's obligation to evaluate and use this product safely and to comply with all applicable laws and regulations. The BP Group shall not be responsible for any damage or injury resulting from use, other than the stated product use of the material, from any failure to adhere to recommendations, or from any hazards inherent in the nature of the material. Purchasers of the product for supply to a third party for use at work, have a duty to take all necessary steps to ensure that any person handling or using the product is provided with the information in this sheet. Employers have a duty to tell employees and others who may be affected of any hazards described in this sheet and of any precautions that should be taken. You can contact the BP Group to ensure that this document is the most current available. Alteration of this document is strictly prohibited.

Date of issue/Date of revision : 11/01/2016 Date of previous issue : 18/08/2015 Version : 3.01 10/10

Product name Rustilo DWX 32

Version 3.01 Date of issue 11/01/2016

Format China

Language ENGLISH

Page: 10/10

China (ENGLISH)

Product code 451220-TH04