
Uncommissioned
not in the registry:
does nothing
installer registers it
Fallback
no valid command:
design flow
CO₂ > 1100
command accepted
TTL expired
(300 model-s)
Following
travels to the commanded
flow, floor enforced
CO₂ > 1100
CO₂ ≤ 1100
Override
CO₂ reading > 1100 ppm:
maximum flow
TTL expired on
its own clock
Own clock
(time signal lost)
keeps time itself
no beat for 5 s
beat returns