







AUDIO_CLK1 and AUDIO_CLK2 Require pull resistor on the Carrier when not in use!!!













A




B




C




| DESIGNED BY | DRAWN BY | PCB SCH. | PCB SCHEMATIC |
|-------------|---|---------------|---------------|
| mistywest | 554 E 15th Ave. Vancouver, BC V5T 2R5 | Approved Name | PROJECT |
| DATE | PCB # | SOM001 | REV B |
| | | | SHT * OF * |





A



SCIF0 is the Default Console interface; can be used to boot CPU




A





B



C







| Revision | Changes Since Last Revision |
|----------|--|
| A | New Release |
| B | Added LDO1 and LDO2 circuits to PMIC Changed revision setup on U5 to 000 0010 |

A

A

B

B


C

C

D

D

| | | | | |
|--|---|-------------|---------------|------------------|
| | 554 E 15th Ave. Vancouver, BC V5T 2R5 | DESIGNED BY | DWG TYPE | PCB SCHEMATIC |
| | | DRAWN BY | PCB SCH. | Revisions.SchDoc |
| | | APPROVED BY | Approved Name | PROJECT |
| | | DATE | PCB # | SOM001 |



Verify if this is necessary!!!

Based on feedback from Renesas the following pins are grounded on both ETH0 and ETH1:

TX_COL
TX_CRS
RX_ERR
LINKSTA

