

ROK019 01.00 Entrances								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
1.01	APS – D3.2 (2) (a)	If there is more than one pedestrian entrance, are 50% of them accessible (including the principal pedestrian entrance)	Entrance		Y			There is no evidence of non-compliance at 60% Review
1.02	APS – D3.2 (2) (b)	If the building is more than 500m² is any non accessible entry within 50m from an accessible entry.	Accessible Entry within 50m of Non-Accessible Entry		Y			There is no evidence of non-compliance at 60% Review
1.03	APS – D3.6 (e) Cl. 5.1	If there is a non accessible entrance doorway, is there appropriate signage provided (int. Symbol, direction arrow) directing users to an accessible entrance.	Non-Accessible Door Signage	TBA				Signage not designed at 60% review
1.04	APS – D3.2 (3) (a) (4) fig D3.2	If the pedestrian entrance is required to be accessible and consists of not more than 3 doorways, is not less than one doorway accessible.	Less than 3 doorways	TBA				Doors not defined at 60% review
1.05	AS 1428.1 Cl. 10.4.3 / AS 1428.2 Cl. 28	If there are security entry controls (card / buttons / intercom) are these at 900 – 1100mm-grasped/turned, 900-1200mm-pushed, 900-1260mm (not less than 600mm from corner)-touched, (ticket slot 800 – 900mm), and easy to operate.	Security door controls	TBA				Door hardware and security not defined to this level at 60% review
1.06	APS - A1.1	If there is a revolving door / turnstile, is there an alternative accessible hinged / sliding door	Revolving Door				NA	No revolving door
1.07	AS 1428.1 Cl. 10.4.2	Can the door be unlocked and opened by one hand (i.e. D or D lever handles).	Door Handle	TBA				Door hardware not specified to this level at 60% review
1.08	AS 1428.1 Cl. 10.4.2 (b)	Is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handle	TBA				Door hardware not specified to this level at 60% review
1.09	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles, snibs, locks) that need to be grasped or turned located between 900 – 1100mm high.	Door Controls	TBA				Door hardware not specified to this level at 60% review
1.10	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed located between 900 – 1200mm high.	Door Controls	TBA				Door hardware not specified to this level at 60% review
1.11	AS 1735.12 AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched located between 900 – 1260mm high and not less than 600mm from an internal corner except as specified in AS 1735.12 AS 1428.1 Cl. 10.4.3 (c)	Door Controls	TBA				Door hardware not specified to this level at 60% review
1.12	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handle	TBA				Door hardware not specified to this level at 60% review
1.13	AS 1428.1 Cl. 10.4.2 (f)	If an outward opening door is not self closing, is there a horizontal handrail or pull bar installed at a height between 900 – 1100mm (min. 60mm clearance from edge of door / door handle) on the inside of the door.	Door Handle	TBA				Door hardware not specified to this level at 60% review
1.14	AS 1428.1 Cl. 10.4.4	If doors are power operated, are the push button controls a min. of 25mm dia., proud of the surface (activating door before the button becomes level with surrounding surface).	Power operated door	TBA				Door hardware not specified to this level at 60% review
1.15	AS 1428.1 Cl. 10.4.3 (e)	If doors are power operated, are the controls at least 600mm from an internal corner and between 600 – 1000mm from arch of the hinged door leaf (in any position) / or clear of a surface-mounted sliding door in the open position.	Power operated door	TBA				Door hardware not specified to this level at 60% review
1.16	AS 1428.1 Cl. 3.6	If the doors / sidelights are frameless or fully glazed, are they clearly marked for safety and ease of identification across the full door width, with a solid and non-transparent contrasting line (viewable from 2m inside and outside) (luminance 30%). Size of line not less than 75mm high, with the lower edge at a height of 900 – 1000mm above finished floor level.	Door Material	TBA				Door hardware not specified to this level at 60% review
1.17	AS 1428.1 Cl. 10.1	Do all the doors or doorframes have a min. luminance contrast of 30% to their adjacent surfaces.	Door Frame Contrast	TBA				Finishes not specified to this level at 60% Review
1.18	AS 1428.1 Cl. 10.4.2 (e)	Is the entrance door easy, to initially open, (no heavy closer or spring) 20N max. (4.3lbf)	Door Pressure	TBA				Door closers not defined at 60% review
1.19	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	Is the min. clear opening of a doorway at the PPE 860mm or greater.	Min clear opening		Y			There is no evidence of non-compliance at 60% Review
1.20	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	If the doorway has 2 independent operated leaves, is the open doorway a min. of 860mm wide.	2 leaves	TBA				Door leaf size not defined at 60% review
1.21	AS 1428.1 Cl. 7.5 / 7.5	Is the door threshold level or is there an appropriate threshold ramp available at the entry (i.e. no step, inappropriate mat, weather strip etc.)	Door Threshold	TBA				Door thresholds not defined at 60% review
1.22	AS 1428.1 Cl. 7.5	If there is a threshold (max. rise 35mm) at the entrance or doorway (not more than 20mm from door leaf it serves), is there a ramp of not more than 280mm in length and min. ratio of 1:8. (Note: if the rise is greater a step ramp will be required).	Door Threshold	TBA				Door thresholds not defined at 60% review
1.23	AS 1428.1 Cl. 7.5	If the threshold ramp does not abut a wall or kerb, are sides tapered or splayed (min. 45°)	Door Threshold	TBA				Door thresholds not defined at 60% review
1.24	AS 1428.1 Cl. 4.2	If there is a recessed mat within the CAPT is the abutment of the surfaces no more than 3mm if vertical or 5mm if bevelled (rounded).	Door Threshold	TBA				Door thresholds not defined at 60% review

ROK019 01.00 Entrances								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
1.25	AS 1428.1 Cl. 4.3.1	If there is a carpet leading edge at the entrance is there a vertical face no higher than 3mm or a rounded bevelled edge no higher than 5mm or above that height a gradient of 1:8 up to a total max. height of 10mm.	Carpet	TBA				Door thresholds not defined at 60% review
1.26	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space outside the entrance doorway (not steeper that 1:40) (Doorway circulations spaces may overlap other circulation spaces).	Circulation Space outside		YES			There appears to be no issue with turning circle outside the lift and the entrance at 8D,9D on drawing CQU-ROK-033-02-ARC-21-02 REV 2
1.27	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space inside the entrance doorway (not steeper that 1:40) (Doorway circulations spaces may overlap other circulation spaces).	Circulation Space inside		YES			There appears to be no issue with turning circle outside the lift and the entrance at B8,B9 on drawing CQU-ROK-033-02-ARC-21-02 REV 2
1.28	AS 1428.1 Cl. 10.3.5	If there is an airlock, vestibule, or enclosed space, is there not less than 1460mm between the doorway (plus the door leaf width if the door encroaches into the space).	Airlock				NA	No Airlock defined at 60% Review
1.29	AS 1428.1 Cl. 3.7	If there are glazed viewing panels in doors, is the lower edge of the glazing not more than 1000mm above FFL, upper edge not less than 1600mm above FFL.	Glazed Viewing Panels	TBA				Door leaf + viewing panels not defined at 60% review
1.30	AS 1428.1 Cl 3.7	If there are glazed viewing panels in doors, is the width of the glazing within 200mm from latch edge of the door and min 160mm wide.	Glazed Viewing Panels	TBA				Door leaf + viewing panels not defined at 60% review
Universal Accessibility Options: not mandatory								
1.37	AS 1428.2 Cl. 23.3 (b)	Are the door handles provided with an appropriate luminance contrast	Door Handles	TBA				Door hardware not defined at 60% review
1.38		Do automatic self-opening doors have effective motion, and presence sensors installed	Automatic Doors	TBA				Door Control not defined at 60% Review
1.39		If there is an alarm control pad, is it located at a height between 900 – 1200mm high, accessible and easy to operate	Door Control	TBA				Door hardware not defined at 60% review
1.40		If there is a doorbell, is it accessible and easy to operate, located at a height between 900 – 1200mm	Doorbell	TBA				Door hardware not defined at 60% review
1.41		Is there appropriate lighting at the PPE	Lighting	TBA				Lighting not defined at 60% Review

ROK019 02.00 Customer Service Areas								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
2.01	APS – DP1	If there is a reception area, is there a direct CAPT from the PPE to the reception counter area.	CAPT		Y			No evidence of non-compliance at 60% Review
2.02	APS – DP9 / D3.6	Does any screened reception counter / ticket or tellers booth, with an inbuilt amplification system, have a hearing augmentation system installed.	SCREENED RECEPTION	TBA				Detail of Screen not on drawings at 60% Review
2.03	AS 1428.1 Cl. 4.1	Is the floor surface slip resistant.	FLOOR SURFACE	TBA				Type of floor surface defined at 60% Review but not Specification.
2.04	APS – Amdt. 1	If carpeted, is it short pile (<11mm and backing <4mm) and securely attached to the floor surface.	CARPET	TBA				Type of floor surface defined at 60% Review but not Specification.
2.05	AS 1428.1 Cl. 4.3.1	Are any exposed edges of carpet fastened to the floor surface and have a trim along the entire length of the exposed edge.	CARPET	TBA				Type of floor surface defined at 60% Review but not Specification.
2.06	AS 1428.1 Cl. 3.3	Are internal walkways a min. of 1000mm wide (1200mm preferred).	WALKWAY WIDTH		Y			No evidence of non-compliance at 60% Review - This will be monitored throughout all stages.
Universal Accessibility Options: not mandatory								
2.07	AS 1428.2 Cl. 24.1.1	Does the reception counter / ticket or tellers booth provide a wheelchair accessible section at a height of 830 – 870mm with leg clearance at a height of 800 – 840mm underneath, for a min. length of 900mm.	WHEELCHAIR ACCESSIBLE SECTION	TBA				Consider best practice to provide a wheelchair accessible section.
2.08	AS 1428.2 Cl. 27.2	Is some seating provided 450 – 520mm high, with armrests at a height of 220 – 300mm above the seat and a seat back, for use in the customer service area.	SEATING	TBA				Furniture specification not on drawings at 60% Review
2.09	AS 1428.2 Cl. 19	Is the customer service area appropriately lit and is the lighting even.	LIGHTING	TBA				Lighting not specified at 60% Review
2.1	AS 1428.2 Cl. 22	Are display and information stands within common reach ranges (230 – 1350mm) for wheelchair users (Note: different angles of approach e.g. side approach)	DISPLAY STANDS	TBA				Display Stands not included at 60% Review
2.11		Are there accessible height security alarm pads	SECURITY ALARMS	TBA				Security not defined at 60% Review
2.12		Are there effective contrasts between vertical and horizontal surfaces / objects	CONTRAST	TBA				Paint Finishes not defined at 60% Review

ROK019 03.00 Internal Accessways

Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
3.01	AS 1428.1 Cl. 3.3	Does the accessway have a min. width of 1000mm i.e. structurally and maintained to remain clear of temporary obstructions e.g. pot plants, bins.	Min Width		Y			There is no evidence that the accessway would not have a min width of 1000mm. This will be continued to be monitored through further stages of the project.
3.02	AS 1428.1 Cl. 3.2	Does the full length of the accessway have an overhead clearance of 2000mm (1980mm allowed at doorway)	Overhead Clearance		Y			There is no evidence that the accessway would not have an overhead clearance of 2m at 60% Review
3.03	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.4	Do accessways provide a passing space where a direct line of sight is not available to the end of the walkway (max. 20m intervals) (min. 1800mm wide x 2000mm long)	Turn Circle		Y			All Accessways have direct line of sight to the end. Accessways also have turning circles at each end.
3.04	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.5	Do accessways provide a turning space near the end of the walkway where it is not possible to continue (within 2m of end)	Turn Circle		Y			No evidence of non-compliance at 60% Review This will be continued to be monitored through further stages of the project.
3.05	AS 1428.1 Cl. 3.5	If a change of direction is required, is there appropriate circulation space provided along the accessway for the angle of the turn.	Circulation		Y			No evidence of inadequate circulation space at end of north-south accessway
3.06	AS 1428.1 Cl. 4.1	Does the accessway have a slip-resistant surface with a texture that is traversable by a wheelchair.	Slip Resistant	TBA				Floor surfaces not designed at 60% Review
3.07	APS – D3.6 (e) AS 1428.1 CL 5	If there is a non-accessible entrance doorway, is there appropriate signage provided (int. Symbol, direction arrow) directing users to an accessible entrance	Signage	TBA				Floor surface type is included in 60%Review but not specification.
3.08	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	Is the min. clear opening of a doorway on any accessway 850mm or greater.	Min Clear open		Y			No evidence of doorways that are less than 850mm
3.09	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space outside the doorway (NOTE: 1:40 grade, additional considerations at surface mounted sliding doors) (Doorway circulation space may overlap other circulation spaces)	Circulation		Y			No evidence of inappropriate circulation spaces outside each doorway. To be checked again at 60%
3.10	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space inside the doorway (NOTE: 1:40 grade, additional considerations at surface mounted sliding doors) (Doorway circulation space may overlap other circulation spaces)	Circulation		Y			No evidence of inappropriate circulation spaces inside each doorway. To be checked again at 60%
3.11	AS 1428.1 Cl. 10.4.2 (a)	Can the door be unlocked and opened by one hand (i.e. D or D lever handles)	Door Handles	TBA				Door hardware not designed at 60% Review
3.12	AS 1428.1 Cl. 10.4.2 (b)	Is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handles	TBA				Door hardware not designed at 60% Review
3.13	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles) that need to be grasped or turned between 900 – 1100mm high.	Door Handles	TBA				Door hardware not designed at 60% Review
3.14	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed between 900 – 1200mm high.	Door Handles	TBA				Door hardware not designed at 60% Review
3.15	AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched between 900 – 1250mm high (and not less than 500mm from an internal corner, except as specified in AS 1735.12)	Door Handles	TBA				Door hardware not designed at 60% Review
3.16	AS 1428.1 Cl.10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 1000 – 2000mm from the hinged swing door leaf (in any position) / or doorway of sliding door.	Power Door	TBA				Doors that are power operated not designed at 60% Review
3.17	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handles	TBA				Door hardware not designed at 60% Review
3.18	AS 1428.1 Cl. 10.4.2 (e)	Are all doors (other than fire / smoke doors) provided with the appropriate opening force (20N).	Door Force	TBA				Door Force not designed at 60% Review
3.19	AS 1428.1 Cl. 10.3.5	If there is an airlock, vestibule, or enclosed space, is there not less than 1450mm between the doorway (plus the door leaf width if the door encroaches into the space).	Air Vestibule				NA	No airlocks designed at 60% Review
3.20	AS 1428.1 Cl. 10.4.2 (g)	If an outward opening door is not self closing, is there a horizontal handrail or pull bar installed at a height between 900 – 1100mm (min. 50mm clearance from edge of door / door handle) on the inside of the door.	Hoor Handles	TBA				Door hardware not designed at 60% Review
3.21	AS 1428.1 Cl 11.1	Are all switches and controls provided on a CAPT (other than general purpose outlets (GPOs)) located at a height of 900 – 1100mm and not less than 500mm from an internal corner.	Switches and Controls	TBA				Door hardware not designed at 60% Review

ROK019 04.00 Accessible Toilet

Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
04.01	APS – F2.4 (a)	Is a toilet designated as wheelchair accessible available in the building / facility.	Access Toilet		Y			
04.02	APS – F2.4	Is a USAT provided on each floor level that toilets are provided on APS – F2.4.	Access Toilet		Y			
04.03	APS – F2.4 (g)	If there is more than 1 USAT is the 2 nd of the opposite hand.					NA	Only 1 USAT designed at 60% Review
04.04	AS 1428.1 Cl. 12.2.8.1	Is the min. circulation space 1900mm wide and 2300mm long to a height of 2000mm (Note: accepted intrusions)	Circulation Space		Y			
04.05	APS – F2.4 (f)	Is the toilet/s on a CAPT from the PPE (ensuring that access does not necessitate the traversing an area reserved for one sex only).	On CAPT		Y			
04.06	APS – D3.6 (c) / D4 / AS 1428.1 Cl 5	Is the toilet/s sign posted with the appropriate International Symbol of Access, and separate Male and Female symbols, located on the wall between 1200 - 1600mm high on the latch side of the doorway (Note: to include raised and visual versions).	Sign	TBA				Signage not designed at 60% Review
04.07	APS – D3.6 (c) / D4 / AS 1428.1 Cl 5	Does the signage indicate if the facility is suitable for left or right hand use.	Sign	TBA				Signage not designed at 60% Review
04.08	APS – D3.6 (f) / D4	If there is a non-accessible toilet provided, is there signage available that directs users to an accessible toilet (where in different locations).	Sign	TBA				Signage not designed at 60% Review
04.09	APS – D4.3 (2); AS 1428.1 Cl 5	If available on the sign, is the text provided in Title Case.	Sign	TBA				Signage not designed at 60% Review
04.10	AS 1428.1 Cl. 10.2	Is the min. clear opening width 850mm or greater for the toilet.	Min Opening		Y			No evidence of non-compliance at 60% review
04.11	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space at the door (inside and outside).	Circulation Space		Y			No evidence of non-compliance at 60% review
04.12	AS 1428.1 Cl. 12.2.9 (b)	Does the cubicle door have an 'occupied' (in-use) indicator and a bolt or catch (which is openable from the outside in an emergency).	Door Indicator	TBA				Door Hardware Specification not included at 60% Review
04.13	AS 1428.1 Cl. 12.2.9 (b)	If a snib catch is in use, does the snib handle have a min. length of 45mm from the centre of the spindle.	Snib Catch	TBA				Door Hardware Specification not included at 60% Review
04.14	AS 1428.1 Cl. 10.4.2 (e)	Is the cubicle door easy to initially open (no heavy closer) 20N max.	Door Pressure	TBA				Door Hardware Specification not included at 60% Review
04.15	AS 1428.1 Cl. 12.2.9 (a)	If the door is outward opening does it have a hinge mechanism that holds the door in a closed position without the use of a latch.	Hinge Mechanism	TBA				Door Hardware Specification not included at 60% Review
04.16	AS 1428.1 Cl. 10.4.2 (a)	Can the door be unlocked and opened by one hand (i.e. D lever or D handles and approp. hardware).	Door Handle	TBA				Door Hardware Specification not included at 60% Review
04.17	AS 1428.1 Cl. 10.4.2 (b)	Throughout its operation, is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handle	TBA				Door Hardware Specification not included at 60% Review
04.18	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles) that need to be grasped or turned between 900 – 1100mm high.	Door Handle	TBA				Review
04.19	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed between 900 – 1200mm high.	Door Handle				NA	Door Hardware not designed at 60% Review
04.20	AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched between 900 – 1250mm high and not less than 500mm from an internal corner.	Door Handle				NA	Door Hardware not designed at 60% Review
04.21	AS 1428.1 Cl. 10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 1000 – 2000mm from the hinged swing door leaf (in any position) / or doorway of sliding door.	Power Door				NA	Power Doors no defined at 60% Review
04.22	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handle	TBA				Door Hardware Specification not included at 60% Review
04.23	AS 1428.1 Cl. 10.1	Does the doorway have a min. luminance contrast of 30% to its adjacent surfaces.	Contrast	TBA				Paint Finishes not defined at 60% Review
04.24	AS 1428.1 Cl. 12.2.8 (fig 43)	Is there a 1500mm space in front of the pan (Note: basin overlap of 100mm permitted if located at front of pan only).	Space in front of pan		Y			No evidence of non-compliance at 60% review
04.25	AS 1428.1 Cl. 12.2.8 (fig 43)	Is there 1240 – 1250mm at one side of the pan (this allows side transfers from a wheelchair) (basin not permitted to overlap if located to side of pan).	Space side of pan		Y			No evidence of non-compliance at 60% review
04.26	AS 1428.1 Cl. 12.2.3 (a) (b) (c) (d)	Is there a full round toilet seat securely hinged to the pan (load rated to 150kg).	Sanitary Ware	TBA				Toilet Seat Specification not included at 60% review
04.27	AS 1428.1 Cl. 12.2.3 (e)	Does the toilet seat have a min. 30% luminance contrast with the background e.g. (pan, wall or floor).	Sanitary Ware	TBA				Toilet Seat Specification not included at 60% review
04.28	AS 1428.1 Cl. 12.2.2	Is the height to the top of the seat between 460 – 480mm.	Sanitary Ware		Y			No evidence of non-compliance at 60% review
04.29	AS 1428.1 Cl. 12.2.2	Is the front of the pan 790 - 810mm from the rear wall.	Sanitary Ware		Y			No evidence of non-compliance at 60% review
04.30	AS 1428.1 Cl. 12.2.2	Is the centreline of the pan 450 - 460mm from the side wall.	Sanitary Ware		Y			No evidence of non-compliance at 60% review
04.31	AS 1428.1 Cl. 12.2.2	Is the width of the pan a max. of 400mm.	Sanitary Ware		Y			No evidence of non-compliance at 60% review
04.32	AS 1428.1 – 2009 Cl. 12.2.2	Is the front of the pan a min. of 600mm from any back wall mounted fixture.	Sanitary Ware		Y			No evidence of non-compliance at 60% review
04.33	AS 1428.1 Cl. 12.2.4 (a)	Is a backrest provided on the USAT which is capable of withstanding a force in any direction of 1100N.	Sanitary Ware		Y			No evidence of non-compliance at 60% review
04.34	AS 1428.1 Cl. 12.2. 4 (b)	At its face, is the height of the lower edge of the backrest to the top of the WC seat between 120 – 150mm.	Sanitary Ware		Y			No evidence of non-compliance at 60% review
04.35	AS 1428.1 Cl. 15.2. 4 (c)	Does the backrest have a vertical height of 150 – 200mm and a width of 350 – 400mm.	Sanitary Ware		Y			No evidence of non-compliance at 60% review
04.36	AS 1428.1 Cl. 12.2. 4 (c) (d)	Does the backrest have its face centered on the pan centreline, positioned to achieve an angle of between 95 - 100° back from the seat hinge.	Sanitary Ware		Y			No evidence of non-compliance at 60% review
04.37	AS 1428.1 Cl. 12.2.7 (fig 42)	If a concealed or high level cistern is used, is a continuous grab rail at 800 – 810mm (30 – 40mm dia.) provided across the rear and side wall nearest the pan.	Sanitary Ware				NA	
04.38	AS 1428.1 Cl. 12.2.7 (fig 42)	If the grab rail on the side wall is one continuous rail, does it provide the appropriate angled extension and clearances from pan / wall.	Sanitary Ware				NA	
04.39	AS 1428.1 Cl. 12.2.7 (fig 42)	Is the outside edge of any back wall grab rail at least 450mm from the side of the pan (dependent on length of grab rail).	Sanitary Ware		Y			No evidence of non-compliance at 60% review

ROK019 04.00 Accessible Toilet

Number	Standard	Item	Item	TBA	Y	N	NA	Action
04.40	AS 1428.1 Cl. 14	Is the grab rail fixed and constructed to withstand a force of 1100N applied in any position and in any direction (without deformation or loosening or rotation of the fastenings or fittings).	Sanitary Ware	TBA				Grab Rail Force Specification not included at 60% review
04.41	AS 1428.1 Cl. 14	Is the clearance between the grab rail and the adjacent wall surface or other obstruction not less than 50mm and not more than 60mm.	Sanitary Ware		Y			
04.42	AS 1428.1 Cl. 14	Is there a min. 600mm clearance above the horizontal grab rail, with a min. of 50mm below any horizontal or angled rail (except at fixing points).	Sanitary Ware		Y			
04.43	AS 1428.1 Cl. 14	Are exposed edges and corners of grab rails provided with a radius of not less than 5mm.	Sanitary Ware	TBA				Grab Rail Detailed Specification not included at 60% review
04.44	AS 1428.1 Cl. 12.2.7 (fig 42)	If a surface mounted / low level cistern is used, is there a wall mounted grab rail (30 – 40mm dia.) a min. length 300mm on the rear wall located within 50mm of the cistern, together with a grab rail mounted on the sidewall at 800 – 810mm high (as per diagram).	Sanitary Ware				NA	Sanitary ware not defined at 60% Review
04.45	AS 1428.1 Cl. 12.2.2	Is the bottom edge of the cistern a min. of 600mm above floor level.	Sanitary Ware		Y			No evidence of non-compliance at 60% review
04.46	AS 1428.1 Cl. 12.2.6 (fig 41)	Can the toilet paper be easily reached (max. outside edge 300mm forward of pan and top edge 700mm max. height) and the roll dispenser have no greater than 150mm projection from the wall.	Sanitary Ware		Y			No evidence of non-compliance at 60% Review
04.47	AS 1428.1 Cl. 12.2.5 (fig 40)	If the flushing control is located on the back wall, is it within reach, easy to operate (activating the flush before level with the surrounding surface) <i>contrasting 30% with adjacent surfaces</i> (min height 600mm / max. height 1100mm / outside edge max. 500mm from centre line)	Sanitary Ware	TBA				Flushing control detail not defined at 60% Review
04.48	1428.1 Cl. 12.2.5 (fig 40)	If not located on the back wall as above, is it located in the centre line of the toilet AS.	Sanitary Ware	TBA				Flushing control detail not defined at 60% Review
04.49	AS 1428.1 Cl. 12.2.5 (fig 40)	If the flushing control is located on the side wall is it within the approp. zone (inside edge no further than 300mm over the pan / outside edge no further than 300m from the front of the pan – at a height between 600 – 1100mm above finished floor level.	Sanitary Ware	TBA				Flushing control detail not defined at 60% Review
04.50	AS 1428.1 Cl. 12.2.10	Is there a basin inside the unisex accessible toilet	Sanitary Ware		Y			No evidence of non-compliance at 60% review
04.51	AS 1428.1 Cl. 12.2.8 (fig 43)	Is the distance between the basin and pan at least 1400mm (front of pan location only permitted for 100mm overlap).	Sanitary Ware		Y			No evidence of non-compliance at 60% review
04.52	AS 1428.1 Cl. 12.3.1 (d) (fig 44 (a) (b))	If a semi recessed washbasin is installed (other than within a SOU) is the front top edge 800 – 840mm above the floor.	Sanitary Ware				NA	Sanitary ware not defined at 60% Review
04.53	AS 1428.1 Cl. 12.3.1 (d) (fig 44 (a) (b))	If a wall mounted washbasin is installed is the front top edge 800 – 830mm above the floor.	Sanitary Ware			Y		No evidence of non-compliance at 60% review
04.54	AS 1428.1 Cl. 12.3.1 (d) (fig 44 (a) (b))	If a semi recessed basin is provided (except within a SOU) is the bench provided at a height between 800 – 830mm (outside of circulation spaces).	Sanitary Ware				NA	Sanitary ware not defined at 60% Review
04.55	AS 1428.1 Cl. 12.3.1 (d) (fig 46)	Is the centre line of the washbasin (rear) provided with a min. 225mm either side.	Sanitary Ware			Y		No evidence of non-compliance at 60% review
04.56	AS 1428.1 Cl. 12.3.1 (d) (fig 44)	Is the centre line of the washbasin a min. of 425mm from any wall.	Sanitary Ware			Y		No evidence of non-compliance at 60% review
04.57	AS 1428.1 Cl. 12.3.1 (d) (fig 44)	Is the circulation space a min. of 450mm wide (rear of basin).	Sanitary Ware			Y		No evidence of non-compliance at 60% review
04.58	AS 1428.1 Cl. 12.3.1 (d) (fig 46)	Is the circulation space for the washbasin a min. 1500mm long and 850mm wide (from rear of washbasin).	Sanitary Ware			Y		No evidence of non-compliance at 60% review
04.59	AS 1428.1 Cl. 12.3.1 (d) (fig 44)	Is the position of the taps, bowl and drain outlet appropriate.	Sanitary Ware			Y		No evidence of non-compliance at 60% review
04.60	AS 1428.1 Cl. 12.3.1 (d) (fig 44) (a)	Does the basin have appropriate foot / knee / leg space underneath.	Sanitary Ware			Y		No evidence of non-compliance at 60% review
04.61	AS 1428.1 Cl. 12.3.1 (c) (e)	If the downpipes are exposed are they insulated or located so as to ensure they do not present a hazard to the user and sit outside the circulation space under the washbasin.	Downpipe			Y		No evidence of non-compliance at 60% review
04.62	AS 1428.1 Cl. 12.2.1 (d)	If hot water is provided, is water delivered through a mixing spout.	Mixing Spout			Y		No evidence of non-compliance at 60% review
04.63	AS 1428.1 Cl. 12.2.1 (c)	If hot water is provided, is the hot tap located on the left of or above the cold tap.	Hot / Cold Tap				NA	Mixer Tap
04.64	AS 1428.1 Cl. 15.2.1 (a)	Are the tap handles lever, sensor plates, voice activation or other similar controls.	Tap Handles	TBA				Sanitary ware not defined at 60% Review
04.65	AS 1428.1 Cl. 12.2.1 (b)	If the taps have lever handles, are they located more than 50mm from adjacent surfaces.	Tap Handles	TBA				Tap Handles specification not included at 60% Review
04.66	AS 1428.1 Cl 12.2.1 (c)	Are taps clearly identified as hot and cold (colour and text) and in the appropriate location.	Tap Handles				NA	Mixer Tap
04.67	AS 1428.1 Cl. 12.4.4	Is there a clothes hanging device 1200 – 1350mm from the floor (not less than 500mm from an internal corner (Note: shower exception)	Clothes Hanger			Y		No evidence of non-compliance at 60% review
04.68	AS 1428.1 Cl. 12.4.1	Is a mirror provided and located either adjacent to or above the washbasin at a min. of 350mm wide.	Mirror			Y		No evidence of non-compliance at 60% review
04.69	1428.1 Cl. 12.4.1	If the mirror is above the basin, does it extend between 900mm – 1850mm above the floor, or If adjacent to the basin, at a height of not more than 780mm to a height of not less than 1800mm above the floor.	Mirror			Y		No evidence of non-compliance at 60% review
04.70	AS 1428.1 Cl. 12.4.3	If a hand dryer / towel dispenser is provided, is the operative component at a height between 900 – 1100mm and within reach of a user at the washbasin (not closer than 500mm from any internal corner) does not encroach more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Hand Dryer			Y		No evidence of non-compliance at 60% review
04.71	AS 1428.1 Cl. 12.4.3	If a soap dispenser is provided, is the operative component at a height between 900 – 1100mm and within reach of a user at the washbasin (not closer than 500mm from any internal corner) does not encroach more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Soap Dispenser			Y		No evidence of non-compliance at 60% review
04.72	AS 1428.1 Cl. 12.4.2 (a)	One of the following three shelves must be provided. If a shelf is provided as a vanity top is it located at a height between 800 – 830mm with a min. width of 120mm and depth of 300mm and a depth no greater than the bowl plus its front and back flanges, without	Shelf			Y		No evidence of non-compliance at 60% review
04.73	AS 1428.1 Cl. 12.4.2 (b) (i)	If a shelf is provided within the circulation space as a separate fixture, is it available at a height between 900 – 1000mm with a min. width of 120 -150mm and length of 300 – 450mm.	Shelf				NA	Basin includes vanity top

ROK019 04.00 Accessible Toilet								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
04.74	AS 1428.1 Cl. 12.4.2 (b) (ii)	If a shelf is provided external to the circulation space as a separate fixture, is it at a height between 790 – 1000mm with a min. width of 120mm and length of 400mm and does not encroach more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Shelf				NA	Basin includes vanity top
04.75	AS 1428.1 Cl. 12.4.5 (a) (fig 43)	If there is a portable sanitary disposal unit available, is it provided in the rear corner between the pan and the closest wall.	Sanitary Disposal			Y		No evidence of non-compliance at 60% review
04.76	AS 1428.1 Cl. 12.4.5 (b)	If a recessed sanitary disposal unit is provided, is it located within 500mm of the pan.	Sanitary Disposal			Y		No evidence of non-compliance at 60% review
04.77	AS 1428.1 Cl. 12.2.8.1 (iv)	If a wall cabinet is provided, does it encroach not more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Wall Cabinet			Y		No evidence of non-compliance at 60% review
04.78	AS 1428.1 Cl. 11.2	Are rocker action / toggle switches provided which are a min. 30 x 30mm.	Switches	TBA				Sanitary ware not defined at 60% Review
04.79	AS 1428.1 Cl. 11.2	If push pad switches are provided are they a min. of 25mm dia.	Switches	TBA				Sanitary ware not defined at 60% Review
04.80	AS 1428.1 Cl. 11.2	If provided near the washbasin, are switches and power points 600 –1100mm high, not less than 500mm from the internal corners <i>and close to any shelf or worktop</i> .	Switches	TBA				Sanitary ware not defined at 60% Review
04.81	AS 1428.1 Cl. 12.2.8.2	If there is a baby change table, is it located at a height of 820 mm with leg clearance height underneath of 720 when open (must sit outside of circ. space when folded up).	Baby Change Table			Y		No evidence of non-compliance at 60% review
Ambulant Toilets								
	Standard	Items						
04.82	APS – F2.4	If there are one or more toilets provided in addition to the USAT at the bank of toilets, is an ambulant male and an ambulant female toilet provided	Ambulant Toilet			Y		No evidence of non-compliance at 60% review
04.83	AS 1428.1 Cl. 13.4.	If ambulant toilets are provided, installed at the airlock serving the area that contains the facilities identifying the facilities within AS 1428.1 Cl. 13.4.	Signage	TBA				Signage not defined at 60% Review
04.84	APS – D3.6 (d) / AS 1428.1 Amdt. 1 Cl. 8.1.	Is there signage (raised text and Braille, and raised and visual symbols) installed on the door of the facility.	Signage	TBA				Signage not defined at 60% Review
04.85	AS 1428.1 Cl. 10.3	If there is an airlock enroute to an ambulant toilet, is there appropriate circulation space.	Airlock		N			See Markup in Appendix A - there needs to be more circulation space for airlock.
04.86	AS 1428.1 Cl. 13.3	Is the min. clear opening width of the ambulant toilet doorway 700mm.	Width of Doorway			Y		No evidence of non-compliance at 60% review
04.87	AS 1428.1 Cl. 13.3	Does the cubicle door have an 'occupied' (in-use) indicator and a bolt or catch (which is openable from the outside in an emergency).	Indicator	TBA				Ambulant toilet lock not defined at 60% Review
04.88	AS 1428.1 Cl. 13.3	If a snib catch is in use, does the snib handle have a min length of 45mm from the centre of the spindle	Snib Catch	TBA				Ambulant toilet not defined at 60% Review
04.89	AS 1428.1 Cl. 16.1	Is the width of the ambulant toilet compartment between 900 – 920mm.	Width of Ambulant			Y		No evidence of non-compliance at 60% review
04.90	AS 1428.1 Cl. 13.1 fig 52 (B)	Is there a clear min. circulation space of 900mm long x 900-920mm wide in front of the toilet pan.	Min Circulation in			Y		No evidence of non-compliance at 60% review
04.91	AS 1428.1 Cl. 13.3 fig 52 (B)	Is there a clear circulation space a min. of 900 x 900mm outside the door (Note: variety of placement options).	Min Circulation out			Y		No evidence of non-compliance at 60% review
04.92	AS 1428.1 Cl. 12.2.7	Are appropriate grab rails installed on the wall located at a height between 800 – 810mm.	Grab Rail			Y		No evidence of non-compliance at 60% review
04.93	AS 1428.1 Cl. 14	Is the grab rail fixed and constructed to withstand a force of 1100N applied in any position and in any direction (without deformation or loosening or rotation of the fastenings or fittings).	Grab Rail			Y		No evidence of non-compliance at 60% review
04.94	AS 1428.1 Cl. 14	Is the clearance between the grab rail and the adjacent wall surface or other obstruction not less than 50mm and not more than 60mm.	Grab Rail	TBA				Elevation detail of Ambulant Toilet not provided at 60% to check.
04.95	AS 1428.1 Cl. 14	Is there a min. 600mm clearance above the horizontal grab rail, with a min. of 50mm below any horizontal or angled rail (except at fixing points).	Grab Rail			Y		No evidence of non-compliance at 60% review
04.96	AS 1428.1 Cl. 14	Are exposed edges and corners of grab rails provided with a radius of not less than 5mm.	Grab Rail	TBA				Elevation detail of Ambulant Toilet not provided at 60% to check.
04.97	AS 1428.1 Cl. 13.1	Is the toilet pan provided with the standard projection of between 610 – 660mm.	Pan Projection			Y		No evidence of non-compliance at 60% review
04.98	AS 1428.1 Cl. 13.1	Is the height to the top of the seat between 460 – 480mm.	Height to top of seat			Y		No evidence of non-compliance at 60% review
04.99	AS 1428.1 Cl. 13.1 fig 52 (A)	Can the toilet paper be easily reached (max. outside edge 300mm forward of pan and top edge 700mm max. height).	Toilet Paper position	TBA				Elevation detail of Ambulant Toilet not provided at 60% to check.
Universal Accessibility Options: not mandatory								
4.100		Are the door handles or controls colour contrasting to the background (30%)	Contrast	TBA				Door Hardware not defined at 60% Review
4.101		Is appropriate lighting provided inside the toilet	Lighting	TBA				Lighting not defined at 60% Review
4.102		Is there an emergency alarm installed in the cubicle, for users requiring assistance	Alarm	TBA				Alarm system not defined

ROK019 05.00 Change / Shower Facilities								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
05.01	APS – F2.4 (b) NOTE: can still be considered under equity requirements of DDA	Is there a designated accessible shower cubicle for people using wheelchairs (requirement dependant on class of building under APS).	Accessible Shower Cubicle				NA	One shower only on ROK019 Level 3
05.02	AS 1428.1 Cl. 12.5.1 (c)	If two or more shower recesses are provided, is at least one of the opposite hand.	LH / RH				NA	One shower only on ROK019 Level 3
05.03	AS 1428.1 Cl. 10.2	Does the shower doorway have a min. clear opening width of 850mm.	Shower Doorway		Y			No evidence of non-compliance at 60% review
05.04	AS 1428.1 Cl. 10.1	Does the door / doorframe into the shower area have a min. luminance contrast of 30% to the adjacent surfaces.	Doorframe contrast	TBA				Shower detail not provided at 60% Review
05.05	AS 1428.1 Cl. 12.2.9 (b)	If an inward opening shower door is provided, is it operable or removable from outside in an emergency.	Inward open Shower door	TBA				Shower detail not provided at 60% Review
05.06	AS 1428.1 Cl. 12.5.1 / 12.5.3	Is the shower circulation space a min. size of 1600mm x 2500mm for a three walled enclosure, or 1600mm x 2350mm for a two walled enclosure.	Shower Circulation		Y			No evidence of non-compliance at 60% review
05.07	AS 1428.1 Cl. 12.5.2	Is the shower recess accessible with no hob or step and at a gradient of between 1:60 and 1:80.	No Hob	TBA				Shower detail not provided at 60% Review
05.08	AS 1428.1 Cl. 12.5.2	Is the slope of the remainder of the sanitary facility provided at a grade of between 1:80 and 1:100	Gradient of slope	TBA				Shower detail not provided at 60% Review
05.09	AS 1428.1 Cl. 12.5.1 (a)	Is the circulation space clear to a height of not less than 2000mm (excluding allowable fittings).	Circulation Space	TBA				Shower detail not provided at 60% Review
05.10	AS 1428.1 Cl. 12.5.4	Are there appropriate grab rails (30 – 40mm dia.) available at 800 – 810mm high (back wall).	Grab Rails	TBA				Shower detail not provided at 60% Review
05.11	AS 1428.1 Cl. 12.5. / 14	Is there a showerhead support grab rail (vertical 30 – 40mm dia.) installed with the bottom end between 1000 – 1100 and the top end between 1880 – 1900mm high (Note: optional extension available)	Grab Rails	TBA				Shower detail not provided at 60% Review
05.12	AS 1428.1 Cl. 12.5. / 14	Is the vertical showerhead support grab rail located 580 – 600mm from the internal corner of the shower.	Grab Rails	TBA				Shower detail not provided at 60% Review
05.13	AS 1428.1 Cl. 12.5.9	Is a foldable, self-draining, slip resistant seat (960mm x 390 / 400mm) provided in the shower recess at a height of 470 – 480mm, with an appropriate clearance from adjacent surfaces (i.e. 40mm max.)(requires rounded edges and must fold upwards – refer AS)	Shower Seat	TBA				Shower detail not provided at 60% Review
05.14	AS 1428.1 Cl. 12.5.9	Is the shower seat able to withstand a force of 1100N.	Shower Seat	TBA				Shower detail not provided at 60% Review
05.15	AS 1428.1 Cl. 12.5.9	If the shower seat is in the folded up position, is the grab rail accessible.	Shower Seat	TBA				Shower detail not provided at 60% Review
05.16	AS 1428.1 Cl. 12.5.9	Are the drainage gaps / slots within the shower seat 4 – 6mm wide.	Shower Seat	TBA				Shower detail not provided at 60% Review
05.17	AS 1428.1 Cl. 12.5.6	Is a hand held and adjustable shower head available within reach when seated.	Shower Head	TBA				Shower detail not provided at 60% Review
05.18	AS 1428.1 Cl. 12.5.6	Is a flexible hose provided for the shower that is a min. length of 1500mm (Note: requirements of back flow prevention device).	Shower Hose	TBA				Shower detail not provided at 60% Review
05.19	AS 1428.1 Cl. 4.1	Is the floor slip resistant.	Slip Resistance	TBA				Shower detail not provided at 60% Review
05.20	AS 1428.1 Cl. 12.2.1	Is the tap/s located on the wall at a height between 900 – 1100mm.	Taps	TBA				Shower detail not provided at 60% Review
05.21	AS 1428.1 Cl. 12.2.1	Is the hot tap located on the left of / or above the cold tap.	Taps	TBA				Shower detail not provided at 60% Review
05.22	AS 1428.1 Cl. 12.2.1	Are the tap handles lever or sensor control or voice activated.	Taps	TBA				Shower detail not provided at 60% Review
05.23	AS 1428.1 – Cl. 12.2.1/12.5.8	If the taps have lever handles, are they located more than 50mm from adjacent surfaces and nor more than 100mm long.	Taps	TBA				Shower detail not provided at 60% Review
05.24	AS 1428.1 Cl. 12.5.8	Is the tap fixture located no closer than 50mm from the vertical grab rail (to ensure clearance around grab rail).	Soap Holder	TBA				Shower detail not provided at 60% Review
05.25	AS 1428.1 Cl. 12.5.7	Is there a soap holder located between 900 – 1100mm no closer than 50mm of the vertical support rail (protruding type preferred).	Soap Holder	TBA				Shower detail not provided at 60% Review
05.26	AS 1428.1 Cl. 12.4.4 / 12.5.1	Are a minimum of two clothes hanging devices provided at 1200 - 1350mm high, with one within 390 – 410mm and the 2nd within 590 – 610mm of the folding seat and not less than 500mm out from any internal corner.	Clothes Hanging Devices	TBA				Shower detail not provided at 60% Review
05.27	AS 1428.1 Cl. 12.2.8.2	If there is a baby change table available, is it at a height of 820mm with leg clearance height underneath of 720mm.	Baby Change Table	TBA				Shower detail not provided at 60% Review
05.28	AS 1428.1 Cl. 12.5.2 (b) (Note: A linear drain may be provided)	If the waste outlet is in the centre line of the shower floor, is it (525 - 575mm from the wall with tap / 555 – 605mm from the wall with the seat).	Waste Outlet	TBA				Shower detail not provided at 60% Review
Universal Accessibility Options: not mandatory								
05.29		Are the taps clearly identified as hot and cold (colour and text)	Taps	TBA				Shower detail not provided at 60% Review

ROK019 06.00 Passenger Lifts

Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
06.01	APS 4.4 / E3.6	Is there a lift available to all floors (where required).	All Floors		Y			
06.02	APS – E3.6b	Is the lift door installed with a min. clear opening width of 900mm.	Min. Clear Width	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.03	AS 1735.12 - Sect. 6	Is the internal lift floor surface level with the external surface for an unobstructed entry into the lift (12mm variation allowed).	Floor Surface	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.04	APS - E3.6 / 1735.12 – Sect. 2	If the lift was approved with building permit issued prior to 1st May 2011, (or new and travels not more than 12m), is the min. floor area 1100mm wide x 1400mm deep.	Age of Lift				NA	
06.05	APS – 4.4 / E3.6	If the lift was approved with building permit issued on or after 1st May 2011 and travels more than 12m, is the min. floor area 1400mm wide x 1600mm deep.	Age of Lift	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.06	AS 1735.12 – Cl. 3.1 / APS Amdt. (6)	If carpet is provided within the lift, is it appropriate (pile <11mm, backing <4mm)	Carpet	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.07	AS 1735.12 – Cl. 4.2	Is an appropriate door operating sensor (passenger protection system) in place which whilst activated holds the doors open.	Sensor	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.08	AS 1735.12 – Cl. 4.3	Do the doors, when responding to a landing button, remain open for a full 6 seconds.	Open Time	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.09	AS 1735.12 Cl. 4.3	If there are three or more lifts in line and they are interconnected in their operation, is the door dwell time extended to a min. 8 sec (Note: dwell times may be shortened in some instances).	More than 1 lift				NA	
06.10	AS 1735.12 Cl. 8.5	If there are three or more lifts in the bank of lifts is there visible and audible notification on each lift landing to indicate the lift arrival and direction of travel.	More than 1 lift				NA	
06.11	AS 1735.12 Cl. 5.1	Are the adjacent parallel surfaces in the lift car located within 300mm of the control buttons, provided with a surface that reduces glare and reflection.	Parallel Surfaces	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.12	AS 1735.12 Cl. 5.2	Are car operating panels, seats, handrails provided so as to not obstruct or reduce the width of the door opening.	Internal Car Fitout	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.13	AS 1735.12 Cl. 5.3.2 (a)	Is a handrail available which is a min. length of 600mm, located in the lift at a height between 850 – 950mm.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.14	AS 1735.12 Cl. 5.3.1	Is this handrail a max. of 500mm from any button or device to operate the lift.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.15	AS 1735.12 Cl. 5.3.2 (a)	Does the handrail have a circular diameter of 30 – 50mm for a min. of 270°.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.16	AS 1735.12 Cl. 5.3.2 (c)	Are exposed edges of the handrail provided with a radius of not less than 5mm.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.17	AS 1735.12 Cl. 5.3.2 (f)	Are clearances above the handrail (including clearances to the control panel) less than 5mm or not less than 100mm.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.18	AS 1735.12 Cl. 5.3.2 (g)	Are handrails set 50mm from the car wall.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.19	AS 1735.12 Cl. 5.3.2 (g)	If there is a gap less than 50mm between the wall and handrail (i.e. where handrail is returned to the wall) is it filled in (enclosed)	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.20	AS 1735.12 Cl. 5.4	If there is a fixed seat within the lift, does it sit outside of the min. car size (Note: hinged seats not acceptable).	Seat within Lift	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.21	AS 1735.12 Cl. 7.1	Is each landing provided with one or more control buttons to call the lift.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.22	AS 1735.12 Cl. 7.3.1	Is the centre of landing control buttons, key switches and card readers located between 900mm –1200mm above the landing floor.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.23	AS 1735.12 Cl. 7.3.3	Are the landing control buttons located adjacent to the lift entrances and not closer than 500mm from any internal corner or fixed obstruction.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.24	AS 1735.12 Cl. 7.1	If up and down buttons are provided on a landing, and are not located vertically within 200mm of each other, is a tactile symbol and Braille equivalent provided (above or to the left or on the face of the respective button).	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.25	AS 1735.12 Cl. 7.2.3	If a key pad is provided, is it set up like a telephone key pad and located at a height between 900 - 1100mm from the floor.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.26	AS 1735.12 Cl. 7.2.3 / 7.4	If a key pad is provided, is there a tactile dot provided in the centre of the number 5 (unless the tactile symbol is on the face of the button).	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.27	AS 1735.12 Cl. 7.2.1	If the lift has a dimension less than 1400mm, are there two lift control panels provided (one to the left and one to the right of a person entering the lift).	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.28	AS 1735.12 Cl. 7.2.2 Figure 8.4.2 (c)	Is the communication button located at the right hand end of the lowest row of buttons and identified by a visible symbol.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.29	AS 1735.12 Cl. 7.2.2 / 8.3 Figure 8.4.2 (c)	Is there a tactile symbol and Braille equivalent above or to the left or on the face of the respective buttons.	Signage	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.30	APS – E3.6 (b) / AS 1735.12 – Sect 9.2 / 9.3	Is there an emergency hands-free communication system installed, (including a button that alerts a call centre of a problem and a light to signal that the call has been received).	Emergency comms	TBA				Existing Lift Detail not shown in drawings at 60% Review

ROK019 06.00 Passenger Lifts								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
06.31	AS 1735.12 Cl. 7.3.1	Is the centre of the face of the control buttons within the lift located at a height between 700 – 1250mm.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.32	AS 1735.12 Cl. 7.3.2	Are the control buttons within the lift located within the appropriate zones / distance from the door / corners.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.33	AS 1735.12 Cl. 7.4	Are the control buttons of the appropriate size, design and easy to use (2N – 5N).	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.34	APS – E3.6 (b)	If the lift travels more than 2 floors, is there appropriate audible information to identify when the lift stops.	Audible	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.35	APS – E3.6 (b)	If the lift travels more than 2 floors, is there appropriate audible and visual indication at each lift landing to indicate the arrival of the lift.	Audible	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.36	AS 1735.12 Cl. 8.6	Is an appropriate lift position indication provided within the lift (i.e. lift on 2nd floor, 4th floor etc.).	Position Indicator	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.37	AS 1735.12 Cl. 10.2	Is there appropriate lighting within the lift.	Lighting	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.38	AS 1735.12 Cl. 10.3	Are the lift control buttons appropriately lit.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
Universal Accessibility Options: not mandatory								
06.39	AS 1428.2 – Cl. 12	Can a wheelchair turn around in the lift (recommended 1700x 1900mm)	Circulation	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.40		Are the handrails in contrast to the walls	Handrail Contrast	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.41		Are the internal walls of the lift of a non-reflective material	Wall Finish	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.42		Are the emergency procedures clearly identified in the event of a lift malfunction	Signage	TBA				Existing Lift Detail not shown in drawings at 60% Review

ROK019 07.00 Kitchens								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
07.01	AS 1428.1 Cl. 3	Is there a CAPT provided to the kitchen / bar / dining / laundry / canteen area.	CAPT		Y			CAPT to Staffroom
07.02	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there a continuous internal accessible path of travel to any canteen window.	Canteen				NA	
07.03	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there a continuous external accessible path of travel to any external canteen / servery window.	Canteen				NA	
07.04	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there appropriate circulation space within the kitchen area, to enable a user ease of use for all facilities.	Circulation Space		Y			Appendix A - See markup of CQU-ROK-19-3-ARC-40-007
Universal Accessibility Options: not mandatory								
07.05	AS 1428.2 Cl. 24	Does the counter have a wheelchair accessible section at a height between 830 – 870mm for a min. length of 900mm.	Counter	TBA				Consider best practice of a portion of the counter being wheelchair accessible.
07.06	AS 1428.2 Cl. 24	Does the counter have at the wheelchair accessible section, a leg clearance underneath at a height between 800 – 840mm for a min. length of 900mm.	Counter	TBA				Consider best practice of a portion of the counter being wheelchair accessible.
07.07	AS 1428.2- A5	Is the sink / basin accessible to people in wheelchairs (height 770 – 800mm).	Basin		Y			
07.08	AS 1428.2- A5	Is the sink / basin accessible to people in wheelchairs (leg clearance height underneath 640-650mm) with appropriate unobstructed circulation space.	Basin		Y			
07.09	AS 1428.2 Cl. 24	If there is a canteen / servery window does it have a wheelchair accessible section at a height between 830 – 870mm with a leg clearance underneath at a height of 800 – 840mm for a min. length of 900mm.	Canteen Window				NA	
07.10	AS 1428.2 Cl. 29	Are the operative components of any vending machine, for pre-packaged food and drink, accessible and between 700 – 1200mm high.	Vending Machine				NA	
07.11	AS 1428.2 Cl. 27.2	If seating is available, is it at a height of 450 – 520mm with armrests located at a height between 220 – 300mm above the seat and backs.	Seating	TBA				Consider some chairs to have armrests.
07.12		If tea and coffee facilities are provided (other than vending machine), are the highest operable components located at a height between 900 – 1100mm.	Tea / Coffee	TBA				Consider accessible tea and coffee facilities.

ROK019 08.00 Meeting Spaces								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
08.01	AS 1428.2 Cl. 26.2 (a)	If an inbuilt stage or podium is provided, is there ramp access (in addition to any step / stair).	Stage				NA	No stages or podium on Level 3 ROK019
08.02	APS – D3.7 (1) (2) (3)	If a sound amplification system is installed / inbuilt, is there a hearing augmentation system that covers 80% of the total enclosed space if an induction loop is inbuilt, or 95% if a receiver system is in use.	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification and hearing augmentation not defined at 60% Review
08.03	APS – D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, (excluding letter 'T') indicate the area where an assistive listening system is operational and the area covered.	Signage	TBA				Signage not defined at 60% Review
08.04	APS – D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, (excluding letter 'T') indicate which type of system is in place.	Signage	TBA				Signage not defined at 60% Review
08.05	APS – D3.7 (1) (2) (3)	If receivers are being used, does the signage indicate where the receivers can be obtained.	Signage	TBA				Signage not defined at 50 Review
08.06	AS 1428.1 Cl. 4.1	Is there a level, slip resistant floor surface.	Slip Resistance	TBA				Floor Surfaces not defined at 60% Review
08.07	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there adequate circulation space between all furniture and fittings.	Circulation Space			N		See Appendix A markup there are meeting rooms that will have sections that are inaccessible.
Universal Accessibility Options: not mandatory								
08.08		Is there appropriate lighting to the area.	Lighting	TBA				Lighting not defined at 60% Review
08.09		Is there clear, concise signage, incorporating Braille and tactile components that identifies all elements e.g. toilet, emergency exits.	Signage	TBA				Signage not defined at 50 Review
08.10		Is there sufficient level circulation space provided for a person using a wheelchair to sit at a meeting table in various locations.	Circulation Space			N		See Appendix A markup there are meeting rooms that will have sections that are inaccessible.
08.11	AS 1428.2 Cl. 27.2	Is there some seating available which is 450 – 520mm high with armrests provided at a height of 220 – 300mm above the seat and a back.	Seating	TBA				Meeting room furniture not defined at 60% Review
08.12	AS 1428.2 Cl. 26.2	Are boundaries of any stage or podium defined by barriers or an appropriate contrast to the floor surface, (colour and texture)	Stage				NA	No podium defined at 60% Review
08.13	AS 1428.2 Cl. 26.2 (b) / 6.3	Are all stage / podium controls able to be operated by a person when seated	Stage				NA	No podium defined at 60% Review
08.14	AS 1428.5 - 3	Is hearing augmentation available in meeting rooms (seating 5 or more participants)	Hearing Augmentation	TBA				Hearing Augmentation not defined at 60% Review

ROK019 09.00 Hearing Augmentation								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
09.01	APS – D3.7 (1) (2) (3)	If a sound amplification system is installed / inbuilt is there a hearing augmentation system that covers 80% of the total enclosed space if an induction loop is inbuilt, or 95% if a receiver system in use.	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.02	APS – D3.7 (1) (2) (3)	Is hearing augmentation available at any screened / enclosed reception area / ticket or tellers cash booth (that has an inbuilt amplification system).	Screened Booth				NA	
09.02	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl 5.2.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Signage	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.03	APS – D3.6 (b) (ii) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, indicate which type of system is in place.	Signage	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.04	APS D3.6 (b) (iii)	If receivers are being used, does the signage indicate where the receivers can be obtained.	Signage	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.05	APS – D3.7 (4)	If a screen or scoreboard is capable of displaying public announcements, is it capable of supplementing any public address system (other than a system used for emergency warning purposes only).	Signage	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.06	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl 5.2.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Signage	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
Universal Accessibility Options: not mandatory								
09.07	AS 1428.5 - 3	Is hearing augmentation available in meeting rooms (seating 5 or more participants).	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.08	AS 1428.5 - 3	Is hearing augmentation available in any lift to assist with communication in an emergency.	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.09		Is appropriate seating with backs and armrests available that provides good lines of sight for lip reading.	Seating lines of sight	TBA				Tiered seating not defined at 60% Review
09.10		Are there acoustic design elements to reduce noise e.g. rubber tips on furniture legs, soft furnishings, low pile carpet, double glazing, quiet equipment etc.	Acoustic Design Elements	TBA				Finishes not defined at 60% Review
09.11	AS 1428.5 - 3	Are there visible alarms at any security checkpoint.	Alarms	TBA				Security not defined at 60% Review
09.12		Are there visible emergency alarms throughout the building.	Alarms	TBA				Security not defined at 60% Review
09.13		Is there effective lighting for lip reading and sign language interpreters.	Lighting	TBA				Luminance not defined at 60% Review

ROK019 10.00 Contrasts								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
10.01	AS 1428.1 Cl. 10.1	Doorways / frames / walls etc	Door Contrast	TBA				Finishes not defined at 60% Review
10.02	AS 1428.1 Cl. 3.6	Glass doors (solid, non-transparent contrasting strip across full width of glass and side partitions)	Glass Doors	TBA				Door Material not defined at 60% Review
10.03	APS – D3.8 1 (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Ramps (TGSIs at top and bottom - as required)	Ramp TGSI	TBA				TGSI detail not defined at 60% Review
10.04	APS – D4.5	Signs	Signage	TBA				Signage not defined at 60% Review
10.05	APS – D3.8 1 (a) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Stairs (TGSIs at top and bottom – as required)	Stair TGSI	TBA				Stair detail not defined at 60% Review
10.06	AS 1428.1 Cl. 8.1 (f) (g)	Stair nosing strips	Stair Detailing	TBA				Stair detail not defined at 60% Review
10.07	AS 1428.1 – 2021 Cl. 12.2.3 (e)	Toilet seats and cisterns	Sanitary Ware	TBA				Sanitary ware not defined at 60% Review

ROK019 11.00 Floor / Ground Surfaces								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
11.01	AS 1428.1 Cl. 4.1	Is the ground / floor surface firm and level (e.g. with no sharp transitions at abutting surfaces).	Firm Level Surface	TBA				Floor Finishes not defined at 60% Review
11.02	AS 1428.1 Cl. 4.1	Is the floor / ground surface slip resistant (in wet and dry conditions) allowing traction for a person using a wheelchair and people with ambulant or sensory disability.	Slip Resistant	TBA				Floor Finishes not defined at 60% Review
11.03	AS 1428.1 Cl 4.3	If carpeted, is it short pile (<11mm and backing <4mm) and securely attached to the floor surface.	Carpet	TBA				Floor Finishes Specification not defined at 60% Review
11.04	AS 1428.1 Cl 4.5	If timber decking boards are installed and are no greater than 150mm wide, is there a maximum 6mm gap between boards.	Timber Decking	TBA				Floor Finishes not defined at 60% Review
11.05	AS 1428.1 Cl 4.5	If timber decking boards are installed that are over 150mm wide, is there a maximum gap of 10mm between boards, and if the gap is over 8mm do the boards run transverse to the direction of travel	Timber Decking	TBA				
11.06	AS 1428.1 Cl 4.5	If timber decking boards are installed, are adjacent boards level with a maximum vertical 3mm tolerance	Timber Decking	TBA				Floor Finishes not defined at 60% Review
Universal Accessibility Options: not mandatory								
11.07		Does the floor / ground surface have effective contrasts to walls and doors / doorframes	Contrast					Floor and Wall Finishes not defined at 60% Review.

ROK019 12.00 Emergency Egress / Evacuation								
Number	Standard	Item	Item	Y	Y	N	NA	Action
Universal Accessibility Options: not mandatory								
12.01		Is there an accessible (e.g. appropriate door handle, clear door opening width, opening force) emergency exit in addition to the main entry	Accessible Emergency Exit	TBA				Emergency Door Material, Hardware, Width etc not defined at 60% Review
12.02		Is there clear, visible, accessible signage on emergency exits	Signage for Exit	TBA				Signage not defined at 60% Review
12.03		Is there a continuous accessible path of travel from the building to any nominated assembly area (e.g. firm path, no steps, stairs, well lit)	CAPT to Assemeby	TBA				Emergency Alarms not defined at 60% Review
12.04		Are audible emergency alarms provided in the building	Alarms	TBA				Emergency Alarms not defined at 60% Review
12.05		Are visible emergency alarms provided in the building	Alarms	TBA				Refuge place not defined at 60% Review
12.06		Are there places of refuge provided for people with mobility difficulties on levels above the main entrance level	Refuge on Level 1	TBA				Refuge place not defined at 60% Review
12.07		Are audible security alarms provided at any security checkpoints	Alarms	TBA				Security Alarms not defined at 60% Review
12.08		Are visible security alarms provided at any security checkpoints	Alarms	TBA				Security Alarms not defined at 60% Review
12.09		Are any fire hoses and extinguishers located at 700 – 1200mm high	Fire Extinguishers	TBA				Fire Strategy not defined at 60% Review
12.10		Is the emergency management plan located at an accessible height in a public area in an accessible format (e.g. large print, tactile, Braille)	Emergency Management Plan	TBA				Emergency Management Plan not defined at 60% Review
12.11		Is there an accessible (e.g. appropriate door handle, clear door opening width, opening force) emergency exit in addition to the main entry	Emergency Exit	TBA				Emergency Exit not defined at 60% Review
12.12		Is there clear, visible, accessible signage on emergency exits	Accessible Emergency Exit Signage	TBA				Emergency Exit not defined at 60% Review

ROK019 17.00 Stairs								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
17.01	APS – 3.3 (f) 4.4 / D3.1 / D3.2 / D3.3 / E3.6	Is there an accessible alternative route close to the stairs (e.g. ramp, lift) (where required – see Concessions in Premises Standards)	Accessible Alternative Route close to stairs			N		There is no accessible route close to the stairs on North West Corner.
17.02	AS 1428.1 Cl. 8.1 (a) (b) / 9	If the stairs abut an internal corridor / external boundary, are they setback to allow a min. of one tread width plus 300mm internally / min. 900mm externally	Setback		Y			There is no indication that setback is not designed at 60% Review.
17.03	APS – D3.8 1 (a) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Are there appropriate TGSIs (hazard – extending the width of path, luminance, depth) at the top and bottom of the stairs.	TGSI	TBA				TGSIs are not defined at 60% Review
17.04	AS 1428.1 Cl. 11 / AS 1428.4.1 Cl. 2.3 / 2.4	If a non enclosed landing is provided on the stairs, are TGSIs installed as required.	TGSI	TBA				TGSIs are not defined at 60% Review
17.05	AS 1428.4.1 – Cl. 2.4	If the distance of the landing is 3000mm or more to the nearest nosing edge, are the warning indicators spread over a distance of 600 – 800mm.	TGSI	TBA				TGSIs are not defined at 60% Review
17.06	AS 1428.1 Cl. 4.1	Do the stairs have a slip resistant surface.	Slip Resistance	TBA				Finishes are not defined at 60% Review
17.07	AS 1428.1 Cl. 8.1 (c)	Are all of the step risers enclosed and of opaque construction.	Step Risers	TBA				Step Risers material not defined at 60% Review
17.08	AS 1428.1 Cl. 8.1 (f) (g)	Do front edges of stairs nosing have a single strip of continuous colour not less than 50mm and not more than 75mm with a min. 30% luminance contrast (full width of path of travel) (can be set back 15mm) (must not project beyond the face of the riser and not extend more than 10mm down the riser when provided with a contrast and not set back from nosing).	Nosing Strips	TBA				Nosing Strips not defined at 60% Review
17.09	AS 1428.1 Cl. 11.1 (d)	Are the stair nosings level with the face of the riser (riser may be vertical or max. splay backward up to 25mm)	Nosing Strips	TBA				Nosing Strips not defined at 60% Review
17.10	AS 1428.1 Cl. 8.1 (e)	Are the profile of the nosings provided with a sharp transition; rounded up to 5mm radius or chamfered up to 5mm x 5mm.	Nosing	TBA				Profile of Nosing not defined at 60% Review
17.11	APS – D3.8 (3) / 1428.4.1 Cl. 2.2 / 2.3 / 2.4	On a continuous flight of stairs (within an aged care facility), is there a domed button 4 - 5mm high x 10 - 12mm diameter if handrails are not continuous on stair flights and around landings. (on top 150mm from end of rail),					NA	Not an Aged Care Facility
17.12	AS 1428.1 Cl. 8.2	Are appropriate handrails provided on two sides of the stairs (Note: if a balustrade is required at a height greater than the handrail, both shall be provided).	Handrail	TBA				Handrails not defined at 60% Review
17.13	AS 1428.1 Cl. 8.2 / 9 (j)	Are handrails continuous throughout the stair flight, and where practicable on landings.	Handrail	TBA				Handrails not defined at 60% Review
17.14	AS 1428.1 Cl. 8.2 (d) (e) (f)	Do the handrails extend at least one tread width plus 300mm past the edge of the bottom step, and a min of 300mm at the top step (Note: refer AS requirement at intermediate landings).	Handrail	TBA				Handrails not defined at 60% Review
17.15	AS 1428.1 Cl. 8 / 9 (h) (i)	Do the handrails have a min. clearance of 50mm from an adjacent wall and min. 600mm clearance above.	Handrail	TBA				Handrails not defined at 60% Review
17.16	AS 1428.1 Cl. 8 / 9 (i)	Are handrails constructed and fixed, ensuring no obstruction to the passage of the hand along the entire handrail.	Handrail	TBA				Handrails not defined at 60% Review
17.17	AS 1428.1 Cl. 9 (d) (e)	Is the handrail height consistent at a measurement between 865 – 1000mm above the stair nosing (throughout the stairs and on any landing) Construction tolerance of 10mm allowable and Height of handrail may vary at stairway handrail extension or where handrail transitions between flights or to a balustrade).	Handrail	TBA				Handrails not defined at 60% Review
17.18	AS 1428.1 Cl. 9 (b)	Do the handrails have a circular diameter of 30 – 52mm for a min. of 270°.	Handrail	TBA				Handrails not defined at 60% Review
17.19	AS 1428.1 Cl. 8.2 (c)	Do the handrails follow the angle of the nosings.	Handrail	TBA				Handrails not defined at 60% Review
17.20	AS 1428.1 Cl. 9 (c)	Are exposed edges and corners of handrails provided with a radius of not less than 5mm.	Handrail	TBA				Handrails not defined at 60% Review
17.21	AS 1428.1 Cl. 8. 2 (b)	Is there a min. clearance of 1000mm between handrails.	Handrail	TBA				Handrails not defined at 60% Review
17.22	AS 1428.1 Cl. 9 (g)	Are the handrails securely fixed, with ends returned to a side wall / post or turned through 180°.	Handrail	TBA				Handrails not defined at 60% Review
17.23	AS 1428.1 Cl. 9 (a)	Do the handrails (and balustrades) sit outside of required circulation spaces.	Handrail	TBA				Handrails not defined at 60% Review
Universal Accessibility Options: not mandatory								
17.24		Are the tread heights between 150 – 165mm high AS 1428.2 – Cl. 13.2	Tread Heights	TBA				Tread Heights not defined at 60% Review
17.25		Are the treads a min. of 275 – 300mm deep AS 1428.2 – Cl. 13.2	Tread depth	TBA				Tread Depths not defined at 60% Review
17.26		Is there appropriate, uniform lighting of the stairs for night time use	Lighting	TBA				Lighting not defined at 60% Review
17.27		Are the handrails of non-reflective material and a contrasting colour to the background	Handrail Materials	TBA				Handrails not defined at 60% Review

ROK019 18.00 Tactile Ground Surface Indicators								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
18.01	AS 1428.4.1 Cl. 2.5	Are there appropriate hazard tactile ground surface indicators (TGSIs) prior to a hazard (e.g. roadway) i.e. (width x 600 – 800mm, setback 300mm ± 10mm).	Appropriate TGSi	TBA				TGSIs not defined at 60% Review
18.02	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3 / 2.5	Are appropriately installed TGSIs provided at existing defined pedestrian crossing point/s with a level transition over a vehicular traffic way on the pathway(width x 600 – 800mm setback 300mm ± 10mm).	Pedestrian Crossing TGSi				NA	
18.03	AS 1428.4.1 Cl. 2.2 / 2.3 / 2.5	Are appropriate installed TGSIs provided at existing defined vehicle drop off areas, with blended kerbs and a level transition, if provided on the pathway (width x 600 – 800mm setback 300mm ± 10mm).	Vehicle dropoff TGSi				NA	
18.04	APS – D3.8 1 (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Are there appropriate TGSIs (hazard – extending the width of path, luminance, depth) at the top and bottom of a ramp (as required).	Ramp TGSi	TBA				TGSIs not defined at 60% Review
18.06	AS 1428.1 Cl. 11 / AS 1428.4.1 Cl. 2.3 / 2.4	If a non enclosed landing is provided on the stairs, are TGSIs installed as appropriate.	Non-enclosed landing TGSi	TBA				TGSIs not defined at 60% Review
18.07	AS 1428.4.1 Cl. 2.4	If the distance of the landing is 3000mm or more to the nearest nosing edge, are the warning indicators spread over a distance of 600 – 800mm.	Landing TGSi	TBA				TGSIs not defined at 60% Review
18.08	APS – D3.8 / AS 1428.4.1 Cl. 2.6	If there is an overhead obstruction less than 2000mm (other than a doorway) are appropriate TGSIs installed (in the absence of any other barrier) (e.g. undercroft of stairs) (NOTE: an alternative type of barrier is preferred).	Overhead Obstruction TGSi	TBA				No Overhead Obstructions identified at 60% Review
18.09	AS 1428.4.1 Cl. 2.3.3 (b)	Are the warning indicators installed at right angles to path of travel on pathways.	Warning Indicators	TBA				Warning Indicators not defined at 60% Review
18.10	AS 1428.4.1 Cl. 2.3.3 (c) / 3.4 / 3.5	Are there warning indicators installed along edges of hazardous areas e.g. train platforms, wharves, level roadway crossing points etc.	Warning Indicators	TBA				Warning Indicators not defined at 60% Review
18.11	AS 1428.4.1 Cl. 2.2 / App. E	Are TGSIs installed with appropriate contrasts to background surfaces.	TGSi Contrast	TBA				TGSIs not defined at 60% Review
18.12	AS 1428.4.1 Cl. 2.3	Are the TGSIs installed to ensure no tripping hazard is produced.	No Tripping Hazards	TBA				TGSIs not defined at 60% Review
Universal Accessibility Options: not mandatory								
18.13	AS 1428.4.1 Cl. 3.1 (c) (i)	Are there appropriate directional TGSIs on any pathway adjacent where a kerb ramp is at a mid block section or not on a direct path of travel.	Directional TGSi				NA	ROK019 does not include external works.
18.14	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3	Are TGSIs provided at changes in direction on the pathway to the PPE.	Directional TGSi				NA	ROK019 does not include external works.
18.15	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3	Are warning TGSIs (hazard) provided at changes in direction of directional indicators on the pathway to the PPE.	Warning TGSi				NA	ROK019 does not include external works.
18.16		Are there any appropriate TGSIs (hazard) indicators prior to the existing kerb ramps on the pathway (width x 600 – 800mm, setback 300mm ± 10mm).	Kerb Ramps				NA	ROK019 does not include external works.
18.17	AS 1428.4.1 App. D	Are there directional indicators installed to provide direction to elements e.g. bus stops, kerb ramps, street furniture, toilets, train platforms, road crossings etc.	External Kerb Ramps				NA	ROK019 does not include external works.
18.18	AS 1428.4.1 App. A 3.1	Are TGSIs used with consistent application throughout an area.	TGSi	TBA				Existing Condition of TGSi not indicated at 60% Review
18.19		Are the TGSIs well maintained.	TGSi	TBA				Existing Condition of TGSi not indicated at 60% Review
18.20		Are the TGSIs used to promote pedestrian safety.	TGSi	TBA				Existing Condition of TGSi not indicated at 60% Review

ROK019 20.00 Signage								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
20.01	APS – DP1 (b) / AS 1428.1 CL 5.1	Is appropriate signage available where directional decisions are made.	Directional Signage	TBA				Signage not defined at 60% Review
20.02	APS – D3.6 (e) / D4 / AS 1428.1 Cl. 5.1	If there is a non accessible entrance doorway, is there appropriate signage provided directing users to accessible entrance.	Non-Accessible Access Signage	TBA				Signage not defined at 60% Review
20.03	APS – D3.6 / D4 / AS 1428.1 Cl. 5.2	Where the symbol for access is used, does it comply with the international standard in style, colour and layout.	Symbol for Access	TBA				Signage not defined at 60% Review
20.04	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Symbol for Deafness	TBA				Signage not defined at 60% Review
20.05	APS – D3.6 (b) (ii) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2	Does signage including the international symbol of deafness, indicate which type of system is in place.	Symbol for Deafness	TBA				Signage not defined at 60% Review
20.06	APS D3.6 (b) (iii)	If receivers are being used for hearing augmentation, does the signage indicate where the receivers can be obtained.	Hearing Augmentation Signage	TBA				Signage not defined at 60% Review
20.07	APS – D3.6 (b) / D4 / AS 1428.1 CL 5.1	Is raised tactile information provided on signs between 1200 – 1600mm.	Signage Raised Text	TBA				Signage not defined at 60% Review
20.08	APS – D4.5	Is there appropriate illumination of signage for day and night use (where required e.g. to maintain luminance).	Illumination	TBA				Signage not defined at 60% Review
20.09	APS – D3.6 (f) / D4	If there is a non-accessible toilet provided, is there signage available that directs users to an accessible toilet (where in different locations).	Signage to Accessible toilet at non-accessible toilet	TBA				Signage not defined at 60% Review
20.10	APS – D3.6 (c) / D4 / AS 1428.1 Cl 5.1	Does the signage indicate if the accessible toilet facility is suitable for left or right hand.	L or R Hand Accessible Facility	TBA				Signage not defined at 60% Review
20.11	APS – D4.3 (2); Title Case AS 1428.1 C 5.1	If available on the sign, is the text provided in Title Case.	Signage - Title Case	TBA				Signage not defined at 60% Review
20.12	APS-D3.6 (a) / AS 1428.1 Cl 5.1	Is there signage (incorporating raised text and Braille, and raised and visual symbols) installed identifying available sanitary facilities.	Signage to All Toilets	TBA				Signage not defined at 60% Review
20.13	APS – D3.6 (d) / AS 1428.1 Cl. 5.1	If there is an ambulant toilet, is appropriate signage installed at the airlock serving the area that contains the facilities identifying the facilities within.	Signage Ambulant Toilet	TBA				Signage not defined at 60% Review
20.14	APS – D3.6 (d) / AS 1428.1 Cl. 5.1	If there is an ambulant toilet, is there signage to identify the facility (Note: may be located on door if required).	Signage Ambulant Toilet	TBA				Signage not defined at 60% Review
Universal Accessibility Options: not mandatory								
20.15		Is signage (including tactile and Braille) located at the main building entry, both inside and out, giving directional and general information about buildings and facilities including services and access for people with disabilities.	Main Entry Signage	TBA				Signage not defined at 60% Review

ROK032		01.00 Entrances						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
1.01	APS – D3.2 (2) (a)	If there is more than one pedestrian entrance, are 50% of them accessible (including the principal pedestrian entrance)	Entrance	TBA				Need to determine existing conditions for accessibility in ROK-032
1.02	APS – D3.2 (2) (b)	If the building is more than 500m² is any non accessible entry within 50m from an accessible entry.	Accessible Entry within 50m of Non-Accessible Entry	TBA				Need to determine existing conditions for accessibility in ROK-032
1.03	APS – D3.6 (e) Cl. 5.1	If there is a non accessible entrance doorway, is there appropriate signage provided (int. Symbol, direction arrow) directing users to an accessible entrance.	Non-Accessible Door Signage	TBA				Need to determine existing conditions for accessibility in ROK-032
1.04	APS – D3.2 (3) (a) (4) fig D3.2	If the pedestrian entrance is required to be accessible and consists of not more than 3 doorways, is not less than one doorway accessible.	Less than 3 doorways	TBA				Need to determine existing conditions for accessibility in ROK-032
1.05	AS 1428.1 Cl. 10.4.3 / AS 1428.2 Cl. 28	If there are security entry controls (card / buttons / intercom) are these at 900 – 1100mm-grasped/turned, 900-1200mm-pushed, 900-1250mm (not less than 500mm from corner)-touched, (ticket slot 800 – 900mm), and easy to operate.	Security door controls	TBA				Need to determine existing conditions for accessibility in ROK-032
1.06	APS - A1.1	If there is a revolving door / turnstile, is there an alternative accessible hinged / sliding door	Revolving Door	TBA				Need to determine existing conditions for accessibility in ROK-032
1.07	AS 1428.1 Cl. 10.4.2	Can the door be unlocked and opened by one hand (i.e. D or D lever handles).	Door Handle	TBA				Need to determine existing conditions for accessibility in ROK-032
1.08	AS 1428.1 Cl. 10.4.2 (b)	Is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handle	TBA				Need to determine existing conditions for accessibility in ROK-032
1.09	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles, snibs, locks) that need to be grasped or turned located between 900 – 1100mm high.	Door Controls	TBA				Need to determine existing conditions for accessibility in ROK-032
1.10	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed located between 900 – 1200mm high.	Door Controls	TBA				Need to determine existing conditions for accessibility in ROK-032
1.11	AS 1735.12 AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched located between 900 – 1250mm high and not less than 500mm from an internal corner except as specified in AS 1735.12 AS 1428.1 Cl. 10.4.3 (c)	Door Controls	TBA				Need to determine existing conditions for accessibility in ROK-032
1.12	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handle	TBA				Need to determine existing conditions for accessibility in ROK-032
1.13	AS 1428.1 Cl. 10.4.2 (f)	If an outward opening door is not self closing, is there a horizontal handrail or pull bar installed at a height between 900 – 1100mm (min. 50mm clearance from edge of door / door handle) on the inside of the door.	Door Handle	TBA				Need to determine existing conditions for accessibility in ROK-032
1.14	AS 1428.1 Cl. 10.4.4	If doors are power operated, are the push button controls a min. of 25mm dia., proud of the surface (activating door before the button becomes level with surrounding surface).	Power operated door	TBA				Need to determine existing conditions for accessibility in ROK-032
1.15	AS 1428.1 Cl. 10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 500 – 1000mm from arch of the hinged door leaf (in any position) / or clear of a surface-mounted sliding door in the open position.	Power operated door	TBA				Need to determine existing conditions for accessibility in ROK-032
1.16	AS 1428.1 Cl. 3.6	If the doors / sidelights are frameless or fully glazed, are they clearly marked for safety and ease of identification across the full door width, with a solid and non-transparent contrasting line (viewable from 2m inside and outside) (luminance 30%). Size of line not less than 75mm high, with the lower edge at a height of 900 – 1000mm above finished floor level.	Door Material	TBA				Need to determine existing conditions for accessibility in ROK-032
1.17	AS 1428.1 Cl. 10.1	Do all the doors or doorframes have a min. luminance contrast of 30% to their adjacent surfaces.	Door Frame Contrast	TBA				Need to determine existing conditions for accessibility in ROK-032
1.18	AS 1428.1 Cl. 10.4.2 (e)	Is the entrance door easy, to initially open, (no heavy closer or spring) 20N max. (4.3lbf)	Door Pressure	TBA				Need to determine existing conditions for accessibility in ROK-032
1.19	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	Is the min. clear opening of a doorway at the PPE 850mm or greater.	Min clear opening	TBA				Need to determine existing conditions for accessibility in ROK-032
1.20	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	If the doorway has 2 independent operated leaves, is the open doorway a min. of 850mm wide.	2 leaves	TBA				Need to determine existing conditions for accessibility in ROK-032
1.21	AS 1428.1 Cl. 7.5 / 7.5	Is the door threshold level or is there an appropriate threshold ramp available at the entry (i.e. no step, inappropriate mat, weather strip etc.)	Door Threshold	TBA				Need to determine existing conditions for accessibility in ROK-032
1.22	AS 1428.1 Cl. 7.5	If there is a threshold (max. rise 35mm) at the entrance or doorway (not more than 20mm from door leaf it serves), is there a ramp of not more than 280mm in length and min. ratio of 1:8. (Note: if the rise is greater a step ramp will be required).	Door Threshold	TBA				Need to determine existing conditions for accessibility in ROK-032
1.23	AS 1428.1 Cl. 7.5	If the threshold ramp does not abut a wall or kerb, are sides tapered or splayed (min. 45°)	Door Threshold	TBA				Need to determine existing conditions for accessibility in ROK-032
1.24	AS 1428.1 Cl. 4.2	If there is a recessed mat within the CAPT is the abutment of the surfaces no more than 3mm if vertical or 5mm if bevelled (rounded).	Door Threshold	TBA				Need to determine existing conditions for accessibility in ROK-032
1.25	AS 1428.1 Cl. 4.3.1	If there is a carpet leading edge at the entrance is there a vertical face no higher than 3mm or a rounded bevelled edge no higher than 5mm or above that height a gradient of 1:8 up to a total max. height of 10mm.	Carpet	TBA				Need to determine existing conditions for accessibility in ROK-032
1.26	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space outside the entrance doorway (not steeper that 1:40) (Doorway circulations spaces may overlap other circulation spaces).	Circulation Space outside	TBA				Need to determine existing conditions for accessibility in ROK-032
1.27	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space inside the entrance doorway (not steeper that 1:40) (Doorway circulations spaces may overlap other circulation spaces).	Circulation Space inside	TBA				Need to determine existing conditions for accessibility in ROK-032

ROK032		01.00 Entrances						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
1.28	AS 1428.1 Cl. 10.3.5	If there is an airlock, vestibule, or enclosed space, is there not less than 1450mm between the doorway (plus the door leaf width if the door encroaches into the space).	Airlock	TBA				Need to determine existing conditions for accessibility in ROK-032
1.29	AS 1428.1 Cl. 3.7	If there are glazed viewing panels in doors, is the lower edge of the glazing not more than 1000mm above FFL, upper edge not less than 1600mm above FFL.	Glazed Viewing Panels	TBA				Need to determine existing conditions for accessibility in ROK-032
1.30	AS 1428.1 Cl 3.7	If there are glazed viewing panels in doors, is the width of the glazing within 200mm from latch edge of the door and min 150mm wide.	Glazed Viewing Panels	TBA				Need to determine existing conditions for accessibility in ROK-032
Universal Accessibility Options: not mandatory								
1.37	AS 1428.2 Cl. 23.3 (b)	Are the door handles provided with an appropriate luminance contrast	Door Handles	TBA				Door hardware not defined at 60% Review
1.38		Do automatic self-opening doors have effective motion, and presence sensors installed	Automatic Doors	TBA				Door Control not defined at 60% Review
1.39		If there is an alarm control pad, is it located at a height between 900 – 1200mm high, accessible and easy to operate	Door Control	TBA				Door hardware not defined at 60% Review
1.40		If there is a doorbell, is it accessible and easy to operate, located at a height between 900 – 1200mm	Doorbell	TBA				Door hardware not defined at 60% Review
1.41		Is there appropriate lighting at the PPE	Lighting	TBA				Lighting not defined at 60% Review

ROK032		03.00 Internal Accessways						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
3.01	AS 1428.1 Cl. 3.3	Does the accessway have a min. width of 1000mm i.e. structurally and maintained to remain clear of temporary obstructions e.g. pot plants, bins.	Min Width	TBA				Need to determine existing conditions for accessibility in ROK-032
3.02	AS 1428.1 Cl. 3.2	Does the full length of the accessway have an overhead clearance of 2000mm (1980mm allowed at doorway)	Overhead Clearance	TBA				Need to determine existing conditions for accessibility in ROK-032
3.03	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.4	Do accessways provide a passing space where a direct line of sight is not available to the end of the walkway (max. 20m intervals) (min. 1800mm wide x 2000mm long)	Turn Circle	TBA				Need to determine existing conditions for accessibility in ROK-032
3.04	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.5	Do accessways provide a turning space near the end of the walkway where it is not possible to continue (within 2m of end)	Turn Circle	TBA				Need to determine existing conditions for accessibility in ROK-032
3.05	AS 1428.1 Cl. 3.5	If a change of direction is required, is there appropriate circulation space provided along the accessway for the angle of the turn.	Circulation	TBA				Need to determine existing conditions for accessibility in ROK-032
3.06	AS 1428.1 Cl. 4.1	Does the accessway have a slip-resistant surface with a texture that is traversable by a wheelchair.	Slip Resistant	TBA				Need to determine existing conditions for accessibility in ROK-032
3.07	APS – D3.6 (e) AS 1428.1 CL 5	If there is a non-accessible entrance doorway, is there appropriate signage provided (int. Symbol, direction arrow) directing users to an accessible entrance	Signage	TBA				Need to determine existing conditions for accessibility in ROK-032
3.08	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	Is the min. clear opening of a doorway on any accessway 850mm or greater.	Min Clear open	TBA				Need to determine existing conditions for accessibility in ROK-032
3.09	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space outside the doorway (NOTE: 1:40 grade, additional considerations at surface mounted sliding doors) (Doorway circulation space may overlap other circulation spaces)	Circulation	TBA				Need to determine existing conditions for accessibility in ROK-032
3.10	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space inside the doorway (NOTE: 1:40 grade, additional considerations at surface mounted sliding doors) (Doorway circulation space may overlap other circulation spaces)	Circulation	TBA				Need to determine existing conditions for accessibility in ROK-032
3.11	AS 1428.1 Cl. 10.4.2 (a)	Can the door be unlocked and opened by one hand (i.e. D or D lever handles)	Door Handles	TBA				Need to determine existing conditions for accessibility in ROK-032
3.12	AS 1428.1 Cl. 10.4.2 (b)	Is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handles	TBA				Need to determine existing conditions for accessibility in ROK-032
3.13	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles) that need to be grasped or turned between 900 – 1100mm high.	Door Handles	TBA				Need to determine existing conditions for accessibility in ROK-032
3.14	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed between 900 – 1200mm high.	Door Handles	TBA				Need to determine existing conditions for accessibility in ROK-032
3.15	AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched between 900 – 1250mm high (and not less than 500mm from an internal corner, except as specified in AS 1735.12)	Door Handles	TBA				Need to determine existing conditions for accessibility in ROK-032
3.16	AS 1428.1 Cl.10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 1000 – 2000mm from the hinged swing door leaf (in any position) / or doorway of sliding door.	Power Door	TBA				Need to determine existing conditions for accessibility in ROK-032
3.17	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handles	TBA				Need to determine existing conditions for accessibility in ROK-032
3.18	AS 1428.1 Cl. 10.4.2 (e)	Are all doors (other than fire / smoke doors) provided with the appropriate opening force (20N).	Door Force	TBA				Need to determine existing conditions for accessibility in ROK-032
3.19	AS 1428.1 Cl. 10.3.5	If there is an airlock, vestibule, or enclosed space, is there not less than 1450mm between the doorway (plus the door leaf width if the door encroaches into the space).	Air Vestibule	TBA				Need to determine existing conditions for accessibility in ROK-032
3.20	AS 1428.1 Cl. 10.4.2 (g)	If an outward opening door is not self closing, is there a horizontal handrail or pull bar installed at a height between 900 – 1100mm (min. 50mm clearance from edge of door / door handle) on the inside of the door.	Hoor Handles	TBA				Need to determine existing conditions for accessibility in ROK-032
3.21	AS 1428.1 Cl 11.1	Are all switches and controls provided on a CAPT (other than general purpose outlets (GPOs)) located at a height of 900 – 1100mm and not less than 500mm from an internal corner.	Switches and Controls	TBA				Need to determine existing conditions for accessibility in ROK-032

ROK032		10.00 Contrasts						
Number	Standard	Item	Item	Y	Y	N	NA	Action
Mandatory Items								
10.01	AS 1428.1 Cl. 10.1	Doorways / frames / walls etc	Door Contrast	TBA				Finishes not defined at 60% Review
10.02	AS 1428.1 Cl. 3.6	Glass doors (solid, non-transparent contrasting strip across full width of glass and side partitions)	Glass Doors	TBA				Door Material not defined at 60% Review
10.03	APS – D3.8 1 (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Ramps (TGSIs at top and bottom - as required)	Ramp TGSI	TBA				TGSI detail not defined at 60% Review
10.04	APS – D4.5	Signs	Signage	TBA				Signage not defined at 60% Review
10.05	APS – D3.8 1 (a) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Stairs (TGSIs at top and bottom – as required)	Stair TGSI	TBA				Stair detail not defined at 60% Review
10.06	AS 1428.1 Cl. 8.1 (f) (g)	Stair nosing strips	Stair Detailing	TBA				Stair detail not defined at 60% Review
10.07	AS 1428.1 – 2021 Cl. 12.2.3 (e)	Toilet seats and cisterns	Sanitary Ware	TBA				Sanitary ware not defined at 60% Review

ROK032		11.00 Floor / Ground Surfaces						
Number	Standard	Item	Item	Y	Y	N	NA	Action
Mandatory Items								
11.01	AS 1428.1 Cl. 4.1	Is the ground / floor surface firm and level (e.g. with no sharp transitions at abutting surfaces).	Firm Level Surface	TBA				Floor Finishes not defined at 60% Review
11.02	AS 1428.1 Cl. 4.1	Is the floor / ground surface slip resistant (in wet and dry conditions) allowing traction for a person using a wheelchair and people with ambulant or sensory disability.	Slip Resistant	TBA				Floor Finishes not defined at 60% Review
11.03	AS 1428.1 Cl 4.3	If carpeted, is it short pile (<11mm and backing <4mm) and securely attached to the floor surface.	Carpet	TBA				Floor Finishes not defined at 60% Review
11.04	AS 1428.1 Cl 4.5	If timber decking boards are installed and are no greater than 150mm wide, is there a maximum 6mm gap between boards.	Timber Decking	TBA				Floor Finishes not defined at 60% Review
11.05	AS 1428.1 Cl 4.5	If timber decking boards are installed that are over 150mm wide, is there a maximum gap of 10mm between boards, and if the gap is over 8mm do the boards run transverse to the direction of travel	Timber Decking	TBA				Floor Finishes not defined at 60% Review
11.06	AS 1428.1 Cl 4.5	If timber decking boards are installed, are adjacent boards level with a maximum vertical 3mm tolerance	Timber Decking	TBA				Floor Finishes not defined at 60% Review
Universal Accessibility Options: not mandatory								
11.07		Does the floor / ground surface have effective contrasts to walls and doors / doorframes	Contrast					Floor and Wall Finishes not defined at 60% Review.

ROK032		12.00 Emergency Egress / Evacuation						
Number	Standard	Item	Item	Y	Y	N	NA	Action
Universal Accessibility Options: not mandatory								
12.01		Is there an accessible (e.g. appropriate door handle, clear door opening width, opening force) emergency exit in addition to the main entry	Accessible Emergency Exit	TBA				Emergency Door Material, Hardware, Width etc not defined at 60% Review
12.02		Is there clear, visible, accessible signage on emergency exits	Signage for Exit	TBA				Signage not defined at 60% Review
12.03		Is there a continuous accessible path of travel from the building to any nominated assembly area (e.g. firm path, no steps, stairs, well lit)	CAPT to Assemeby	TBA				Emergency Alarms not defined at 60% Review
12.04		Are audible emergency alarms provided in the building	Alarms	TBA				Emergency Alarms not defined at 60% Review
12.05		Are visible emergency alarms provided in the building	Alarms	TBA				Refuge place not defined at 60% Review
12.06		Are there places of refuge provided for people with mobility difficulties on levels above the main entrance level	Refuge on Level 1	TBA				Refuge place not defined at 60% Review
12.07		Are audible security alarms provided at any security checkpoints	Alarms	TBA				Security Alarms not defined at 60% Review
12.08		Are visible security alarms provided at any security checkpoints	Alarms	TBA				Security Alarms not defined at 60% Review
12.09		Are any fire hoses and extinguishers located at 700 – 1200mm high	Fire Extinguishers	TBA				Fire Strategy not defined at 60% Review
12.10		Is the emergency management plan located at an accessible height in a public area in an accessible format (e.g. large print, tactile, Braille)	Emergency Management Plan	TBA				Emergency Management Plan not defined at 60% Review
12.11		Is there an accessible (e.g. appropriate door handle, clear door opening width, opening force) emergency exit in addition to the main entry	Emergency Exit	TBA				Emergency Exit not defined at 60% Review
12.12		Is there clear, visible, accessible signage on emergency exits	Accessible Emergency Exit Signage	TBA				Emergency Exit not defined at 60% Review

ROK032 16.00 Pathways (Accessways)								
Number	Standard	Item	Item	tba	Y	N	NA	Action
Mandatory Items								
16.01	APS - D3.2	Does an accessible pathway lead users from the designated accessible parking bay to the building entrance.	Accessible Pathway	TBA				Need to determine existing conditions for accessibility in ROK-032
16.02	APS - D3.2	Does an accessible pathway lead users from the allotment boundary to the building entrance.	Accessible Pathway	TBA				Need to determine existing conditions for accessibility in ROK-032
16.03	APS - D3.2	Does an accessible pathway lead users from any adjoining building required to be accessible (if linked by a pedestrian pathway).	Accessible Pathway	TBA				Need to determine existing conditions for accessibility in ROK-032
16.04	AS 1428.1 Cl. 4.2	If there is an abutment of surfaces on the pathway, are they no greater than 3mm if the abutment is vertical, or 5mm if a bevelled edge.	Accessible Pathway	TBA				Need to determine existing conditions for accessibility in ROK-032
16.05	AS 1428.1 Cl. 4.2 Figure 7(A)	If raked joint pavers are used, is the abutment of surfaces appropriate.	Pavers	TBA				Need to determine existing conditions for accessibility in ROK-032
16.06	AS 1428.1 Cl. 3.3	Are all accessways a min. width of 1000mm.	Accessway 1000mm	TBA				Need to determine existing conditions for accessibility in ROK-032
16.07	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.4	Do accessways provide a passing space where a direct line of sight is not available to the end of the walkway (max. 20m intervals) (min. 1800mm wide x 2000mm long).	Passing Space	TBA				Need to determine existing conditions for accessibility in ROK-032
16.08	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.5	Do accessways provide a turning space near the end of the walkway where it is not possible to continue (within 2m of end).	Turning Space	TBA				Need to determine existing conditions for accessibility in ROK-032
16.09	AS 1428.1 Cl. 3.5	If a change of direction is required, is there appropriate circulation space provided along the accessway for the angle of the turn.	Circulation Space	TBA				Need to determine existing conditions for accessibility in ROK-032
16.10	AS 1428.1 Cl. 3.2	Does the full length of the pathway have overhead clearance of 2000mm (1980mm allowed at doorway).	Overhead Clearance	TBA				Need to determine existing conditions for accessibility in ROK-032
16.11	AS 1428.1 Cl. 4.1	Does the pathway have a slip-resistant surface with a texture that is traversable by a wheelchair or a person with ambulant or sensory disability.	Slip Resistance	TBA				Need to determine existing conditions for accessibility in ROK-032
16.12	AS 1428.1 Cl. 4.1	If a grate is installed on the accessway, are circular openings not greater than 13mm in diameter; or where slotted openings are in use are they not greater than 13mm width and 150mm long and oriented so that the long dimension is transverse to the direction of travel. If linear opening is less than 8mm wide – Where linear openings are less than 8mm wide, orientation is optional.	Grate	TBA				Need to determine existing conditions for accessibility in ROK-032
16.13	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3 / 2.5	Are appropriately installed TGSIs provided at existing defined pedestrian crossing point/s with a level transition over a vehi.ular traffic way on the pathway (width x 600 – 800mm, setback 300mm ± 10mm)	TGSI	TBA				Need to determine existing conditions for accessibility in ROK-032
16.14	AS 1428.4.1 Cl. 2.2 / 2.3 / 2.5	Are appropriate installed TGSIs provided at existing defined vehicle drop off areas, with blended kerbs and a level transition, if provided on the pathway (width x 600 – 800mm, setback 300mm ± 10mm)	TGSI	TBA				Need to determine existing conditions for accessibility in ROK-032
16.15	AS 1428.1 Cl. 10.4	If there is a gate on the pathway, does it have handles and locks inside and outside that can be operated by one hand and are located at an accessible height (900 – 1100mm grasped or turned, 900 – 1200mm if pushed, 900 – 1250mm if touched)	Gate	TBA				Need to determine existing conditions for accessibility in ROK-032
16.16	APS – DP1 AS 1428.1 Cl. 7.1	Is there appropriate circulation space and a level landing at the entrance / childproof gate/s.	Circulation Space	TBA				Need to determine existing conditions for accessibility in ROK-032
16.17	AS 1428.1 Cl 7.2	Is the floor or ground surface abutting the sides of the accessway, firm and level and of a different material to that of the accessway, at the same level as the accessway and extend horizontally for a min of 600mm (unless there is a kerb, a wall, fence, a balustrade or similar barrier).	Floor Surface	TBA				Need to determine existing conditions for accessibility in ROK-032
16.18	AS148.2 Cl 7.2	Are appropriate landings provided on accessways (walkways).	Landings	TBA				Need to determine existing conditions for accessibility in ROK-032
Universal Accessibility Options: not mandatory								
16.19	AS 1428.2 Cl. 27.1 (b)	<i>Do objects on the accessway, such as seats, tables, drinking fountains, bins etc have a luminance contrast (intensity of light reflected) of not less than 0.3 (30%) to background or surrounding surfaces.</i>	Luminance Contrast	TBA				Need to determine existing conditions for accessibility in ROK-032
16.20		<i>Are the edges of the pathways in colour contrast to their background (e.g. colour strip or grass on same ground surface)</i>	Contrast against edge	TBA				Need to determine existing conditions for accessibility in ROK-032
16.21	AS 1428.2 Cl. 27.1 (a)	<i>Is seating at a height between 450 – 520mm with armrests between 220 – 300mm above the seat with a back provided along the pathway (min. every 60m) (set back a min. of 500mm).</i>	Seating on pathway	TBA				Need to determine existing conditions for accessibility in ROK-032
16.22		<i>Is there uniform appropriate lighting of the pathways for nighttime use.</i>	Lighting	TBA				Need to determine existing conditions for accessibility in ROK-032
16.23	AS 1428.4.1 Cl. 3.2 / 3.3	<i>Are warning TGSIs (hazard) provided at changes in direction of directional indicators on the pathway.</i>	TGSI	TBA				Need to determine existing conditions for accessibility in ROK-032
16.24		<i>If there is a childproof gate, does it have an accessible doorbell or intercom system, located at a height between 900 – 1200mm, which can be heard from inside the premises</i>	Childproof Gate	TBA				Need to determine existing conditions for accessibility in ROK-032
16.25		<i>If the entrance / childproof gate is located within a continual height fence, is it highlighted to assist recognition by a child or a person with vision impairment</i>	Childproof Gage	TBA				Need to determine existing conditions for accessibility in ROK-032

ROK032		20.00 Signage						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
20.01	APS – DP1 (b) / AS 1428.1 CL 5.1	Is appropriate signage available where directional decisions are made.	Directional Signage	TBA				Signage not defined at 60% Review
20.02	APS – D3.6 (e) / D4 / AS 1428.1 Cl. 5.1	If there is a non accessible entrance doorway, is there appropriate signage provided directing users to accessible entrance.	Non-Accessible Access Signage	TBA				Signage not defined at 60% Review
20.03	APS – D3.6 / D4 / AS 1428.1 Cl. 5.2	Where the symbol for access is used, does it comply with the international standard in style, colour and layout.	Symbol for Access	TBA				Signage not defined at 60% Review
20.04	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Symbol for Deafness	TBA				Signage not defined at 60% Review
20.05	APS – D3.6 (b) (ii) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2	Does signage including the international symbol of deafness, indicate which type of system is in place.	Symbol for Deafness	TBA				Signage not defined at 60% Review
20.06	APS D3.6 (b) (iii)	If receivers are being used for hearing augmentation, does the signage indicate where the receivers can be obtained.	Hearing Augmentation Signage	TBA				Signage not defined at 60% Review
20.07	APS – D3.6 (b) / D4 / AS 1428.1 CL 5.1	Is raised tactile information provided on signs between 1200 – 1600mm.	Signage Raised Text	TBA				Signage not defined at 60% Review
20.08	APS – D4.5	Is there appropriate illumination of signage for day and night use (where required e.g. to maintain luminance).	Illumination	TBA				Signage not defined at 60% Review
20.09	APS – D3.6 (f) / D4	If there is a non-accessible toilet provided, is there signage available that directs users to an accessible toilet (where in different locations).	Signage to Accessible toilet at non-accessible toilet	TBA				Signage not defined at 60% Review
20.10	APS – D3.6 (c) / D4 / AS 1428.1 Cl 5.1	Does the signage indicate if the accessible toilet facility is suitable for left or right hand.	L or R Hand Accessible Facility	TBA				Signage not defined at 60% Review
20.11	APS – D4.3 (2); Title Case AS 1428.1 C 5.1	If available on the sign, is the text provided in Title Case.	Signage - Title Case	TBA				Signage not defined at 60% Review
20.12	APS-D3.6 (a) / AS 1428.1 Cl 5.1	Is there signage (incorporating raised text and Braille, and raised and visual symbols) installed identifying available sanitary facilities.	Signage to All Toilets	TBA				Signage not defined at 60% Review
20.13	APS – D3.6 (d) / AS 1428.1 Cl. 5.1	If there is an ambulant toilet, is appropriate signage installed at the airlock serving the area that contains the facilities identifying the facilities within.	Signage Ambulant Toilet	TBA				Signage not defined at 60% Review
20.14	APS – D3.6 (d) / AS 1428.1 Cl. 5.1	If there is an ambulant toilet, is there signage to identify the facility (Note: may be located on door if required).	Signage Ambulant Toilet	TBA				Signage not defined at 60% Review
Universal Accessibility Options: not mandatory								
20.15		Is signage (including tactile and Braille) located at the main building entry, both inside and out, giving directional and general information about buildings and facilities including services and access for people with disabilities.	Main Entry Signage	TBA				Signage not defined at 60% Review

ROK033		01.00 Entrances						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
1.01	APS – D3.2 (2) (a)	If there is more than one pedestrian entrance, are 60% of them accessible (including the principal pedestrian entrance)	Entrance		Y			Is the pathways to Building 32 and 34 to be accessible?
1.02	APS – D3.2 (2) (b)	If the building is more than 500m² is any non accessible entry within 50m from an accessible entry.	Accessible Entry within 50m of Non-Accessible Entry		Y			There is no accessible entrance within 50 metres of the existing fire stairs at North West corner.
1.03	APS – D3.6 (e) Cl. 5.1	If there is a non accessible entrance doorway, is there appropriate signage provided (int. Symbol, direction arrow) directing users to an accessible entrance.	Non-Accessible Door Signage	TBA				Signage not designed at 60% review
1.04	APS – D3.2 (3) (a) (4) fig D3.2	If the pedestrian entrance is required to be accessible and consists of not more than 3 doorways, is not less than one doorway accessible.	Less than 3 doorways		Y			Doors not defined at 60% review
1.05	AS 1428.1 Cl. 10.4.3 / AS 1428.2 Cl. 28	If there are security entry controls (card / buttons / intercom) are these at 900 – 1100mm-grasped/turned, 900-1200mm-pushed, 900-1250mm (not less than 500mm from corner)-touched, (ticket slot 800 – 900mm), and easy to operate.	Security door controls	TBA				Door hardware and security not defined at 60% review
1.06	APS - A1.1	If there is a revolving door / turnstile, is there an alternative accessible hinged / sliding door	Revolving Door				NA	No Revolving Door or Turnstile
1.07	AS 1428.1 Cl. 10.4.2	Can the door be unlocked and opened by one hand (i.e. D or D lever handles).	Door Handle	TBA				Door hardware not defined at 60% review
1.08	AS 1428.1 Cl. 10.4.2 (b)	Is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handle	TBA				Door hardware not defined at 60% review
1.09	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles, snibs, locks) that need to be grasped or turned located between 900 – 1100mm high.	Door Controls	TBA				Door hardware not defined at 60% review
1.10	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed located between 900 – 1200mm high.	Door Controls	TBA				Door hardware not defined at 60% review
1.11	AS 1735.12 AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched located between 900 – 1250mm high and not less than 500mm from an internal corner except as specified in AS 1735.12 AS 1428.1 Cl. 10.4.3 (c)	Door Controls	TBA				Door hardware not defined at 60% review
1.12	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handle	TBA				Door hardware not defined at 60% review
1.13	AS 1428.1 Cl. 10.4.2 (f)	If an outward opening door is not self closing, is there a horizontal handrail or pull bar installed at a height between 900 – 1100mm (min. 50mm clearance from edge of door / door handle) on the inside of the door.	Door Handle	TBA				Door hardware not defined at 60% review
1.14	AS 1428.1 Cl. 10.4.4	If doors are power operated, are the push button controls a min. of 25mm dia., proud of the surface (activating door before the button becomes level with surrounding surface).	Power operated door	TBA				Door hardware not defined at 60% review
1.15	AS 1428.1 Cl. 10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 500 – 1000mm from arch of the hinged door leaf (in any position) / or clear of a surface-mounted sliding door in the open position.	Power operated door	TBA				Door hardware not defined at 60% review
1.16	AS 1428.1 Cl. 3.6	If the doors / sidelights are frameless or fully glazed, are they clearly marked for safety and ease of identification across the full door width, with a solid and non-transparent contrasting line (viewable from 2m inside and outside) (luminance 30%). Size of line not less than 75mm high, with the lower edge at a height of 900 – 1000mm above finished floor level.	Door Material	TBA				Door hardware not defined at 60% review
1.17	AS 1428.1 Cl. 10.1	Do all the doors or doorframes have a min. luminance contrast of 30% to their adjacent surfaces.	Door Frame Contrast	TBA				Door hardware not defined at 60% review
1.18	AS 1428.1 Cl. 10.4.2 (e)	Is the entrance door easy, to initially open, (no heavy closer or spring) 20N max. (4.3lbf)	Door Pressure	TBA				Door closers not defined at 60% review
1.19	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	Is the min. clear opening of a doorway at the PPE 850mm or greater.	Min clear opening	TBA				Doors or gates to the entrance not defined at 60% review
1.20	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	If the doorway has 2 independent operated leaves, is the open doorway a min. of 850mm wide.	2 leaves	TBA				Door leaf size not defined at 60% review
1.21	AS 1428.1 Cl. 7.5 / 7.5	Is the door threshold level or is there an appropriate threshold ramp available at the entry (i.e. no step, inappropriate mat, weather strip etc.)	Door Threshold	TBA				Door thresholds not defined at 60% review
1.22	AS 1428.1 Cl. 7.5	If there is a threshold (max. rise 35mm) at the entrance or doorway (not more than 20mm from door leaf it serves), is there a ramp of not more than 280mm in length and min. ratio of 1:8. (Note: if the rise is greater a step ramp will be required).	Door Threshold	TBA				Door thresholds not defined at 60% review
1.23	AS 1428.1 Cl. 7.5	If the threshold ramp does not abut a wall or kerb, are sides tapered or splayed (min. 45°)	Door Threshold	TBA				Door thresholds not defined at 60% review
1.24	AS 1428.1 Cl. 4.2	If there is a recessed mat within the CAPT is the abutment of the surfaces no more than 3mm if vertical or 5mm if bevelled (rounded).	Door Threshold	TBA				Door thresholds not defined at 60% review
1.25	AS 1428.1 Cl. 4.3.1	If there is a carpet leading edge at the entrance is there a vertical face no higher than 3mm or a rounded bevelled edge no higher than 5mm or above that height a gradient of 1:8 up to a total max. height of 10mm.	Carpet	TBA				Door thresholds not defined at 60% review
1.26	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space outside the entrance doorway (not steeper that 1:40) (Doorway circulations spaces may overlap other circulation spaces).	Circulation Space outside		YES			There appears to be no issue with turning circle outside the lift and the entrance at B8,B9 on drawing CQU-ROK-033-01-ARC-21-01 REV2
1.27	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space inside the entrance doorway (not steeper that 1:40) (Doorway circulations spaces may overlap other circulation spaces).	Circulation Space inside		YES			There appears to be no issue with turning circle outside the lift and the entrance
1.28	AS 1428.1 Cl. 10.3.5	If there is an airlock, vestibule, or enclosed space, is there not less than 1450mm between the doorway (plus the door leaf width if the door encroaches into the space).	Airlock				NA	No Airlock defined at 60% Review

ROK033		01.00 Entrances						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
1.29	AS 1428.1 Cl. 3.7	If there are glazed viewing panels in doors, is the lower edge of the glazing not more than 1000mm above FFL, upper edge not less than 1600mm above FFL.	Glazed Viewing Panels	TBA				Door leaf + viewing panels not defined at 60% review
1.30	AS 1428.1 Cl 3.7	If there are glazed viewing panels in doors, is the width of the glazing within 200mm from latch edge of the door and min 150mm wide.	Glazed Viewing Panels	TBA				Door leaf + viewing panels not defined at 60% review
Universal Accessibility Options: not mandatory								
1.37	AS 1428.2 Cl. 23.3 (b)	Are the door handles provided with an appropriate luminance contrast	Door Handles	TBA				Door hardware not defined at 60% review
1.38		Do automatic self-opening doors have effective motion, and presence sensors installed	Automatic Doors	TBA				Door Control not defined at 60% Review
1.39		If there is an alarm control pad, is it located at a height between 900 – 1200mm high, accessible and easy to operate	Door Control	TBA				Door hardware not defined at 60% review
1.40		If there is a doorbell, is it accessible and easy to operate, located at a height between 900 – 1200mm	Doorbell				NA	Door hardware not defined at 60% review
1.41		Is there appropriate lighting at the PPE	Lighting	TBA				Lighting not defined at 60% Review

ROK033		03.00 Internal Accessways						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
3.01	AS 1428.1 Cl. 3.3	Does the accessway have a min. width of 1000mm i.e. structurally and maintained to remain clear of temporary obstructions e.g. pot plants, bins.	Min Width		Y			Accessways are all min width of 1000mm at 60% Review
3.02	AS 1428.1 Cl. 3.2	Does the full length of the accessway have an overhead clearance of 2000mm (1980mm allowed at doorway)	Overhead Clearance		Y			There is no evidence that the accessway would not have an overhead clearance of 2m at 60% Review
3.03	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.4	Do accessways provide a passing space where a direct line of sight is not available to the end of the walkway (max. 20m intervals) (min. 1800mm wide x 2000mm long)	Turn Circle		Y			All Accessways have direct line of sight to the end. Accessways also have turning circles at each end.
3.04	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.5	Do accessways provide a turning space near the end of the walkway where it is not possible to continue (within 2m of end)	Turn Circle		Y			No evidence of inadequate turning space in internal accessways
3.05	AS 1428.1 Cl. 3.5	If a change of direction is required, is there appropriate circulation space provided along the accessway for the angle of the turn.	Circulation		Y			No evidence of inadequate circulation space
3.06	AS 1428.1 Cl. 4.1	Does the accessway have a slip-resistant surface with a texture that is traversable by a wheelchair.	Slip Resistant	TBA				Surface for accessway not designed at 60% Review
3.07	APS – D3.6 (e) AS 1428.1 CL 5	If there is a non-accessible entrance doorway, is there appropriate signage provided (int. Symbol, direction arrow) directing users to an accessible entrance	Signage	TBA				Signage not designed at 60% Review
3.08	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	Is the min. clear opening of a doorway on any accessway 850mm or greater.	Min Clear open		Y			No evidence of doorways that are less than 850mm
3.09	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space outside the doorway (NOTE: 1:40 grade, additional considerations at surface mounted sliding doors) (Doorway circulation space may overlap other circulation spaces)	Circulation		Y			No evidence of inappropriate circulation spaces outside each doorway. To be checked again at 60%
3.10	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space inside the doorway (NOTE: 1:40 grade, additional considerations at surface mounted sliding doors) (Doorway circulation space may overlap other circulation spaces)	Circulation		Y			No evidence of inappropriate circulation spaces inside each doorway. To be checked again at 60%
3.11	AS 1428.1 Cl. 10.4.2 (a)	Can the door be unlocked and opened by one hand (i.e. D or D lever handles)	Door Handles	TBA				Door hardware not designed at 60% Review
3.12	AS 1428.1 Cl. 10.4.2 (b)	Is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handles	TBA				Door hardware not designed at 60% Review
3.13	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles) that need to be grasped or turned between 900 – 1100mm high.	Door Handles	TBA				Door hardware not designed at 60% Review
3.14	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed between 900 – 1200mm high.	Door Handles	TBA				Door hardware not designed at 60% Review
3.15	AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched between 900 – 1250mm high (and not less than 500mm from an internal corner, except as specified in AS 1735.12)	Door Handles	TBA				Door hardware not designed at 60% Review
3.16	AS 1428.1 Cl.10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 1000 – 2000mm from the hinged swing door leaf (in any position) / or doorway of sliding door.	Power Door	TBA				Doors that are power operated not designed at 60% Review
3.17	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handles	TBA				Door hardware not designed at 60% Review
3.18	AS 1428.1 Cl. 10.4.2 (e)	Are all doors (other than fire / smoke doors) provided with the appropriate opening force (20N).	Door Force	TBA				Door Force not designed at 60% Review
3.19	AS 1428.1 Cl. 10.3.5	If there is an airlock, vestibule, or enclosed space, is there not less than 1450mm between the doorway (plus the door leaf width if the door encroaches into the space).	Air Vestibule				NA	No airlocks designed at 60% Review
3.20	AS 1428.1 Cl. 10.4.2 (g)	If an outward opening door is not self closing, is there a horizontal handrail or pull bar installed at a height between 900 – 1100mm (min. 50mm clearance from edge of door / door handle) on the inside of the door.	Hoor Handles	TBA				Door hardware not designed at 60% Review
3.21	AS 1428.1 Cl 11.1	Are all switches and controls provided on a CAPT (other than general purpose outlets (GPOs)) located at a height of 900 – 1100mm and not less than 500mm from an internal corner.	Switches and Controls	TBA				Door hardware not designed at 60% Review

ROK033		04.00 Accessible Toilet						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
04.01	APS – F2.4 (a)	Is a toilet designated as wheelchair accessible available in the building / facility.	Access Toilet		Y			
04.02	APS – F2.4	Is a USAT provided on each floor level that toilets are provided on APS – F2.4.	Access Toilet		Y			
04.03	APS – F2.4 (g)	If there is more than 1 USAT is the 2 nd of the opposite hand.					NA	Only 1 USAT per level designed at 60% Review
04.04	AS 1428.1 Cl. 12.2.8.1	Is the min. circulation space 1900mm wide and 2300mm long to a height of 2000mm (Note: accepted intrusions)	Circulation Space		Y			
04.05	APS – F2.4 (f)	Is the toilet/s on a CAPT from the PPE (ensuring that access does not necessitate the traversing an area reserved for one sex only).	On CAPT		Y			
04.06	APS – D3.6 (c) / D4 / AS 1428.1 Cl 5	Is the toilet/s sign posted with the appropriate International Symbol of Access, and separate Male and Female symbols, located on the wall between 1200 - 1600mm high on the latch side of the doorway (Note: to include raised and visual versions).	Sign	TBA				Signage not designed at 60% Review
04.07	APS – D3.6 (c) / D4 / AS 1428.1 Cl 5	Does the signage indicate if the facility is suitable for left or right hand use.	Sign	TBA				Signage not designed at 60% Review
04.08	APS – D3.6 (f) / D4	If there is a non-accessible toilet provided, is there signage available that directs users to an accessible toilet (where in different locations).	Sign	TBA				Signage not designed at 60% Review
04.09	APS – D4.3 (2); AS 1428.1 Cl 5	If available on the sign, is the text provided in Title Case.	Sign	TBA				Signage not designed at 60% Review
04.10	AS 1428.1 Cl. 10.2	Is the min. clear opening width 850mm or greater for the toilet.	Min Opening		Y			
04.11	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space at the door (inside and outside).	Circulation Space		Y			
04.12	AS 1428.1 Cl. 12.2.9 (b)	Does the cubicle door have an ‘occupied’ (in-use) indicator and a bolt or catch (which is openable from the outside in an emergency).	Door Indicator	TBA				Door Hardware not designed at 60% Review
04.13	AS 1428.1 Cl. 12.2.9 (b)	If a snib catch is in use, does the snib handle have a min. length of 45mm from the centre of the spindle.	Snib Catch	TBA				Door Hardware not designed at 60% Review
04.14	AS 1428.1 Cl. 10.4.2 (e)	Is the cubicle door easy to initially open (no heavy closer) 20N max.	Door Pressure	TBA				Door Hardware not designed at 60% Review
04.15	AS 1428.1 Cl. 12.2.9 (a)	If the door is outward opening does it have a hinge mechanism that holds the door in a closed position without the use of a latch.	Hinge Mechanism	TBA				Door Hardware not designed at 60% Review
04.16	AS 1428.1 Cl. 10.4.2 (a)	Can the door be unlocked and opened by one hand (i.e. D lever or D handles and approp. hardware).	Door Handle	TBA				Door Hardware not designed at 60% Review
04.17	AS 1428.1 Cl. 10.4.2 (b)	Throughout its operation, is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.18	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles) that need to be grasped or turned between 900 – 1100mm high.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.19	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed between 900 – 1200mm high.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.20	AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched between 900 – 1250mm high and not less than 500mm from an internal corner.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.21	AS 1428.1 Cl. 10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 1000 – 2000mm from the hinged swing door leaf (in any position) / or doorway of sliding door.	Power Door	TBA				Power Doors no defined at 60% Review
04.22	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.23	AS 1428.1 Cl. 10.1	Does the doorway have a min. luminance contrast of 30% to its adjacent surfaces.	Contrast	TBA				Paint Finishes not defined at 60% Review
04.24	AS 1428.1 Cl. 12.2.8 (fig 43)	Is there a 1500mm space in front of the pan (Note: basin overlap of 100mm permitted if located at front of pan only).	Space in front of pan		Y			No evidence of non-compliance.
04.25	AS 1428.1 Cl. 12.2.8 (fig 43)	Is there 1240 – 1250mm at one side of the pan (this allows side transfers from a wheelchair) (basin not permitted to overlap if located to side of pan).	Space side of pan		Y			Sanitary ware not defined to this level at 60% Review
04.26	AS 1428.1 Cl. 12.2.3 (a) (b) (c) (d)	Is there a full round toilet seat securely hinged to the pan (load rated to 150kg).	Sanitary Ware	TBA				Sanitary ware not defined at 60% Review
04.27	AS 1428.1 Cl. 12.2.3 (e)	Does the toilet seat have a min. 30% luminance contrast with the background e.g. (pan, wall or floor).	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.28	AS 1428.1 Cl. 12.2.2	Is the height to the top of the seat between 460 – 480mm.	Sanitary Ware		Y			No evidence of non-compliance.
04.29	AS 1428.1 Cl. 12.2.2	Is the front of the pan 790 - 810mm from the rear wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.30	AS 1428.1 Cl. 12.2.2	Is the centreline of the pan 450 - 460mm from the side wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.31	AS 1428.1 Cl. 12.2.2	Is the width of the pan a max. of 400mm.	Sanitary Ware		Y			No evidence of non-compliance.
04.32	AS 1428.1 – 2009 Cl. 12.2.2	Is the front of the pan a min. of 600mm from any back wall mounted fixture.	Sanitary Ware		Y			No evidence of non-compliance.
04.33	AS 1428.1 Cl. 12.2.4 (a)	Is a backrest provided on the USA T which is capable of withstanding a force in any direction of 1100N.	Sanitary Ware		Y			No evidence of non-compliance.
04.34	AS 1428.1 Cl. 12.2. 4 (b)	At its face, is the height of the lower edge of the backrest to the top of the WC seat between 120 – 150mm.	Sanitary Ware		Y			No evidence of non-compliance.
04.35	AS 1428.1 Cl. 15.2. 4 (c)	Does the backrest have a vertical height of 150 – 200mm and a width of 350 – 400mm.	Sanitary Ware		Y			No evidence of non-compliance.
04.36	AS 1428.1 Cl. 12.2. 4 (c) (d)	Does the backrest have its face centered on the pan centreline, positioned to achieve an angle of between 95 - 100° back from the seat hinge.	Sanitary Ware		Y			No evidence of non-compliance.
04.37	AS 1428.1 Cl. 12.2.7 (fig 42)	If a concealed or high level cistern is used, is a continuous grab rail at 800 – 810mm (30 – 40mm dia.) provided across the rear and side wall nearest the pan.	Sanitary Ware		Y			No evidence of non-compliance.
04.38	AS 1428.1 Cl. 12.2.7 (fig 42)	If the grab rail on the side wall is one continuous rail, does it provide the appropriate angled extension and clearances from pan / wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.39	AS 1428.1 Cl. 12.2.7 (fig 42)	Is the outside edge of any back wall grab rail at least 450mm from the side of the pan (dependent on length of grab rail).	Sanitary Ware		Y			No evidence of non-compliance.
04.40	AS 1428.1 Cl. 14	Is the grab rail fixed and constructed to withstand a force of 1100N applied in any position and in any direction (without deformation or loosening or rotation of the fastenings or fittings).	Sanitary Ware		Y			No evidence of non-compliance.
04.41	AS 1428.1 Cl. 14	Is the clearance between the grab rail and the adjacent wall surface or other obstruction not less than 50mm and not more than 60mm.	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.42	AS 1428.1 Cl. 14	Is there a min. 600mm clearance above the horizontal grab rail, with a min. of 50mm below any horizontal or angled rail (except at fixing points).	Sanitary Ware		Y			No evidence of non-compliance.

ROK033 04.00 Accessible Toilet								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
04.43	AS 1428.1 Cl. 14	Are exposed edges and corners of grab rails provided with a radius of not less than 5mm.	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.44	AS 1428.1 Cl. 12.2.7 (fig 42)	If a surface mounted / low level cistern is used, is there a wall mounted grab rail (30 – 40mm dia.) a min. length 300mm on the rear wall located within 50mm of the cistern, together with a grab rail mounted on the sidewall at 800 – 810mm high (as per diagram).	Sanitary Ware		Y			No evidence of non-compliance.
04.45	AS 1428.1 Cl. 12.2.2	Is the bottom edge of the cistern a min. of 600mm above floor level.	Sanitary Ware		Y			No evidence of non-compliance.
04.46	AS 1428.1 Cl. 12.2.6 (fig 41)	Can the toilet paper be easily reached (max. outside edge 300mm forward of pan and top edge 700mm max. height) and the roll dispenser have no greater than 150mm projection from the wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.47	AS 1428.1 Cl. 12.2.5 (fig 40)	If the flushing control is located on the back wall, is it within reach, easy to operate (activating the flush before level with the surrounding surface) <i>contrasting 30% with adjacent surfaces</i> (min height 600mm / max. height 1100mm / outside edge max. 500mm from centre line)	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.48	1428.1 Cl. 12.2.5 (fig 40)	If not located on the back wall as above, is it located in the centre line of the toilet AS.	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.49	AS 1428.1 Cl. 12.2.5 (fig 40)	If the flushing control is located on the side wall is it within the approp. zone (inside edge no further than 300mm over the pan / outside edge no further than 300m from the front of the pan – at a height between 600 – 1100mm above finished floor level.	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.50	AS 1428.1 Cl. 12.2.10	Is there a basin inside the unisex accessible toilet	Sanitary Ware		Y			No evidence of non-compliance.
04.51	AS 1428.1 Cl. 12.2.8 (fig 43)	Is the distance between the basin and pan at least 1400mm (front of pan location only permitted for 100mm overlap).	Sanitary Ware		Y			No evidence of non-compliance.
04.52	AS 1428.1 Cl. 12.3.1 (d) (fig 44 (a) (b))	If a semi recessed washbasin is installed (other than within a SOU) is the front top edge 800 – 840mm above the floor.	Sanitary Ware				NA	No semi-recessed washbasin
04.53	AS 1428.1 Cl. 12.3.1 (d) (fig 44 (a) (b))	If a wall mounted washbasin is installed is the front top edge 800 – 830mm above the floor.	Sanitary Ware		Y			No evidence of non-compliance.
04.54	AS 1428.1 Cl. 12.3.1 (d) (fig 44 (a) (b))	If a semi recessed basin is provided (except within a SOU) is the bench provided at a height between 800 – 830mm (outside of circulation spaces).	Sanitary Ware				NA	No semi-recessed washbasin
04.55	AS 1428.1 Cl. 12.3.1 (d) (fig 46)	Is the centre line of the washbasin (rear) provided with a min. 225mm either side.	Sanitary Ware		Y			No evidence of non-compliance.
04.56	AS 1428.1 Cl. 12.3.1 (d) (fig 44)	Is the centre line of the washbasin a min. of 425mm from any wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.57	AS 1428.1 Cl. 12.3.1 (d) (fig 44)	Is the circulation space a min. of 450mm wide (rear of basin).	Sanitary Ware		Y			No evidence of non-compliance.
04.58	AS 1428.1 Cl. 12.3.1 (d) (fig 46)	Is the circulation space for the washbasin a min. 1500mm long and 850mm wide (from rear of washbasin).	Sanitary Ware		Y			No evidence of non-compliance.
04.59	AS 1428.1 Cl. 12.3.1 (d) (fig 44)	Is the position of the taps, bowl and drain outlet appropriate.	Sanitary Ware		Y			No evidence of non-compliance.
04.60	AS 1428.1 Cl. 12.3.1 (d) (fig 44) (a)	Does the basin have appropriate foot / knee / leg space underneath.	Sanitary Ware		Y			No evidence of non-compliance.
04.61	AS 1428.1 Cl. 12.3.1 (c) (e)	If the downpipes are exposed are they insulated or located so as to ensure they do not present a hazard to the user and sit outside the circulation space under the washbasin.	Downpipe		Y			No evidence of non-compliance.
04.62	AS 1428.1 Cl. 12.2.1 (d)	If hot water is provided, is water delivered through a mixing spout.	Mixing Spout		Y			No evidence of non-compliance.
04.63	AS 1428.1 Cl. 12.2.1 (c)	If hot water is provided, is the hot tap located on the left of or above the cold tap.	Hot / Cold Tap				NA	Mixing spout
04.64	AS 1428.1 Cl. 15.2.1 (a)	Are the tap handles lever, sensor plates, voice activation or other similar controls.	Tap Handles		Y			No evidence of non-compliance.
04.65	AS 1428.1 Cl. 12.2.1 (b)	If the taps have lever handles, are they located more than 50mm from adjacent surfaces.	Tap Handles		Y			No evidence of non-compliance.
04.66	AS 1428.1 Cl. 12.2.1 (c)	Are taps clearly identified as hot and cold (colour and text) and in the appropriate location.	Tap Handles				NA	Mixing spout
04.67	AS 1428.1 Cl. 12.4.4	Is there a clothes hanging device 1200 – 1350mm from the floor (not less than 500mm from an internal corner (Note: shower exception)	Clothes Hanger			N		See Markup in Appendix A
04.68	AS 1428.1 Cl. 12.4.1	Is a mirror provided and located either adjacent to or above the washbasin at a min. of 350mm wide.	Mirror		Y			No evidence of non-compliance.
04.69	1428.1 Cl. 12.4.1	If the mirror is above the basin, does it extend between 900mm – 1850mm above the floor, or If adjacent to the basin, at a height of not more than 780mm to a height of not less than 1800mm above the floor.	Mirror		Y			No evidence of non-compliance.
04.70	AS 1428.1 Cl. 12.4.3	If a hand dryer / towel dispenser is provided, is the operative component at a height between 900 – 1100mm and within reach of a user at the washbasin (not closer than 500mm from any internal corner) does not encroach more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Hand Dryer		Y			No evidence of non-compliance.
04.71	AS 1428.1 Cl. 12.4.3	If a soap dispenser is provided, is the operative component at a height between 900 – 1100mm and within reach of a user at the washbasin (not closer than 500mm from any internal corner) does not encroach more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Soap Dispenser		Y			No evidence of non-compliance.
04.72	AS 1428.1 Cl. 12.4.2 (a)	One of the following three shelves must be provided. If a shelf is provided as a vanity top is it located at a height between 800 – 830mm with a min. width of 120mm and depth of 300mm and a depth no greater than the bowl plus its front and back flanges, without	Shelf		Y			No evidence of non-compliance.
04.73	AS 1428.1 Cl. 12.4.2 (b) (i)	If a shelf is provided within the circulation space as a separate fixture, is it available at a height between 900 – 1000mm with a min. width of 120 -150mm and length of 300 – 450mm.	Shelf				NA	Shelf with basin
04.74	AS 1428.1 Cl. 12.4.2 (b) (ii)	If a shelf is provided external to the circulation space as a separate fixture, is it at a height between 790 – 1000mm with a min. width of 120mm and length of 400mm and does not encroach more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Shelf				NA	Shelf with basin
04.75	AS 1428.1 Cl. 12.4.5 (a) (fig 43)	If there is a portable sanitary disposal unit available, is it provided in the rear corner between the pan and the closest wall.	Sanitary Disposal			N		See Markup in Appendix A
04.76	AS 1428.1 Cl. 12.4.5 (b)	If a recessed sanitary disposal unit is provided, is it located within 500mm of the pan.	Sanitary Disposal			N		See Markup in Appendix A
04.77	AS 1428.1 Cl. 12.2.8.1 (iv)	If a wall cabinet is provided, does it encroach not more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Wall Cabinet			N		See Markup in Appendix A
04.78	AS 1428.1 Cl. 11.2	Are rocker action / toggle switches provided which are a min. 30 x 30mm.	Switches	TBA				Switch detail not defined at 60% Review

ROK033		04.00 Accessible Toilet						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
04.79	AS 1428.1 Cl. 11.2	If push pad switches are provided are they a min. of 25mm dia.	Switches	TBA				Switch detail not defined at 60% Review
04.80	AS 1428.1 Cl. 11.2	If provided near the washbasin, are switches and power points 600 –1100mm high, not less than 500mm from the internal corners and close to any shelf or worktop.	Switches	TBA				Switch detail not defined at 60% Review
04.81	AS 1428.1 Cl. 12.2.8.2	If there is a baby change table, is it located at a height of 820 mm with leg clearance height underneath of 720 when open (must sit outside of circ. space when folded up).	Baby Change Table			N		See Markup in Appendix A
Ambulant Toilets								
	Standard	Items						
04.82	APS – F2.4	If there are one or more toilets provided in addition to the USAT at the bank of toilets, is an ambulant male and an ambulant female toilet provided	Ambulant Toilet		Y			No evidence of non-compliance at 60% Review
04.83	AS 1428.1 Cl. 13.4.	If ambulant toilets are provide is signage (raised text and Braille, and raised and visual symbols) installed at the airlock serving the area that contains the facilities identifying the facilities within AS 1428.1 Cl. 13.4.	Signage	TBA				Signage not defined at 60% Review
04.84	APS – D3.6 (d) / AS 1428.1 Amdt. 1 Cl. 8.1.	Is there signage (raised text and Braille, and raised and visual symbols) installed on the door of the facility.	Signage	TBA				Signage not defined at 60% Review
04.85	AS 1428.1 Cl. 10.3	If there is an airlock enrout ^e to an ambulant toilet, is there appropriate circulation space.	Airlock				NA	Airlock not designed at 60% Review
04.86	AS 1428.1 Cl. 13.3	Is the min. clear opening width of the ambulant toilet doorway 700mm.	Width of Doorway		Y			No evidence of non-compliance at 60% Review
04.87	AS 1428.1 Cl. 13.3	Does the cubicle door have an ‘occupied’ (in-use) indicator and a bolt or catch (which is openable from the outside in an emergency).	Indicator		Y			No evidence of non-compliance at 60% Review
04.88	AS 1428.1 Cl. 13.3	If a snib catch is in use, does the snib handle have a min length of 45mm from the centre of the spindle	Snib Catch	TBA				Door Hardware not detailed at 60% Review
04.89	AS 1428.1 Cl. 16.1	Is the width of the ambulant toilet compartment between 900 – 920mm.	Width of Ambulant		Y			No evidence of non-compliance at 60% Review
04.90	AS 1428.1 Cl. 13.1 fig 52 (B)	Is there a clear min. circulation space of 900mm long x 900-920mm wide in front of the toilet pan.	Min Circulation in					
04.91	AS 1428.1 Cl. 13.3 fig 52 (B)	Is there a clear circulation space a min. of 900 x 900mm outside the door (Note: variety of placement options).	Min Circulation out		Y			No evidence of non-compliance at 60% Review
04.92	AS 1428.1 Cl. 12.2.7	Are appropriate grab rails installed on the wall located at a height between 800 – 810mm.	Grab Rail		Y			No evidence of non-compliance at 60% Review
04.93	AS 1428.1 Cl. 14	Is the grab rail fixed and constructed to withstand a force of 1100N applied in any position and in any direction (without deformation or loosening or rotation of the fastenings or fittings).	Grab Rail	TBA				Ambulant toilet not defined to this level at 60% Review
04.94	AS 1428.1 Cl. 14	Is the clearance between the grab rail and the adjacent wall surface or other obstruction not less than 50mm and not more than 60mm.	Grab Rail	TBA				Ambulant toilet not defined to this level at 60% Review
04.95	AS 1428.1 Cl. 14	Is there a min. 600mm clearance above the horizontal grab rail, with a min. of 50mm below any horizontal or angled rail (except at fixing points).	Grab Rail	TBA				Ambulant toilet not defined to this level at 60% Review
04.96	AS 1428.1 Cl. 14	Are exposed edges and corners of grab rails provided with a radius of not less than 5mm.	Grab Rail	TBA				Ambulant toilet not defined to this level at 60% Review
04.97	AS 1428.1 Cl. 13.1	Is the toilet pan provided with the standard projection of between 610 – 660mm.	Pan Projection		Y			No evidence of non-compliance at 60% Review
04.98	AS 1428.1 Cl. 13.1	Is the height to the top of the seat between 460 – 480mm.	Height to top of seat		Y			No evidence of non-compliance at 60% Review
04.99	AS 1428.1 Cl. 13.1 fig 52 (A)	Can the toilet paper be easily reached (max. outside edge 300mm forward of pan and top edge 700mm max. height).	Toilet Paper position		Y			No evidence of non-compliance at 60% Review
Universal Accessibility Options: not mandatory								
4.100		Are the door handles or controls colour contrasting to the background (30%)	Contrast	TBA				Door Hardware not defined at 60% Review
4.101		Is appropriate lighting provided inside the toilet	Lighting	TBA				Lighting not defined at 60% Review
4.102		Is there an emergency alarm installed in the cubicle, for users requiring assistance	Alarm	TBA				Alarm system not defined

ROK033		06.00 Passenger Lifts						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
06.01	APS 4.4 / E3.6	Is there a lift available to all floors (where required).	All Floors		Y			
06.02	APS – E3.6b	Is the lift door installed with a min. clear opening width of 900mm.	Min. Clear Width	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.03	AS 1735.12 - Sect. 6	Is the internal lift floor surface level with the external surface for an unobstructed entry into the lift (12mm variation allowed).	Floor Surface	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.04	APS - E3.6 / 1735.12 – Sect. 2	If the lift was approved with building permit issued prior to 1st May 2011, (or new and travels not more than 12m), is the min. floor area 1100mm wide x 1400mm deep.	Age of Lift				NA	
06.05	APS – 4.4 / E3.6	If the lift was approved with building permit issued on or after 1st May 2011 and travels more than 12m, is the min. floor area 1400mm wide x 1600mm deep.	Age of Lift	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.06	AS 1735.12 – Cl. 3.1 / APS Amdt. (6)	If carpet is provided within the lift, is it appropriate (pile <11mm, backing <4mm)	Carpet	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.07	AS 1735.12 – Cl. 4.2	Is an appropriate door operating sensor (passenger protection system) in place which whilst activated holds the doors open.	Sensor	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.08	AS 1735.12 – Cl. 4.3	Do the doors, when responding to a landing button, remain open for a full 6 seconds.	Open Time	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.09	AS 1735.12 Cl. 4.3	If there are three or more lifts in line and they are interconnected in their operation, is the door dwell time extended to a min. 8 sec (Note: dwell times may be shortened in some instances).	More than 1 lift				NA	
06.10	AS 1735.12 Cl. 8.5	If there are three or more lifts in the bank of lifts is there visible and audible notification on each lift landing to indicate the lift arrival and direction of travel.	More than 1 lift				NA	
06.11	AS 1735.12 Cl. 5.1	Are the adjacent parallel surfaces in the lift car located within 300mm of the control buttons, provided with a surface that reduces glare and reflection.	Parallel Surfaces	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.12	AS 1735.12 Cl. 5.2	Are car operating panels, seats, handrails provided so as to not obstruct or reduce the width of the door opening.	Internal Car Fitout	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.13	AS 1735.12 Cl. 5.3.2 (a)	Is a handrail available which is a min. length of 600mm, located in the lift at a height between 850 – 950mm.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.14	AS 1735.12 Cl. 5.3.1	Is this handrail a max. of 500mm from any button or device to operate the lift.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.15	AS 1735.12 Cl. 5.3.2 (a)	Does the handrail have a circular diameter of 30 – 50mm for a min. of 270°.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.16	AS 1735.12 Cl. 5.3.2 (c)	Are exposed edges of the handrail provided with a radius of not less than 5mm.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.17	AS 1735.12 Cl. 5.3.2 (f)	Are clearances above the handrail (including clearances to the control panel) less than 5mm or not less than 100mm.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.18	AS 1735.12 Cl. 5.3.2 (g)	Are handrails set 50mm from the car wall.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.19	AS 1735.12 Cl. 5.3.2 (g)	If there is a gap less than 50mm between the wall and handrail (i.e. where handrail is returned to the wall) is it filled in (enclosed)	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.20	AS 1735.12 Cl. 5.4	If there is a fixed seat within the lift, does it sit outside of the min. car size (Note: hinged seats not acceptable).	Seat within Lift	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.21	AS 1735.12 Cl. 7.1	Is each landing provided with one or more control buttons to call the lift.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.22	AS 1735.12 Cl. 7.3.1	Is the centre of landing control buttons, key switches and card readers located between 900mm –1200mm above the landing floor.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.23	AS 1735.12 Cl. 7.3.3	Are the landing control buttons located adjacent to the lift entrances and not closer than 500mm from any internal corner or fixed obstruction.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.24	AS 1735.12 Cl. 7.1	If up and down buttons are provided on a landing, and are not located vertically within 200mm of each other, is a tactile symbol and Braille equivalent provided (above or to the left or on the face of the respective button).	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.25	AS 1735.12 Cl. 7.2.3	If a key pad is provided, is it set up like a telephone key pad and located at a height between 900 - 1100mm from the floor.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.26	AS 1735.12 Cl. 7.2.3 / 7.4	If a key pad is provided, is there a tactile dot provided in the centre of the number 5 (unless the tactile symbol is on the face of the button).	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.27	AS 1735.12 Cl. 7.2.1	If the lift has a dimension less than 1400mm, are there two lift control panels provided (one to the left and one to the right of a person entering the lift).	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.28	AS 1735.12 Cl. 7.2.2 Figure 8.4.2 (c)	Is the communication button located at the right hand end of the lowest row of buttons and identified by a visible symbol.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.29	AS 1735.12 Cl. 7.2.2 / 8.3 Figure 8.4.2 (c)	Is there a tactile symbol and Braille equivalent above or to the left or on the face of the respective buttons.	Signage	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.30	APS – E3.6 (b) / AS 1735.12 – Sect 9.2 / 9.3	Is there an emergency hands-free communication system installed, (including a button that alerts a call centre of a problem and a light to signal that the call has been received).	Emergency comms	TBA				Existing Lift Detail not shown in drawings at 60% Review

ROK033		06.00 Passenger Lifts						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
06.31	AS 1735.12 Cl. 7.3.1	Is the centre of the face of the control buttons within the lift located at a height between 700 – 1250mm.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.32	AS 1735.12 Cl. 7.3.2	Are the control buttons within the lift located within the appropriate zones / distance from the door / corners.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.33	AS 1735.12 Cl. 7.4	Are the control buttons of the appropriate size, design and easy to use (2N – 5N).	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.34	APS – E3.6 (b)	If the lift travels more than 2 floors, is there appropriate audible information to identify when the lift stops.	Audible	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.35	APS – E3.6 (b)	If the lift travels more than 2 floors, is there appropriate audible and visual indication at each lift landing to indicate the arrival of the lift.	Audible	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.36	AS 1735.12 Cl. 8.6	Is an appropriate lift position indication provided within the lift (i.e. lift on 2nd floor, 4th floor etc.).	Position Indicator	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.37	AS 1735.12 Cl. 10.2	Is there appropriate lighting within the lift.	Lighting	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.38	AS 1735.12 Cl. 10.3	Are the lift control buttons appropriately lit.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
Universal Accessibility Options: not mandatory								
06.39	AS 1428.2 – Cl. 12	Can a wheelchair turn around in the lift (recommended 1700x 1900mm)	Circulation	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.40		Are the handrails in contrast to the walls	Handrail Contrast	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.41		Are the internal walls of the lift of a non-reflective material	Wall Finish	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.42		Are the emergency procedures clearly identified in the event of a lift malfunction	Signage	TBA				Existing Lift Detail not shown in drawings at 60% Review

ROK033		07.00 Kitchens						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
07.01	AS 1428.1 Cl. 3	Is there a CAPT provided to the kitchen / bar / dining / laundry / canteen area.	CAPT		Y			
07.02	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there a continuous internal accessible path of travel to any canteen window.	Canteen				NA	
07.03	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there a continuous external accessible path of travel to any external canteen / servery window.	Canteen				NA	
07.04	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there appropriate circulation space within the kitchen area, to enable a user ease of use for all facilities.	Circulation Space	TBA				Level 1 - Fixed Furniture appears accessible. Refer to markups with issues with flexible furniture. Level 2 - Fixed Furniture also appears accessible. Refer to markups with issues with flexible furniture.
Universal Accessibility Options: not mandatory								
07.05	AS 1428.2 Cl. 24	Does the counter have a wheelchair accessible section at a height between 830 – 870mm for a min. length of 900mm.	Counter	TBA				
07.06	AS 1428.2 Cl. 24	Does the counter have at the wheelchair accessible section, a leg clearance underneath at a height between 800 – 840mm for a min. length of 900mm.	Counter	TBA				
07.07	AS 1428.2- A5	Is the sink / basin accessible to people in wheelchairs (height 770 – 800mm).	Basin	TBA				
07.08	AS 1428.2- A5	Is the sink / basin accessible to people in wheelchairs (leg clearance height underneath 640-650mm) with appropriate unobstructed circulation space.	Basin	TBA				
07.09	AS 1428.2 Cl. 24	If there is a canteen / servery window does it have a wheelchair accessible section at a height between 830 – 870mm with a leg clearance underneath at a height of 800 – 840mm for a min. length of 900mm.	Canteen Window				NA	
07.10	AS 1428.2 Cl. 29	Are the operative components of any vending machine, for pre-packaged food and drink, accessible and between 700 – 1200mm high.	Vending Machine				NA	
07.11	AS 1428.2 Cl. 27.2	If seating is available, is it at a height of 450 – 520mm with armrests located at a height between 220 – 300mm above the seat and backs.	Seating	TBA				
07.12		If tea and coffee facilities are provided (other than vending machine), are the highest operable components located at a height between 900 – 1100mm.	Tea / Coffee	TBA				

ROK03308.00 Meeting Spaces								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
08.01	AS 1428.2 Cl. 26.2 (a)	If an inbuilt stage or podium is provided, is there ramp access (in addition to any step / stair).	Stage				NA	No stages defined at 60%
08.02	APS – D3.7 (1) (2) (3)	If a sound amplification system is installed / inbuilt, is there a hearing augmentation system that covers 80% of the total enclosed space if an induction loop is inbuilt, or 95% if a receiver system is in use.	Sound Amplification = Hearing Augmentation	TBA				Sound amplification not defined at 60% Review
08.03	APS – D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, (excluding letter 'T') indicate the area where an assistive listening system is operational and the area covered.	Signage	TBA				Signage not defined at 60% Review
08.04	APS – D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, (excluding letter 'T') indicate which type of system is in place.	Signage	TBA				Signage not defined at 60% Review
08.05	APS – D3.7 (1) (2) (3)	If receivers are being used, does the signage indicate where the receivers can be obtained.	Signage	TBA				Signage not defined at 60% Review
08.06	AS 1428.1 Cl. 4.1	Is there a level, slip resistant floor surface.	Slip Resistance	TBA				Slip Resistance not defined at 60% Review
08.07	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there adequate circulation space between all furniture and fittings.	Circulation Space	TBA				Some issues with circulation space - Refer to markups
Universal Accessibility Options: not mandatory								
08.08		Is there appropriate lighting to the area.	Lighting	TBA				Lighting not defined at 60% Review
08.09		Is there clear, concise signage, incorporating Braille and tactile components that identifies all elements e.g. toilet, emergency exits.	Signage	TBA				Signage not defined at 60% Review
08.10		Is there sufficient level circulation space provided for a person using a wheelchair to sit at a meeting table in various locations.	Circulation Space	TBA				Some issues with circulation space - Refer to markups
08.11	AS 1428.2 Cl. 27.2	Is there some seating available which is 450 – 520mm high with armrests provided at a height of 220 – 300mm above the seat and a back.	Seating	TBA				Furniture specification not detailed at 60% Review
08.12	AS 1428.2 Cl. 26.2	Are boundaries of any stage or podium defined by barriers or an appropriate contrast to the floor surface, (colour and texture)	Stage				NA	Multiple Meeting Room Fiouts are not defined at 60% Review
08.13	AS 1428.2 Cl. 26.2 (b) / 6.3	Are all stage / podium controls able to be operated by a person when seated	Stage				NA	Multiple Meeting Room Fiouts are not defined at 60% Review
08.14	AS 1428.5 - 3	Is hearing augmentation available in meeting rooms (seating 5 or more participants)	Hearing Augmentation	TBA				Sound amplification not defined at 60% Review

ROK033		09.00 Hearing Augmentation						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
09.01	APS – D3.7 (1) (2) (3)	If a sound amplification system is installed / inbuilt is there a hearing augmentation system that covers 80% of the total enclosed space if an induction loop is inbuilt, or 95% if a receiver system in use.	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.02	APS – D3.7 (1) (2) (3)	Is hearing augmentation available at any screened / enclosed reception area / ticket or tellers cash booth (that has an inbuilt amplification system).	Screened Booth				NA	No Screened booth designed.
09.02	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Signage	TBA				Signage not defined at 60% Review
09.03	APS – D3.6 (b) (ii) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, indicate which type of system is in place.	Signage	TBA				Signage not defined at 60% Review
09.04	APS D3.6 (b) (iii)	If receivers are being used, does the signage indicate where the receivers can be obtained.	Signage	TBA				Signage not defined at 60% Review
09.05	APS – D3.7 (4)	If a screen or scoreboard is capable of displaying public announcements, is it capable of supplementing any public address system (other than a system used for emergency warning purposes only).	Signage	TBA				Signage not defined at 60% Review
09.06	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl 5.2.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Signage	TBA				Signage not defined at 60% Review
Universal Accessibility Options: not mandatory								
09.07	AS 1428.5 - 3	Is hearing augmentation available in meeting rooms (seating 5 or more participants).	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.08	AS 1428.5 - 3	Is hearing augmentation available in any lift to assist with communication in an emergency.	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.09		Is appropriate seating with backs and armrests available that provides good lines of sight for lip reading.	Seating lines of sight	TBA				Tiered seating not defined at 60% Review
09.10		Are there acoustic design elements to reduce noise e.g. rubber tips on furniture legs, soft furnishings, low pile carpet, double glazing, quiet equipment etc.	Acoustic Design Elements	TBA				Finishes not defined at 60% Review
09.11	AS 1428.5 - 3	Are there visible alarms at any security checkpoint.	Alarms	TBA				Security not defined at 60% Review
09.12		Are there visible emergency alarms throughout the building.	Alarms	TBA				Security not defined at 60% Review
09.13		Is there effective lighting for lip reading and sign language interpreters.	Lighting	TBA				Luminance not defined at 60% Review

ROK033		10.00 Contrasts						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
10.01	AS 1428.1 Cl. 10.1	Doorways / frames / walls etc	Door Contrast	TBA				Finishes not defined at 60% Review
10.02	AS 1428.1 Cl. 3.6	Glass doors (solid, non-transparent contrasting strip across full width of glass and side partitions)	Glass Doors	TBA				Door Material not defined at 60% Review
10.03	APS – D3.8 1 (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Ramps (TGSIs at top and bottom - as required)	Ramp TGSI	TBA				TGSI detail not defined at 60% Review
10.04	APS – D4.5	Signs	Signage	TBA				Signage not defined at 60% Review
10.05	APS – D3.8 1 (a) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Stairs (TGSIs at top and bottom – as required)	Stair TGSI	TBA				Stair detail not defined at 60% Review
10.06	AS 1428.1 Cl. 8.1 (f) (g)	Stair nosing strips	Stair Detailing	TBA				Stair detail not defined at 60% Review
10.07	AS 1428.1 – 2021 Cl. 12.2.3 (e)	Toilet seats and cisterns	Sanitary Ware	TBA				Sanitary ware not defined at 60% Review

ROK033		11.00 Floor / Ground Surfaces						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
11.01	AS 1428.1 Cl. 4.1	Is the ground / floor surface firm and level (e.g. with no sharp transitions at abutting surfaces).	Firm Level Surface	TBA				Floor Finishes not defined at 60% Review
11.02	AS 1428.1 Cl. 4.1	Is the floor / ground surface slip resistant (in wet and dry conditions) allowing traction for a person using a wheelchair and people with ambulant or sensory disability.	Slip Resistant	TBA				Floor Finishes not defined at 60% Review
11.03	AS 1428.1 Cl 4.3	If carpeted, is it short pile (<11mm and backing <4mm) and securely attached to the floor surface.	Carpet	TBA				Floor Finishes not defined at 60% Review
11.04	AS 1428.1 Cl 4.5	If timber decking boards are installed and are no greater than 150mm wide, is there a maximum 6mm gap between boards.	Timber Decking	TBA				Floor Finishes not defined at 60% Review
11.05	AS 1428.1 Cl 4.5	If timber decking boards are installed that are over 150mm wide, is there a maximum gap of 10mm between boards, and if the gap is over 8mm do the boards run transverse to the direction of travel	Timber Decking	TBA				Floor Finishes not defined at 60% Review
11.06	AS 1428.1 Cl 4.5	If timber decking boards are installed, are adjacent boards level with a maximum vertical 3mm tolerance	Timber Decking	TBA				Floor Finishes not defined at 60% Review
Universal Accessibility Options: not mandatory								
11.07		Does the floor / ground surface have effective contrasts to walls and doors / doorframes	Contrast	TBA				Floor and Wall Finishes not defined at 60% Review.

ROK03312.00 Emergency Egress / Evacuation								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Universal Accessibility Options: not mandatory								
12.01		Is there an accessible (e.g. appropriate door handle, clear door opening width, opening force) emergency exit in addition to the main entry	Accessible Emergency Exit	TBA				Emergency Door Material, Hardware, Width etc not defined at 60% Review
12.02		Is there clear, visible, accessible signage on emergency exits	Signage for Exit	TBA				Signage not defined at 60% Review
12.03		Is there a continuous accessible path of travel from the building to any nominated assembly area (e.g. firm path, no steps, stairs, well lit)	CAPT to Assemebly	TBA				Emergency Alarms not defined at 60% Review
12.04		Are audible emergency alarms provided in the building	Alarms	TBA				Emergency Alarms not defined at 60% Review
12.05		Are visible emergency alarms provided in the building	Alarms	TBA				Refuge place not defined at 60% Review
12.06		Are there places of refuge provided for people with mobility difficulties on levels above the main entrance level	Refuge on Level 1	TBA				Refuge place not defined at 60% Review
12.07		Are audible security alarms provided at any security checkpoints	Alarms	TBA				Security Alarms not defined at 60% Review
12.08		Are visible security alarms provided at any security checkpoints	Alarms	TBA				Security Alarms not defined at 60% Review
12.09		Are any fire hoses and extinguishers located at 700 – 1200mm high	Fire Extinguishers	TBA				Fire Strategy not defined at 60% Review
12.10		Is the emergency management plan located at an accessible height in a public area in an accessible format (e.g. large print, tactile, Braille)	Emergency Management Plan	TBA				Emergency Management Plan not defined at 60% Review

ROK033		17.00 Stairs						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
17.01	APS – 3.3 (f) 4.4 / D3.1 / D3.2 / D3.3 / E3.6	Is there an accessible alternative route close to the stairs (e.g. ramp, lift) (where required – see Concessions in Premises Standards)	Accessible Alternative Route close to stairs		Y			Accessible routes within 50 metres of stairs.
17.02	AS 1428.1 Cl. 8.1 (a) (b) / 9	If the stairs abut an internal corridor / external boundary, are they setback to allow a min. of one tread width plus 300mm internally / min. 900mm externally	Setback		Y			There is no indication that setback is not designed at 60% Review.
17.03	APS – D3.8 1 (a) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Are there appropriate TGSIs (hazard – extending the width of path, luminance, depth) at the top and bottom of the stairs.	TGSI	TBA				TGSIs are not defined at 60% Review
17.04	AS 1428.1 Cl. 11 / AS 1428.4.1 Cl. 2.3 / 2.4	If a non enclosed landing is provided on the stairs, are TGSIs installed as required.	TGSI	TBA				TGSIs are not defined at 60% Review
17.05	AS 1428.4.1 – Cl. 2.4	If the distance of the landing is 3000mm or more to the nearest nosing edge, are the warning indicators spread over a distance of 600 – 800mm.	TGSI	TBA				TGSIs are not defined at 60% Review
17.06	AS 1428.1 Cl. 4.1	Do the stairs have a slip resistant surface.	Slip Resistance	TBA				Finishes are not defined at 60% Review
17.07	AS 1428.1 Cl. 8.1 (c)	Are all of the step risers enclosed and of opaque construction.	Step Risers	TBA				Step Risers material not defined at 60% Review
17.08	AS 1428.1 Cl. 8.1 (f) (g)	Do front edges of stairs nosing have a single strip of continuous colour not less than 50mm and not more than 75mm with a min. 30% luminance contrast (full width of path of travel) (can be set back 15mm) (must not project beyond the face of the riser and not extend more than 10mm down the riser when provided with a contrast and not set back from nosing).	Nosing Strips	TBA				Nosing Strips not defined at 60% Review
17.09	AS 1428.1 Cl. 11.1 (d)	Are the stair nosings level with the face of the riser (riser may be vertical or max. splay backward up to 25mm)	Nosing Strips	TBA				Nosing Strips not defined at 60% Review
17.10	AS 1428.1 Cl. 8.1 (e)	Are the profile of the nosings provided with a sharp transition; rounded up to 5mm radius or chamfered up to 5mm x 5mm.	Nosing	TBA				Profile of Nosing not defined at 60% Review
17.11	APS – D3.8 (3) / 1428.4.1 Cl. 2.2 / 2.3 / 2.4	On a continuous flight of stairs (within an aged care facility), is there a domed button 4 - 5mm high x 10 - 12mm diameter if handrails are not continuous on stair flights and around landings. (on top 150mm from end of rail),					NA	Not an Aged Care Facility
17.12	AS 1428.1 Cl. 8.2	Are appropriate handrails provided on two sides of the stairs (Note: if a balustrade is required at a height greater than the handrail, both shall be provided).	Handrail	TBA				Handrails not defined at 60% Review
17.13	AS 1428.1 Cl. 8.2 / 9 (j)	Are handrails continuous throughout the stair flight, and where practicable on landings.	Handrail	TBA				Handrails not defined at 60% Review
17.14	AS 1428.1 Cl. 8.2 (d) (e) (f)	Do the handrails extend at least one tread width plus 300mm past the edge of the bottom step, and a min of 300mm at the top step (Note: refer AS requirement at intermediate landings).	Handrail	TBA				Handrails not defined at 60% Review
17.15	AS 1428.1 Cl. 8 / 9 (h) (i)	Do the handrails have a min. clearance of 50mm from an adjacent wall and min. 600mm clearance above.	Handrail	TBA				Handrails not defined at 60% Review
17.16	AS 1428.1 Cl. 8 / 9 (i)	Are handrails constructed and fixed, ensuring no obstruction to the passage of the hand along the entire handrail.	Handrail	TBA				Handrails not defined at 60% Review
17.17	AS 1428.1 Cl. 9 (d) (e)	Is the handrail height consistent at a measurement between 865 – 1000mm above the stair nosing (throughout the stairs and on any landing) Construction tolerance of 10mm allowable and Height of handrail may vary at stairway handrail extension or where handrail transitions between flights or to a balustrade).	Handrail	TBA				Handrails not defined at 60% Review
17.18	AS 1428.1 Cl. 9 (b)	Do the handrails have a circular diameter of 30 – 52mm for a min. of 270°.	Handrail	TBA				Handrails not defined at 60% Review
17.19	AS 1428.1 Cl. 8.2 (c)	Do the handrails follow the angle of the nosings.	Handrail	TBA				Handrails not defined at 60% Review
17.20	AS 1428.1 Cl. 9 (c)	Are exposed edges and corners of handrails provided with a radius of not less than 5mm.	Handrail	TBA				Handrails not defined at 60% Review
17.21	AS 1428.1 Cl. 8. 2 (b)	Is there a min. clearance of 1000mm between handrails.	Handrail	TBA				Handrails not defined at 60% Review
17.22	AS 1428.1 Cl. 9 (g)	Are the handrails securely fixed, with ends returned to a side wall / post or turned through 180°.	Handrail	TBA				Handrails not defined at 60% Review
17.23	AS 1428.1 Cl. 9 (a)	Do the handrails (and balustrades) sit outside of required circulation spaces.	Handrail	TBA				Handrails not defined at 60% Review
Universal Accessibility Options: not mandatory								
17.24		Are the tread heights between 150 – 165mm high AS 1428.2 – Cl. 13.2	Tread Heights	TBA				Tread Heights not defined at 60% Review
17.25		Are the treads a min. of 275 – 300mm deep AS 1428.2 – Cl. 13.2	Tread depth	TBA				Tread Depths not defined at 60% Review
17.26		Is there appropriate, uniform lighting of the stairs for night time use	Lighting	TBA				Lighting not defined at 60% Review
17.27		Are the handrails of non-reflective material and a contrasting colour to the background	Handrail Materials	TBA				Handrails not defined at 60% Review

ROK033	18.00 Tactile Ground Surface Indicators							
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
18.01	AS 1428.4.1 Cl. 2.5	Are there appropriate hazard tactile ground surface indicators (TGSIs) prior to a hazard (e.g. roadway) i.e. (width x 600 – 800mm, setback 300mm ± 10mm).	Appropriate TGSi	TBA				TGSIs not defined at 60% Review
18.02	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3 / 2.5	Are appropriately installed TGSIs provided at existing defined pedestrian crossing point/s with a level transition over a vehicular traffic way on the pathway(width x 600 – 800mm setback 300mm ± 10mm).	Pedestrian Crossing TGSi				NA	
18.03	AS 1428.4.1 Cl. 2.2 / 2.3 / 2.5	Are appropriate installed TGSIs provided at existing defined vehicle drop off areas, with blended kerbs and a level transition, if provided on the pathway (width x 600 – 800mm setback 300mm ± 10mm).	Vehicle dropoff TGSi				NA	
18.04	APS – D3.8 1 (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Are there appropriate TGSIs (hazard – extending the width of path, luminance, depth) at the top and bottom of a ramp (as required).	Ramp TGSi	TBA				TGSIs not defined at 60% Review
18.06	AS 1428.1 Cl. 11 / AS 1428.4.1 Cl. 2.3 / 2.4	If a non enclosed landing is provided on the stairs, are TGSIs installed as appropriate.	Non-enclosed landing TGSi	TBA				TGSIs not defined at 60% Review
18.07	AS 1428.4.1 Cl. 2.4	If the distance of the landing is 3000mm or more to the nearest nosing edge, are the warning indicators spread over a distance of 600 – 800mm.	Landing TGSi	TBA				TGSIs not defined at 60% Review
18.08	APS – D3.8 / AS 1428.4.1 Cl. 2.6	If there is an overhead obstruction less than 2000mm (other than a doorway) are appropriate TGSIs installed (in the absence of any other barrier) (e.g. undercroft of stairs) (NOTE: an alternative type of barrier is preferred).	Overhead Obstruction TGSi		Y			No Overhead Obstructions identified at 60% Review
18.09	AS 1428.4.1 Cl. 2.3.3 (b)	Are the warning indicators installed at right angles to path of travel on pathways.	Warning Indicators	TBA				Warning Indicators not defined at 60% Review
18.10	AS 1428.4.1 Cl. 2.3.3 (c) / 3.4 / 3.5	Are there warning indicators installed along edges of hazardous areas e.g. train platforms, wharves, level roadway crossing points etc.	Warning Indicators	TBA				Warning Indicators not defined at 60% Review
18.11	AS 1428.4.1 Cl. 2.2 / App. E	Are TGSIs installed with appropriate contrasts to background surfaces.	TGSi Contrast	TBA				TGSIs not defined at 60% Review
18.12	AS 1428.4.1 Cl. 2.3	Are the TGSIs installed to ensure no tripping hazard is produced.	No Tripping Hazards	TBA				TGSIs not defined at 60% Review
Universal Accessibility Options: not mandatory								
18.13	AS 1428.4.1 Cl. 3.1 (c) (i)	Are there appropriate directional TGSIs on any pathway adjacent where a kerb ramp is at a mid block section or not on a direct path of travel.	Directional TGSi					TGSIs not defined at 60% Review
18.14	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3	Are TGSIs provided at changes in direction on the pathway to the PPE.	Directional TGSi					TGSIs not defined at 60% Review
18.15	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3	Are warning TGSIs (hazard) provided at changes in direction of directional indicators on the pathway to the PPE.	Warning TGSi					TGSIs not defined at 60% Review
18.16		Are there any appropriate TGSIs (hazard) indicators prior to the existing kerb ramps on the pathway (width x 600 – 800mm, setback 300mm ± 10mm).	Kerb Ramps				NA	
18.17	AS 1428.4.1 App. D	Are there directional indicators installed to provide direction to elements e.g. bus stops, kerb ramps, street furniture, toilets, train platforms, road crossings etc.	External Kerb Ramps				NA	
18.18	AS 1428.4.1 App. A 3.1	Are TGSIs used with consistent application throughout an area.	TGSi	TBA				Existing Condition of TGSi not indicated at 60% Review
18.19		Are the TGSIs well maintained.	TGSi	TBA				Existing Condition of TGSi not indicated at 60% Review
18.20		Are the TGSIs used to promote pedestrian safety.	TGSi	TBA				Existing Condition of TGSi not indicated at 60% Review

ROK033		20.00 Signage						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
20.01	APS – DP1 (b) / AS 1428.1 CL 5.1	Is appropriate signage available where directional decisions are made.	Directional Signage	TBA				Signage not defined at 60% Review
20.02	APS – D3.6 (e) / D4 / AS 1428.1 Cl. 5.1	If there is a non accessible entrance doorway, is there appropriate signage provided directing users to accessible entrance.	Non-Accessible Access Signage	TBA				Signage not defined at 60% Review
20.03	APS – D3.6 / D4 / AS 1428.1 Cl. 5.2	Where the symbol for access is used, does it comply with the international standard in style, colour and layout.	Symbol for Access	TBA				Signage not defined at 60% Review
20.04	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Symbol for Deafness	TBA				Signage not defined at 60% Review
20.05	APS – D3.6 (b) (ii) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2	Does signage including the international symbol of deafness, indicate which type of system is in place.	Symbol for Deafness	TBA				Signage not defined at 60% Review
20.06	APS D3.6 (b) (iii)	If receivers are being used for hearing augmentation, does the signage indicate where the receivers can be obtained.	Hearing Augmentation Signage	TBA				Signage not defined at 60% Review
20.07	APS – D3.6 (b) / D4 / AS 1428.1 CL 5.1	Is raised tactile information provided on signs between 1200 – 1600mm.	Signage Raised Text	TBA				Signage not defined at 60% Review
20.08	APS – D4.5	Is there appropriate illumination of signage for day and night use (where required e.g. to maintain luminance).	Illumination	TBA				Signage not defined at 60% Review
20.09	APS – D3.6 (f) / D4	If there is a non-accessible toilet provided, is there signage available that directs users to an accessible toilet (where in different locations).	Signage to Accessible toilet at non-accessible toilet	TBA				Signage not defined at 60% Review
20.10	APS – D3.6 (c) / D4 / AS 1428.1 Cl 5.1	Does the signage indicate if the accessible toilet facility is suitable for left or right hand.	L or R Hand Accessible Facility	TBA				Signage not defined at 60% Review
20.11	APS – D4.3 (2); Title Case AS 1428.1 C 5.1	If available on the sign, is the text provided in Title Case.	Signage - Title Case	TBA				Signage not defined at 60% Review
20.12	APS-D3.6 (a) / AS 1428.1 Cl 5.1	Is there signage (incorporating raised text and Braille, and raised and visual symbols) installed identifying available sanitary facilities.	Signage to All Toilets	TBA				Signage not defined at 60% Review
20.13	APS – D3.6 (d) / AS 1428.1 Cl. 5.1	If there is an ambulant toilet, is appropriate signage installed at the airlock serving the area that contains the facilities identifying the facilities within.	Signage Ambulant Toilet	TBA				Signage not defined at 60% Review
20.14	APS – D3.6 (d) / AS 1428.1 Cl. 5.1	If there is an ambulant toilet, is there signage to identify the facility (Note: may be located on door if required).	Signage Ambulant Toilet	TBA				Signage not defined at 60% Review
Universal Accessibility Options: not mandatory								
20.15		Is signage (including tactile and Braille) located at the main building entry, both inside and out, giving directional and general information about buildings and facilities including services and access for people with disabilities.	Signage	TBA				Signage not defined at 60% Review

ROK034 01.00 Entrances								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
1.01	APS – D3.2 (2) (a)	If there is more than one pedestrian entrance, are 50% of them accessible (including the principal pedestrian entrance)	Entrance	TBA				Question to design team - see markup
1.02	APS – D3.2 (2) (b)	If the building is more than 500m² is any non accessible entry within 50m from an accessible entry.	Accessible Entry within 50m of Non-Accessible Entry				NA	Not greater than 500m2
1.03	APS – D3.6 (e) Cl. 5.1	If there is a non accessible entrance doorway, is there appropriate signage provided (int. Symbol, direction arrow) directing users to an accessible entrance.	Non-Accessible Door Signage	TBA				Signage not designed at 60% Review
1.04	APS – D3.2 (3) (a) (4) fig D3.2	If the pedestrian entrance is required to be accessible and consists of not more than 3 doorways, is not less than one doorway accessible.	Less than 3 doorways	TBA				Doors not defined at 60% Review
1.05	AS 1428.1 Cl. 10.4.3 / AS 1428.2 Cl. 28	If there are security entry controls (card / buttons / intercom) are these at 900 – 1100mm-grasped/turned, 900-1200mm-pushed, 900-1250mm (not less than 500mm from corner)-touched, (ticket slot 800 – 900mm), and easy to operate.	Security door controls	TBA				Door hardware and security not defined at 60% Review
1.06	APS - A1.1	If there is a revolving door / turnstile, is there an alternative accessible hinged / sliding door	Revolving Door				NA	Door hardware not defined at 60% Review
1.07	AS 1428.1 Cl. 10.4.2	Can the door be unlocked and opened by one hand (i.e. D or D lever handles).	Door Handle	TBA				Door hardware not defined at 60% Review
1.08	AS 1428.1 Cl. 10.4.2 (b)	Is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handle	TBA				Door hardware not defined at 60% Review
1.09	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles, snibs, locks) that need to be grasped or turned located between 900 – 1100mm high.	Door Controls	TBA				Door hardware not defined at 60% Review
1.10	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed located between 900 – 1200mm high.	Door Controls	TBA				Door hardware not defined at 60% Review
1.11	AS 1735.12 AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched located between 900 – 1250mm high and not less than 500mm from an internal corner except as specified in AS 1735.12 AS 1428.1 Cl. 10.4.3 (c)	Door Controls	TBA				Door hardware not defined at 60% Review
1.12	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handle	TBA				Door hardware not defined at 60% Review
1.13	AS 1428.1 Cl. 10.4.2 (f)	If an outward opening door is not self closing, is there a horizontal handrail or pull bar installed at a height between 900 – 1100mm (min. 50mm clearance from edge of door / door handle) on the inside of the door.	Door Handle	TBA				Door hardware not defined at 60% Review
1.14	AS 1428.1 Cl. 10.4.4	If doors are power operated, are the push button controls a min. of 25mm dia., proud of the surface (activating door before the button becomes level with surrounding surface).	Power operated door	TBA				Door hardware not defined at 60% Review
1.15	AS 1428.1 Cl. 10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 500 – 1000mm from arch of the hinged door leaf (in any position) / or clear of a surface-mounted sliding door in the open position.	Power operated door	TBA				Door hardware not defined at 60% Review
1.16	AS 1428.1 Cl. 3.6	If the doors / sidelights are frameless or fully glazed, are they clearly marked for safety and ease of identification across the full door width, with a solid and non-transparent contrasting line (viewable from 2m inside and outside) (luminance 30%). Size of line not less than 75mm high, with the lower edge at a height of 900 – 1000mm above finished floor level.	Door Material	TBA				Door hardware not defined at 60% Review
1.17	AS 1428.1 Cl. 10.1	Do all the doors or doorframes have a min. luminance contrast of 30% to their adjacent surfaces.	Door Frame Contrast	TBA				Door hardware not defined at 60% Review
1.18	AS 1428.1 Cl. 10.4.2 (e)	Is the entrance door easy, to initially open, (no heavy closer or spring) 20N max. (4.3lbf)	Door Pressure	TBA				Door closers not defined at 60% Review
1.19	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	Is the min. clear opening of a doorway at the PPE 850mm or greater.	Min clear opening	TBA				Doors or gates to the entrance not defined at 60% Review
1.20	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	If the doorway has 2 independent operated leaves, is the open doorway a min. of 850mm wide.	2 leaves	TBA				Door leaf size not defined at 60% Review
1.21	AS 1428.1 Cl. 7.5 / 7.5	Is the door threshold level or is there an appropriate threshold ramp available at the entry (i.e. no step, inappropriate mat, weather strip etc.)	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.22	AS 1428.1 Cl. 7.5	If there is a threshold (max. rise 35mm) at the entrance or doorway (not more than 20mm from door leaf it serves), is there a ramp of not more than 280mm in length and min. ratio of 1:8. (Note: if the rise is greater a step ramp will be required).	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.23	AS 1428.1 Cl. 7.5	If the threshold ramp does not abut a wall or kerb, are sides tapered or splayed (min. 45°)	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.24	AS 1428.1 Cl. 4.2	If there is a recessed mat within the CAPT is the abutment of the surfaces no more than 3mm if vertical or 5mm if bevelled (rounded).	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.25	AS 1428.1 Cl. 4.3.1	If there is a carpet leading edge at the entrance is there a vertical face no higher than 3mm or a rounded bevelled edge no higher than 5mm or above that height a gradient of 1:8 up to a total max. height of 10mm.	Carpet	TBA				Door thresholds not defined at 60% Review
1.26	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space outside the entrance doorway (not steeper that 1:40) (Doorway circulations spaces may overlap other circulation spaces).	Circulation Space outside		YES			There appears to be no issue with wheelchair circulation space inside any doors on drawing CQU-ROK-034-G-ARC03-06
1.27	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space inside the entrance doorway (not steeper that 1:40) (Doorway circulations spaces may overlap other circulation spaces).	Circulation Space inside		YES			There appears to be no issue with wheelchair circulation space outside any doors on drawing CQU-ROK-034-G-ARC03-06
1.28	AS 1428.1 Cl. 10.3.5	If there is an airlock, vestibule, or enclosed space, is there not less than 1450mm between the doorway (plus the door leaf width if the door encroaches into the space).	Airlock				NA	No Airlock defined at 60% Review
1.29	AS 1428.1 Cl. 3.7	If there are glazed viewing panels in doors, is the lower edge of the glazing not more than 1000mm above FFL, upper edge not less than 1600mm above FFL.	Glazed Viewing Panels	TBA				Door leaf + viewing panels not defined at 60% Review
1.30	AS 1428.1 Cl. 3.7	If there are glazed viewing panels in doors, is the width of the glazing within 200mm from latch edge of the door and min 150mm wide.	Glazed Viewing Panels	TBA				Door leaf + viewing panels not defined at 60% Review
Universal Accessibility Options: not mandatory								
1.37	AS 1428.2 Cl. 23.3 (b)	Are the door handles provided with an appropriate luminance contrast	Door Handles	TBA				Door hardware not defined at 60% Review
1.38		Do automatic self-opening doors have effective motion, and presence sensors installed	Automatic Doors	TBA				Door Control not defined at 60% Review

ROK034 01.00 Entrances								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
1.39		If there is an alarm control pad, is it located at a height between 900 – 1200mm high, accessible and easy to operate	Door Control	TBA				Door hardware not defined at 60% Review
1.40		If there is a doorbell, is it accessible and easy to operate, located at a height between 900 – 1200mm	Doorbell				NA	Door hardware not defined at 60% Review
1.41		Is there appropriate lighting at the PPE	Lighting	TBA				Lighting not defined at 60% Review

ROK034 03.00 Internal Accessways

Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
3.01	AS 1428.1 Cl. 3.3	Does the accessway have a min. width of 1000mm i.e. structurally and maintained to remain clear of temporary obstructions e.g. pot plants, bins.	Min Width			N		See Markup in Appendix A
3.02	AS 1428.1 Cl. 3.2	Does the full length of the accessway have an overhead clearance of 2000mm (1980mm allowed at doorway)	Overhead Clearance		Y			There is no evidence that the accessway would not have an overhead clearance of 2m at 60% Review
3.03	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.4	Do accessways provide a passing space where a direct line of sight is not available to the end of the walkway (max. 20m intervals) (min. 1800mm wide x 2000mm long)	Turn Circle		Y			All Accessways have direct line of sight to the end. Accessways also have turning circles at each end.
3.04	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.5	Do accessways provide a turning space near the end of the walkway where it is not possible to continue (within 2m of end)	Turn Circle		Y			Accessways appear to have turning circles at each end.
3.05	AS 1428.1 Cl. 3.5	If a change of direction is required, is there appropriate circulation space provided along the accessway for the angle of the turn.	Circulation		Y			No evidence of inadequate circulation space
3.06	AS 1428.1 Cl. 4.1	Does the accessway have a slip-resistant surface with a texture that is traversable by a wheelchair.	Slip Resistant	TBA				Surface for accessway not designed at 60% Review
3.07	APS – D3.6 (e) AS 1428.1 CL 5	If there is a non-accessible entrance doorway, is there appropriate signage provided (int. Symbol, direction arrow) directing users to an accessible entrance	Signage	TBA				Signage not designed at 60% Review
3.08	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	Is the min. clear opening of a doorway on any accessway 850mm or greater.	Min Clear open		Y			No evidence of doorways that are less than 850mm
3.09	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space outside the doorway (NOTE: 1:40 grade, additional considerations at surface mounted sliding doors) (Doorway circulation space may overlap other circulation spaces)	Circulation		Y			No evidence of inappropriate circulation spaces outside each doorway. To be checked again at 60%
3.10	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space inside the doorway (NOTE: 1:40 grade, additional considerations at surface mounted sliding doors) (Doorway circulation space may overlap other circulation spaces)	Circulation		Y			No evidence of inappropriate circulation spaces inside each doorway. To be checked again at 60%
3.11	AS 1428.1 Cl. 10.4.2 (a)	Can the door be unlocked and opened by one hand (i.e. D or D lever handles)	Door Handles	TBA				Door hardware not designed at 60% Review
3.12	AS 1428.1 Cl. 10.4.2 (b)	Is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handles	TBA				Door hardware not designed at 60% Review
3.13	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles) that need to be grasped or turned between 900 – 1100mm high.	Door Handles	TBA				Door hardware not designed at 60% Review
3.14	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed between 900 – 1200mm high.	Door Handles	TBA				Door hardware not designed at 60% Review
3.15	AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched between 900 – 1250mm high (and not less than 500mm from an internal corner, except as specified in AS 1735.12)	Door Handles	TBA				Door hardware not designed at 60% Review
3.16	AS 1428.1 Cl.10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 1000 – 2000mm from the hinged swing door leaf (in any position) / or doorway of sliding door.	Power Door	TBA				Doors that are power operated not designed at 60% Review
3.17	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handles	TBA				Door hardware not designed at 60% Review
3.18	AS 1428.1 Cl. 10.4.2 (e)	Are all doors (other than fire / smoke doors) provided with the appropriate opening force (20N).	Door Force	TBA				Door Force not designed at 60% Review
3.19	AS 1428.1 Cl. 10.3.5	If there is an airlock, vestibule, or enclosed space, is there not less than 1450mm between the doorway (plus the door leaf width if the door encroaches into the space).	Air Vestibule				NA	No airlocks designed at 60% Review
3.20	AS 1428.1 Cl. 10.4.2 (g)	If an outward opening door is not self closing, is there a horizontal handrail or pull bar installed at a height between 900 – 1100mm (min. 50mm clearance from edge of door / door handle) on the inside of the door.	Hoor Handles	TBA				Door hardware not designed at 60% Review
3.21	AS 1428.1 Cl 11.1	Are all switches and controls provided on a CAPT (other than general purpose outlets (GPOs)) located at a height of 900 – 1100mm and not less than 500mm from an internal corner.	Switches and Controls	TBA				Door hardware not designed at 60% Review

ROK034 07.00 Kitchens								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
07.01	AS 1428.1 Cl. 3	Is there a CAPT provided to the kitchen / bar / dining / laundry / canteen area.	CAPT		Y			No evidence of non compliance
07.02	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there a continuous internal accessible path of travel to any canteen window.	Canteen				NA	No canteen
07.03	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there a continuous external accessible path of travel to any external canteen / servery window.	Canteen				NA	no canteen window
07.04	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there appropriate circulation space within the kitchen area, to enable a user ease of use for all facilities.	Circulation Space		Y			No evidence of non compliance
Universal Accessibility Options: not mandatory								
07.05	AS 1428.2 Cl. 24	Does the counter have a wheelchair accessible section at a height between 830 – 870mm for a min. length of 900mm.	Counter			N		Counter does not have wheelchair section however tables are available.
07.06	AS 1428.2 Cl. 24	Does the counter have at the wheelchair accessible section, a leg clearance underneath at a height between 800 – 840mm for a min. length of 900mm.	Counter			N		Counter does not have wheelchair section however tables are available.
07.07	AS 1428.2- A5	Is the sink / basin accessible to people in wheelchairs (height 770 – 800mm).	Basin		Y			Both sinks have wheelchair clearance
07.08	AS 1428.2- A5	Is the sink / basin accessible to people in wheelchairs (leg clearance height underneath 640-650mm) with appropriate unobstructed circulation space.	Basin		Y			Both sinks have wheelchair clearance
07.09	AS 1428.2 Cl. 24	If there is a canteen / servery window does it have a wheelchair accessible section at a height between 830 – 870mm with a leg clearance underneath at a height of 800 – 840mm for a min. length of 900mm.	Canteen Window				NA	No canteen
07.10	AS 1428.2 Cl. 29	Are the operative components of any vending machine, for pre-packaged food and drink, accessible and between 700 – 1200mm high.	Vending Machine				NA	no vending machine detailed
07.11	AS 1428.2 Cl. 27.2	If seating is available, is it at a height of 450 – 520mm with armrests located at a height between 220 – 300mm above the seat and backs.	Seating	TBA				type of seating not detailed at 50%
07.12		If tea and coffee facilities are provided (other than vending machine), are the highest operable components located at a height between 900 – 1100mm.	Tea / Coffee	TBA				components will be on the bench which is set at 850mm.

ROK034 10.00 Contrasts								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
10.01	AS 1428.1 Cl. 10.1	Doorways / frames / walls etc	Door Contrast	TBA				Finishes not defined at 60% Review
10.02	AS 1428.1 Cl. 3.6	Glass doors (solid, non-transparent contrasting strip across full width of glass and side partitions)	Glass Doors	TBA				Door Material not defined at 60% Review
10.03	APS – D3.8 1 (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Ramps (TGSIs at top and bottom - as required)	Ramp TGSI	TBA				TGSI detail not defined at 60% Review
10.04	APS – D4.5	Signs	Signage	TBA				Signage not defined at 60% Review
10.05	APS – D3.8 1 (a) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Stairs (TGSIs at top and bottom – as required)	Stair TGSI				NA	No Stair
10.06	AS 1428.1 Cl. 8.1 (f) (g)	Stair nosing strips	Stair Detailing				NA	No Stair
10.07	AS 1428.1 – 2021 Cl. 12.2.3 (e)	Toilet seats and cisterns	Sanitary Ware				NA	No Sanitary
Universal Accessibility Options: not mandatory								
10.08		Emergency alarm buttons						
10.09		Equipment controls (fans, air conditioners, heaters etc)						
10.10		Exposed vertical building supports (posts, columns etc)						
10.11		Flushing controls on toilets						
10.12		Furniture and floors						
10.13		Grab and hand rails						
10.14		Kerb ramps						
10.15		Lift buttons						
10.16		Light switches						
10.17		Lips and edges						
10.18		Non reflective surfaces						
10.19		Seating						
10.20		Shower doors or curtains						
10.21		Taps						
10.22		Toilet roll holders						
10.23		Traffic calming devices						
10.24		Vehicle / pedestrian conflicts						
10.25		Vertical and horizontal connections e.g. floor and wall						
10.26		Window frames						
10.27		Window coverings						
10.28		All elements of non reflective material						
10.29		All elements glare free						
10.30		Bollards (e.g. contrasting strip close to the top)						
10.31		Counter tops (e.g. contrast between top and supporting surface)						
10.32		Cupboard and door handles						

ROK034 11.00 Floor / Ground Surfaces								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
11.01	AS 1428.1 Cl. 4.1	Is the ground / floor surface firm and level (e.g. with no sharp transitions at abutting surfaces).	Firm Level Surface	TBA				Floor Finishes not defined at 60% Review
11.02	AS 1428.1 Cl. 4.1	Is the floor / ground surface slip resistant (in wet and dry conditions) allowing traction for a person using a wheelchair and people with ambulant or sensory disability.	Slip Resistant	TBA				Floor Finishes not defined at 60% Review
11.03	AS 1428.1 Cl 4.3	If carpeted, is it short pile (<11mm and backing <4mm) and securely attached to the floor surface.	Carpet	TBA				Floor Finishes not defined at 60% Review
11.04	AS 1428.1 Cl 4.5	If timber decking boards are installed and are no greater than 150mm wide, is there a maximum 6mm gap between boards.	Timber Decking	TBA				Floor Finishes not defined at 60% Review
11.05	AS 1428.1 Cl 4.5	If timber decking boards are installed that are over 150mm wide, is there a maximum gap of 10mm between boards, and if the gap is over 8mm do the boards run transverse to the direction of travel	Timber Decking	TBA				Floor Finishes not defined at 60% Review
11.06	AS 1428.1 Cl 4.5	If timber decking boards are installed, are adjacent boards level with a maximum vertical 3mm tolerance	Timber Decking	TBA				Floor Finishes not defined at 60% Review
Universal Accessibility Options: not mandatory								
11.07		Does the floor / ground surface have effective contrasts to walls and doors / doorframes	Contrast					Floor and Wall Finishes not defined at 60% Review.

ROK034 12.00 Emergency Egress / Evacuation								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Universal Accessibility Options: not mandatory								
12.01		Is there an accessible (e.g. appropriate door handle, clear door opening width, opening force) emergency exit in addition to the main entry	Accessible Emergency Exit	TBA				Emergency Door Material, Hardware, Width etc not defined at 60% Review
12.02		Is there clear, visible, accessible signage on emergency exits	Signage for Exit	TBA				Signage not defined at 60% Review
12.03		Is there a continuous accessible path of travel from the building to any nominated assembly area (e.g. firm path, no steps, stairs, well lit)	CAPT to Assemebly	TBA				Emergency Alarms not defined at 60% Review
12.04		Are audible emergency alarms provided in the building	Alarms	TBA				Emergency Alarms not defined at 60% Review
12.05		Are visible emergency alarms provided in the building	Alarms	TBA				Refuge place not defined at 60% Review
12.06		Are there places of refuge provided for people with mobility difficulties on levels above the main entrance level	Refuge on Level 1	TBA				Refuge place not defined at 60% Review
12.07		Are audible security alarms provided at any security checkpoints	Alarms	TBA				Security Alarms not defined at 60% Review
12.08		Are visible security alarms provided at any security checkpoints	Alarms	TBA				Security Alarms not defined at 60% Review
12.09		Are any fire hoses and extinguishers located at 700 – 1200mm high	Fire Extinguishers	TBA				Fire Strategy not defined at 60% Review
12.10		Is the emergency management plan located at an accessible height in a public area in an accessible format (e.g. large print, tactile, Braille)	Emergency Management Plan	TBA				Emergency Management Plan not defined at 60% Review

ROK034 15.00 Landscaping								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Universal Accessibility Options: not mandatory								
15.01		Are pathways free from plant species that develop overhanging foliage, and / or leaves or drop seed pods, berries, leaf and bark litter	Foilage				NA	Existing Audit Requirement only
15.02		Are there landscape designs, materials, plants, etc., that contribute to pedestrian safety	Safety in Design	TBA				
15.03		Are any plantings used to provide orientation or direction cues for people with vision impairment e.g. distinctive scents, sounds, appearance or texture	Planting				NA	Existing Audit Requirement only
15.04		Are any planter boxes appropriately located clear of any pathway	Planting		Y			
15.05		Are any dense plantings maintained to provide a clear line of sight	Planting				NA	Existing Audit Requirement only

ROK034 16.00 Pathways (Accessways)								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
16.01	APS - D3.2	Does an accessible pathway lead users from the designated accessible parking bay to the building entrance.	From Parking Bay		Y			No evidence of non-compliance
16.02	APS - D3.2	Does an accessible pathway lead users from the allotment boundary to the building entrance.	Allotment Boundary		Y			No evidence of non-compliance
16.03	APS - D3.2	Does an accessible pathway lead users from any adjoining building required to be accessible (if linked by a pedestrian pathway).	Adjoining Building		Y			No evidence of non-compliance
16.04	AS 1428.1 Cl. 4.2	If there is an abutment of surfaces on the pathway, are they no greater than 3mm if the abutment is vertical, or 5mm if a bevelled edge.	Surface abutments		Y			No evidence of non-compliance
16.05	AS 1428.1 Cl. 4.2 Figure 7(A)	If raked joint pavers are used, is the abutment of surfaces appropriate.	Pavers	TBA				Existing and new surface treatments not detailed at this level at 60% Review.
16.06	AS 1428.1 Cl. 3.3	Are all accessways a min. width of 1000mm.	Min width 1000mm		Y			All accessways appear 1000mm wide
16.07	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.4	Do accessways provide a passing space where a direct line of sight is not available to the end of the walkway (max. 20m intervals) (min. 1800mm wide x 2000mm long).	Line of Sight				NA	
16.08	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.5	Do accessways provide a turning space near the end of the walkway where it is not possible to continue (within 2m of end).	Turning Space at end	TBA				Other end of accessway not detailed at 60% Review
16.09	AS 1428.1 Cl. 3.5	If a change of direction is required, is there appropriate circulation space provided along the accessway for the angle of the turn.	Change of direction				NA	
16.10	AS 1428.1 Cl. 3.2	Does the full length of the pathway have overhead clearance of 2000mm (1980mm allowed at doorway).	Overhead Clearance		Y			No evidence that overhead clearance is maintained
16.11	AS 1428.1 Cl. 4.1	Does the pathway have a slip-resistant surface with a texture that is traversable by a wheelchair or a person with ambulant or sensory disability.	Surface slip resistance	TBA				Existing and new surface treatments not detailed at this level at 60% Review.
16.12	AS 1428.1 Cl. 4.1	If a grate is installed on the accessway, are circular openings not greater than 13mm in diameter; or where slotted openings are in use are they not greater than 13mm width and 150mm long and oriented so that the long dimension is transverse to the direction of travel. If linear opening is less than 8mm wide – Where linear openings are less than 8mm wide, orientation is optional.	Grate	TBA				Existing and new surface treatments not detailed at this level at 60% Review.
16.13	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3 / 2.5	Are appropriately installed TGSIs provided at existing defined pedestrian crossing point/s with a level transition over a vehicular traffic way on the pathway (width x 600 – 800mm, setback 300mm ± 10mm)	TGSI	TBA				TGSI not detailed at 60% Review
16.14	AS 1428.4.1 Cl. 2.2 / 2.3 / 2.5	Are appropriate installed TGSIs provided at existing defined vehicle drop off areas, with blended kerbs and a level transition, if provided on the pathway (width x 600 – 800mm, setback 300mm ± 10mm)	TGSI	TBA				TGSI not detailed at 60% Review
16.15	AS 1428.1 Cl. 10.4	If there is a gate on the pathway, does it have handles and locks inside and outside that can be operated by one hand and are located at an accessible height (900 – 1100mm grasped or turned, 900 – 1200mm if pushed, 900 – 1250mm if touched)	Gate				NA	No gate detailed at 60% Review
16.16	APS – DP1 AS 1428.1 Cl. 7.1	Is there appropriate circulation space and a level landing at the entrance / childproof gate/s.	Childproof Gate				NA	Not childcare centre
16.17	AS 1428.1 Cl 7.2	Is the floor or ground surface abutting the sides of the accessway, firm and level and of a different material to that of the accessway, at the same level as the accessway and extend horizontally for a min of 600mm (unless there is a kerb, a wall, fence, a balustrade or similar barrier).	Floor Treatments abutment	TBA				Existing and new surface treatments not detailed at this level at 60% Review.
16.18	AS148.2 Cl 7.2	Are appropriate landings provided on accessways (walkways).	landings		Y			No evidence that overhead clearance is maintained
Universal Accessibility Options: not mandatory								
16.19	AS 1428.2 Cl. 27.1 (b)	Do objects on the accessway, such as seats, tables, drinking fountains, bins etc have a luminance contrast (intensity of light reflected) of not less than 0.3 (30%) to background or surrounding surfaces.						
16.20		Are the edges of the pathways in colour contrast to their background (e.g. colour strip or grass on same ground surface)						
16.21	AS 1428.2 Cl. 27.1 (a)	Is seating at a height between 450 – 520mm with armrests between 220 – 300mm above the seat with a back provided along the pathway (min. every 60m) (set back a min. of 500mm).						
16.22		Is there uniform appropriate lighting of the pathways for nighttime use.						
16.23	AS 1428.4.1 Cl. 3.2 / 3.3	Are warning TGSIs (hazard) provided at changes in direction of directional indicators on the pathway.						
16.24		If there is a childproof gate, does it have an accessible doorbell or intercom system, located at a height between 900 – 1200mm, which can be heard from inside the premises						
16.25		If the entrance / childproof gate is located within a continual height fence, is it highlighted to assist recognition by a child or a person with vision impairment						

ROK034 17.00 Stairs								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
17.01	APS – 3.3 (f) 4.4 / D3.1 / D3.2 / D3.3 / E3.6	Is there an accessible alternative route close to the stairs (e.g. ramp, lift) (where required – see Concessions in Premises Standards)	Accessible Alternative Route close to stairs		Y			Ramp Adjacent
17.02	AS 1428.1 Cl. 8.1 (a) (b) / 9	If the stairs abut an internal corridor / external boundary, are they setback to allow a min. of one tread width plus 300mm internally / min. 900mm externally	Setback				NA	Not abutting internal corridor - check boundary
17.03	APS – D3.8 1 (a) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Are there appropriate TGSIs (hazard – extending the width of path, luminance, depth) at the top and bottom of the stairs.	TGSI	TBA				TGSI existing or proposed not defined at 60% Review
17.04	AS 1428.1 Cl. 11 / AS 1428.4.1 Cl. 2.3 / 2.4	If a non enclosed landing is provided on the stairs, are TGSIs installed as required.	TGSI	TBA				TGSI existing or proposed not defined at 60% Review
17.05	AS 1428.4.1 – Cl. 2.4	If the distance of the landing is 3000mm or more to the nearest nosing edge, are the warning indicators spread over a distance of 600 – 800mm.	TGSI	TBA				TGSI existing or proposed not defined at 60% Review
17.06	AS 1428.1 Cl. 4.1	Do the stairs have a slip resistant surface.	Slip Resistance	TBA				Floor finish not defined at 60% Review
17.07	AS 1428.1 Cl. 8.1 (c)	Are all of the step risers enclosed and of opaque construction.	Step Risers	TBA				Step risers not defined at 60% Review
17.08	AS 1428.1 Cl. 8.1 (f) (g)	Do front edges of stairs nosing have a single strip of continuous colour not less than 50mm and not more than 75mm with a min. 30% luminance contrast (full width of path of travel) (can be set back 15mm) (must not project beyond the face of the riser and not extend more than 10mm down the riser when provided with a contrast and not set back from nosing).	Nosing Strips	TBA				Nosing Strips not defined at 60% Review
17.09	AS 1428.1 Cl. 11.1 (d)	Are the stair nosings level with the face of the riser (riser may be vertical or max. splay backward up to 25mm)	Nosing Strips	TBA				Nosing Strips not defined at 60% Review
17.10	AS 1428.1 Cl. 8.1 (e)	Are the profile of the nosings provided with a sharp transition; rounded up to 5mm radius or chamfered up to 5mm x 5mm.	Nosing	TBA				Profile of Nosing not defined at 60% Review
17.11	APS – D3.8 (3) / 1428.4.1 Cl. 2.2 / 2.3 / 2.4	On a continuous flight of stairs (within an aged care facility), is there a domed button 4 - 5mm high x 10 - 12mm diameter if handrails are not continuous on stair flights and around landings. (on top 150mm from end of rail),					NA	Not an Aged Care Facility
17.12	AS 1428.1 Cl. 8.2	Are appropriate handrails provided on two sides of the stairs (Note: if a balustrade is required at a height greater than the handrail, both shall be provided).	Handrail	TBA				Handrails not defined at 60% Review
17.13	AS 1428.1 Cl. 8.2 / 9 (j)	Are handrails continuous throughout the stair flight, and where practicable on landings.	Handrail	TBA				Handrails not defined at 60% Review
17.14	AS 1428.1 Cl. 8.2 (d) (e) (f)	Do the handrails extend at least one tread width plus 300mm past the edge of the bottom step, and a min of 300mm at the top step (Note: refer AS requirement at intermediate landings).	Handrail	TBA				Handrails not defined at 60% Review
17.15	AS 1428.1 Cl. 8 / 9 (h) (i)	Do the handrails have a min. clearance of 50mm from an adjacent wall and min. 600mm clearance above.	Handrail	TBA				Handrails not defined at 60% Review
17.16	AS 1428.1 Cl. 8 / 9 (i)	Are handrails constructed and fixed, ensuring no obstruction to the passage of the hand along the entire handrail.	Handrail	TBA				Handrails not defined at 60% Review
17.17	AS 1428.1 Cl. 9 (d) (e)	Is the handrail height consistent at a measurement between 865 – 1000mm above the stair nosing (throughout the stairs and on any landing) Construction tolerance of 10mm allowable and Height of handrail may vary at stairway handrail extension or where handrail transitions between flights or to a balustrade).	Handrail	TBA				Handrails not defined at 60% Review
17.18	AS 1428.1 Cl. 9 (b)	Do the handrails have a circular diameter of 30 – 52mm for a min. of 270°.	Handrail	TBA				Handrails not defined at 60% Review
17.19	AS 1428.1 Cl. 8.2 (c)	Do the handrails follow the angle of the nosings.	Handrail	TBA				Handrails not defined at 60% Review
17.20	AS 1428.1 Cl. 9 (c)	Are exposed edges and corners of handrails provided with a radius of not less than 5mm.	Handrail	TBA				Handrails not defined at 60% Review
17.21	AS 1428.1 Cl. 8. 2 (b)	Is there a min. clearance of 1000mm between handrails.	Handrail	TBA				Handrails not defined at 60% Review
17.22	AS 1428.1 Cl. 9 (g)	Are the handrails securely fixed, with ends returned to a side wall / post or turned through 180°.	Handrail	TBA				Handrails not defined at 60% Review
17.23	AS 1428.1 Cl. 9 (a)	Do the handrails (and balustrades) sit outside of required circulation spaces.	Handrail	TBA				Handrails not defined at 60% Review
Universal Accessibility Options: not mandatory								
17.24		Are the tread heights between 150 – 165mm high AS 1428.2 – Cl. 13.2	Tread Heights	TBA				Tread Heights not defined at 60% Review
17.25		Are the treads a min. of 275 – 300mm deep AS 1428.2 – Cl. 13.2	Tread depth	TBA				Tread Depths not defined at 60% Review
17.26		Is there appropriate, uniform lighting of the stairs for night time use	Lighting	TBA				Lighting not defined at 60% Review
17.27		Are the handrails of non-reflective material and a contrasting colour to the background	Handrail Materials	TBA				Handrails not defined at 60% Review

ROK034 18.00 Tactile Ground Surface Indicators								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
18.01	AS 1428.4.1 Cl. 2.5	Are there appropriate hazard tactile ground surface indicators (TGSIs) prior to a hazard (e.g. roadway) i.e. (width x 600 – 800mm, setback 300mm ± 10mm).	Appropriate TGSI				NA	
18.02	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3 / 2.5	Are appropriately installed TGSIs provided at existing defined pedestrian crossing point/s with a level transition over a vehicular traffic way on the pathway(width x 600 – 800mm setback 300mm ± 10mm).	Pedestrian Crossing TGSI				NA	
18.03	AS 1428.4.1 Cl. 2.2 / 2.3 / 2.5	Are appropriate installed TGSIs provided at existing defined vehicle drop off areas, with blended kerbs and a level transition, if provided on the pathway (width x 600 – 800mm setback 300mm ± 10mm).	Vehicle dropoff TGSI				NA	
18.04	APS – D3.8 1 (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Are there appropriate TGSIs (hazard – extending the width of path, luminance, depth) at the top and bottom of a ramp (as required).	Ramp TGSI	TBA				TGSIs not defined at 60% Review
18.06	AS 1428.1 Cl. 11 / AS 1428.4.1 Cl. 2.3 / 2.4	If a non enclosed landing is provided on the stairs, are TGSIs installed as appropriate.	Non-enclosed landing TGSI	TBA				TGSIs not defined at 60% Review
18.07	AS 1428.4.1 Cl. 2.4	If the distance of the landing is 3000mm or more to the nearest nosing edge, are the warning indicators spread over a distance of 600 – 800mm.	Landing TGSI	TBA				TGSIs not defined at 60% Review
18.08	APS – D3.8 / AS 1428.4.1 Cl. 2.6	If there is an overhead obstruction less than 2000mm (other than a doorway) are appropriate TGSIs installed (in the absence of any other barrier) (e.g. undercroft of stairs) (NOTE: an alternative type of barrier is preferred).	Overhead Obstruction TGSI	TBA				No Overhead Obstructions identified at 60% Review
18.09	AS 1428.4.1 Cl. 2.3.3 (b)	Are the warning indicators installed at right angles to path of travel on pathways.	Warning Indicators	TBA				Warning Indicators not defined at 60% Review
18.10	AS 1428.4.1 Cl. 2.3.3 (c) / 3.4 / 3.5	Are there warning indicators installed along edges of hazardous areas e.g. train platforms, wharves, level roadway crossing points etc.	Warning Indicators	TBA				Warning Indicators not defined at 60% Review
18.11	AS 1428.4.1 Cl. 2.2 / App. E	Are TGSIs installed with appropriate contrasts to background surfaces.	TGSI Contrast	TBA				TGSIs not defined at 60% Review
18.12	AS 1428.4.1 Cl. 2.3	Are the TGSIs installed to ensure no tripping hazard is produced.	No Tripping Hazards	TBA				TGSIs not defined at 60% Review
Universal Accessibility Options: not mandatory								
18.13	AS 1428.4.1 Cl. 3.1 (c) (i)	Are there appropriate directional TGSIs on any pathway adjacent where a kerb ramp is at a mid block section or not on a direct path of travel.	Directional TGSI	TBA				TGSIs not defined at 60% Review
18.14	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3	Are TGSIs provided at changes in direction on the pathway to the PPE.	Directional TGSI	TBA				TGSIs not defined at 60% Review
18.15	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3	Are warning TGSIs (hazard) provided at changes in direction of directional indicators on the pathway to the PPE.	Warning TGSI	TBA				TGSIs not defined at 60% Review
18.16		Are there any appropriate TGSIs (hazard) indicators prior to the existing kerb ramps on the pathway (width x 600 – 800mm, setback 300mm ± 10mm).	Kerb Ramps	TBA				TGSIs not defined at 60% Review
18.17	AS 1428.4.1 App. D	Are there directional indicators installed to provide direction to elements e.g. bus stops, kerb ramps, street furniture, toilets, train platforms, road crossings etc.	External Kerb Ramps	TBA				TGSIs not defined at 60% Review
18.18	AS 1428.4.1 App. A 3.1	Are TGSIs used with consistent application throughout an area.	TGSI	TBA				TGSIs not defined at 60% Review
18.19		Are the TGSIs well maintained.	TGSI	TBA				TGSIs not defined at 60% Review
18.20		Are the TGSIs used to promote pedestrian safety.	TGSI	TBA				TGSIs not defined at 60% Review

ROK034 19.00 Ramps								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
19.01	APS – D3.11	If a vertical rise of more than 3.6m is provided through a series of connected ramps, is an alternative means of access provided.	Rise of more than 3.6 m	TBA				Existing ramp not detailed to answer this question at 60% Review
19.02	AS 1428.1 Cl. 7.3	Do all ramps have a slope / gradient where the max. ratio is 1:14 (tolerance 3% provide no section is steeper than 1:14).	Gradient	TBA				Existing ramp not detailed to answer this question at 60% Review
19.03	AS 1428.1 Cl. 7.3	Do the 1:14 ramps have landings a min. of every nine metres or less at changes in directions.	Landings every 9m	TBA				Existing ramp not detailed to answer this question at 60% Review
19.04	AS 1428.1 Cl. 7.3	If the ramp abuts an internal corridor, is it set back a min of 400mm or, if it abuts an external boundary a min. of 900mm.	Corridor abut setback	TBA				Existing ramp not detailed to answer this question at 60% Review
19.05	APS – D3.11 (b)	If there are connected ramps / step ramps, are the landings free from any overlap.	Connected Ramps	TBA				Existing ramp not detailed to answer this question at 60% Review
19.06	AS 1428.1 Cl. 7.8	Are landings 1200mm (where no change of direction required) in length or greater) (NOTE: sharp transitions are required between the planes of landings and ramps, refer AS for gradients).	Landing 1200mm - no direction change	TBA				Existing ramp not detailed to answer this question at 60% Review
19.07	AS 1428.1 Cl. 7.8	If the landing has a change of direction not exceeding 90°, is the landing a min. 1500mm, with the internal corner truncated for a min of 500mm in both directions.	Landing 1500mm - max 90 degree turn	TBA				Existing ramp not detailed to answer this question at 60% Review
19.08	AS 1428.1 Cl. 7.8	If the landing has a 180° turn, is the landing a min. of 1540mm deep with other required dimensions as per the Standard.	Landing 1540mm - 180 degree turn				NA	No 180 degree turn on ramp
19.09	AS 1428.1 Cl. 7.8	If the landing is at a door, which is approached from the side, is there appropriate circulation space.	landing at door				NA	No landing at a door
19.10	AS 1428.1 Cl. 7.8	If the ramp is constructed with a change of direction, does the angle of approach create a 90° angle to the line of transition between the ramp surface and the landing surface.	angle of approach at 90 degree	TBA				Existing ramp not detailed to answer this question at 60% Review
19.11	AS 1428.1 Cl. 9	Do all ramps have an unobstructed width (in between handrails) a min. of 1000mm.	unobstructed width 1000mm	TBA				Existing ramp not detailed to answer this question at 60% Review
19.12	AS 1428.1 Cl. 7.3	Do any ramps (and landings as approp.) have kerbs on both sides with the top between 65 – 75mm, or higher than 150mm (see fig 18 AS).	Kerbs on both sides					Existing ramp not detailed to answer this question at 60% Review
19.13	AS 1428.1 Cl. 3	Does the full length of any ramp have min. overhead clearance of 2000mm.	Overhead Clearance		Y			No evidence that overhead clearance less than 2000mm
19.14	AS 1428.1 – Cl. 7.4	If ramps are curved, do they have a min. width of 1500mm and end with 1500mm long straight landings.	Curved Ramp				NA	Ramp not curved
19.15	AS 1428.1 Cl. 4.2	Is the ramp surface slip resistant with smooth transitions between different sections (i.e. abutment of surfaces).	TGSI	TBA				Existing ramp not detailed to answer this question at 60% Review
19.16	APS – D3.8 (1) (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Are there appropriate TGSIs (hazard – extending the width of path, luminance, depth) at the top and bottom of the ramp (NOTE: refer to AS for differing requirements for landings).	TGSI	TBA				Existing ramp not detailed to answer this question at 60% Review
19.17	AS 1428.1 Cl. 7.3/9	Do all ramps have appropriate handrails on two sides (Note: if a balustrade is required at a height greater than the handrail, both shall be provided).	Ramp handrail	TBA				Existing ramp not detailed to answer this question at 60% Review
19.18	AS 1428.1 Cl. 9	Do the handrails have a circular diameter of 30 – 50mm for a min. of 270°.	Ramp handrail	TBA				Existing ramp not detailed to answer this question at 60% Review
19.19	AS 1428.1 Cl. 9	Are exposed edges (at ends) and corners of handrails provided with a radius of not less than 5mm.	Ramp handrail	TBA				Existing ramp not detailed to answer this question at 60% Review
19.20	AS 1428.1 Cl. 9	Is the handrail height consistent (measured at a height between 865 - 1000mm) throughout the ramp and any landing.	Ramp handrail	TBA				Existing ramp not detailed to answer this question at 60% Review
19.21	AS 1428.1 Cl. 9	Do the handrails have a min. clearance of 50mm from an adjacent wall and min. 600mm clearance above.	Ramp handrail	TBA				Existing ramp not detailed to answer this question at 60% Review
19.22	AS 1428.1 Cl. 7.3/9	Do the handrails extend a min. of 300mm past the ends of the ramp.	Ramp handrail	TBA				Existing ramp not detailed to answer this question at 60% Review
19.23	AS 1428.1 Cl. 9/9	Are handrails constructed and fixed, ensuring no obstruction to the passage of the hand along the entire handrail.	Ramp handrail	TBA				Existing ramp not detailed to answer this question at 60% Review
19.24	AS 1428.1 Cl. 9/9	Are handrails securely fixed, with ends returned to a side post / wall or downwards through 180°.	Ramp handrail	TBA				Existing ramp not detailed to answer this question at 60% Review
19.25	AS 1428.1 Cl. 9	Do the handrails (and balustrades) sit outside of required circulation spaces.	Ramp handrail	TBA				Existing ramp not detailed to answer this question at 60% Review
19.26	AS 1428.1 Cl. 7.6	If less than 1900mm in length, does the step ramp have a gradient a max. ratio of 1:10 and a max. rise 190mm.	Step Ramp				NA	No evidence of Step Ramp
19.27	AS 1428.1 Cl. 7.6.2	If a step ramp is installed and there is pedestrian cross traffic, do the edges of the step ramp have a 45° splay or a wall, fence, balustrade or suitable barrier or a kerb or where an open balustrade is provided, a kerb or kerb rail.	Step Ramp				NA	No evidence of Step Ramp
19.28	AS1428.1 Cl 7.6.1	If a step ramp is installed, is the top and bottom aligned at 90 degrees to the direction of travel and have sharp transitions at the top and bottom and at any tapered or splayed edges	Step Ramp				NA	No evidence of Step Ramp
19.29	AS 1428.1 Cl. 7.6/8	If the landing at the top and bottom of the step ramp follows the direction of travel, is it a min. of 1200mm long.	Step Ramp				NA	No evidence of Step Ramp
19.30	AS 1428.1 Cl. 7.6/8	If the landing at the top and bottom of the step ramp requires a change of direction, is it a min. of 1500mm.	Step Ramp				NA	No evidence of Step Ramp
19.31	AS 1428.1 Cl. 7.8 / 10	If the landing at the top and bottom of the step ramp is at a doorway, is the appropriate door circulation space provided.	Step Ramp				NA	No evidence of Step Ramp
19.32	AS 1428.1 Cl. 7.5	If there is a threshold ramp at the doorway, does it have sharp transitions at the top and bottom and be located not more than 20mm from door leaf it serves, not more than 280mm in length and a min. ratio of 1:8.	Threshold Ramp				NA	No evidence of Threshold Ramp
19.33	AS 1428.1 Cl. 7.5	If the threshold ramp does not abut a wall or kerb, are sides tapered or splayed (min. 45°).	Threshold Ramp				NA	No evidence of Threshold Ramp

ROK034 19.00 Ramps								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Universal Accessibility Options: not mandatory								
19.34	AS 1428.2 Cl. 8.4.5	Do the edges of the ramps have colour contrast to their background.	Colour Contrast	TBA				Existing ramp not detailed to answer this question at 60% Review
19.35	AS 1428.2 Cl. 19	Is there appropriate uniform lighting of the ramp for night time use.	Luminance	TBA				Existing ramp not detailed to answer this question at 60% Review
19.36		Are the handrails of non-reflective material and a contrasting colour to the background.	Handrails	TBA				Existing ramp not detailed to answer this question at 60% Review

ROK034 20.00 Signage								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
20.01	APS – DP1 (b) / AS 1428.1 CL 5.1	Is appropriate signage available where directional decisions are made.	Directional Signage	TBA				Signage not defined at 60% Review
20.02	APS – D3.6 (e) / D4 / AS 1428.1 Cl. 5.1	If there is a non accessible entrance doorway, is there appropriate signage provided directing users to accessible entrance.	Non-Accessible Access Signage	TBA				Signage not defined at 60% Review
20.03	APS – D3.6 / D4 / AS 1428.1 Cl. 5.2	Where the symbol for access is used, does it comply with the international standard in style, colour and layout.	Symbol for Access	TBA				Signage not defined at 60% Review
20.04	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Symbol for Deafness	TBA				Signage not defined at 60% Review
20.05	APS – D3.6 (b) (ii) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2	Does signage including the international symbol of deafness, indicate which type of system is in place.	Symbol for Deafness	TBA				Signage not defined at 60% Review
20.06	APS D3.6 (b) (iii)	If receivers are being used for hearing augmentation, does the signage indicate where the receivers can be obtained.	Hearing Augmentation Signage	TBA				Signage not defined at 60% Review
20.07	APS – D3.6 (b) / D4 / AS 1428.1 CL 5.1	Is raised tactile information provided on signs between 1200 – 1600mm.	Signage Raised Text	TBA				Signage not defined at 60% Review
20.08	APS – D4.5	Is there appropriate illumination of signage for day and night use (where required e.g. to maintain luminance).	Illumination	TBA				Signage not defined at 60% Review
20.09	APS – D3.6 (f) / D4	If there is a non-accessible toilet provided, is there signage available that directs users to an accessible toilet (where in different locations).	Signage to Accessible toilet at non-accessible toilet	TBA				Signage not defined at 60% Review
20.10	APS – D3.6 (c) / D4 / AS 1428.1 Cl 5.1	Does the signage indicate if the accessible toilet facility is suitable for left or right hand.	L or R Hand Accessible Facility	TBA				Signage not defined at 60% Review
20.11	APS – D4.3 (2); Title Case AS 1428.1 C 5.1	If available on the sign, is the text provided in Title Case.	Signage - Title Case	TBA				Signage not defined at 60% Review
20.12	APS-D3.6 (a) / AS 1428.1 Cl 5.1	Is there signage (incorporating raised text and Braille, and raised and visual symbols) installed identifying available sanitary facilities.	Signage to All Toilets	TBA				Signage not defined at 60% Review
20.13	APS – D3.6 (d) / AS 1428.1 Cl. 5.1	If there is an ambulant toilet, is appropriate signage installed at the airlock serving the area that contains the facilities identifying the facilities within.	Signage Ambulant Toilet	TBA				Signage not defined at 60% Review
20.14	APS – D3.6 (d) / AS 1428.1 Cl. 5.1	If there is an ambulant toilet, is there signage to identify the facility (Note: may be located on door if required).	Signage Ambulant Toilet	TBA				Signage not defined at 60% Review
Universal Accessibility Options: not mandatory								
20.15		Is signage (including tactile and Braille) located at the main building entry, both inside and out, giving directional and general information about buildings and facilities including services and access for people with disabilities.	Main Entry Signage	TBA				Signage not defined at 60% Review

R0K036		01.00 Entrances						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
1.01	APS – D3.2 (2) (a)	If there is more than one pedestrian entrance, are 50% of them accessible (including the principal pedestrian entrance)	Entrance		Y			
1.02	APS – D3.2 (2) (b)	If the building is more than 500m² is any non accessible entry within 50m from an accessible entry.	Accessible Entry within 50m of Non-Accessible Entry		Y			
1.03	APS – D3.6 (e) Cl. 5.1	If there is a non accessible entrance doorway, is there appropriate signage provided (int. Symbol, direction arrow) directing users to an accessible entrance.	Non-Accessible Door Signage	TBA				Signage not designed at 60% Review
1.04	APS – D3.2 (3) (a) (4) fig D3.2	If the pedestrian entrance is required to be accessible and consists of not more than 3 doorways, is not less than one doorway accessible.	Less than 3 doorways	TBA				Doors not defined at 60% Review
1.05	AS 1428.1 Cl. 10.4.3 / AS 1428.2 Cl. 28	If there are security entry controls (card / buttons / intercom) are these at 900 – 1100mm-grasped/turned, 900-1200mm-pushed, 900-1250mm (not less than 500mm from corner)-touched, (<i>ticket slot 800 – 900mm</i>), and easy to operate.	Security door controls	TBA				Door hardware and security not defined at 60% Review
1.06	APS – A1.1	If there is a revolving door / turnstile, is there an alternative accessible hinged / sliding door	Revolving Door				NA	Door hardware not defined at 60% Review
1.07	AS 1428.1 Cl. 10.4.2	Can the door be unlocked and opened by one hand (i.e. D or D lever handles).	Door Handle	TBA				Door hardware not defined at 60% Review
1.08	AS 1428.1 Cl. 10.4.2 (b)	Is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handle	TBA				Door hardware not defined at 60% Review
1.09	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles, snibs, locks) that need to be grasped or turned located between 900 – 1100mm high.	Door Controls	TBA				Door hardware not defined at 60% Review
1.10	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed located between 900 – 1200mm high.	Door Controls	TBA				Door hardware not defined at 60% Review
1.11	AS 1735.12 AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched located between 900 – 1250mm high and not less than 500mm from an internal corner except as specified in AS 1735.12 AS 1428.1 Cl. 10.4.3 (c)	Door Controls	TBA				Door hardware not defined at 60% Review
1.12	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handle	TBA				Door hardware not defined at 60% Review
1.13	AS 1428.1 Cl. 10.4.2 (f)	If an outward opening door is not self closing, is there a horizontal handrail or pull bar installed at a height between 900 – 1100mm (min. 50mm clearance from edge of door / door handle) on the inside of the door.	Door Handle	TBA				Door hardware not defined at 60% Review
1.14	AS 1428.1 Cl. 10.4.4	If doors are power operated, are the push button controls a min. of 25mm dia., proud of the surface (activating door before the button becomes level with surrounding surface).	Power operated door	TBA				Door hardware not defined at 60% Review
1.15	AS 1428.1 Cl. 10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 500 – 1000mm from arch of the hinged door leaf (in any position) / or clear of a surface-mounted sliding door in the open position.	Power operated door	TBA				Door hardware not defined at 60% Review
1.16	AS 1428.1 Cl. 3.6	If the doors / sidelights are frameless or fully glazed, are they clearly marked for safety and ease of identification across the full door width, with a solid and non-transparent contrasting line (viewable from 2m inside and outside) (luminance 30%). Size of line not less than 75mm high, with the lower edge at a height of 900 – 1000mm above finished floor level.	Door Material	TBA				Door hardware not defined at 60% Review
1.17	AS 1428.1 Cl. 10.1	Do all the doors or doorframes have a min. luminance contrast of 30% to their adjacent surfaces.	Door Frame Contrast	TBA				Door hardware not defined at 60% Review
1.18	AS 1428.1 Cl. 10.4.2 (e)	Is the entrance door easy, to initially open, (no heavy closer or spring) 20N max. (4.3lbf)	Door Pressure	TBA				Door closers not defined at 60% Review
1.19	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	Is the min. clear opening of a doorway at the PPE 850mm or greater.	Min clear opening	TBA				Doors or gates to the entrance not defined at 60% Review
1.20	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	If the doorway has 2 independent operated leaves, is the open doorway a min. of 850mm wide.	2 leaves	TBA				Door leaf size not defined at 60% Review
1.21	AS 1428.1 Cl. 7.5 / 7.5	Is the door threshold level or is there an appropriate threshold ramp available at the entry (i.e. no step, inappropriate mat, weather strip etc.)	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.22	AS 1428.1 Cl. 7.5	If there is a threshold (max. rise 35mm) at the entrance or doorway (not more than 20mm from door leaf it serves), is there a ramp of not more than 280mm in length and min. ratio of 1:8. (Note: if the rise is greater a step ramp will be required).	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.23	AS 1428.1 Cl. 7.5	If the threshold ramp does not abut a wall or kerb, are sides tapered or splayed (min. 45°)	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.24	AS 1428.1 Cl. 4.2	If there is a recessed mat within the CAPT is the abutment of the surfaces no more than 3mm if vertical or 5mm if bevelled (rounded).	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.25	AS 1428.1 Cl. 4.3.1	If there is a carpet leading edge at the entrance is there a vertical face no higher than 3mm or a rounded bevelled edge no higher than 5mm or above that height a gradient of 1:8 up to a total max. height of 10mm.	Carpet	TBA				Door thresholds not defined at 60% Review
1.26	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space outside the entrance doorway (not steeper that 1:40) (Doorway circulations spaces may overlap other circulation spaces).	Circulation Space outside		YES			No evidence of non-compliance
1.27	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space inside the entrance doorway (not steeper that 1:40) (Doorway circulations spaces may overlap other circulation spaces).	Circulation Space inside		YES			No evidence of non-compliance
1.28	AS 1428.1 Cl. 10.3.5	If there is an airlock, vestibule, or enclosed space, is there not less than 1450mm between the doorway (plus the door leaf width if the door encroaches into the space).	Airlock				NA	No Airlock at entrance
1.29	AS 1428.1 Cl. 3.7	If there are glazed viewing panels in doors, is the lower edge of the glazing not more than 1000mm above FFL, upper edge not less than 1600mm above FFL.	Glazed Viewing Panels	TBA				Door leaf + viewing panels not defined at 60% Review
1.30	AS 1428.1 Cl 3.7	If there are glazed viewing panels in doors, is the width of the glazing within 200mm from latch edge of the door and min 150mm wide.	Glazed Viewing Panels	TBA				Door leaf + viewing panels not defined at 60% Review
Universal Accessibility Options: not mandatory								
1.37	AS 1428.2 Cl. 23.3 (b)	Are the door handles provided with an appropriate luminance contrast	Door Handles	TBA				Door hardware not defined at 60% Review
1.38		Do automatic self-opening doors have effective motion, and presence sensors installed	Automatic Doors	TBA				Door Control not defined at 60% Review

ROK036		01.00 Entrances						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
1.39		If there is an alarm control pad, is it located at a height between 900 – 1200mm high, accessible and easy to operate	Door Control	TBA				Door hardware not defined at 60% Review
1.40		If there is a doorbell, is it accessible and easy to operate, located at a height between 900 – 1200mm	Doorbell				NA	Door hardware not defined at 60% Review
1.41		Is there appropriate lighting at the PPE	Lighting	TBA				Lighting not defined at 60% Review

ROK036		02.00 Customer Service Areas						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
2.01	APS – DP1	If there is a reception area, is there a direct CAPT from the PPE to the reception counter area.	CAPT		YES			No evidence of non-compliance
2.02	APS – DP9 / D3.6	Does any screened reception counter / ticket or tellers booth, with an inbuilt amplification system, have a hearing augmentation system installed.	SCREENED RECEPTION	TBA				Detail of Screen not on drawings at 60% Review
2.03	AS 1428.1 Cl. 4.1	Is the floor surface slip resistant.	FLOOR SURFACE	TBA				Floor surface not on drawings at 60% Review
2.04	APS – Amdt. 1	If carpeted, is it short pile (<11mm and backing <4mm) and securely attached to the floor surface.	CARPET	TBA				Floor surface not on drawings at 60% Review
2.05	AS 1428.1 Cl. 4.3.1	Are any exposed edges of carpet fastened to the floor surface and have a trim along the entire length of the exposed edge.	CARPET	TBA				Floor surface not on drawings at 60% Review
2.06	AS 1428.1 Cl. 3.3	Are internal walkways a min. of 1000mm wide (1200mm preferred).	WALKWAY WIDTH			N		Refer to Markup where there is less than 1 metre accessway around furniture.
Universal Accessibility Options: not mandatory								
2.07	AS 1428.2 Cl. 24.1.1	Does the reception counter / ticket or tellers booth provide a wheelchair accessible section at a height of 830 – 870mm with leg clearance at a height of 800 – 840mm underneath, for a min. length of 900mm.	WHEELCHAIR ACCESSIBLE SECTION	TBA				Consider best practice to provide a wheelchair accessible section.
2.08	AS 1428.2 Cl. 27.2	Is some seating provided 450 – 520mm high, with armrests at a height of 220 – 300mm above the seat and a seat back, for use in the customer service area.	SEATING	TBA				Furniture specification to determine height etc not on drawings at 60% Review
2.09	AS 1428.2 Cl. 19	Is the customer service area appropriately lit and is the lighting even.	LIGHTING	TBA				Lighting not specified at 60% Review
2.1	AS 1428.2 Cl. 22	Are display and information stands within common reach ranges (230 – 1350mm) for wheelchair users (Note: different angles of approach e.g. side approach)	DISPLAY STANDS	TBA				Display Stands not included at 60% Review
2.11		Are there accessible height security alarm pads	SECURITY ALARMS	TBA				Security not defined at 60% Review
2.12		Are there effective contrasts between vertical and horizontal surfaces / objects	CONTRAST	TBA				Paint Finishes not defined at 60% Review

ROK036		03.00 Internal Accessways						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
3.01	AS 1428.1 Cl. 3.3	Does the accessway have a min. width of 1000mm i.e. structurally and maintained to remain clear of temporary obstructions e.g. pot plants, bins.	1000mm min			N		Refer to Markup where there is less than 1 metre accessway around furniture.
3.02	AS 1428.1 Cl. 3.2	Does the full length of the accessway have an overhead clearance of 2000mm (1980mm allowed at doorway)	Overhead Clearance		Y			There is no evidence that the accessway would not have an overhead clearance of 2m.
3.03	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.4	Do accessways provide a passing space where a direct line of sight is not available to the end of the walkway (max. 20m intervals) (min. 1800mm wide x 2000mm long)	Turn Circle		Y			All Accessways have direct line of sight to the end. Accessways also have turning circles at each end.
3.04	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.5	Do accessways provide a turning space near the end of the walkway where it is not possible to continue (within 2m of end)	Turn Circle		Y			No evidence of inadequate turning space in internal accessways. To be checked again at 60%
3.05	AS 1428.1 Cl. 3.5	If a change of direction is required, is there appropriate circulation space provided along the accessway for the angle of the turn.	Circulation		Y			No evidence of inadequate circulation space
3.06	AS 1428.1 Cl. 4.1	Does the accessway have a slip-resistant surface with a texture that is traversable by a wheelchair.	Slip Resistant	TBA				Surface for accessway not designed at 60% Review
3.07	APS – D3.6 (e) AS 1428.1 CL 5	If there is a non-accessible entrance doorway, is there appropriate signage provided (int. Symbol, direction arrow) directing users to an accessible entrance	Signage	TBA				Signage not designed at 60% Review
3.08	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	Is the min. clear opening of a doorway on any accessway 850mm or greater.	Min Clear open		Y			No evidence of doorways that are less than 850mm
3.09	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space outside the doorway (NOTE: 1:40 grade, additional considerations at surface mounted sliding doors) (Doorway circulation space may overlap other circulation spaces)	Circulation		Y			No evidence of inappropriate circulation spaces outside each doorway. To be checked again at 60%
3.10	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space inside the doorway (NOTE: 1:40 grade, additional considerations at surface mounted sliding doors) (Doorway circulation space may overlap other circulation spaces)	Circulation		Y			No evidence of inappropriate circulation spaces inside each doorway. To be checked again at 60%
3.11	AS 1428.1 Cl. 10.4.2 (a)	Can the door be unlocked and opened by one hand (i.e. D or D lever handles)	Door Handles	TBA				Door hardware not designed at 60% Review
3.12	AS 1428.1 Cl. 10.4.2 (b)	Is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handles	TBA				Door hardware not designed at 60% Review
3.13	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles) that need to be grasped or turned between 900 – 1100mm high.	Door Handles	TBA				Door hardware not designed at 60% Review
3.14	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed between 900 – 1200mm high.	Door Handles	TBA				Door hardware not designed at 60% Review
3.15	AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched between 900 – 1250mm high (and not less than 500mm from an internal corner, except as specified in AS 1735.12)	Door Handles	TBA				Door hardware not designed at 60% Review
3.16	AS 1428.1 Cl.10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 1000 – 2000mm from the hinged swing door leaf (in any position) / or doorway of sliding door.	Power Door	TBA				Doors that are power operated not designed at 60% Review
3.17	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handles	TBA				Door hardware not designed at 60% Review
3.18	AS 1428.1 Cl. 10.4.2 (e)	Are all doors (other than fire / smoke doors) provided with the appropriate opening force (20N).	Door Force	TBA				Door Force not designed at 60% Review
3.19	AS 1428.1 Cl. 10.3.5	If there is an airlock, vestibule, or enclosed space, is there not less than 1450mm between the doorway (plus the door leaf width if the door encroaches into the space).	Air Vestibule				NA	No airlocks designed at 60% Review
3.20	AS 1428.1 Cl. 10.4.2 (g)	If an outward opening door is not self closing, is there a horizontal handrail or pull bar installed at a height between 900 – 1100mm (min. 50mm clearance from edge of door / door handle) on the inside of the door.	Hoor Handles	TBA				Door hardware not designed at 60% Review
3.21	AS 1428.1 Cl 11.1	Are all switches and controls provided on a CAPT (other than general purpose outlets (GPOs)) located at a height of 900 – 1100mm and not less than 500mm from an internal corner.	Switches and Controls	TBA				Door hardware not designed at 60% Review

ROK036		04.00 Accessible Toilet						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
04.01	APS – F2.4 (a)	Is a toilet designated as wheelchair accessible available in the building / facility.	Access Toilet		Y			
04.02	APS – F2.4	Is a USAT provided on each floor level that toilets are provided on APS – F2.4.	Access Toilet		Y			
04.03	APS – F2.4 (g)	If there is more than 1 USAT is the 2 nd of the opposite hand.					NA	Only 1 USAT per level designed at 60% Review
04.04	AS 1428.1 Cl. 12.2.8.1	Is the min. circulation space 1900mm wide and 2300mm long to a height of 2000mm (Note: accepted intrusions)	Circulation Space		Y			
04.05	APS – F2.4 (f)	Is the toilet/s on a CAPT from the PPE (ensuring that access does not necessitate the traversing an area reserved for one sex only).	On CAPT		Y			
04.06	APS – D3.6 (c) / D4 / AS 1428.1 Cl 5	Is the toilet/s sign posted with the appropriate International Symbol of Access, and separate Male and Female symbols, located on the wall between 1200 - 1600mm high on the latch side of the doorway (Note: to include raised and visual versions).	Sign	TBA				Signage not designed at 60% Review
04.07	APS – D3.6 (c) / D4 / AS 1428.1 Cl 5	Does the signage indicate if the facility is suitable for left or right hand use.	Sign	TBA				Signage not designed at 60% Review
04.08	APS – D3.6 (f) / D4	If there is a non-accessible toilet provided, is there signage available that directs users to an accessible toilet (where in different locations).	Sign	TBA				Signage not designed at 60% Review
04.09	APS – D4.3 (2); AS 1428.1 Cl 5	If available on the sign, is the text provided in Title Case.	Sign	TBA				Signage not designed at 60% Review
04.10	AS 1428.1 Cl. 10.2	Is the min. clear opening width 850mm or greater for the toilet.	Min Opening		Y			
04.11	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space at the door (inside and outside).	Circulation Space		Y			
04.12	AS 1428.1 Cl. 12.2.9 (b)	Does the cubicle door have an ‘occupied’ (in-use) indicator and a bolt or catch (which is openable from the outside in an emergency).	Door Indicator	TBA				Door Hardware not designed at 60% Review
04.13	AS 1428.1 Cl. 12.2.9 (b)	If a snib catch is in use, does the snib handle have a min. length of 45mm from the centre of the spindle.	Snib Catch	TBA				Door Hardware not designed at 60% Review
04.14	AS 1428.1 Cl. 10.4.2 (e)	Is the cubicle door easy to initially open (no heavy closer) 20N max.	Door Pressure	TBA				Door Hardware not designed at 60% Review
04.15	AS 1428.1 Cl. 12.2.9 (a)	If the door is outward opening does it have a hinge mechanism that holds the door in a closed position without the use of a latch.	Hinge Mechanism	TBA				Door Hardware not designed at 60% Review
04.16	AS 1428.1 Cl. 10.4.2 (a)	Can the door be unlocked and opened by one hand (i.e. D lever or D handles and approp. hardware).	Door Handle	TBA				Door Hardware not designed at 60% Review
04.17	AS 1428.1 Cl. 10.4.2 (b)	Throughout its operation, is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.18	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles) that need to be grasped or turned between 900 – 1100mm high.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.19	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed between 900 – 1200mm high.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.20	AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched between 900 – 1250mm high and not less than 500mm from an internal corner.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.21	AS 1428.1 Cl. 10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 1000 – 2000mm from the hinged swing door leaf (in any position) / or doorway of sliding door.	Power Door	TBA				Power Doors no defined at 60% Review
04.22	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.23	AS 1428.1 Cl. 10.1	Does the doorway have a min. luminance contrast of 30% to its adjacent surfaces.	Contrast	TBA				Paint Finishes not defined at 60% Review
04.24	AS 1428.1 Cl. 12.2.8 (fig 43)	Is there a 1500mm space in front of the pan (Note: basin overlap of 100mm permitted if located at front of pan only).	Space in front of pan		Y			No evidence of non-compliance.
04.25	AS 1428.1 Cl. 12.2.8 (fig 43)	Is there 1240 – 1250mm at one side of the pan (this allows side transfers from a wheelchair) (basin not permitted to overlap if located to side of pan).	Space side of pan		Y			Sanitary ware not defined to this level at 60% Review
04.26	AS 1428.1 Cl. 12.2.3 (a) (b) (c) (d)	Is there a full round toilet seat securely hinged to the pan (load rated to 150kg).	Sanitary Ware	TBA				Sanitary ware not defined at 60% Review
04.27	AS 1428.1 Cl. 12.2.3 (e)	Does the toilet seat have a min. 30% luminance contrast with the background e.g. (pan, wall or floor).	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.28	AS 1428.1 Cl. 12.2.2	Is the height to the top of the seat between 460 – 480mm.	Sanitary Ware		Y			No evidence of non-compliance.
04.29	AS 1428.1 Cl. 12.2.2	Is the front of the pan 790 - 810mm from the rear wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.30	AS 1428.1 Cl. 12.2.2	Is the centreline of the pan 450 - 460mm from the side wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.31	AS 1428.1 Cl. 12.2.2	Is the width of the pan a max. of 400mm.	Sanitary Ware		Y			No evidence of non-compliance.
04.32	AS 1428.1 – 2009 Cl. 12.2.2	Is the front of the pan a min. of 600mm from any back wall mounted fixture.	Sanitary Ware		Y			No evidence of non-compliance.
04.33	AS 1428.1 Cl. 12.2.4 (a)	Is a backrest provided on the USA T which is capable of withstanding a force in any direction of 1100N.	Sanitary Ware		Y			No evidence of non-compliance.
04.34	AS 1428.1 Cl. 12.2. 4 (b)	At its face, is the height of the lower edge of the backrest to the top of the WC seat between 120 – 150mm.	Sanitary Ware		Y			No evidence of non-compliance.
04.35	AS 1428.1 Cl. 15.2. 4 (c)	Does the backrest have a vertical height of 150 – 200mm and a width of 350 – 400mm.	Sanitary Ware		Y			No evidence of non-compliance.
04.36	AS 1428.1 Cl. 12.2. 4 (c) (d)	Does the backrest have its face centered on the pan centreline, positioned to achieve an angle of between 95 - 100° back from the seat hinge.	Sanitary Ware		Y			No evidence of non-compliance.
04.37	AS 1428.1 Cl. 12.2.7 (fig 42)	If a concealed or high level cistern is used, is a continuous grab rail at 800 – 810mm (30 – 40mm dia.) provided across the rear and side wall nearest the pan.	Sanitary Ware		Y			No evidence of non-compliance.
04.38	AS 1428.1 Cl. 12.2.7 (fig 42)	If the grab rail on the side wall is one continuous rail, does it provide the appropriate angled extension and clearances from pan / wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.39	AS 1428.1 Cl. 12.2.7 (fig 42)	Is the outside edge of any back wall grab rail at least 450mm from the side of the pan (dependent on length of grab rail).	Sanitary Ware		Y			No evidence of non-compliance.
04.40	AS 1428.1 Cl. 14	Is the grab rail fixed and constructed to withstand a force of 1100N applied in any position and in any direction (without deformation or loosening or rotation of the fastenings or fittings).	Sanitary Ware		Y			No evidence of non-compliance.
04.41	AS 1428.1 Cl. 14	Is the clearance between the grab rail and the adjacent wall surface or other obstruction not less than 50mm and not more than 60mm.	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.42	AS 1428.1 Cl. 14	Is there a min. 600mm clearance above the horizontal grab rail, with a min. of 50mm below any horizontal or angled rail (except at fixing points).	Sanitary Ware		Y			No evidence of non-compliance.

ROK036		04.00 Accessible Toilet						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
04.43	AS 1428.1 Cl. 14	Are exposed edges and corners of grab rails provided with a radius of not less than 5mm.	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.44	AS 1428.1 Cl. 12.2.7 (fig 42)	If a surface mounted / low level cistern is used, is there a wall mounted grab rail (30 – 40mm dia.) a min. length 300mm on the rear wall located within 50mm of the cistern, together with a grab rail mounted on the sidewall at 800 – 810mm high (as per diagram).	Sanitary Ware		Y			No evidence of non-compliance.
04.45	AS 1428.1 Cl. 12.2.2	Is the bottom edge of the cistern a min. of 600mm above floor level.	Sanitary Ware		Y			No evidence of non-compliance.
04.46	AS 1428.1 Cl. 12.2.6 (fig 41)	Can the toilet paper be easily reached (max. outside edge 300mm forward of pan and top edge 700mm max. height) and the roll dispenser have no greater than 150mm projection from the wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.47	AS 1428.1 Cl. 12.2.5 (fig 40)	If the flushing control is located on the back wall, is it within reach, easy to operate (activating the flush before level with the surrounding surface) <i>contrasting 30% with adjacent surfaces</i> (min height 600mm / max. height 1100mm / outside edge max. 500mm from centre line)	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.48	1428.1 Cl. 12.2.5 (fig 40)	If not located on the back wall as above, is it located in the centre line of the toilet AS.	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.49	AS 1428.1 Cl. 12.2.5 (fig 40)	If the flushing control is located on the side wall is it within the approp. zone (inside edge no further than 300mm over the pan / outside edge no further than 300m from the front of the pan – at a height between 600 – 1100mm above finished floor level.	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.50	AS 1428.1 Cl. 12.2.10	Is there a basin inside the unisex accessible toilet	Sanitary Ware		Y			No evidence of non-compliance.
04.51	AS 1428.1 Cl. 12.2.8 (fig 43)	Is the distance between the basin and pan at least 1400mm (front of pan location only permitted for 100mm overlap).	Sanitary Ware		Y			No evidence of non-compliance.
04.52	AS 1428.1 Cl. 12.3.1 (d) (fig 44 (a) (b))	If a semi recessed washbasin is installed (other than within a SOU) is the front top edge 800 – 840mm above the floor.	Sanitary Ware				NA	No semi-recessed washbasin
04.53	AS 1428.1 Cl. 12.3.1 (d) (fig 44 (a) (b))	If a wall mounted washbasin is installed is the front top edge 800 – 830mm above the floor.	Sanitary Ware		Y			No evidence of non-compliance.
04.54	AS 1428.1 Cl. 12.3.1 (d) (fig 44 (a) (b))	If a semi recessed basin is provided (except within a SOU) is the bench provided at a height between 800 – 830mm (outside of circulation spaces).	Sanitary Ware				NA	No semi-recessed washbasin
04.55	AS 1428.1 Cl. 12.3.1 (d) (fig 46)	Is the centre line of the washbasin (rear) provided with a min. 225mm either side.	Sanitary Ware		Y			No evidence of non-compliance.
04.56	AS 1428.1 Cl. 12.3.1 (d) (fig 44)	Is the centre line of the washbasin a min. of 425mm from any wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.57	AS 1428.1 Cl. 12.3.1 (d) (fig 44)	Is the circulation space a min. of 450mm wide (rear of basin).	Sanitary Ware		Y			No evidence of non-compliance.
04.58	AS 1428.1 Cl. 12.3.1 (d) (fig 46)	Is the circulation space for the washbasin a min. 1500mm long and 850mm wide (from rear of washbasin).	Sanitary Ware		Y			No evidence of non-compliance.
04.59	AS 1428.1 Cl. 12.3.1 (d) (fig 44)	Is the position of the taps, bowl and drain outlet appropriate.	Sanitary Ware		Y			No evidence of non-compliance.
04.60	AS 1428.1 Cl. 12.3.1 (d) (fig 44) (a)	Does the basin have appropriate foot / knee / leg space underneath.	Sanitary Ware		Y			No evidence of non-compliance.
04.61	AS 1428.1 Cl. 12.3.1 (c) (e)	If the downpipes are exposed are they insulated or located so as to ensure they do not present a hazard to the user and sit outside the circulation space under the washbasin.	Downpipe		Y			No evidence of non-compliance.
04.62	AS 1428.1 Cl. 12.2.1 (d)	If hot water is provided, is water delivered through a mixing spout.	Mixing Spout		Y			No evidence of non-compliance.
04.63	AS 1428.1 Cl. 12.2.1 (c)	If hot water is provided, is the hot tap located on the left of or above the cold tap.	Hot / Cold Tap				NA	Mixing spout
04.64	AS 1428.1 Cl. 15.2.1 (a)	Are the tap handles lever, sensor plates, voice activation or other similar controls.	Tap Handles		Y			No evidence of non-compliance.
04.65	AS 1428.1 Cl. 12.2.1 (b)	If the taps have lever handles, are they located more than 50mm from adjacent surfaces.	Tap Handles		Y			No evidence of non-compliance.
04.66	AS 1428.1 Cl. 12.2.1 (c)	Are taps clearly identified as hot and cold (colour and text) and in the appropriate location.	Tap Handles				NA	Mixing spout
04.67	AS 1428.1 Cl. 12.4.4	Is there a clothes hanging device 1200 – 1350mm from the floor (not less than 500mm from an internal corner (Note: shower exception)	Clothes Hanger			N		See Markup in Appendix A
04.68	AS 1428.1 Cl. 12.4.1	Is a mirror provided and located either adjacent to or above the washbasin at a min. of 350mm wide.	Mirror		Y			No evidence of non-compliance.
04.69	1428.1 Cl. 12.4.1	If the mirror is above the basin, does it extend between 900mm – 1850mm above the floor, or If adjacent to the basin, at a height of not more than 780mm to a height of not less than 1800mm above the floor.	Mirror		Y			No evidence of non-compliance.
04.70	AS 1428.1 Cl. 12.4.3	If a hand dryer / towel dispenser is provided, is the operative component at a height between 900 – 1100mm and within reach of a user at the washbasin (not closer than 500mm from any internal corner) does not encroach more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Hand Dryer		Y			No evidence of non-compliance.
04.71	AS 1428.1 Cl. 12.4.3	If a soap dispenser is provided, is the operative component at a height between 900 – 1100mm and within reach of a user at the washbasin (not closer than 500mm from any internal corner) does not encroach more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Soap Dispenser		Y			No evidence of non-compliance.
04.72	AS 1428.1 Cl. 12.4.2 (a)	One of the following three shelves must be provided. If a shelf is provided as a vanity top is it located at a height between 800 – 830mm with a min. width of 120mm and depth of 300mm and a depth no greater than the bowl plus its front and back flanges, without	Shelf		Y			No evidence of non-compliance.
04.73	AS 1428.1 Cl. 12.4.2 (b) (i)	If a shelf is provided within the circulation space as a separate fixture, is it available at a height between 900 – 1000mm with a min. width of 120 -150mm and length of 300 – 450mm.	Shelf				NA	Shelf with basin
04.74	AS 1428.1 Cl. 12.4.2 (b) (ii)	If a shelf is provided external to the circulation space as a separate fixture, is it at a height between 790 – 1000mm with a min. width of 120mm and length of 400mm and does not encroach more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Shelf				NA	Shelf with basin
04.75	AS 1428.1 Cl. 12.4.5 (a) (fig 43)	If there is a portable sanitary disposal unit available, is it provided in the rear corner between the pan and the closest wall.	Sanitary Disposal			N		See Markup in Appendix A
04.76	AS 1428.1 Cl. 12.4.5 (b)	If a recessed sanitary disposal unit is provided, is it located within 500mm of the pan.	Sanitary Disposal			N		See Markup in Appendix A
04.77	AS 1428.1 Cl. 12.2.8.1 (iv)	If a wall cabinet is provided, does it encroach not more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Wall Cabinet			N		See Markup in Appendix A
04.78	AS 1428.1 Cl. 11.2	Are rocker action / toggle switches provided which are a min. 30 x 30mm.	Switches	TBA				Switch detail not defined at 60% Review

ROK036		04.00 Accessible Toilet						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
04.79	AS 1428.1 Cl. 11.2	If push pad switches are provided are they a min. of 25mm dia.	Switches	TBA				Switch detail not defined at 60% Review
04.80	AS 1428.1 Cl. 11.2	If provided near the washbasin, are switches and power points 600 –1100mm high, not less than 500mm from the internal corners and close to any shelf or worktop.	Switches	TBA				Switch detail not defined at 60% Review
04.81	AS 1428.1 Cl. 12.2.8.2	If there is a baby change table, is it located at a height of 820 mm with leg clearance height underneath of 720 when open (must sit outside of circ. space when folded up).	Baby Change Table			N		See Markup in Appendix A
Ambulant Toilets								
	Standard	Items						
04.82	APS – F2.4	If there are one or more toilets provided in addition to the USAT at the bank of toilets, is an ambulant male and an ambulant female toilet provided	Ambulant Toilet		Y			No evidence of non-compliance at 60% Review
04.83	AS 1428.1 Cl. 13.4.	If ambulant toilets are provided, (use a separate Checklist for each ambulant toilet and identify each as Male or Female, is signage (raised text and Braille, and raised and visual symbols) installed at the airlock serving the area that contains the facilities identifying the facilities within AS 1428.1 Cl. 13.4.	Signage	TBA				Signage not defined at 60% Review
04.84	APS – D3.6 (d) / AS 1428.1 Amdt. 1 Cl. 8.1.	Is there signage (raised text and Braille, and raised and visual symbols) installed on the door of the facility.	Signage	TBA				Signage not defined at 60% Review
04.85	AS 1428.1 Cl. 10.3	If there is an airlock enroute to an ambulant toilet, is there appropriate circulation space.	Airlock				NA	Airlock not designed at 60% Review
04.86	AS 1428.1 Cl. 13.3	Is the min. clear opening width of the ambulant toilet doorway 700mm.	Width of Doorway		Y			No evidence of non-compliance at 60% Review
04.87	AS 1428.1 Cl. 13.3	Does the cubicle door have an ‘occupied’ (in-use) indicator and a bolt or catch (which is openable from the outside in an emergency).	Indicator		Y			No evidence of non-compliance at 60% Review
04.88	AS 1428.1 Cl. 13.3	If a snib catch is in use, does the snib handle have a min length of 45mm from the centre of the spindle	Snib Catch	TBA				Door Hardware not detailed at 60% Review
04.89	AS 1428.1 Cl. 16.1	Is the width of the ambulant toilet compartment between 900 – 920mm.	Width of Ambulant		Y			No evidence of non-compliance at 60% Review
04.90	AS 1428.1 Cl. 13.1 fig 52 (B)	Is there a clear min. circulation space of 900mm long x 900-920mm wide in front of the toilet pan.	Min Circulation in					
04.91	AS 1428.1 Cl. 13.3 fig 52 (B)	Is there a clear circulation space a min. of 900 x 900mm outside the door (Note: variety of placement options).	Min Circulation out		Y			No evidence of non-compliance at 60% Review
04.92	AS 1428.1 Cl. 12.2.7	Are appropriate grab rails installed on the wall located at a height between 800 – 810mm.	Grab Rail		Y			No evidence of non-compliance at 60% Review
04.93	AS 1428.1 Cl. 14	Is the grab rail fixed and constructed to withstand a force of 1100N applied in any position and in any direction (without deformation or loosening or rotation of the fastenings or fittings).	Grab Rail	TBA				Ambulant toilet not defined to this level at 60% Review
04.94	AS 1428.1 Cl. 14	Is the clearance between the grab rail and the adjacent wall surface or other obstruction not less than 50mm and not more than 60mm.	Grab Rail	TBA				Ambulant toilet not defined to this level at 60% Review
04.95	AS 1428.1 Cl. 14	Is there a min. 600mm clearance above the horizontal grab rail, with a min. of 50mm below any horizontal or angled rail (except at fixing points).	Grab Rail	TBA				Ambulant toilet not defined to this level at 60% Review
04.96	AS 1428.1 Cl. 14	Are exposed edges and corners of grab rails provided with a radius of not less than 5mm.	Grab Rail	TBA				Ambulant toilet not defined to this level at 60% Review
04.97	AS 1428.1 Cl. 13.1	Is the toilet pan provided with the standard projection of between 610 – 660mm.	Pan Projection		Y			No evidence of non-compliance at 60% Review
04.98	AS 1428.1 Cl. 13.1	Is the height to the top of the seat between 460 – 480mm.	Height to top of seat		Y			No evidence of non-compliance at 60% Review
04.99	AS 1428.1 Cl. 13.1 fig 52 (A)	Can the toilet paper be easily reached (max. outside edge 300mm forward of pan and top edge 700mm max. height).	Toilet Paper position		Y			No evidence of non-compliance at 60% Review
Universal Accessibility Options: not mandatory								
4.100		Are the door handles or controls colour contrasting to the background (30%)	Contrast	TBA				Door Hardware not defined at 60% Review
4.101		Is appropriate lighting provided inside the toilet	Lighting	TBA				Lighting not defined at 60% Review
4.102		Is there an emergency alarm installed in the cubicle, for users requiring assistance	Alarm	TBA				Alarm system not defined

ROK036		05.00 Accessible Shower						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
05.01	APS – F2.4 (b) NOTE: can still be considered under equity requirements of DDA	Is there a designated accessible shower cubicle for people using wheelchairs (requirement dependant on class of building under APS).	Accessible Shower Cubicle			N		Refer to Markup
05.02	AS 1428.1 Cl. 12.5.1 (c)	If two or more shower recesses are provided, is at least one of the opposite hand.	LH / RH				NA	One shower only on ROK019 Level 3
05.03	AS 1428.1 Cl. 10.2	Does the shower doorway have a min. clear opening width of 850mm.	Shower Doorway			N		Refer to Markup
05.04	AS 1428.1 Cl. 10.1	Does the door / doorframe into the shower area have a min. luminance contrast of 30% to the adjacent surfaces.	Doorframe contrast			N		Refer to Markup
05.05	AS 1428.1 Cl. 12.2.9 (b)	If an inward opening shower door is provided, is it operable or removable from outside in an emergency.	Inward open Shower door			N		Refer to Markup
05.06	AS 1428.1 Cl. 12.5.1 / 12.5.3	Is the shower circulation space a min. size of 1600mm x 2500mm for a three walled enclosure, or 1600mm x 2350mm for a two walled enclosure.	Shower Circulation			N		Refer to Markup
05.07	AS 1428.1 Cl. 12.5.2	Is the shower recess accessible with no hob or step and at a gradient of between 1:60 and 1:80.	No Hob		Y			No evidence of non-compliance
05.08	AS 1428.1 Cl. 12.5.2	Is the slope of the remainder of the sanitary facility provided at a grade of between 1:80 and 1:100	Gradient of slope			N		Refer to Markup
05.09	AS 1428.1 Cl. 12.5.1 (a)	Is the circulation space clear to a height of not less than 2000mm (excluding allowable fittings).	Circulation Space			N		Refer to Markup
05.10	AS 1428.1 Cl. 12.5.4	Are there appropriate grab rails (30 – 40mm dia.) available at 800 – 810mm high (back wall).	Grab Rails			N		Refer to Markup
05.11	AS 1428.1 Cl. 12.5. / 14	Is there a showerhead support grab rail (vertical 30 – 40mm dia.) installed with the bottom end between 1000 – 1100 and the top end between 1880 – 1900mm high (Note: optional extension available)	Grab Rails			N		Refer to Markup
05.12	AS 1428.1 Cl. 12.5. / 14	Is the vertical showerhead support grab rail located 580 – 600mm from the internal corner of the shower.	Grab Rails			N		Refer to Markup
05.13	AS 1428.1 Cl. 12.5.9	Is a foldable, self-draining, slip resistant seat (960mm x 390 / 400mm) provided in the shower recess at a height of 470 – 480mm, with an appropriate clearance from adjacent surfaces (i.e. 40mm max.)(requires rounded edges and must fold upwards – refer AS)	Shower Seat			N		Refer to Markup
05.14	AS 1428.1 Cl. 12.5.9	Is the shower seat able to withstand a force of 1100N.	Shower Seat			N		Refer to Markup
05.15	AS 1428.1 Cl. 12.5.9	If the shower seat is in the folded up position, is the grab rail accessible.	Shower Seat			N		Refer to Markup
05.16	AS 1428.1 Cl. 12.5.9	Are the drainage gaps / slots within the shower seat 4 – 6mm wide.	Shower Seat			N		Refer to Markup
05.17	AS 1428.1 Cl. 12.5.6	Is a hand held and adjustable shower head available within reach when seated.	Shower Head			N		Refer to Markup
05.18	AS 1428.1 Cl. 12.5.6	Is a flexible hose provided for the shower that is a min. length of 1500mm (Note: requirements of back flow prevention device).	Shower Hose			N		Refer to Markup
05.19	AS 1428.1 Cl. 4.1	Is the floor slip resistant.	Slip Resistance			N		Refer to Markup
05.20	AS 1428.1 Cl. 12.2.1	Is the tap/s located on the wall at a height between 900 – 1100mm.	Taps			N		Refer to Markup
05.21	AS 1428.1 Cl. 12.2.1	Is the hot tap located on the left of / or above the cold tap.	Taps			N		Refer to Markup
05.22	AS 1428.1 Cl. 12.2.1	Are the tap handles lever or sensor control or voice activated.	Taps			N		Refer to Markup
05.23	AS 1428.1 – Cl. 12.2.1/12.5.8	If the taps have lever handles, are they located more than 50mm from adjacent surfaces and nor more than 100mm long.	Taps			N		Refer to Markup
05.24	AS 1428.1 Cl. 12.5.8	Is the tap fixture located no closer than 50mm from the vertical grab rail (to ensure clearance around grab rail).	Soap Holder			N		Refer to Markup
05.25	AS 1428.1 Cl. 12.5.7	Is there a soap holder located between 900 – 1100mm no closer than 50mm of the vertical support rail (protruding type preferred).	Soap Holder			N		Refer to Markup
05.26	AS 1428.1 Cl. 12.4.4 / 12.5.1	Are a minimum of two clothes hanging devices provided at 1200 - 1350mm high, with one within 390 – 410mm and the 2nd within 590 – 610mm of the folding seat and not less than 500mm out from any internal corner.	Clothes Hanging Devices			N		Refer to Markup
05.27	AS 1428.1 Cl. 12.2.8.2	If there is a baby change table available, is it at a height of 820mm with leg clearance height underneath of 720mm.	Baby Change Table			N		Refer to Markup
05.28	AS 1428.1 Cl. 12.5.2 (b) (Note: A linear drain may be provided)	If the waste outlet is in the centre line of the shower floor, is it (525 - 575mm from the wall with tap / 555 – 605mm from the wall with the seat).	Waste Outlet			N		Refer to Markup
Universal Accessibility Options: not mandatory								
05.29		Are the taps clearly identified as hot and cold (colour and text)	Taps	TBA				Shower detail not provided at 60% Review

ROK036		06.00 Passenger Lifts						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
06.01	APS 4.4 / E3.6	Is there a lift available to all floors (where required).	All Floors		Y			
06.02	APS – E3.6b	Is the lift door installed with a min. clear opening width of 900mm.	Min. Clear Width	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.03	AS 1735.12 - Sect. 6	Is the internal lift floor surface level with the external surface for an unobstructed entry into the lift (12mm variation allowed).	Floor Surface	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.04	APS - E3.6 / 1735.12 – Sect. 2	If the lift was approved with building permit issued prior to 1st May 2011, (or new and travels not more than 12m), is the min. floor area 1100mm wide x 1400mm deep.	Age of Lift				NA	
06.05	APS – 4.4 / E3.6	If the lift was approved with building permit issued on or after 1st May 2011 and travels more than 12m, is the min. floor area 1400mm wide x 1600mm deep.	Age of Lift	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.06	AS 1735.12 – Cl. 3.1 / APS Amdt. (6)	If carpet is provided within the lift, is it appropriate (pile <11mm, backing <4mm)	Carpet	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.07	AS 1735.12 – Cl. 4.2	Is an appropriate door operating sensor (passenger protection system) in place which whilst activated holds the doors open.	Sensor	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.08	AS 1735.12 – Cl. 4.3	Do the doors, when responding to a landing button, remain open for a full 6 seconds.	Open Time	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.09	AS 1735.12 Cl. 4.3	If there are three or more lifts in line and they are interconnected in their operation, is the door dwell time extended to a min. 8 sec (Note: dwell times may be shortened in some instances).	More than 1 lift				NA	
06.10	AS 1735.12 Cl. 8.5	If there are three or more lifts in the bank of lifts is there visible and audible notification on each lift landing to indicate the lift arrival and direction of travel.	More than 1 lift				NA	
06.11	AS 1735.12 Cl. 5.1	Are the adjacent parallel surfaces in the lift car located within 300mm of the control buttons, provided with a surface that reduces glare and reflection.	Parallel Surfaces	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.12	AS 1735.12 Cl. 5.2	Are car operating panels, seats, handrails provided so as to not obstruct or reduce the width of the door opening.	Internal Car Fitout	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.13	AS 1735.12 Cl. 5.3.2 (a)	Is a handrail available which is a min. length of 600mm, located in the lift at a height between 850 – 950mm.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.14	AS 1735.12 Cl. 5.3.1	Is this handrail a max. of 500mm from any button or device to operate the lift.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.15	AS 1735.12 Cl. 5.3.2 (a)	Does the handrail have a circular diameter of 30 – 50mm for a min. of 270°.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.16	AS 1735.12 Cl. 5.3.2 (c)	Are exposed edges of the handrail provided with a radius of not less than 5mm.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.17	AS 1735.12 Cl. 5.3.2 (f)	Are clearances above the handrail (including clearances to the control panel) less than 5mm or not less than 100mm.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.18	AS 1735.12 Cl. 5.3.2 (g)	Are handrails set 50mm from the car wall.	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.19	AS 1735.12 Cl. 5.3.2 (g)	If there is a gap less than 50mm between the wall and handrail (i.e. where handrail is returned to the wall) is it filled in (enclosed)	Handrail	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.20	AS 1735.12 Cl. 5.4	If there is a fixed seat within the lift, does it sit outside of the min. car size (Note: hinged seats not acceptable).	Seat within Lift	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.21	AS 1735.12 Cl. 7.1	Is each landing provided with one or more control buttons to call the lift.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.22	AS 1735.12 Cl. 7.3.1	Is the centre of landing control buttons, key switches and card readers located between 900mm –1200mm above the landing floor.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.23	AS 1735.12 Cl. 7.3.3	Are the landing control buttons located adjacent to the lift entrances and not closer than 500mm from any internal corner or fixed obstruction.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.24	AS 1735.12 Cl. 7.1	If up and down buttons are provided on a landing, and are not located vertically within 200mm of each other, is a tactile symbol and Braille equivalent provided (above or to the left or on the face of the respective button).	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.25	AS 1735.12 Cl. 7.2.3	If a key pad is provided, is it set up like a telephone key pad and located at a height between 900 - 1100mm from the floor.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.26	AS 1735.12 Cl. 7.2.3 / 7.4	If a key pad is provided, is there a tactile dot provided in the centre of the number 5 (unless the tactile symbol is on the face of the button).	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.27	AS 1735.12 Cl. 7.2.1	If the lift has a dimension less than 1400mm, are there two lift control panels provided (one to the left and one to the right of a person entering the lift).	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.28	AS 1735.12 Cl. 7.2.2 Figure 8.4.2 (c)	Is the communication button located at the right hand end of the lowest row of buttons and identified by a visible symbol.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.29	AS 1735.12 Cl. 7.2.2 / 8.3 Figure 8.4.2 (c)	Is there a tactile symbol and Braille equivalent above or to the left or on the face of the respective buttons.	Signage	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.30	APS – E3.6 (b) / AS 1735.12 – Sect 9.2 / 9.3	Is there an emergency hands-free communication system installed, (including a button that alerts a call centre of a problem and a light to signal that the call has been received).	Emergency comms	TBA				Existing Lift Detail not shown in drawings at 60% Review

ROK036		06.00 Passenger Lifts						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
06.31	AS 1735.12 Cl. 7.3.1	Is the centre of the face of the control buttons within the lift located at a height between 700 – 1250mm.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.32	AS 1735.12 Cl. 7.3.2	Are the control buttons within the lift located within the appropriate zones / distance from the door / corners.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.33	AS 1735.12 Cl. 7.4	Are the control buttons of the appropriate size, design and easy to use (2N – 5N).	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.34	APS – E3.6 (b)	If the lift travels more than 2 floors, is there appropriate audible information to identify when the lift stops.	Audible	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.35	APS – E3.6 (b)	If the lift travels more than 2 floors, is there appropriate audible and visual indication at each lift landing to indicate the arrival of the lift.	Audible	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.36	AS 1735.12 Cl. 8.6	Is an appropriate lift position indication provided within the lift (i.e. lift on 2nd floor, 4th floor etc.).	Position Indicator	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.37	AS 1735.12 Cl. 10.2	Is there appropriate lighting within the lift.	Lighting	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.38	AS 1735.12 Cl. 10.3	Are the lift control buttons appropriately lit.	Controls	TBA				Existing Lift Detail not shown in drawings at 60% Review
Universal Accessibility Options: not mandatory								
06.39	AS 1428.2 – Cl. 12	Can a wheelchair turn around in the lift (recommended 1700x 1900mm)	Circulation	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.40		Are the handrails in contrast to the walls	Handrail Contrast	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.41		Are the internal walls of the lift of a non-reflective material	Wall Finish	TBA				Existing Lift Detail not shown in drawings at 60% Review
06.42		Are the emergency procedures clearly identified in the event of a lift malfunction	Signage	TBA				Existing Lift Detail not shown in drawings at 60% Review

ROK036		07.00 Kitchens						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
07.01	AS 1428.1 Cl. 3	Is there a CAPT provided to the kitchen / bar / dining / laundry / canteen area.	CAPT		Y			
07.02	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there a continuous internal accessible path of travel to any canteen window.	Canteen		Y			
07.03	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there a continuous external accessible path of travel to any external canteen / servery window.	Canteen		Y			
07.04	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there appropriate circulation space within the kitchen area, to enable a user ease of use for all facilities.	Circulation Space		Y			
Universal Accessibility Options: not mandatory								
07.05	AS 1428.2 Cl. 24	Does the counter have a wheelchair accessible section at a height between 830 – 870mm for a min. length of 900mm.	Counter	TBA				
07.06	AS 1428.2 Cl. 24	Does the counter have at the wheelchair accessible section, a leg clearance underneath at a height between 800 – 840mm for a min. length of 900mm.	Counter	TBA				
07.07	AS 1428.2- A5	Is the sink / basin accessible to people in wheelchairs (height 770 – 800mm).	Basin	TBA				
07.08	AS 1428.2- A5	Is the sink / basin accessible to people in wheelchairs (leg clearance height underneath 640-650mm) with appropriate unobstructed circulation space.	Basin	TBA				
07.09	AS 1428.2 Cl. 24	If there is a canteen / servery window does it have a wheelchair accessible section at a height between 830 – 870mm with a leg clearance underneath at a height of 800 – 840mm for a min. length of 900mm.	Canteen Window			N		Consider accessible section of canteen window
07.10	AS 1428.2 Cl. 29	Are the operative components of any vending machine, for pre-packaged food and drink, accessible and between 700 – 1200mm high.	Vending Machine				NA	
07.11	AS 1428.2 Cl. 27.2	If seating is available, is it at a height of 450 – 520mm with armrests located at a height between 220 – 300mm above the seat and backs.	Seating	TBA				
07.12		If tea and coffee facilities are provided (other than vending machine), are the highest operable components located at a height between 900 – 1100mm.	Tea / Coffee	TBA				

ROK036 08.00 Meeting Spaces								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
08.01	AS 1428.2 Cl. 26.2 (a)	If an inbuilt stage or podium is provided, is there ramp access (in addition to any step / stair).	Stage				NA	No stages defined at 50%
08.02	APS – D3.7 (1) (2) (3)	If a sound amplification system is installed / inbuilt, is there a hearing augmentation system that covers 80% of the total enclosed space if an induction loop is inbuilt, or 95% if a receiver system is in use.	Sound Amplification = Hearing Augmentation	TBA				Sound amplification not defined at 60% Review
08.03	APS – D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, (excluding letter 'T') indicate the area where an assistive listening system is operational and the area covered.	Signage	TBA				Signage not defined at 60% Review
08.04	APS – D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, (excluding letter 'T') indicate which type of system is in place.	Signage	TBA				Signage not defined at 60% Review
08.05	APS – D3.7 (1) (2) (3)	If receivers are being used, does the signage indicate where the receivers can be obtained.	Signage	TBA				Signage not defined at 60% Review
08.06	AS 1428.1 Cl. 4.1	Is there a level, slip resistant floor surface.	Slip Resistance	TBA				Slip Resistance not defined at 60% Review
08.07	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there adequate circulation space between all furniture and fittings.	Circulation Space	TBA				Some issues with circulation space - Refer to markups
Universal Accessibility Options: not mandatory								
08.08		Is there appropriate lighting to the area.	Lighting	TBA				Lighting not defined at 60% Review
08.09		Is there clear, concise signage, incorporating Braille and tactile components that identifies all elements e.g. toilet, emergency exits.	Signage	TBA				Signage not defined at 60% Review
08.10		Is there sufficient level circulation space provided for a person using a wheelchair to sit at a meeting table in various locations.	Circulation Space	TBA				Some issues with circulation space - Refer to markups
08.11	AS 1428.2 Cl. 27.2	Is there some seating available which is 450 – 520mm high with armrests provided at a height of 220 – 300mm above the seat and a back.	Seating	TBA				Furniture specification not detailed at 60% Review
08.12	AS 1428.2 Cl. 26.2	Are boundaries of any stage or podium defined by barriers or an appropriate contrast to the floor surface, (colour and texture)	Stage				NA	No stages designed at 60% Review
08.13	AS 1428.2 Cl. 26.2 (b) / 6.3	Are all stage / podium controls able to be operated by a person when seated	Stage				NA	No stages designed at 60% Review
08.14	AS 1428.5 - 3	Is hearing augmentation available in meeting rooms (seating 5 or more participants)	Hearing Augmentation	TBA				Sound amplification not defined at 60% Review

ROK036		09.00 Hearing Augmentation						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
09.01	APS – D3.7 (1) (2) (3)	If a sound amplification system is installed / inbuilt is there a hearing augmentation system that covers 80% of the total enclosed space if an induction loop is inbuilt, or 95% if a receiver system in use.	Sound Amplification = Hearing Augmentation			N		Sound Amplification is planned for the 1.13 Hairdressing Room then Audio Loop system is required.
09.02	APS – D3.7 (1) (2) (3)	Is hearing augmentation available at any screened / enclosed reception area / ticket or tellers cash booth (that has an inbuilt amplification system).	Screened Booth				NA	No Screened booth designed.
09.02	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl 5.2.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Signage	TBA				Signage not defined at 60% Review
09.03	APS – D3.6 (b) (ii) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, indicate which type of system is in place.	Signage	TBA				Signage not defined at 60% Review
09.04	APS D3.6 (b) (iii)	If receivers are being used, does the signage indicate where the receivers can be obtained.	Signage	TBA				Signage not defined at 60% Review
09.05	APS – D3.7 (4)	If a screen or scoreboard is capable of displaying public announcements, is it capable of supplementing any public address system (other than a system used for emergency warning purposes only).	Signage	TBA				Signage not defined at 60% Review
09.06	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl 5.2.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Signage	TBA				Signage not defined at 60% Review
Universal Accessibility Options: not mandatory								
09.07	AS 1428.5 - 3	Is hearing augmentation available in meeting rooms (seating 5 or more participants).	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.08	AS 1428.5 - 3	Is hearing augmentation available in any lift to assist with communication in an emergency.	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.09		Is appropriate seating with backs and armrests available that provides good lines of sight for lip reading.	Seating lines of sight				NA	No Tiered Seating
09.10		Are there acoustic design elements to reduce noise e.g. rubber tips on furniture legs, soft furnishings, low pile carpet, double glazing, quiet equipment etc.	Acoustic Design Elements	TBA				Finishes not defined at 60% Review
09.11	AS 1428.5 - 3	Are there visible alarms at any security checkpoint.	Alarms	TBA				Security not defined at 60% Review
09.12		Are there visible emergency alarms throughout the building.	Alarms	TBA				Security not defined at 60% Review
09.13		Is there effective lighting for lip reading and sign language interpreters.	Lighting	TBA				Luminance not defined at 60% Review

ROK036		10.00 Contrasts						
Number	Standard	Item	Item	Y	Y	N	NA	Action
Mandatory Items								
10.01	AS 1428.1 Cl. 10.1	Doorways / frames / walls etc	Door Contrast	TBA				Finishes not defined at 60% Review
10.02	AS 1428.1 Cl. 3.6	Glass doors (solid, non-transparent contrasting strip across full width of glass and side partitions)	Glass Doors	TBA				Door Material not defined at 60% Review
10.03	APS – D3.8 1 (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Ramps (TGSIs at top and bottom - as required)	Ramp TGSI	TBA				TGSI detail not defined at 60% Review
10.04	APS – D4.5	Signs	Signage	TBA				Signage not defined at 60% Review
10.05	APS – D3.8 1 (a) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Stairs (TGSIs at top and bottom – as required)	Stair TGSI	TBA				Stair detail not defined at 60% Review
10.06	AS 1428.1 Cl. 8.1 (f) (g)	Stair nosing strips	Stair Detailing	TBA				Stair detail not defined at 60% Review
10.07	AS 1428.1 – 2021 Cl. 12.2.3 (e)	Toilet seats and cisterns	Sanitary Ware	TBA				Sanitary ware not defined at 60% Review

ROK036		11.00 Floor / Ground Surfaces						
Number	Standard	Item	Item	Y	Y	N	NA	Action
Mandatory Items								
11.01	AS 1428.1 Cl. 4.1	Is the ground / floor surface firm and level (e.g. with no sharp transitions at abutting surfaces).	Firm Level Surface	TBA				Floor Finishes not defined at 60% Review
11.02	AS 1428.1 Cl. 4.1	Is the floor / ground surface slip resistant (in wet and dry conditions) allowing traction for a person using a wheelchair and people with ambulant or sensory disability.	Slip Resistant	TBA				Floor Finishes not defined at 60% Review
11.03	AS 1428.1 Cl 4.3	If carpeted, is it short pile (<11mm and backing <4mm) and securely attached to the floor surface.	Carpet	TBA				Floor Finishes not defined at 60% Review
11.04	AS 1428.1 Cl 4.5	If timber decking boards are installed and are no greater than 150mm wide, is there a maximum 6mm gap between boards.	Timber Decking	TBA				Floor Finishes not defined at 60% Review
11.05	AS 1428.1 Cl 4.5	If timber decking boards are installed that are over 150mm wide, is there a maximum gap of 10mm between boards, and if the gap is over 8mm do the boards run transverse to the direction of travel	Timber Decking	TBA				Floor Finishes not defined at 60% Review
11.06	AS 1428.1 Cl 4.5	If timber decking boards are installed, are adjacent boards level with a maximum vertical 3mm tolerance	Timber Decking	TBA				Floor Finishes not defined at 60% Review
Universal Accessibility Options: not mandatory								
11.07		Does the floor / ground surface have effective contrasts to walls and doors / doorframes	Contrast	TBA				Floor and Wall Finishes not defined at 60% Review.

R0K036		12.00 Emergency Egress / Evacuation						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Universal Accessibility Options: not mandatory								
12.01		Is there an accessible (e.g. appropriate door handle, clear door opening width, opening force) emergency exit in addition to the main entry	Accessible Emergency Exit	TBA				Emergency Door Material, Hardware, Width etc not defined at 60% Review
12.02		Is there clear, visible, accessible signage on emergency exits	Signage for Exit	TBA				Signage not defined at 60% Review
12.03		Is there a continuous accessible path of travel from the building to any nominated assembly area (e.g. firm path, no steps, stairs, well lit)	CAPT to Assemeby	TBA				Emergency Alarms not defined at 60% Review
12.04		Are audible emergency alarms provided in the building	Alarms	TBA				Emergency Alarms not defined at 60% Review
12.05		Are visible emergency alarms provided in the building	Alarms	TBA				Refuge place not defined at 60% Review
12.06		Are there places of refuge provided for people with mobility difficulties on levels above the main entrance level	Refuge on Level 1	TBA				Refuge place not defined at 60% Review
12.07		Are audible security alarms provided at any security checkpoints	Alarms	TBA				Security Alarms not defined at 60% Review
12.08		Are visible security alarms provided at any security checkpoints	Alarms	TBA				Security Alarms not defined at 60% Review
12.09		Are any fire hoses and extinguishers located at 700 – 1200mm high	Fire Extinguishers	TBA				Fire Strategy not defined at 60% Review
12.10		Is the emergency management plan located at an accessible height in a public area in an accessible format (e.g. large print, tactile, Braille)	Emergency Management Plan	TBA				Emergency Management Plan not defined at 60% Review
12.11		Is there an accessible (e.g. appropriate door handle, clear door opening width, opening force) emergency exit in addition to the main entry	Emergency Exit	TBA				Emergency Exit not defined at 60% Review
12.12		Is there clear, visible, accessible signage on emergency exits	Accessible Emergency Exit Signage	TBA				Emergency Exit not defined at 60% Review

ROK036		13.00 Accessible Car Parking						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
13.01	Note not required to be designated if 5 or less under APS) APS table D3.5, DP8	Check APS Table - appropriate numbers of designated accessible parking bays for people with disabilities provided.	Number of Parks	TBA				Not defined by Certifer at 60% Review
13.02	AS / NZS 2890.6 Cl. 2.4	Designated accessible bay/s (DAPB) have min. overhead clearance of 2500mm	Overhead Clearance	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.03	AS / NZS 2890.6 Cl. 2.4	Is there an overhead clearance a min. of 2200mm at the car park entry	Overhead Clearance at Entry	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.04	AS / NZS 2890.6 Cl. 3.1	Is the DAPB noted on the ground with the international symbol of access (white symbol between 800 – 1000mm high within a blue rectangle not more than1200 x 1200mm) located in the centre of the space between 500 – 600mm from the entry point	Symbol of Access	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.05	AS / NZS 2890.6 Cl. 3.2	Is the DAPB (dedicated) space delineated by yellow slip resistant lines (unbroken 80 – 100mm wide all sides – except	Yellow lines	TBA				Car Parking / Drop off Bays not detailed at 60% Review
		any side delineated by a kerb, barrier, wall)	Walkway lines	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.06	AS / NZS 2890.6 Cl. 3.2	Is any walkway within or partly within a shared area marked with yellow slip resistant lines (unbroken longitudinal lines on both sides – excepting any side delineated by a kerb, barrier, wall)	Parallel DAPB	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.07	AS / NZS 2890.6 Cl. 2.2.2	If the DAPB is parallel (to the roadway / parking aisle), is it a min. width of 3200mm and 7800mm long with an appropriate 1600mm wide x 7800mm long connecting pathway (pathway can be above grade of bay).	Angled DAPB	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.08	AS / NZS 2890.6 Cl. 2.2.1, Cl.3.2 b) 11)	If the DAPB is angled (to the roadway / parking aisle), is it 2400mm wide and 5400mm long, with an adjoining shared pathway a min of 2400mm wide x 5400 (plus 2400 x 2400 at front or rear) (must be at grade of parking bay). Is the shared area marked with diagonal stripes 150 to 200 mm wide with spaces 200 mm to 300 mm between stripes. The stripes shall be at an angle of 45 ±10 degrees to the side of the space.	Bollard	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.09	AS / NZS 2890.6 Cl. 2.2.1(e)	Is a bollard provided within the shared area (central in space – set back from the end of the parking module 750 – 850mm)	Level Ground, Firm Surface, Crossfall	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.10	AS / NZS 2890.6 Cl. 2.3	Is the DAPB on level ground, with a firm surface and free of loose material. Crossfall (not more 1:40 in any direction or 1:33 if bitumen / outside)	Kerb	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.11	AS / NZS 2890.6 Cl. 2.2.2 / 2.5	If kerbs exist, at a parallel parking bay, is there an appropriate kerb ramp (at front or rear end) provided from the DAPB (Note: pathway may require an increase in width to accommodate kerb ramp)	Slip Resistant Kerb	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.12	AS 1428.1 Cl. 4.1 and 7.7.3	Do existing kerb ramp/s at parking bay, have a slip resistant surface	Kerb Ramps	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.13	AS 1428.1 Cl. 7.2.2	Are the existing kerb ramp/s at DAPB, a max. length of 1520mm and maximum rise of 190mm with a slope / gradient where the ratio is not greater than 1:8	Kerb Ramp width	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.14	AS 1428.1 Cl. 7.7	Do existing kerb ramp/s at DAPB, have a min. width of 1000mm	Kerb Ramp Landing	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.15	AS 1428.1 Cl. 7.7	Do existing kerb ramp/s have an appropriate landing at the top and bottom of the ramp (Note: consider change of direction)	Kerb Ramp transition	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.16	AS 1428.1 Cl. 7	Do the existing kerb ramp/s at DAPB, have a smooth transition between the road and pathway (max. diff. 5mm with rounded edge)	TGSI	TBA				Car Parking / Drop off Bays not detailed at 60% Review
Universal Accessibility Options: not mandatory								
13.18	AS / NZS 2890.6 – A3	Is the DAPB clearly visible with elevated signs with blue international access symbol	Signage	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.19		Are the DAPBs adjacent to, or as near as possible, to the principal pedestrian entry of the building or facility	Near as possible to entrance		Y			Directly in front of building.
13.20	AS 1428.2 Cl. 19	Is the area for the DAPBs etc well-lit and is the lighting even	Luminance	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.21	AS / NZS 2890.6 – A3	Are direction signs to DAPB provided, if DAPB sign not visible from car park entry	Signage	TBA				Car Parking / Drop off Bays not detailed at 60% Review
13.22	AS 1428.4.1 Cl. 3.1 (c) (i)	Are there appropriate directional TGSIs on any pathway adjacent to a DAPB, where a kerb ramp is at a mid-block section or not on a direct path of travel	TGSI	TBA				Car Parking / Drop off Bays not detailed at 60% Review

ROK036		14.00 Kerb Ramps						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
14.01	AS 1428.1. Cl. 4	If the pathway on the accessway crosses any vehicle traffic areas, (e.g. parking lot, internal road) is it free from any changes in level (e.g. kerbs, steps etc.).	Pathway level changes	TBA				Kerb Ramps not detailed at 60% Review
14.02	AS 1428.1. Cl. 4 / 7.7.3	Is the ground surface on the kerb ramp slip resistant.	Slip Resistant	TBA				Kerb Ramps not detailed at 60% Review
14.03	AS / NZS 2890.6 - Cl. 2.2.2 / 2.5	If the kerb ramps are inserted into the pathway, has the pathway width been extended to accommodate the kerb ramp.	Kerb ramps	TBA				Kerb Ramps not detailed at 60% Review
14.04	AS 1428.1. Cl. 7.7.1	If there is an opposing kerb ramp / pedestrian refuge / median, are the centre lines of the kerb ramps aligned.	Opposing Kerb Ramp	TBA				Kerb Ramps not detailed at 60% Review
14.05	AS 1428.1. Cl. 7.7.2	Do the kerb ramps on the accessway, have a max. rise of 190mm, length of 1520mm and do they have a slope / gradient where the ratio is not greater than 1:8.	Kerb ramp gradient	TBA				Kerb Ramps not detailed at 60% Review
14.06	AS 1428.1. Cl. 3.3	Are the openings of the kerb ramps a min. of 1000mm wide.	Openings min 1000mm	TBA				Kerb Ramps not detailed at 60% Review
14.07	AS 1428.1. Cl. 7.7.2	Do the kerb ramps, on the pathway to the PPE, have a smooth transition between the road and the pathway (max. diff. 5mm with rounded or bevelled edge).	Smooth Transition	TBA				Kerb Ramps not detailed at 60% Review
14.08	AS 1428.1. Cl. 7.7.2	Do the kerb ramps have an appropriate side profile i.e. splayed or tapered 45°.	Side Profile	TBA				Kerb Ramps not detailed at 60% Review
14.09	AS 1428.1. Cl. 7.7.2	Is the angle between the ramp surface and the lower surface (i.e. base of kerb) provided at an angle of 166°.	Angle	TBA				Kerb Ramps not detailed at 60% Review
14.10	AS 1428.1. Cl. 7.8.3	Do kerb ramps on the pathway have a landing of 1200mm min in length at the top and bottom of the ramp (following direction of travel).	Kerb Ramp Landing	TBA				Kerb Ramps not detailed at 60% Review
14.11	AS 1428.1. Cl. 7.8.3	Do kerb ramps on the pathway have a landing of 1500mm x 2000mm at any change of direction (T junction).	Kerb Ramp Landing	TBA				Kerb Ramps not detailed at 60% Review
14.12	AS 1428.1. Cl. 7.8.3	Do kerb ramps on the pathway have a landing of 1500mm x 1500mm at any single change of direction	Kerb Ramp Landing	TBA				Kerb Ramps not detailed at 60% Review
Universal Accessibility Options: not mandatory								
14.13		Are there any TGSIs (hazard) indicators installed at kerb ramps on the accessway (width x 600 – 800mm, setback 300mm ± 10mm)	TGSI	TBA				TGSI not defined at 60% Review

ROK036		15.00 Landscaping						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Universal Accessibility Options: not mandatory								
15.01		Are pathways free from plant species that develop overhanging foliage, and / or leaves or drop seed pods, berries, leaf and bark litter	Foilage				NA	Existing Audit Requirement only
15.02		Are there landscape designs, materials, plants, etc., that contribute to pedestrian safety	Safety in Design	TBA				
15.03		Are any plantings used to provide orientation or direction cues for people with vision impairment e.g. distinctive scents, sounds, appearance or texture	Planting				NA	
15.04		Are any planter boxes appropriately located clear of any pathway	Planting		Y			
15.05		Are any dense plantings maintained to provide a clear line of sight	Planting				NA	

ROK036		16.00 Pathways (Accessways)						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
16.01	APS - D3.2	Does an accessible pathway lead users from the designated accessible parking bay to the building entrance.	Accessible Pathway		Y			New accessible pavement designed from new dropoff zone.
16.02	APS - D3.2	Does an accessible pathway lead users from the allotment boundary to the building entrance.	Accessible Pathway		Y			
16.03	APS - D3.2	Does an accessible pathway lead users from any adjoining building required to be accessible (if linked by a pedestrian pathway).	Accessible Pathway	TBA				Pathway not detailed at 60% Review
16.04	AS 1428.1 Cl. 4.2	If there is an abutment of surfaces on the pathway, are they no greater than 3mm if the abutment is vertical, or 5mm if a bevelled edge.	Accessible Pathway	TBA				Pathway not detailed at 60% Review
16.05	AS 1428.1 Cl. 4.2 Figure 7(A)	If raked joint pavers are used, is the abutment of surfaces appropriate.	Pavers	TBA				Pathway not detailed at 60% Review
16.06	AS 1428.1 Cl. 3.3	Are all accessways a min. width of 1000mm.	Accessway 1000mm		Y			
16.07	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.4	Do accessways provide a passing space where a direct line of sight is not available to the end of the walkway (max. 20m intervals) (min. 1800mm wide x 2000mm long).	Passing Space	TBA				Pathway not detailed at 60% Review
16.08	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.5	Do accessways provide a turning space near the end of the walkway where it is not possible to continue (within 2m of end).	Turning Space	TBA				Pathway not detailed at 60% Review
16.09	AS 1428.1 Cl. 3.5	If a change of direction is required, is there appropriate circulation space provided along the accessway for the angle of the turn.	Circulation Space	TBA				Pathway not detailed at 60% Review
16.10	AS 1428.1 Cl. 3.2	Does the full length of the pathway have overhead clearance of 2000mm (1980mm allowed at doorway).	Overhead Clearance		Y			
16.11	AS 1428.1 Cl. 4.1	Does the pathway have a slip-resistant surface with a texture that is traversable by a wheelchair or a person with ambulant or sensory disability.	Slip Resistance	TBA				Pathway not detailed at 60% Review
16.12	AS 1428.1 Cl. 4.1	If a grate is installed on the accessway, are circular openings not greater than 13mm in diameter; or where slotted openings are in use are they not greater than 13mm width and 150mm long and oriented so that the long dimension is transverse to the direction of travel. If linear opening is less than 8mm wide – Where linear openings are less than 8mm wide, orientation is optional.	Grate	TBA				Pathway not detailed at 60% Review
16.13	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3 / 2.5	Are appropriately installed TGSIs provided at existing defined pedestrian crossing point/s with a level transition over a vehi.ular traffic way on the pathway (width x 600 – 800mm, setback 300mm ± 10mm)	TGSI	TBA				Pathway not detailed at 60% Review
16.14	AS 1428.4.1 Cl. 2.2 / 2.3 / 2.5	Are appropriate installed TGSIs provided at existing defined vehicle drop off areas, with blended kerbs and a level transition, if provided on the pathway (width x 600 – 800mm, setback 300mm ± 10mm)	TGSI	TBA				Pathway not detailed at 60% Review
16.15	AS 1428.1 Cl. 10.4	If there is a gate on the pathway, does it have handles and locks inside and outside that can be operated by one hand and are located at an accessible height (900 – 1100mm grasped or turned, 900 – 1200mm if pushed, 900 – 1250mm if touched)	Gate				NA	No Gate
16.16	APS – DP1 AS 1428.1 Cl. 7.1	Is there appropriate circulation space and a level landing at the entrance / childproof gate/s.	Circulation Space				NA	No Gate
16.17	AS 1428.1 Cl 7.2	Is the floor or ground surface abutting the sides of the accessway, firm and level and of a different material to that of the accessway, at the same level as the accessway and extend horizontally for a min of 600mm (unless there is a kerb, a wall, fence, a balustrade or similar barrier).	Floor Surface	TBA				Pathway not detailed at 60% Review
16.18	AS148.2 Cl 7.2	Are appropriate landings provided on accessways (walkways).	Landings	TBA				Pathway not detailed at 60% Review
Universal Accessibility Options: not mandatory								
16.19	AS 1428.2 Cl. 27.1 (b)	Do objects on the accessway, such as seats, tables, drinking fountains, bins etc have a luminance contrast (intensity of light reflected) of not less than 0.3 (30%) to background or surrounding surfaces.	Luminance Contrast	TBA				Pathway not detailed at 60% Review
16.20		Are the edges of the pathways in colour contrast to their background (e.g. colour strip or grass on same ground surface)	Contrast against edge	TBA				Pathway not detailed at 60% Review
16.21	AS 1428.2 Cl. 27.1 (a)	Is seating at a height between 450 – 520mm with armrests between 220 – 300mm above the seat with a back provided along the pathway (min. every 60m) (set back a min. of 500mm).	Seating on pathway	TBA				Pathway not detailed at 60% Review
16.22		Is there uniform appropriate lighting of the pathways for nighttime use.	Lighting	TBA				Pathway not detailed at 60% Review
16.23	AS 1428.4.1 Cl. 3.2 / 3.3	Are warning TGSIs (hazard) provided at changes in direction of directional indicators on the pathway.	TGSI	TBA				Pathway not detailed at 60% Review
16.24		If there is a childproof gate, does it have an accessible doorbell or intercom system, located at a height between 900 – 1200mm, which can be heard from inside the premises	Childproof Gate	TBA				Pathway not detailed at 60% Review
16.25		If the entrance / childproof gate is located within a continual height fence, is it highlighted to assist recognition by a child or a person with vision impairment	Childproof Gage	TBA				Pathway not detailed at 60% Review

R0K036		17.00 Stairs						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
17.01	APS – 3.3 (f) 4.4 / D3.1 / D3.2 / D3.3 / E3.6	Is there an accessible alternative route close to the stairs (e.g. ramp, lift) (where required – see Concessions in Premises Standards)	Accessible Alternative Route close to stairs		Y			Ramp Adjacent to staircase on Ground
17.02	AS 1428.1 Cl. 8.1 (a) (b) / 9	If the stairs abut an internal corridor / external boundary, are they setback to allow a min. of one tread width plus 300mm internally / min. 900mm externally	Setback				NA	Not abutting internal corridor
17.03	APS – D3.8 1 (a) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Are there appropriate TGSIs (hazard – extending the width of path, luminance, depth) at the top and bottom of the stairs.	TGSI	TBA				TGSI existing or proposed not defined at 60% Review
17.04	AS 1428.1 Cl. 11 / AS 1428.4.1 Cl. 2.3 / 2.4	If a non enclosed landing is provided on the stairs, are TGSIs installed as required.	TGSI	TBA				TGSI existing or proposed not defined at 60% Review
17.05	AS 1428.4.1 – Cl. 2.4	If the distance of the landing is 3000mm or more to the nearest nosing edge, are the warning indicators spread over a distance of 600 – 800mm.	TGSI	TBA				TGSI existing or proposed not defined at 60% Review
17.06	AS 1428.1 Cl. 4.1	Do the stairs have a slip resistant surface.	Slip Resistance	TBA				Floor finish not defined at 60% Review
17.07	AS 1428.1 Cl. 8.1 (c)	Are all of the step risers enclosed and of opaque construction.	Step Risers	TBA				Step risers not defined at 60% Review
17.08	AS 1428.1 Cl. 8.1 (f) (g)	Do front edges of stairs nosing have a single strip of continuous colour not less than 50mm and not more than 75mm with a min. 30% luminance contrast (full width of path of travel) (can be set back 15mm) (must not project beyond the face of the riser and not extend more than 10mm down the riser when provided with a contrast and not set back from nosing).	Nosing Strips	TBA				Nosing Strips not defined at 60% Review
17.09	AS 1428.1 Cl. 11.1 (d)	Are the stair nosings level with the face of the riser (riser may be vertical or max. splay backward up to 25mm)	Nosing Strips	TBA				Nosing Strips not defined at 60% Review
17.10	AS 1428.1 Cl. 8.1 (e)	Are the profile of the nosings provided with a sharp transition; rounded up to 5mm radius or chamfered up to 5mm x 5mm.	Nosing	TBA				Profile of Nosing not defined at 60% Review
17.11	APS – D3.8 (3) / 1428.4.1 Cl. 2.2 / 2.3 / 2.4	On a continuous flight of stairs (within an aged care facility), is there a domed button 4 - 5mm high x 10 - 12mm diameter if handrails are not continuous on stair flights and around landings. (on top 150mm from end of rail),					NA	Not an Aged Care Facility
17.12	AS 1428.1 Cl. 8.2	Are appropriate handrails provided on two sides of the stairs (Note: if a balustrade is required at a height greater than the handrail, both shall be provided).	Handrail	TBA				Handrails not defined at 60% Review
17.13	AS 1428.1 Cl. 8.2 / 9 (j)	Are handrails continuous throughout the stair flight, and where practicable on landings.	Handrail	TBA				Handrails not defined at 60% Review
17.14	AS 1428.1 Cl. 8.2 (d) (e) (f)	Do the handrails extend at least one tread width plus 300mm past the edge of the bottom step, and a min of 300mm at the top step (Note: refer AS requirement at intermediate landings).	Handrail	TBA				Handrails not defined at 60% Review
17.15	AS 1428.1 Cl. 8 / 9 (h) (i)	Do the handrails have a min. clearance of 50mm from an adjacent wall and min. 600mm clearance above.	Handrail	TBA				Handrails not defined at 60% Review
17.16	AS 1428.1 Cl. 8 / 9 (i)	Are handrails constructed and fixed, ensuring no obstruction to the passage of the hand along the entire handrail.	Handrail	TBA				Handrails not defined at 60% Review
17.17	AS 1428.1 Cl. 9 (d) (e)	Is the handrail height consistent at a measurement between 865 – 1000mm above the stair nosing (throughout the stairs and on any landing) Construction tolerance of 10mm allowable and Height of handrail may vary at stairway handrail extension or where handrail transitions between flights or to a balustrade).	Handrail	TBA				Handrails not defined at 60% Review
17.18	AS 1428.1 Cl. 9 (b)	Do the handrails have a circular diameter of 30 – 52mm for a min. of 270°.	Handrail	TBA				Handrails not defined at 60% Review
17.19	AS 1428.1 Cl. 8.2 (c)	Do the handrails follow the angle of the nosings.	Handrail	TBA				Handrails not defined at 60% Review
17.20	AS 1428.1 Cl. 9 (c)	Are exposed edges and corners of handrails provided with a radius of not less than 5mm.	Handrail	TBA				Handrails not defined at 60% Review
17.21	AS 1428.1 Cl. 8. 2 (b)	Is there a min. clearance of 1000mm between handrails.	Handrail	TBA				Handrails not defined at 60% Review
17.22	AS 1428.1 Cl. 9 (g)	Are the handrails securely fixed, with ends returned to a side wall / post or turned through 180°.	Handrail	TBA				Handrails not defined at 60% Review
17.23	AS 1428.1 Cl. 9 (a)	Do the handrails (and balustrades) sit outside of required circulation spaces.	Handrail	TBA				Handrails not defined at 60% Review
Universal Accessibility Options: not mandatory								
17.24		Are the tread heights between 150 – 165mm high AS 1428.2 – Cl. 13.2	Tread Heights	TBA				Tread Heights not defined at 60% Review
17.25		Are the treads a min. of 275 – 300mm deep AS 1428.2 – Cl. 13.2	Tread depth	TBA				Tread Depths not defined at 60% Review
17.26		Is there appropriate, uniform lighting of the stairs for night time use	Lighting	TBA				Lighting not defined at 60% Review
17.27		Are the handrails of non-reflective material and a contrasting colour to the background	Handrail Materials	TBA				Handrails not defined at 60% Review

ROK036	18.00 Tactile Ground Surface Indicators							
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
18.01	AS 1428.4.1 Cl. 2.5	Are there appropriate hazard tactile ground surface indicators (TGSIs) prior to a hazard (e.g. roadway) i.e. (width x 600 – 800mm, setback 300mm ± 10mm).	Appropriate TGSI				NA	
18.02	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3 / 2.5	Are appropriately installed TGSIs provided at existing defined pedestrian crossing point/s with a level transition over a vehicular traffic way on the pathway(width x 600 – 800mm setback 300mm ± 10mm).	Pedestrian Crossing TGSI				NA	
18.03	AS 1428.4.1 Cl. 2.2 / 2.3 / 2.5	Are appropriate installed TGSIs provided at existing defined vehicle drop off areas, with blended kerbs and a level transition, if provided on the pathway (width x 600 – 800mm setback 300mm ± 10mm).	Vehicle dropoff TGSI				NA	
18.04	APS – D3.8 1 (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Are there appropriate TGSIs (hazard – extending the width of path, luminance, depth) at the top and bottom of a ramp (as required).	Ramp TGSI	TBA				TGSIs not defined at 60% Review
18.06	AS 1428.1 Cl. 11 / AS 1428.4.1 Cl. 2.3 / 2.4	If a non enclosed landing is provided on the stairs, are TGSIs installed as appropriate.	Non-enclosed landing TGSI	TBA				TGSIs not defined at 60% Review
18.07	AS 1428.4.1 Cl. 2.4	If the distance of the landing is 3000mm or more to the nearest nosing edge, are the warning indicators spread over a distance of 600 – 800mm.	Landing TGSI	TBA				TGSIs not defined at 60% Review
18.08	APS – D3.8 / AS 1428.4.1 Cl. 2.6	If there is an overhead obstruction less than 2000mm (other than a doorway) are appropriate TGSIs installed (in the absence of any other barrier) (e.g. undercroft of stairs) (NOTE: an alternative type of barrier is preferred).	Overhead Obstruction TGSI		Y			No Overhead Obstructions identified at 60% Review
18.09	AS 1428.4.1 Cl. 2.3.3 (b)	Are the warning indicators installed at right angles to path of travel on pathways.	Warning Indicators	TBA				Warning Indicators not defined at 60% Review
18.10	AS 1428.4.1 Cl. 2.3.3 (c) / 3.4 / 3.5	Are there warning indicators installed along edges of hazardous areas e.g. train platforms, wharves, level roadway crossing points etc.	Warning Indicators	TBA				Warning Indicators not defined at 60% Review
18.11	AS 1428.4.1 Cl. 2.2 / App. E	Are TGSIs installed with appropriate contrasts to background surfaces.	TGSI Contrast	TBA				TGSIs not defined at 60% Review
18.12	AS 1428.4.1 Cl. 2.3	Are the TGSIs installed to ensure no tripping hazard is produced.	No Tripping Hazards	TBA				TGSIs not defined at 60% Review
Universal Accessibility Options: not mandatory								
18.13	AS 1428.4.1 Cl. 3.1 (c) (i)	Are there appropriate directional TGSIs on any pathway adjacent where a kerb ramp is at a mid block section or not on a direct path of travel.	Directional TGSI	TBA				TGSIs not defined at 60% Review
18.14	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3	Are TGSIs provided at changes in direction on the pathway to the PPE.	Directional TGSI	TBA				TGSIs not defined at 60% Review
18.15	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3	Are warning TGSIs (hazard) provided at changes in direction of directional indicators on the pathway to the PPE.	Warning TGSI	TBA				TGSIs not defined at 60% Review
18.16		Are there any appropriate TGSIs (hazard) indicators prior to the existing kerb ramps on the pathway (width x 600 – 800mm, setback 300mm ± 10mm).	Kerb Ramps	TBA				TGSIs not defined at 60% Review
18.17	AS 1428.4.1 App. D	Are there directional indicators installed to provide direction to elements e.g. bus stops, kerb ramps, street furniture, toilets, train platforms, road crossings etc.	External Kerb Ramps	TBA				TGSIs not defined at 60% Review
18.18	AS 1428.4.1 App. A 3.1	Are TGSIs used with consistent application throughout an area.	TGSI	TBA				TGSIs not defined at 60% Review
18.19		Are the TGSIs well maintained.	TGSI	TBA				TGSIs not defined at 60% Review
18.20		Are the TGSIs used to promote pedestrian safety.	TGSI	TBA				TGSIs not defined at 60% Review

ROK036		19.00 Ramps						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
19.01	APS – D3.11	If a vertical rise of more than 3.6m is provided through a series of connected ramps, is an alternative means of access provided.	Rise of more than 3.6 m				NA	
19.02	AS 1428.1 Cl. 7.3	Do all ramps have a slope / gradient where the max. ratio is 1:14 (tolerance 3% provide no section is steeper than 1:14).	Gradient		Y			
19.03	AS 1428.1 Cl. 7.3	Do the 1:14 ramps have landings a min. of every nine metres or less at changes in directions.	Landings every 9m		Y			
19.04	AS 1428.1 Cl. 7.3	If the ramp abuts an internal corridor, is it set back a min of 400mm or, if it abuts an external boundary a min. of 900mm.	Corridor abut setback				NA	
19.05	APS – D3.11 (b)	If there are connected ramps / step ramps, are the landings free from any overlap.	Connected Ramps				NA	
19.06	AS 1428.1 Cl. 7.8	Are landings 1200mm (where no change of direction required) in length or greater) (NOTE: sharp transitions are required between the planes of landings and ramps, refer AS for gradients).	Landing 1200mm - no direction change				NA	
19.07	AS 1428.1 Cl. 7.8	If the landing has a change of direction not exceeding 90°, is the landing a min. 1500mm, with the internal corner truncated for a min of 500mm in both directions.	Landing 1500mm - max 90 degree turn				NA	
19.08	AS 1428.1 Cl. 7.8	If the landing has a 180° turn, is the landing a min. of 1540mm deep with other required dimensions as per the Standard.	Landing 1540mm - 180 degree turn				NA	
19.09	AS 1428.1 Cl. 7.8	If the landing is at a door, which is approached from the side, is there appropriate circulation space.	landing at door				NA	No landing at a door
19.10	AS 1428.1 Cl. 7.8	If the ramp is constructed with a change of direction, does the angle of approach create a 90° angle to the line of transition between the ramp surface and the landing surface.	angle of approach at 90 degree				NA	No change of direction
19.11	AS 1428.1 Cl. 9	Do all ramps have an unobstructed width (in between handrails) a min. of 1000mm.	unobstructed width 1000mm		Y			
19.12	AS 1428.1 Cl. 7.3	Do any ramps (and landings as approp.) have kerbs on both sides with the top between 65 – 75mm, or higher than 150mm (see fig 18 AS).	Kerbs on both sides					Detail not on ramp at 60% Review
19.13	AS 1428.1 Cl. 3	Does the full length of any ramp have min. overhead clearance of 2000mm.	Overhead Clearance		Y			No evidence that overhead clearance less than 2000mm
19.14	AS 1428.1 – Cl. 7.4	If ramps are curved, do they have a min. width of 1500mm and end with 1500mm long straight landings.	Curved Ramp				NA	Ramp not curved
19.15	AS 1428.1 Cl. 4.2	Is the ramp surface slip resistant with smooth transitions between different sections (i.e. abutment of surfaces).	TGSI	TBA				Detail not on ramp at 60% Review
19.16	APS – D3.8 (1) (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Are there appropriate TGSI's (hazard – extending the width of path, luminance, depth) at the top and bottom of the ramp (NOTE: refer to AS for differing requirements for landings).	TGSI	TBA				Detail not on ramp at 60% Review
19.17	AS 1428.1 Cl. 7.3/9	Do all ramps have appropriate handrails on two sides (Note: if a balustrade is required at a height greater than the handrail, both shall be provided).	Ramp handrail	TBA				Detail not on ramp at 60% Review
19.18	AS 1428.1 Cl. 9	Do the handrails have a circular diameter of 30 – 50mm for a min. of 270°.	Ramp handrail	TBA				Detail not on ramp at 60% Review
19.19	AS 1428.1 Cl. 9	Are exposed edges (at ends) and corners of handrails provided with a radius of not less than 5mm.	Ramp handrail	TBA				Detail not on ramp at 60% Review
19.20	AS 1428.1 Cl. 9	Is the handrail height consistent (measured at a height between 865 - 1000mm) throughout the ramp and any landing.	Ramp handrail	TBA				Detail not on ramp at 60% Review
19.21	AS 1428.1 Cl. 9	Do the handrails have a min. clearance of 50mm from an adjacent wall and min. 600mm clearance above.	Ramp handrail	TBA				Detail not on ramp at 60% Review
19.22	AS 1428.1 Cl. 7.3/9	Do the handrails extend a min. of 300mm past the ends of the ramp.	Ramp handrail	TBA				Detail not on ramp at 60% Review
19.23	AS 1428.1 Cl. 9/9	Are handrails constructed and fixed, ensuring no obstruction to the passage of the hand along the entire handrail.	Ramp handrail	TBA				Detail not on ramp at 60% Review
19.24	AS 1428.1 Cl. 9/9	Are handrails securely fixed, with ends returned to a side post / wall or downwards through 180°.	Ramp handrail	TBA				Detail not on ramp at 60% Review
19.25	AS 1428.1 Cl. 9	Do the handrails (and balustrades) sit outside of required circulation spaces.	Ramp handrail	TBA				Detail not on ramp at 60% Review
19.26	AS 1428.1 Cl. 7.6	If less than 1900mm in length, does the step ramp have a gradient a max. ratio of 1:10 and a max. rise 190mm.	Step Ramp				NA	No evidence of Step Ramp
19.27	AS 1428.1 Cl. 7.6.2	If a step ramp is installed and there is pedestrian cross traffic, do the edges of the step ramp have a 45° splay or a wall, fence, balustrade or suitable barrier or a kerb or where an open balustrade is provided, a kerb or kerb rail.	Step Ramp				NA	No evidence of Step Ramp
19.28	AS1428.1 Cl 7.6.1	If a step ramp is installed, is the top and bottom aligned at 90 degrees to the direction of travel and have sharp transitions at the top and bottom and at any tapered or splayed edges	Step Ramp				NA	No evidence of Step Ramp
19.29	AS 1428.1 Cl. 7.6/8	If the landing at the top and bottom of the step ramp follows the direction of travel, is it a min. of 1200mm long.	Step Ramp				NA	No evidence of Step Ramp
19.30	AS 1428.1 Cl. 7.6/8	If the landing at the top and bottom of the step ramp requires a change of direction, is it a min. of 1500mm.	Step Ramp				NA	No evidence of Step Ramp
19.31	AS 1428.1 Cl. 7.8 / 10	If the landing at the top and bottom of the step ramp is at a doorway, is the appropriate door circulation space provided.	Step Ramp				NA	No evidence of Step Ramp
19.32	AS 1428.1 Cl. 7.5	If there is a threshold ramp at the doorway, does it have sharp transitions at the top and bottom and be located not more than 20mm from door leaf it serves, not more than 280mm in length and a min. ratio of 1:8.	Threshold Ramp				NA	No evidence of Threshold Ramp
19.33	AS 1428.1 Cl. 7.5	If the threshold ramp does not abut a wall or kerb, are sides tapered or splayed (min. 45°).	Threshold Ramp				NA	No evidence of Threshold Ramp
Universal Accessibility Options: not mandatory								
19.34	AS 1428.2 Cl. 8.4.5	Do the edges of the ramps have colour contrast to their background.	Colour Contrast	TBA				Detail not on ramp at 60% Review
19.35	AS 1428.2 Cl. 19	Is there appropriate uniform lighting of the ramp for night time use.	Luminance	TBA				Detail not on ramp at 60% Review
19.36		Are the handrails of non-reflective material and a contrasting colour to the background.	Handrails	TBA				Detail not on ramp at 60% Review

ROK036		20.00 Signage						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
20.01	APS – DP1 (b) / AS 1428.1 CL 5.1	Is appropriate signage available where directional decisions are made.	Directional Signage	TBA				Signage not defined at 60% Review
20.02	APS – D3.6 (e) / D4 / AS 1428.1 Cl. 5.1	If there is a non accessible entrance doorway, is there appropriate signage provided directing users to accessible entrance.	Non-Accessible Access Signage	TBA				Signage not defined at 60% Review
20.03	APS – D3.6 / D4 / AS 1428.1 Cl. 5.2	Where the symbol for access is used, does it comply with the international standard in style, colour and layout.	Symbol for Access	TBA				Signage not defined at 60% Review
20.04	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Symbol for Deafness	TBA				Signage not defined at 60% Review
20.05	APS – D3.6 (b) (ii) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2	Does signage including the international symbol of deafness, indicate which type of system is in place.	Symbol for Deafness	TBA				Signage not defined at 60% Review
20.06	APS D3.6 (b) (iii)	If receivers are being used for hearing augmentation, does the signage indicate where the receivers can be obtained.	Hearing Augmentation Signage	TBA				Signage not defined at 60% Review
20.07	APS – D3.6 (b) / D4 / AS 1428.1 Cl. 5.1	Is raised tactile information provided on signs between 1200 – 1600mm.	Signage Raised Text	TBA				Signage not defined at 60% Review
20.08	APS – D4.5	Is there appropriate illumination of signage for day and night use (where required e.g. to maintain luminance).	Illumination	TBA				Signage not defined at 60% Review
20.09	APS – D3.6 (f) / D4	If there is a non-accessible toilet provided, is there signage available that directs users to an accessible toilet (where in different locations).	Signage to Accessible toilet at non-accessible toilet	TBA				Signage not defined at 60% Review
20.10	APS – D3.6 (c) / D4 / AS 1428.1 Cl. 5.1	Does the signage indicate if the accessible toilet facility is suitable for left or right hand.	L or R Hand Accessible Facility	TBA				Signage not defined at 60% Review
20.11	APS – D4.3 (2); Title Case AS 1428.1 C 5.1	If available on the sign, is the text provided in Title Case.	Signage - Title Case	TBA				Signage not defined at 60% Review
20.12	APS-D3.6 (a) / AS 1428.1 Cl. 5.1	Is there signage (incorporating raised text and Braille, and raised and visual symbols) installed identifying available sanitary facilities.	Signage to All Toilets	TBA				Signage not defined at 60% Review
20.13	APS – D3.6 (d) / AS 1428.1 Cl. 5.1	If there is an ambulant toilet, is appropriate signage installed at the airlock serving the area that contains the facilities identifying the facilities within.	Signage Ambulant Toilet	TBA				Signage not defined at 60% Review
20.14	APS – D3.6 (d) / AS 1428.1 Cl. 5.1	If there is an ambulant toilet, is there signage to identify the facility (Note: may be located on door if required).	Signage Ambulant Toilet	TBA				Signage not defined at 60% Review
Universal Accessibility Options: not mandatory								
20.15		Is signage (including tactile and Braille) located at the main building entry, both inside and out, giving directional and general information about buildings and facilities including services and access for people with disabilities.	Main Entry Signage	TBA				Signage not defined at 60% Review

ROK076 01.00 Entrances								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
1.01	APS – D3.2 (2) (a)	If there is more than one pedestrian entrance, are 50% of them accessible (including the principal pedestrian entrance)	Entrance		Y			
1.02	APS – D3.2 (2) (b)	If the building is more than 500m² is any non accessible entry within 50m from an accessible entry.	Accessible Entry within 50m of Non-Accessible Entry				NA	
1.03	APS – D3.6 (e) Cl. 5.1	If there is a non accessible entrance doorway, is there appropriate signage provided (int. Symbol, direction arrow) directing users to an accessible entrance.	Non-Accessible Door Signage				NA	
1.04	APS – D3.2 (3) (a) (4) fig D3.2	If the pedestrian entrance is required to be accessible and consists of not more than 3 doorways, is not less than one doorway accessible.	Less than 3 doorways				NA	Doors not defined at 60% Review
1.05	AS 1428.1 Cl. 10.4.3 / AS 1428.2 Cl. 28	If there are security entry controls (card / buttons / intercom) are these at 900 – 1100mm-grasped/turned, 900-1200mm-pushed, 900-1250mm (not less than 500mm from corner)-touched, (<i>ticket slot 800 – 900mm</i>), and easy to operate.	Security door controls	TBA				Door hardware and security not defined at 60% Review
1.06	APS - A1.1	If there is a revolving door / turnstile, is there an alternative accessible hinged / sliding door	Revolving Door	TBA				Door hardware not defined at 60% Review
1.07	AS 1428.1 Cl. 10.4.2	Can the door be unlocked and opened by one hand (i.e. D or D lever handles).	Door Handle	TBA				Door hardware not defined at 60% Review
1.08	AS 1428.1 Cl. 10.4.2 (b)	Is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handle	TBA				Door hardware not defined at 60% Review
1.09	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles, snibs, locks) that need to be grasped or turned located between 900 – 1100mm high.	Door Controls	TBA				Door hardware not defined at 60% Review
1.10	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed located between 900 – 1200mm high.	Door Controls	TBA				Door hardware not defined at 60% Review
1.11	AS 1735.12 AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched located between 900 – 1250mm high and not less than 500mm from an internal corner except as specified in AS 1735.12 AS 1428.1 Cl. 10.4.3 (c)	Door Controls	TBA				Door hardware not defined at 60% Review
1.12	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handle	TBA				Door hardware not defined at 60% Review
1.13	AS 1428.1 Cl. 10.4.2 (f)	If an outward opening door is not self closing, is there a horizontal handrail or pull bar installed at a height between 900 – 1100mm (min. 50mm clearance from edge of door / door handle) on the inside of the door.	Door Handle	TBA				Door hardware not defined at 60% Review
1.14	AS 1428.1 Cl. 10.4.4	If doors are power operated, are the push button controls a min. of 25mm dia., proud of the surface (activating door before the button becomes level with surrounding surface).	Power operated door	TBA				Door hardware not defined at 60% Review
1.15	AS 1428.1 Cl. 10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 500 – 1000mm from arch of the hinged door leaf (in any position) / or clear of a surface-mounted sliding door in the open position.	Power operated door	TBA				Door hardware not defined at 60% Review
1.16	AS 1428.1 Cl. 3.6	If the doors / sidelights are frameless or fully glazed, are they clearly marked for safety and ease of identification across the full door width, with a solid and non-transparent contrasting line (viewable from 2m inside and outside) (luminance 30%). Size of line not less than 75mm high, with the lower edge at a height of 900 – 1000mm above finished floor level.	Door Material	TBA				Door hardware not defined at 60% Review
1.17	AS 1428.1 Cl. 10.1	Do all the doors or doorframes have a min. luminance contrast of 30% to their adjacent surfaces.	Door Frame Contrast	TBA				Door hardware not defined at 60% Review
1.18	AS 1428.1 Cl. 10.4.2 (e)	Is the entrance door easy, to initially open, (no heavy closer or spring) 20N max. (4.3lbf)	Door Pressure	TBA				Door closers not defined at 60% Review
1.19	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	Is the min. clear opening of a doorway at the PPE 850mm or greater.	Min clear opening	TBA				Doors or gates to the entrance not defined at 60% Review
1.20	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	If the doorway has 2 independent operated leaves, is the open doorway a min. of 850mm wide.	2 leaves	TBA				Door leaf size not defined at 60% Review
1.21	AS 1428.1 Cl. 7.5 / 7.5	Is the door threshold level or is there an appropriate threshold ramp available at the entry (i.e. no step, inappropriate mat, weather strip etc.)	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.22	AS 1428.1 Cl. 7.5	If there is a threshold (max. rise 35mm) at the entrance or doorway (not more than 20mm from door leaf it serves), is there a ramp of not more than 280mm in length and min. ratio of 1:8. (Note: if the rise is greater a step ramp will be required).	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.23	AS 1428.1 Cl. 7.5	If the threshold ramp does not abut a wall or kerb, are sides tapered or splayed (min. 45°)	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.24	AS 1428.1 Cl. 4.2	If there is a recessed mat within the CAPT is the abutment of the surfaces no more than 3mm if vertical or 5mm if bevelled (rounded).	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.25	AS 1428.1 Cl. 4.3.1	If there is a carpet leading edge at the entrance is there a vertical face no higher than 3mm or a rounded bevelled edge no higher than 5mm or above that height a gradient of 1:8 up to a total max. height of 10mm.	Carpet	TBA				Door thresholds not defined at 60% Review
1.26	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space outside the entrance doorway (not steeper that 1:40) (Doorway circulations spaces may overlap other circulation spaces).	Circulation Space outside		YES			
1.27	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space inside the entrance doorway (not steeper that 1:40) (Doorway circulations spaces may overlap other circulation spaces).	Circulation Space inside		YES			
1.28	AS 1428.1 Cl. 10.3.5	If there is an airlock, vestibule, or enclosed space, is there not less than 1450mm between the doorway (plus the door leaf width if the door encroaches into the space).	Airlock				NA	No Airlock defined at 60% Review
1.29	AS 1428.1 Cl. 3.7	If there are glazed viewing panels in doors, is the lower edge of the glazing not more than 1000mm above FFL, upper edge not less than 1600mm above FFL.	Glazed Viewing Panels	TBA				Door leaf + viewing panels not defined at 60% Review

ROK076 01.00 Entrances								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
1.30	AS 1428.1 Cl 3.7	If there are glazed viewing panels in doors, is the width of the glazing within 200mm from latch edge of the door and min 150mm wide.	Glazed Viewing Panels	TBA				Door leaf + viewing panels not defined at 60% Review
Universal Accessibility Options: not mandatory								
1.37	AS 1428.2 Cl. 23.3 (b)	Are the door handles provided with an appropriate luminance contrast	Door Handles	TBA				Door hardware not defined at 60% Review
1.38		Do automatic self-opening doors have effective motion, and presence sensors installed	Automatic Doors	TBA				Door Control not defined at 60% Review
1.39		If there is an alarm control pad, is it located at a height between 900 – 1200mm high, accessible and easy to operate	Door Control	TBA				Door hardware not defined at 60% Review
1.40		If there is a doorbell, is it accessible and easy to operate, located at a height between 900 – 1200mm	Doorbell	TBA				Door hardware not defined at 60% Review
1.41		Is there appropriate lighting at the PPE	Lighting	TBA				Lighting not defined at 60% Review

ROK076 03.00 Internal Accessways

Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
3.01	AS 1428.1 Cl. 3.3	Does the accessway have a min. width of 1000mm i.e. structurally and maintained to remain clear of temporary obstructions e.g. pot plants, bins.	Min Width		Y			1500mm
3.02	AS 1428.1 Cl. 3.2	Does the full length of the accessway have an overhead clearance of 2000mm (1980mm allowed at doorway)	Overhead Clearance		Y			
3.03	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.4	Do accessways provide a passing space where a direct line of sight is not available to the end of the walkway (max. 20m intervals) (min. 1800mm wide x 2000mm long)	Turn Circle		Y			
3.04	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.5	Do accessways provide a turning space near the end of the walkway where it is not possible to continue (within 2m of end)	Turn Circle		Y			
3.05	AS 1428.1 Cl. 3.5	If a change of direction is required, is there appropriate circulation space provided along the accessway for the angle of the turn.	Circulation		Y			
3.06	AS 1428.1 Cl. 4.1	Does the accessway have a slip-resistant surface with a texture that is traversable by a wheelchair.	Slip Resistant		Y			Brushed Concrete
3.07	APS – D3.6 (e) AS 1428.1 CL 5	If there is a non-accessible entrance doorway, is there appropriate signage provided (int. Symbol, direction arrow) directing users to an accessible entrance	Signage				NA	
3.08	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	Is the min. clear opening of a doorway on any accessway 850mm or greater.	Min Clear open		Y			No evidence of doorways that are less than 850mm
3.09	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space outside the doorway (NOTE: 1:40 grade, additional considerations at surface mounted sliding doors) (Doorway circulation space may overlap other circulation spaces)	Circulation		Y			No evidence of inappropriate circulation spaces outside each doorway. To be checked again at 60%
3.10	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space inside the doorway (NOTE: 1:40 grade, additional considerations at surface mounted sliding doors) (Doorway circulation space may overlap other circulation spaces)	Circulation		Y			No evidence of inappropriate circulation spaces inside each doorway. To be checked again at 60%
3.11	AS 1428.1 Cl. 10.4.2 (a)	Can the door be unlocked and opened by one hand (i.e. D or D lever handles)	Door Handles	TBA				Door hardware not designed at 60% Review
3.12	AS 1428.1 Cl. 10.4.2 (b)	Is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handles	TBA				Door hardware not designed at 60% Review
3.13	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles) that need to be grasped or turned between 900 – 1100mm high.	Door Handles	TBA				Door hardware not designed at 60% Review
3.14	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed between 900 – 1200mm high.	Door Handles	TBA				Door hardware not designed at 60% Review
3.15	AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched between 900 – 1250mm high (and not less than 500mm from an internal corner, except as specified in AS 1735.12)	Door Handles	TBA				Door hardware not designed at 60% Review
3.16	AS 1428.1 Cl.10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 1000 – 2000mm from the hinged swing door leaf (in any position) / or doorway of sliding door.	Power Door	TBA				Doors that are power operated not designed at 60% Review
3.17	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handles	TBA				Door hardware not designed at 60% Review
3.18	AS 1428.1 Cl. 10.4.2 (e)	Are all doors (other than fire / smoke doors) provided with the appropriate opening force (20N).	Door Force	TBA				Door Force not designed at 60% Review
3.19	AS 1428.1 Cl. 10.3.5	If there is an airlock, vestibule, or enclosed space, is there not less than 1450mm between the doorway (plus the door leaf width if the door encroaches into the space).	Air Vestibule				NA	No airlocks designed at 60% Review
3.20	AS 1428.1 Cl. 10.4.2 (g)	If an outward opening door is not self closing, is there a horizontal handrail or pull bar installed at a height between 900 – 1100mm (min. 50mm clearance from edge of door / door handle) on the inside of the door.	Hoor Handles	TBA				Door hardware not designed at 60% Review
3.21	AS 1428.1 Cl 11.1	Are all switches and controls provided on a CAPT (other than general purpose outlets (GPOs)) located at a height of 900 – 1100mm and not less than 500mm from an internal corner.	Switches and Controls	TBA				Door hardware not designed at 60% Review

ROK076 09.00 Hearing Augmentation								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
09.01	APS – D3.7 (1) (2) (3)	If a sound amplification system is installed / inbuilt is there a hearing augmentation system that covers 80% of the total enclosed space if an induction loop is inbuilt, or 95% if a receiver system in use.	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.02	APS – D3.7 (1) (2) (3)	Is hearing augmentation available at any screened / enclosed reception area / ticket or tellers cash booth (that has an inbuilt amplification system).	Screened Booth				NA	
09.02	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl 5.2.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Signage	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.03	APS – D3.6 (b) (ii) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, indicate which type of system is in place.	Signage	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.04	APS D3.6 (b) (iii)	If receivers are being used, does the signage indicate where the receivers can be obtained.	Signage	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.05	APS – D3.7 (4)	If a screen or scoreboard is capable of displaying public announcements, is it capable of supplementing any public address system (other than a system used for emergency warning purposes only).	Signage	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.06	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl 5.2.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Signage	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
Universal Accessibility Options: not mandatory								
09.07	AS 1428.5 - 3	Is hearing augmentation available in meeting rooms (seating 5 or more participants).	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.08	AS 1428.5 - 3	Is hearing augmentation available in any lift to assist with communication in an emergency.	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.09		Is appropriate seating with backs and armrests available that provides good lines of sight for lip reading.	Seating lines of sight	TBA				Tiered seating not defined at 60% Review
09.10		Are there acoustic design elements to reduce noise e.g. rubber tips on furniture legs, soft furnishings, low pile carpet, double glazing, quiet equipment etc.	Acoustic Design Elements	TBA				Finishes not defined at 60% Review
09.11	AS 1428.5 - 3	Are there visible alarms at any security checkpoint.	Alarms	TBA				Security not defined at 60% Review
09.12		Are there visible emergency alarms throughout the building.	Alarms	TBA				Security not defined at 60% Review
09.13		Is there effective lighting for lip reading and sign language interpreters.	Lighting	TBA				Luminance not defined at 60% Review

ROK076 10.00 Contrasts								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
10.01	AS 1428.1 Cl. 10.1	Doorways / frames / walls etc	Door Contrast	TBA				Finishes not defined at 60% Review
10.02	AS 1428.1 Cl. 3.6	Glass doors (solid, non-transparent contrasting strip across full width of glass and side partitions)	Glass Doors				NA	
10.03	APS – D3.8 1 (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Ramps (TGSIs at top and bottom - as required)	Ramp TGSI				NA	No Ramps at 50 % Review
10.04	APS – D4.5	Signs	Signage	TBA				Signage not defined at 60% Review
10.05	APS – D3.8 1 (a) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Stairs (TGSIs at top and bottom – as required)	Stair TGSI				NA	
10.06	AS 1428.1 Cl. 8.1 (f) (g)	Stair nosing strips	Stair Detailing				NA	Stair detail not defined at 60% Review
10.07	AS 1428.1 – 2021 Cl. 12.2.3 (e)	Toilet seats and cisterns	Sanitary Ware	TBA				Sanitary ware not defined at 60% Review

ROK076 11.00 Floor / Ground Surfaces								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
11.01	AS 1428.1 Cl. 4.1	Is the ground / floor surface firm and level (e.g. with no sharp transitions at abutting surfaces).	Firm Level Surface		Y			Brushed Concrete
11.02	AS 1428.1 Cl. 4.1	Is the floor / ground surface slip resistant (in wet and dry conditions) allowing traction for a person using a wheelchair and people with ambulant or sensory disability.	Slip Resistant		Y			Brushed Concrete
11.03	AS 1428.1 Cl 4.3	If carpeted, is it short pile (<11mm and backing <4mm) and securely attached to the floor surface.	Carpet				NA	No carpet
11.04	AS 1428.1 Cl 4.5	If timber decking boards are installed and are no greater than 150mm wide, is there a maximum 6mm gap between boards.	Timber Decking				NA	No carpet
11.05	AS 1428.1 Cl 4.5	If timber decking boards are installed that are over 150mm wide, is there a maximum gap of 10mm between boards, and if the gap is over 8mm do the boards run transverse to the direction of travel	Timber Decking				NA	No timber decking
11.06	AS 1428.1 Cl 4.5	If timber decking boards are installed, are adjacent boards level with a maximum vertical 3mm tolerance	Timber Decking				NA	No timber decking
Universal Accessibility Options: not mandatory								
11.07		Does the floor / ground surface have effective contrasts to walls and doors / doorframes	Contrast					Floor and Wall Finishes not defined at 60% Review.

ROK076 12.00 Emergency Egress / Evacuation								
Number	Standard	Item	Item	Y	Y	N	NA	Action
Universal Accessibility Options: not mandatory								
12.01		Is there an accessible (e.g. appropriate door handle, clear door opening width, opening force) emergency exit in addition to the main entry	Accessible Emergency Exit	TBA				Emergency Door Material, Hardware, Width etc not defined at 60% Review
12.02		Is there clear, visible, accessible signage on emergency exits	Signage for Exit	TBA				Signage not defined at 60% Review
12.03		Is there a continuous accessible path of travel from the building to any nominated assembly area (e.g. firm path, no steps, stairs, well lit)	CAPT to Assemeby	TBA				Emergency Alarms not defined at 60% Review
12.04		Are audible emergency alarms provided in the building	Alarms	TBA				Emergency Alarms not defined at 60% Review
12.05		Are visible emergency alarms provided in the building	Alarms	TBA				Refuge place not defined at 60% Review
12.06		Are there places of refuge provided for people with mobility difficulties on levels above the main entrance level	Refuge on Level 1	TBA				Refuge place not defined at 60% Review
12.07		Are audible security alarms provided at any security checkpoints	Alarms	TBA				Security Alarms not defined at 60% Review
12.08		Are visible security alarms provided at any security checkpoints	Alarms	TBA				Security Alarms not defined at 60% Review
12.09		Are any fire hoses and extinguishers located at 700 – 1200mm high	Fire Extinguishers	TBA				Fire Strategy not defined at 60% Review
12.10		Is the emergency management plan located at an accessible height in a public area in an accessible format (e.g. large print, tactile, Braille)	Emergency Management Plan	TBA				Emergency Management Plan not defined at 60% Review
12.11		Is there an accessible (e.g. appropriate door handle, clear door opening width, opening force) emergency exit in addition to the main entry	Emergency Exit	TBA				Emergency Exit not defined at 60% Review
12.12		Is there clear, visible, accessible signage on emergency exits	Accessible Emergency Exit Signage	TBA				Emergency Exit not defined at 60% Review

ROK076 15.00 Landscaping								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Universal Accessibility Options: not mandatory								
15.01		Are pathways free from plant species that develop overhanging foliage, and / or leaves or drop seed pods, berries, leaf and bark litter	Foilage				NA	Existing Audit Requirement only
15.02		Are there landscape designs, materials, plants, etc., that contribute to pedestrian safety	Safety in Design				NA	
15.03		Are any plantings used to provide orientation or direction cues for people with vision impairment e.g. distinctive scents, sounds, appearance or texture	Planting				NA	Existing Audit Requirement only
15.04		Are any planter boxes appropriately located clear of any pathway	Planting		Y			
15.05		Are any dense plantings maintained to provide a clear line of sight	Planting				NA	Existing Audit Requirement only

ROK076 18.00 Tactile Ground Surface Indicators								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
18.01	AS 1428.4.1 Cl. 2.5	Are there appropriate hazard tactile ground surface indicators (TGSIs) prior to a hazard (e.g. roadway) i.e. (width x 600 – 800mm, setback 300mm ± 10mm).	Appropriate TGSi	TBA				TGSIs not defined at 60% Review
18.02	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3 / 2.5	Are appropriately installed TGSIs provided at existing defined pedestrian crossing point/s with a level transition over a vehicular traffic way on the pathway(width x 600 – 800mm setback 300mm ± 10mm).	Pedestrian Crossing TGSi				NA	
18.03	AS 1428.4.1 Cl. 2.2 / 2.3 / 2.5	Are appropriate installed TGSIs provided at existing defined vehicle drop off areas, with blended kerbs and a level transition, if provided on the pathway (width x 600 – 800mm setback 300mm ± 10mm).	Vehicle dropoff TGSi				NA	
18.04	APS – D3.8 1 (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Are there appropriate TGSIs (hazard – extending the width of path, luminance, depth) at the top and bottom of a ramp (as required).	Ramp TGSi	TBA				TGSIs not defined at 60% Review
18.06	AS 1428.1 Cl. 11 / AS 1428.4.1 Cl. 2.3 / 2.4	If a non enclosed landing is provided on the stairs, are TGSIs installed as appropriate.	Non-enclosed landing TGSi	TBA				TGSIs not defined at 60% Review
18.07	AS 1428.4.1 Cl. 2.4	If the distance of the landing is 3000mm or more to the nearest nosing edge, are the warning indicators spread over a distance of 600 – 800mm.	Landing TGSi	TBA				TGSIs not defined at 60% Review
18.08	APS – D3.8 / AS 1428.4.1 Cl. 2.6	If there is an overhead obstruction less than 2000mm (other than a doorway) are appropriate TGSIs installed (in the absence of any other barrier) (e.g. undercroft of stairs) (NOTE: an alternative type of barrier is preferred).	Overhead Obstruction TGSi	TBA				No Overhead Obstructions identified at 60% Review
18.09	AS 1428.4.1 Cl. 2.3.3 (b)	Are the warning indicators installed at right angles to path of travel on pathways.	Warning Indicators	TBA				Warning Indicators not defined at 60% Review
18.10	AS 1428.4.1 Cl. 2.3.3 (c) / 3.4 / 3.5	Are there warning indicators installed along edges of hazardous areas e.g. train platforms, wharves, level roadway crossing points etc.	Warning Indicators	TBA				Warning Indicators not defined at 60% Review
18.11	AS 1428.4.1 Cl. 2.2 / App. E	Are TGSIs installed with appropriate contrasts to background surfaces.	TGSi Contrast	TBA				TGSIs not defined at 60% Review
18.12	AS 1428.4.1 Cl. 2.3	Are the TGSIs installed to ensure no tripping hazard is produced.	No Tripping Hazards	TBA				TGSIs not defined at 60% Review
Universal Accessibility Options: not mandatory								
18.13	AS 1428.4.1 Cl. 3.1 (c) (i)	Are there appropriate directional TGSIs on any pathway adjacent where a kerb ramp is at a mid block section or not on a direct path of travel.	Directional TGSi				NA	ROK019 does not include external works.
18.14	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3	Are TGSIs provided at changes in direction on the pathway to the PPE.	Directional TGSi				NA	ROK019 does not include external works.
18.15	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3	Are warning TGSIs (hazard) provided at changes in direction of directional indicators on the pathway to the PPE.	Warning TGSi				NA	ROK019 does not include external works.
18.16		Are there any appropriate TGSIs (hazard) indicators prior to the existing kerb ramps on the pathway (width x 600 – 800mm, setback 300mm ± 10mm).	Kerb Ramps				NA	ROK019 does not include external works.
18.17	AS 1428.4.1 App. D	Are there directional indicators installed to provide direction to elements e.g. bus stops, kerb ramps, street furniture, toilets, train platforms, road crossings etc.	External Kerb Ramps				NA	ROK019 does not include external works.
18.18	AS 1428.4.1 App. A 3.1	Are TGSIs used with consistent application throughout an area.	TGSi	TBA				Existing Condition of TGSi not indicated at 60% Review
18.19		Are the TGSIs well maintained.	TGSi	TBA				Existing Condition of TGSi not indicated at 60% Review
18.20		Are the TGSIs used to promote pedestrian safety.	TGSi	TBA				Existing Condition of TGSi not indicated at 60% Review

ROK076 20.00 Signage								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
20.01	APS – DP1 (b) / AS 1428.1 CL 5.1	Is appropriate signage available where directional decisions are made.	Directional Signage	TBA				Signage not defined at 60% Review
20.02	APS – D3.6 (e) / D4 / AS 1428.1 Cl. 5.1	If there is a non accessible entrance doorway, is there appropriate signage provided directing users to accessible entrance.	Non-Accessible Access Signage	TBA				Signage not defined at 60% Review
20.03	APS – D3.6 / D4 / AS 1428.1 Cl. 5.2	Where the symbol for access is used, does it comply with the international standard in style, colour and layout.	Symbol for Access	TBA				Signage not defined at 60% Review
20.04	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Symbol for Deafness	TBA				Signage not defined at 60% Review
20.05	APS – D3.6 (b) (ii) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2	Does signage including the international symbol of deafness, indicate which type of system is in place.	Symbol for Deafness	TBA				Signage not defined at 60% Review
20.06	APS D3.6 (b) (iii)	If receivers are being used for hearing augmentation, does the signage indicate where the receivers can be obtained.	Hearing Augmentation Signage	TBA				Signage not defined at 60% Review
20.07	APS – D3.6 (b) / D4 / AS 1428.1 CL 5.1	Is raised tactile information provided on signs between 1200 – 1600mm.	Signage Raised Text	TBA				Signage not defined at 60% Review
20.08	APS – D4.5	Is there appropriate illumination of signage for day and night use (where required e.g. to maintain luminance).	Illumination	TBA				Signage not defined at 60% Review
20.09	APS – D3.6 (f) / D4	If there is a non-accessible toilet provided, is there signage available that directs users to an accessible toilet (where in different locations).	Signage to Accessible toilet at non-accessible toilet	TBA				Signage not defined at 60% Review
20.10	APS – D3.6 (c) / D4 / AS 1428.1 Cl 5.1	Does the signage indicate if the accessible toilet facility is suitable for left or right hand.	L or R Hand Accessible Facility	TBA				Signage not defined at 60% Review
20.11	APS – D4.3 (2); Title Case AS 1428.1 C 5.1	If available on the sign, is the text provided in Title Case.	Signage - Title Case	TBA				Signage not defined at 60% Review
20.12	APS-D3.6 (a) / AS 1428.1 Cl 5.1	Is there signage (incorporating raised text and Braille, and raised and visual symbols) installed identifying available sanitary facilities.	Signage to All Toilets	TBA				Signage not defined at 60% Review
20.13	APS – D3.6 (d) / AS 1428.1 Cl. 5.1	If there is an ambulant toilet, is appropriate signage installed at the airlock serving the area that contains the facilities identifying the facilities within.	Signage Ambulant Toilet	TBA				Signage not defined at 60% Review
20.14	APS – D3.6 (d) / AS 1428.1 Cl. 5.1	If there is an ambulant toilet, is there signage to identify the facility (Note: may be located on door if required).	Signage Ambulant Toilet	TBA				Signage not defined at 60% Review
Universal Accessibility Options: not mandatory								
20.15		Is signage (including tactile and Braille) located at the main building entry, both inside and out, giving directional and general information about buildings and facilities including services and access for people with disabilities.	Main Entry Signage	TBA				Signage not defined at 60% Review

ROK092		01.00 Entrances						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
1.01	APS – D3.2 (2) (a)	If there is more than one pedestrian entrance, are 50% of them accessible (including the principal pedestrian entrance)	Entrance		Y			
1.02	APS – D3.2 (2) (b)	If the building is more than 500m² is any non accessible entry within 50m from an accessible entry.	Accessible Entry within 50m of Non-Accessible Entry		Y			Stair at Front Entrance - Ramp Adjacent
1.03	APS – D3.6 (e) Cl. 5.1	If there is a non accessible entrance doorway, is there appropriate signage provided (int. Symbol, direction arrow) directing users to an accessible entrance.	Non-Accessible Door Signage	TBA				Signage not designed at 60% Review
1.04	APS – D3.2 (3) (a) (4) fig D3.2	If the pedestrian entrance is required to be accessible and consists of not more than 3 doorways, is not less than one doorway accessible.	Less than 3 doorways	TBA				Doors not defined at 60% Review
1.05	AS 1428.1 Cl. 10.4.3 / AS 1428.2 Cl. 28	If there are security entry controls (card / buttons / intercom) are these at 900 – 1100mm-grasped/turned, 900-1200mm-pushed, 900-1250mm (not less than 500mm from corner)-touched, (<i>ticket slot 800 – 900mm</i>), and easy to operate.	Security door controls	TBA				Door hardware and security not defined at 60% Review
1.06	APS - A1.1	If there is a revolving door / turnstile, is there an alternative accessible hinged / sliding door	Revolving Door				NA	Door hardware not defined at 60% Review
1.07	AS 1428.1 Cl. 10.4.2	Can the door be unlocked and opened by one hand (i.e. D or D lever handles).	Door Handle	TBA				Door hardware not defined at 60% Review
1.08	AS 1428.1 Cl. 10.4.2 (b)	Is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handle	TBA				Door hardware not defined at 60% Review
1.09	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles, snibs, locks) that need to be grasped or turned located between 900 – 1100mm high.	Door Controls	TBA				Door hardware not defined at 60% Review
1.10	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed located between 900 – 1200mm high.	Door Controls	TBA				Door hardware not defined at 60% Review
1.11	AS 1735.12 AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched located between 900 – 1250mm high and not less than 500mm from an internal corner except as specified in AS 1735.12 AS 1428.1 Cl. 10.4.3 (c)	Door Controls	TBA				Door hardware not defined at 60% Review
1.12	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handle	TBA				Door hardware not defined at 60% Review
1.13	AS 1428.1 Cl. 10.4.2 (f)	If an outward opening door is not self closing, is there a horizontal handrail or pull bar installed at a height between 900 – 1100mm (min. 50mm clearance from edge of door / door handle) on the inside of the door.	Door Handle	TBA				Door hardware not defined at 60% Review
1.14	AS 1428.1 Cl. 10.4.4	If doors are power operated, are the push button controls a min. of 25mm dia., proud of the surface (activating door before the button becomes level with surrounding surface).	Power operated door	TBA				Door hardware not defined at 60% Review
1.15	AS 1428.1 Cl. 10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 500 – 1000mm from arch of the hinged door leaf (in any position) / or clear of a surface-mounted sliding door in the open position.	Power operated door	TBA				Door hardware not defined at 60% Review
1.16	AS 1428.1 Cl. 3.6	If the doors / sidelights are frameless or fully glazed, are they clearly marked for safety and ease of identification across the full door width, with a solid and non-transparent contrasting line (viewable from 2m inside and outside) (luminance 30%). Size of line not less than 75mm high, with the lower edge at a height of 900 – 1000mm above finished floor level.	Door Material	TBA				Door hardware not defined at 60% Review
1.17	AS 1428.1 Cl. 10.1	Do all the doors or doorframes have a min. luminance contrast of 30% to their adjacent surfaces.	Door Frame Contrast	TBA				Door hardware not defined at 60% Review
1.18	AS 1428.1 Cl. 10.4.2 (e)	Is the entrance door easy, to initially open, (no heavy closer or spring) 20N max. (4.3lbf)	Door Pressure	TBA				Door closers not defined at 60% Review
1.19	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	Is the min. clear opening of a doorway at the PPE 850mm or greater.	Min clear opening	TBA				Doors or gates to the entrance not defined at 60% Review
1.20	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	If the doorway has 2 independent operated leaves, is the open doorway a min. of 850mm wide.	2 leaves	TBA				Door leaf size not defined at 60% Review
1.21	AS 1428.1 Cl. 7.5 / 7.5	Is the door threshold level or is there an appropriate threshold ramp available at the entry (i.e. no step, inappropriate mat, weather strip etc.)	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.22	AS 1428.1 Cl. 7.5	If there is a threshold (max. rise 35mm) at the entrance or doorway (not more than 20mm from door leaf it serves), is there a ramp of not more than 280mm in length and min. ratio of 1:8. (Note: if the rise is greater a step ramp will be required).	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.23	AS 1428.1 Cl. 7.5	If the threshold ramp does not abut a wall or kerb, are sides tapered or splayed (min. 45°)	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.24	AS 1428.1 Cl. 4.2	If there is a recessed mat within the CAPT is the abutment of the surfaces no more than 3mm if vertical or 5mm if bevelled (rounded).	Door Threshold	TBA				Door thresholds not defined at 60% Review
1.25	AS 1428.1 Cl. 4.3.1	If there is a carpet leading edge at the entrance is there a vertical face no higher than 3mm or a rounded bevelled edge no higher than 5mm or above that height a gradient of 1:8 up to a total max. height of 10mm.	Carpet	TBA				Door thresholds not defined at 60% Review
1.26	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space outside the entrance doorway (not steeper that 1:40) (Doorway circulations spaces may overlap other circulation spaces).	Circulation Space outside		YES			There appears to be no issue with turning circle outside the lift and the entrance.
1.27	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space inside the entrance doorway (not steeper that 1:40) (Doorway circulations spaces may overlap other circulation spaces).	Circulation Space inside		YES			There appears to be no issue with turning circle outside the lift and the entrance
1.28	AS 1428.1 Cl. 10.3.5	If there is an airlock, vestibule, or enclosed space, is there not less than 1450mm between the doorway (plus the door leaf width if the door encroaches into the space).	Airlock				NA	No Airlock at entrance
1.29	AS 1428.1 Cl. 3.7	If there are glazed viewing panels in doors, is the lower edge of the glazing not more than 1000mm above FFL, upper edge not less than 1600mm above FFL.	Glazed Viewing Panels	TBA				Door leaf + viewing panels not defined at 60% Review
1.30	AS 1428.1 Cl 3.7	If there are glazed viewing panels in doors, is the width of the glazing within 200mm from latch edge of the door and min 150mm wide.	Glazed Viewing Panels	TBA				Door leaf + viewing panels not defined at 60% Review
Universal Accessibility Options: not mandatory								
1.37	AS 1428.2 Cl. 23.3 (b)	Are the door handles provided with an appropriate luminance contrast	Door Handles	TBA				Door hardware not defined at 60% Review
1.38		Do automatic self-opening doors have effective motion, and presence sensors installed	Automatic Doors	TBA				Door Control not defined at 60% Review
1.39		If there is an alarm control pad, is it located at a height between 900 – 1200mm high, accessible and easy to operate	Door Control	TBA				Door hardware not defined at 60% Review

ROK092		01.00 Entrances						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
1.40		If there is a doorbell, is it accessible and easy to operate, located at a height between 900 – 1200mm	Doorbell				NA	Door hardware not defined at 60% Review
1.41		Is there appropriate lighting at the PPE	Lighting	TBA				Lighting not defined at 60% Review

ROK092		03.00 Internal Accessways						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
3.01	AS 1428.1 Cl. 3.3	Does the accessway have a min. width of 1000mm i.e. structurally and maintained to remain clear of temporary obstructions e.g. pot plants, bins.	Min Width			N		Review Markup in Appendix A for issues with furniture layout.
3.02	AS 1428.1 Cl. 3.2	Does the full length of the accessway have an overhead clearance of 2000mm (1980mm allowed at doorway)	Overhead Clearance		Y			There is no evidence that the accessway would not have an overhead clearance of 2m.
3.03	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.4	Do accessways provide a passing space where a direct line of sight is not available to the end of the walkway (max. 20m intervals) (min. 1800mm wide x 2000mm long)	Turn Circle		Y			All Accessways have direct line of sight to the end. Accessways also have turning circles at each end.
3.04	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.5	Do accessways provide a turning space near the end of the walkway where it is not possible to continue (within 2m of end)	Turn Circle		Y			No evidence of inadequate turning space in internal accessways. To be checked again at 60%
3.05	AS 1428.1 Cl. 3.5	If a change of direction is required, is there appropriate circulation space provided along the accessway for the angle of the turn.	Circulation		Y			No evidence of inadequate circulation space
3.06	AS 1428.1 Cl. 4.1	Does the accessway have a slip-resistant surface with a texture that is traversable by a wheelchair.	Slip Resistant	TBA				Surface for accessway not designed at 60% Review
3.07	APS – D3.6 (e) AS 1428.1 CL 5	If there is a non-accessible entrance doorway, is there appropriate signage provided (int. Symbol, direction arrow) directing users to an accessible entrance	Signage	TBA				Signage not designed at 60% Review
3.08	APS – D3.2 (5) / AS 1428.1 Cl. 10.2	Is the min. clear opening of a doorway on any accessway 850mm or greater.	Min Clear open		Y			No evidence of doorways that are less than 850mm
3.09	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space outside the doorway (NOTE: 1:40 grade, additional considerations at surface mounted sliding doors) (Doorway circulation space may overlap other circulation spaces)	Circulation		Y			No evidence of inappropriate circulation spaces outside each doorway. To be checked again at 60%
3.10	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space inside the doorway (NOTE: 1:40 grade, additional considerations at surface mounted sliding doors) (Doorway circulation space may overlap other circulation spaces)	Circulation		Y			No evidence of inappropriate circulation spaces inside each doorway. To be checked again at 60%
3.11	AS 1428.1 Cl. 10.4.2 (a)	Can the door be unlocked and opened by one hand (i.e. D or D lever handles)	Door Handles	TBA				Door hardware not designed at 60% Review
3.12	AS 1428.1 Cl. 10.4.2 (b)	Is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handles	TBA				Door hardware not designed at 60% Review
3.13	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles) that need to be grasped or turned between 900 – 1100mm high.	Door Handles	TBA				Door hardware not designed at 60% Review
3.14	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed between 900 – 1200mm high.	Door Handles	TBA				Door hardware not designed at 60% Review
3.15	AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched between 900 – 1250mm high (and not less than 500mm from an internal corner, except as specified in AS 1735.12)	Door Handles	TBA				Door hardware not designed at 60% Review
3.16	AS 1428.1 Cl.10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 1000 – 2000mm from the hinged swing door leaf (in any position) / or doorway of sliding door.	Power Door	TBA				Doors that are power operated not designed at 60% Review
3.17	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handles	TBA				Door hardware not designed at 60% Review
3.18	AS 1428.1 Cl. 10.4.2 (e)	Are all doors (other than fire / smoke doors) provided with the appropriate opening force (20N).	Door Force	TBA				Door Force not designed at 60% Review
3.19	AS 1428.1 Cl. 10.3.5	If there is an airlock, vestibule, or enclosed space, is there not less than 1450mm between the doorway (plus the door leaf width if the door encroaches into the space).	Air Vestibule				NA	No airlocks designed at 60% Review
3.20	AS 1428.1 Cl. 10.4.2 (g)	If an outward opening door is not self closing, is there a horizontal handrail or pull bar installed at a height between 900 – 1100mm (min. 50mm clearance from edge of door / door handle) on the inside of the door.	Hoor Handles	TBA				Door hardware not designed at 60% Review
3.21	AS 1428.1 Cl 11.1	Are all switches and controls provided on a CAPT (other than general purpose outlets (GPOs)) located at a height of 900 – 1100mm and not less than 500mm from an internal corner.	Switches and Controls	TBA				Door hardware not designed at 60% Review

ROK092		04.00 Accessible Toilet						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
04.01	APS – F2.4 (a)	Is a toilet designated as wheelchair accessible available in the building / facility.	Access Toilet		Y			
04.02	APS – F2.4	Is a USAT provided on each floor level that toilets are provided on APS – F2.4.	Access Toilet		Y			
04.03	APS – F2.4 (g)	If there is more than 1 USAT is the 2 nd of the opposite hand.					NA	Only 1 USAT per level designed at 60% Review
04.04	AS 1428.1 Cl. 12.2.8.1	Is the min. circulation space 1900mm wide and 2300mm long to a height of 2000mm (Note: accepted intrusions)	Circulation Space		Y			
04.05	APS – F2.4 (f)	Is the toilet/s on a CAPT from the PPE (ensuring that access does not necessitate the traversing an area reserved for one sex only).	On CAPT		Y			
04.06	APS – D3.6 (c) / D4 / AS 1428.1 Cl 5	Is the toilet/s sign posted with the appropriate International Symbol of Access, and separate Male and Female symbols, located on the wall between 1200 - 1600mm high on the latch side of the doorway (Note: to include raised and visual versions).	Sign	TBA				Signage not designed at 60% Review
04.07	APS – D3.6 (c) / D4 / AS 1428.1 Cl 5	Does the signage indicate if the facility is suitable for left or right hand use.	Sign	TBA				Signage not designed at 60% Review
04.08	APS – D3.6 (f) / D4	If there is a non-accessible toilet provided, is there signage available that directs users to an accessible toilet (where in different locations).	Sign	TBA				Signage not designed at 60% Review
04.09	APS – D4.3 (2); AS 1428.1 Cl 5	If available on the sign, is the text provided in Title Case.	Sign	TBA				Signage not designed at 60% Review
04.10	AS 1428.1 Cl. 10.2	Is the min. clear opening width 850mm or greater for the toilet.	Min Opening		Y			
04.11	AS 1428.1 Cl. 10.3	Is there appropriate wheelchair circulation space at the door (inside and outside).	Circulation Space		Y			
04.12	AS 1428.1 Cl. 12.2.9 (b)	Does the cubicle door have an ‘occupied’ (in-use) indicator and a bolt or catch (which is openable from the outside in an emergency).	Door Indicator	TBA				Door Hardware not designed at 60% Review
04.13	AS 1428.1 Cl. 12.2.9 (b)	If a snib catch is in use, does the snib handle have a min. length of 45mm from the centre of the spindle.	Snib Catch	TBA				Door Hardware not designed at 60% Review
04.14	AS 1428.1 Cl. 10.4.2 (e)	Is the cubicle door easy to initially open (no heavy closer) 20N max.	Door Pressure	TBA				Door Hardware not designed at 60% Review
04.15	AS 1428.1 Cl. 12.2.9 (a)	If the door is outward opening does it have a hinge mechanism that holds the door in a closed position without the use of a latch.	Hinge Mechanism	TBA				Door Hardware not designed at 60% Review
04.16	AS 1428.1 Cl. 10.4.2 (a)	Can the door be unlocked and opened by one hand (i.e. D lever or D handles and approp. hardware).	Door Handle	TBA				Door Hardware not designed at 60% Review
04.17	AS 1428.1 Cl. 10.4.2 (b)	Throughout its operation, is the clearance between the handle and the back plate or door face (at the centre grip section) not less than 35mm and not more than 45mm.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.18	AS 1428.1 Cl. 10.4.3 (a)	Are all door controls (handles) that need to be grasped or turned between 900 – 1100mm high.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.19	AS 1428.1 Cl. 10.4.3 (b)	Are all door controls that need to be pushed between 900 – 1200mm high.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.20	AS 1428.1 Cl. 10.4.3 (c)	Are all door controls that only need to be touched between 900 – 1250mm high and not less than 500mm from an internal corner.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.21	AS 1428.1 Cl. 10.4.3 (e)	If doors are power operated, are the controls at least 500mm from an internal corner and between 1000 – 2000mm from the hinged swing door leaf (in any position) / or doorway of sliding door.	Power Door	TBA				Power Doors no defined at 60% Review
04.22	AS 1428.1 Cl. 10.4.3 (d)	Are door handles (D style) on sliding doors not less than 60mm from each doorjamb.	Door Handle	TBA				Door Hardware not designed at 60% Review
04.23	AS 1428.1 Cl. 10.1	Does the doorway have a min. luminance contrast of 30% to its adjacent surfaces.	Contrast	TBA				Paint Finishes not defined at 60% Review
04.24	AS 1428.1 Cl. 12.2.8 (fig 43)	Is there a 1500mm space in front of the pan (Note: basin overlap of 100mm permitted if located at front of pan only).	Space in front of pan		Y			No evidence of non-compliance.
04.25	AS 1428.1 Cl. 12.2.8 (fig 43)	Is there 1240 – 1250mm at one side of the pan (this allows side transfers from a wheelchair) (basin not permitted to overlap if located to side of pan).	Space side of pan		Y			Sanitary ware not defined to this level at 60% Review
04.26	AS 1428.1 Cl. 12.2.3 (a) (b) (c) (d)	Is there a full round toilet seat securely hinged to the pan (load rated to 150kg).	Sanitary Ware	TBA				Sanitary ware not defined at 60% Review
04.27	AS 1428.1 Cl. 12.2.3 (e)	Does the toilet seat have a min. 30% luminance contrast with the background e.g. (pan, wall or floor).	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.28	AS 1428.1 Cl. 12.2.2	Is the height to the top of the seat between 460 – 480mm.	Sanitary Ware		Y			No evidence of non-compliance.
04.29	AS 1428.1 Cl. 12.2.2	Is the front of the pan 790 - 810mm from the rear wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.30	AS 1428.1 Cl. 12.2.2	Is the centreline of the pan 450 - 460mm from the side wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.31	AS 1428.1 Cl. 12.2.2	Is the width of the pan a max. of 400mm.	Sanitary Ware		Y			No evidence of non-compliance.
04.32	AS 1428.1 – 2009 Cl. 12.2.2	Is the front of the pan a min. of 600mm from any back wall mounted fixture.	Sanitary Ware		Y			No evidence of non-compliance.
04.33	AS 1428.1 Cl. 12.2.4 (a)	Is a backrest provided on the USA T which is capable of withstanding a force in any direction of 1100N.	Sanitary Ware		Y			No evidence of non-compliance.
04.34	AS 1428.1 Cl. 12.2. 4 (b)	At its face, is the height of the lower edge of the backrest to the top of the WC seat between 120 – 150mm.	Sanitary Ware		Y			No evidence of non-compliance.
04.35	AS 1428.1 Cl. 15.2. 4 (c)	Does the backrest have a vertical height of 150 – 200mm and a width of 350 – 400mm.	Sanitary Ware		Y			No evidence of non-compliance.
04.36	AS 1428.1 Cl. 12.2. 4 (c) (d)	Does the backrest have its face centered on the pan centreline, positioned to achieve an angle of between 95 - 100° back from the seat hinge.	Sanitary Ware		Y			No evidence of non-compliance.
04.37	AS 1428.1 Cl. 12.2.7 (fig 42)	If a concealed or high level cistern is used, is a continuous grab rail at 800 – 810mm (30 – 40mm dia.) provided across the rear and side wall nearest the pan.	Sanitary Ware		Y			No evidence of non-compliance.
04.38	AS 1428.1 Cl. 12.2.7 (fig 42)	If the grab rail on the side wall is one continuous rail, does it provide the appropriate angled extension and clearances from pan / wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.39	AS 1428.1 Cl. 12.2.7 (fig 42)	Is the outside edge of any back wall grab rail at least 450mm from the side of the pan (dependent on length of grab rail).	Sanitary Ware		Y			No evidence of non-compliance.
04.40	AS 1428.1 Cl. 14	Is the grab rail fixed and constructed to withstand a force of 1100N applied in any position and in any direction (without deformation or loosening or rotation of the fastenings or fittings).	Sanitary Ware		Y			No evidence of non-compliance.
04.41	AS 1428.1 Cl. 14	Is the clearance between the grab rail and the adjacent wall surface or other obstruction not less than 50mm and not more than 60mm.	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.42	AS 1428.1 Cl. 14	Is there a min. 600mm clearance above the horizontal grab rail, with a min. of 50mm below any horizontal or angled rail (except at fixing points).	Sanitary Ware		Y			No evidence of non-compliance.

ROK092 04.00 Accessible Toilet								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
04.43	AS 1428.1 Cl. 14	Are exposed edges and corners of grab rails provided with a radius of not less than 5mm.	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.44	AS 1428.1 Cl. 12.2.7 (fig 42)	If a surface mounted / low level cistern is used, is there a wall mounted grab rail (30 – 40mm dia.) a min. length 300mm on the rear wall located within 50mm of the cistern, together with a grab rail mounted on the sidewall at 800 – 810mm high (as per diagram).	Sanitary Ware		Y			No evidence of non-compliance.
04.45	AS 1428.1 Cl. 12.2.2	Is the bottom edge of the cistern a min. of 600mm above floor level.	Sanitary Ware		Y			No evidence of non-compliance.
04.46	AS 1428.1 Cl. 12.2.6 (fig 41)	Can the toilet paper be easily reached (max. outside edge 300mm forward of pan and top edge 700mm max. height) and the roll dispenser have no greater than 150mm projection from the wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.47	AS 1428.1 Cl. 12.2.5 (fig 40)	If the flushing control is located on the back wall, is it within reach, easy to operate (activating the flush before level with the surrounding surface) <i>contrasting 30% with adjacent surfaces</i> (min height 600mm / max. height 1100mm / outside edge max. 500mm from centre line)	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.48	1428.1 Cl. 12.2.5 (fig 40)	If not located on the back wall as above, is it located in the centre line of the toilet AS.	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.49	AS 1428.1 Cl. 12.2.5 (fig 40)	If the flushing control is located on the side wall is it within the approp. zone (inside edge no further than 300mm over the pan / outside edge no further than 300m from the front of the pan – at a height between 600 – 1100mm above finished floor level.	Sanitary Ware	TBA				Sanitary ware not defined to this level at 60% Review
04.50	AS 1428.1 Cl. 12.2.10	Is there a basin inside the unisex accessible toilet	Sanitary Ware		Y			No evidence of non-compliance.
04.51	AS 1428.1 Cl. 12.2.8 (fig 43)	Is the distance between the basin and pan at least 1400mm (front of pan location only permitted for 100mm overlap).	Sanitary Ware		Y			No evidence of non-compliance.
04.52	AS 1428.1 Cl. 12.3.1 (d) (fig 44 (a) (b))	If a semi recessed washbasin is installed (other than within a SOU) is the front top edge 800 – 840mm above the floor.	Sanitary Ware				NA	No semi-recessed washbasin
04.53	AS 1428.1 Cl. 12.3.1 (d) (fig 44 (a) (b))	If a wall mounted washbasin is installed is the front top edge 800 – 830mm above the floor.	Sanitary Ware		Y			No evidence of non-compliance.
04.54	AS 1428.1 Cl. 12.3.1 (d) (fig 44 (a) (b))	If a semi recessed basin is provided (except within a SOU) is the bench provided at a height between 800 – 830mm (outside of circulation spaces).	Sanitary Ware				NA	No semi-recessed washbasin
04.55	AS 1428.1 Cl. 12.3.1 (d) (fig 46)	Is the centre line of the washbasin (rear) provided with a min. 225mm either side.	Sanitary Ware		Y			No evidence of non-compliance.
04.56	AS 1428.1 Cl. 12.3.1 (d) (fig 44)	Is the centre line of the washbasin a min. of 425mm from any wall.	Sanitary Ware		Y			No evidence of non-compliance.
04.57	AS 1428.1 Cl. 12.3.1 (d) (fig 44)	Is the circulation space a min. of 450mm wide (rear of basin).	Sanitary Ware		Y			No evidence of non-compliance.
04.58	AS 1428.1 Cl. 12.3.1 (d) (fig 46)	Is the circulation space for the washbasin a min. 1500mm long and 850mm wide (from rear of washbasin).	Sanitary Ware		Y			No evidence of non-compliance.
04.59	AS 1428.1 Cl. 12.3.1 (d) (fig 44)	Is the position of the taps, bowl and drain outlet appropriate.	Sanitary Ware		Y			No evidence of non-compliance.
04.60	AS 1428.1 Cl. 12.3.1 (d) (fig 44) (a)	Does the basin have appropriate foot / knee / leg space underneath.	Sanitary Ware		Y			No evidence of non-compliance.
04.61	AS 1428.1 Cl. 12.3.1 (c) (e)	If the downpipes are exposed are they insulated or located so as to ensure they do not present a hazard to the user and sit outside the circulation space under the washbasin.	Downpipe		Y			No evidence of non-compliance.
04.62	AS 1428.1 Cl. 12.2.1 (d)	If hot water is provided, is water delivered through a mixing spout.	Mixing Spout		Y			No evidence of non-compliance.
04.63	AS 1428.1 Cl. 12.2.1 (c)	If hot water is provided, is the hot tap located on the left of or above the cold tap.	Hot / Cold Tap				NA	Mixing spout
04.64	AS 1428.1 Cl. 15.2.1 (a)	Are the tap handles lever, sensor plates, voice activation or other similar controls.	Tap Handles		Y			No evidence of non-compliance.
04.65	AS 1428.1 Cl. 12.2.1 (b)	If the taps have lever handles, are they located more than 50mm from adjacent surfaces.	Tap Handles		Y			No evidence of non-compliance.
04.66	AS 1428.1 Cl. 12.2.1 (c)	Are taps clearly identified as hot and cold (colour and text) and in the appropriate location.	Tap Handles				NA	Mixing spout
04.67	AS 1428.1 Cl. 12.4.4	Is there a clothes hanging device 1200 – 1350mm from the floor (not less than 500mm from an internal corner (Note: shower exception)	Clothes Hanger			N		See Markup in Appendix A
04.68	AS 1428.1 Cl. 12.4.1	Is a mirror provided and located either adjacent to or above the washbasin at a min. of 350mm wide.	Mirror		Y			No evidence of non-compliance.
04.69	1428.1 Cl. 12.4.1	If the mirror is above the basin, does it extend between 900mm – 1850mm above the floor, or If adjacent to the basin, at a height of not more than 780mm to a height of not less than 1800mm above the floor.	Mirror		Y			No evidence of non-compliance.
04.70	AS 1428.1 Cl. 12.4.3	If a hand dryer / towel dispenser is provided, is the operative component at a height between 900 – 1100mm and within reach of a user at the washbasin (not closer than 500mm from any internal corner) does not encroach more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Hand Dryer		Y			No evidence of non-compliance.
04.71	AS 1428.1 Cl. 12.4.3	If a soap dispenser is provided, is the operative component at a height between 900 – 1100mm and within reach of a user at the washbasin (not closer than 500mm from any internal corner) does not encroach more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Soap Dispenser		Y			No evidence of non-compliance.
04.72	AS 1428.1 Cl. 12.4.2 (a)	One of the following three shelves must be provided. If a shelf is provided as a vanity top is it located at a height between 800 – 830mm with a min. width of 120mm and depth of 300mm and a depth no greater than the bowl plus its front and back flanges, without	Shelf		Y			No evidence of non-compliance.
04.73	AS 1428.1 Cl. 12.4.2 (b) (i)	If a shelf is provided within the circulation space as a separate fixture, is it available at a height between 900 – 1000mm with a min. width of 120 -150mm and length of 300 – 450mm.	Shelf				NA	Shelf with basin
04.74	AS 1428.1 Cl. 12.4.2 (b) (ii)	If a shelf is provided external to the circulation space as a separate fixture, is it at a height between 790 – 1000mm with a min. width of 120mm and length of 400mm and does not encroach more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Shelf				NA	Shelf with basin
04.75	AS 1428.1 Cl. 12.4.5 (a) (fig 43)	If there is a portable sanitary disposal unit available, is it provided in the rear corner between the pan and the closest wall.	Sanitary Disposal			N		See Markup in Appendix A
04.76	AS 1428.1 Cl. 12.4.5 (b)	If a recessed sanitary disposal unit is provided, is it located within 500mm of the pan.	Sanitary Disposal			N		See Markup in Appendix A
04.77	AS 1428.1 Cl. 12.2.8.1 (iv)	If a wall cabinet is provided, does it encroach not more than 150mm into the pan circulation space and provide a minimum of 900mm clearance below.	Wall Cabinet			N		See Markup in Appendix A
04.78	AS 1428.1 Cl. 11.2	Are rocker action / toggle switches provided which are a min. 30 x 30mm.	Switches	TBA				Switch detail not defined at 60% Review

ROK092		04.00 Accessible Toilet						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
04.79	AS 1428.1 Cl. 11.2	If push pad switches are provided are they a min. of 25mm dia.	Switches	TBA				Switch detail not defined at 60% Review
04.80	AS 1428.1 Cl. 11.2	If provided near the washbasin, are switches and power points 600 –1100mm high, not less than 500mm from the internal corners <i>and close to any shelf or worktop</i> .	Switches	TBA				Switch detail not defined at 60% Review
04.81	AS 1428.1 Cl. 12.2.8.2	If there is a baby change table, is it located at a height of 820 mm with leg clearance height underneath of 720 when open (must sit outside of circ. space when folded up).	Baby Change Table			N		See Markup in Appendix A
Ambulant Toilets								
	Standard	Items						
04.82	APS – F2.4	If there are one or more toilets provided in addition to the USAT at the bank of toilets, is an ambulant male and an ambulant female toilet provided	Ambulant Toilet		Y			No evidence of non-compliance at 60% Review
04.83	AS 1428.1 Cl. 13.4.	If ambulant toilets are provided, (use a separate Checklist for each ambulant toilet and identify each as Male or Female, is signage (raised text and Braille, and raised and visual symbols) installed at the airlock serving the area that contains the facilities identifying the facilities within AS 1428.1 Cl. 13.4.	Signage	TBA				Signage not defined at 60% Review
04.84	APS – D3.6 (d) / AS 1428.1 Amdt. 1 Cl. 8.1.	Is there signage (raised text and Braille, and raised and visual symbols) installed on the door of the facility.	Signage	TBA				Signage not defined at 60% Review
04.85	AS 1428.1 Cl. 10.3	If there is an airlock enroute to an ambulant toilet, is there appropriate circulation space.	Airlock				NA	Airlock not designed at 60% Review
04.86	AS 1428.1 Cl. 13.3	Is the min. clear opening width of the ambulant toilet doorway 700mm.	Width of Doorway		Y			No evidence of non-compliance at 60% Review
04.87	AS 1428.1 Cl. 13.3	Does the cubicle door have an ‘occupied’ (in-use) indicator and a bolt or catch (which is openable from the outside in an emergency).	Indicator		Y			No evidence of non-compliance at 60% Review
04.88	AS 1428.1 Cl. 13.3	If a snib catch is in use, does the snib handle have a min length of 45mm from the centre of the spindle	Snib Catch	TBA				Door Hardware not detailed at 60% Review
04.89	AS 1428.1 Cl. 16.1	Is the width of the ambulant toilet compartment between 900 – 920mm.	Width of Ambulant		Y			No evidence of non-compliance at 60% Review
04.90	AS 1428.1 Cl. 13.1 fig 52 (B)	Is there a clear min. circulation space of 900mm long x 900-920mm wide in front of the toilet pan.	Min Circulation in					
04.91	AS 1428.1 Cl. 13.3 fig 52 (B)	Is there a clear circulation space a min. of 900 x 900mm outside the door (Note: variety of placement options).	Min Circulation out		Y			No evidence of non-compliance at 60% Review
04.92	AS 1428.1 Cl. 12.2.7	Are appropriate grab rails installed on the wall located at a height between 800 – 810mm.	Grab Rail		Y			No evidence of non-compliance at 60% Review
04.93	AS 1428.1 Cl. 14	Is the grab rail fixed and constructed to withstand a force of 1100N applied in any position and in any direction (without deformation or loosening or rotation of the fastenings or fittings).	Grab Rail	TBA				Ambulant toilet not defined to this level at 60% Review
04.94	AS 1428.1 Cl. 14	Is the clearance between the grab rail and the adjacent wall surface or other obstruction not less than 50mm and not more than 60mm.	Grab Rail	TBA				Ambulant toilet not defined to this level at 60% Review
04.95	AS 1428.1 Cl. 14	Is there a min. 600mm clearance above the horizontal grab rail, with a min. of 50mm below any horizontal or angled rail (except at fixing points).	Grab Rail	TBA				Ambulant toilet not defined to this level at 60% Review
04.96	AS 1428.1 Cl. 14	Are exposed edges and corners of grab rails provided with a radius of not less than 5mm.	Grab Rail	TBA				Ambulant toilet not defined to this level at 60% Review
04.97	AS 1428.1 Cl. 13.1	Is the toilet pan provided with the standard projection of between 610 – 660mm.	Pan Projection		Y			No evidence of non-compliance at 60% Review
04.98	AS 1428.1 Cl. 13.1	Is the height to the top of the seat between 460 – 480mm.	Height to top of seat		Y			No evidence of non-compliance at 60% Review
04.99	AS 1428.1 Cl. 13.1 fig 52 (A)	Can the toilet paper be easily reached (max. outside edge 300mm forward of pan and top edge 700mm max. height).	Toilet Paper position		Y			No evidence of non-compliance at 60% Review
Universal Accessibility Options: not mandatory								
4.100		Are the door handles or controls colour contrasting to the background (30%)	Contrast	TBA				Door Hardware not defined at 60% Review
4.101		Is appropriate lighting provided inside the toilet	Lighting	TBA				Lighting not defined at 60% Review
4.102		Is there an emergency alarm installed in the cubicle, for users requiring assistance	Alarm	TBA				Alarm system not defined

ROK092		06.00 Passenger Lifts						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
06.01	APS 4.4 / E3.6	Is there a lift available to all floors (where required).	All Floors		Y			
06.02	APS – E3.6b	Is the lift door installed with a min. clear opening width of 900mm.	Min. Clear Width	TBA				Lift Shop Drawings not included in drawings at 50%
06.03	AS 1735.12 - Sect. 6	Is the internal lift floor surface level with the external surface for an unobstructed entry into the lift (12mm variation allowed).	Floor Surface	TBA				Lift Shop Drawings not included in drawings at 50%
06.04	APS - E3.6 / 1735.12 – Sect. 2	If the lift was approved with building permit issued prior to 1st May 2011, (or new and travels not more than 12m), is the min. floor area 1100mm wide x 1400mm deep.	Age of Lift				NA	
06.05	APS – 4.4 / E3.6	If the lift was approved with building permit issued on or after 1st May 2011 and travels more than 12m, is the min. floor area 1400mm wide x 1600mm deep.	Age of Lift	TBA				Lift Shop Drawings not included in drawings at 50%
06.06	AS 1735.12 – Cl. 3.1 / APS Amdt. (6)	If carpet is provided within the lift, is it appropriate (pile <11mm, backing <4mm)	Carpet	TBA				Lift Shop Drawings not included in drawings at 50%
06.07	AS 1735.12 – Cl. 4.2	Is an appropriate door operating sensor (passenger protection system) in place which whilst activated holds the doors open.	Sensor	TBA				Lift Shop Drawings not included in drawings at 50%
06.08	AS 1735.12 – Cl. 4.3	Do the doors, when responding to a landing button, remain open for a full 6 seconds.	Open Time	TBA				Lift Shop Drawings not included in drawings at 50%
06.09	AS 1735.12 Cl. 4.3	If there are three or more lifts in line and they are interconnected in their operation, is the door dwell time extended to a min. 8 sec (Note: dwell times may be shortened in some instances).	More than 1 lift				NA	
06.10	AS 1735.12 Cl. 8.5	If there are three or more lifts in the bank of lifts is there visible and audible notification on each lift landing to indicate the lift arrival and direction of travel.	More than 1 lift				NA	
06.11	AS 1735.12 Cl. 5.1	Are the adjacent parallel surfaces in the lift car located within 300mm of the control buttons, provided with a surface that reduces glare and reflection.	Parallel Surfaces	TBA				Lift Shop Drawings not included in drawings at 50%
06.12	AS 1735.12 Cl. 5.2	Are car operating panels, seats, handrails provided so as to not obstruct or reduce the width of the door opening.	Internal Car Fitout	TBA				Lift Shop Drawings not included in drawings at 50%
06.13	AS 1735.12 Cl. 5.3.2 (a)	Is a handrail available which is a min. length of 600mm, located in the lift at a height between 850 – 950mm.	Handrail	TBA				Lift Shop Drawings not included in drawings at 50%
06.14	AS 1735.12 Cl. 5.3.1	Is this handrail a max. of 500mm from any button or device to operate the lift.	Handrail	TBA				Lift Shop Drawings not included in drawings at 50%
06.15	AS 1735.12 Cl. 5.3.2 (a)	Does the handrail have a circular diameter of 30 – 50mm for a min. of 270°.	Handrail	TBA				Lift Shop Drawings not included in drawings at 50%
06.16	AS 1735.12 Cl. 5.3.2 (c)	Are exposed edges of the handrail provided with a radius of not less than 5mm.	Handrail	TBA				Lift Shop Drawings not included in drawings at 50%
06.17	AS 1735.12 Cl. 5.3.2 (f)	Are clearances above the handrail (including clearances to the control panel) less than 5mm or not less than 100mm.	Handrail	TBA				Lift Shop Drawings not included in drawings at 50%
06.18	AS 1735.12 Cl. 5.3.2 (g)	Are handrails set 50mm from the car wall.	Handrail	TBA				Lift Shop Drawings not included in drawings at 50%
06.19	AS 1735.12 Cl. 5.3.2 (g)	If there is a gap less than 50mm between the wall and handrail (i.e. where handrail is returned to the wall) is it filled in (enclosed)	Handrail	TBA				Lift Shop Drawings not included in drawings at 50%
06.20	AS 1735.12 Cl. 5.4	If there is a fixed seat within the lift, does it sit outside of the min. car size (Note: hinged seats not acceptable).	Seat within Lift	TBA				Lift Shop Drawings not included in drawings at 50%
06.21	AS 1735.12 Cl. 7.1	Is each landing provided with one or more control buttons to call the lift.	Controls	TBA				Lift Shop Drawings not included in drawings at 50%
06.22	AS 1735.12 Cl. 7.3.1	Is the centre of landing control buttons, key switches and card readers located between 900mm –1200mm above the landing floor.	Controls	TBA				Lift Shop Drawings not included in drawings at 50%
06.23	AS 1735.12 Cl. 7.3.3	Are the landing control buttons located adjacent to the lift entrances and not closer than 500mm from any internal corner or fixed obstruction.	Controls	TBA				Lift Shop Drawings not included in drawings at 50%
06.24	AS 1735.12 Cl. 7.1	If up and down buttons are provided on a landing, and are not located vertically within 200mm of each other, is a tactile symbol and Braille equivalent provided (above or to the left or on the face of the respective button).	Controls	TBA				Lift Shop Drawings not included in drawings at 50%
06.25	AS 1735.12 Cl. 7.2.3	If a key pad is provided, is it set up like a telephone key pad and located at a height between 900 - 1100mm from the floor.	Controls	TBA				Lift Shop Drawings not included in drawings at 50%
06.26	AS 1735.12 Cl. 7.2.3 / 7.4	If a key pad is provided, is there a tactile dot provided in the centre of the number 5 (unless the tactile symbol is on the face of the button).	Controls	TBA				Lift Shop Drawings not included in drawings at 50%
06.27	AS 1735.12 Cl. 7.2.1	If the lift has a dimension less than 1400mm, are there two lift control panels provided (one to the left and one to the right of a person entering the lift).	Controls	TBA				Lift Shop Drawings not included in drawings at 50%
06.28	AS 1735.12 Cl. 7.2.2 Figure 8.4.2 (c)	Is the communication button located at the right hand end of the lowest row of buttons and identified by a visible symbol.	Controls	TBA				Lift Shop Drawings not included in drawings at 50%
06.29	AS 1735.12 Cl. 7.2.2 / 8.3 Figure 8.4.2 (c)	Is there a tactile symbol and Braille equivalent above or to the left or on the face of the respective buttons.	Signage	TBA				Lift Shop Drawings not included in drawings at 50%
06.30	APS – E3.6 (b) / AS 1735.12 – Sect 9.2 / 9.3	Is there an emergency hands-free communication system installed, (including a button that alerts a call centre of a problem and a light to signal that the call has been received).	Emergency comms	TBA				Lift Shop Drawings not included in drawings at 50%

ROK092		06.00 Passenger Lifts						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
06.31	AS 1735.12 Cl. 7.3.1	Is the centre of the face of the control buttons within the lift located at a height between 700 – 1250mm.	Controls	TBA				Lift Shop Drawings not included in drawings at 50%
06.32	AS 1735.12 Cl. 7.3.2	Are the control buttons within the lift located within the appropriate zones / distance from the door / corners.	Controls	TBA				Lift Shop Drawings not included in drawings at 50%
06.33	AS 1735.12 Cl. 7.4	Are the control buttons of the appropriate size, design and easy to use (2N – 5N).	Controls	TBA				Lift Shop Drawings not included in drawings at 50%
06.34	APS – E3.6 (b)	If the lift travels more than 2 floors, is there appropriate audible information to identify when the lift stops.	Audible	TBA				Lift Shop Drawings not included in drawings at 50%
06.35	APS – E3.6 (b)	If the lift travels more than 2 floors, is there appropriate audible and visual indication at each lift landing to indicate the arrival of the lift.	Audible	TBA				Lift Shop Drawings not included in drawings at 50%
06.36	AS 1735.12 Cl. 8.6	Is an appropriate lift position indication provided within the lift (i.e. lift on 2nd floor, 4th floor etc.).	Position Indicator	TBA				Lift Shop Drawings not included in drawings at 50%
06.37	AS 1735.12 Cl. 10.2	Is there appropriate lighting within the lift.	Lighting	TBA				Lift Shop Drawings not included in drawings at 50%
06.38	AS 1735.12 Cl. 10.3	Are the lift control buttons appropriately lit.	Controls	TBA				Lift Shop Drawings not included in drawings at 50%
Universal Accessibility Options: not mandatory								
06.39	AS 1428.2 – Cl. 12	Can a wheelchair turn around in the lift (recommended 1700x 1900mm)	Circulation	TBA				Lift Shop Drawings not included in drawings at 50%
06.40		Are the handrails in contrast to the walls	Handrail Contrast	TBA				Lift Shop Drawings not included in drawings at 50%
06.41		Are the internal walls of the lift of a non-reflective material	Wall Finish	TBA				Lift Shop Drawings not included in drawings at 50%
06.42		Are the emergency procedures clearly identified in the event of a lift malfunction	Signage	TBA				Lift Shop Drawings not included in drawings at 50%

ROK092		07.00 Kitchens						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
07.01	AS 1428.1 Cl. 3	Is there a CAPT provided to the kitchen / bar / dining / laundry / canteen area.	CAPT		Y			No evidence of non-compliance.
07.02	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there a continuous internal accessible path of travel to any canteen window.	Canteen				NA	
07.03	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there a continuous external accessible path of travel to any external canteen / servery window.	Canteen				NA	
07.04	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there appropriate circulation space within the kitchen area, to enable a user ease of use for all facilities.	Circulation Space		Y			No evidence of non-compliance.
Universal Accessibility Options: not mandatory								
07.05	AS 1428.2 Cl. 24	Does the counter have a wheelchair accessible section at a height between 830 – 870mm for a min. length of 900mm.	Counter	TBA				
07.06	AS 1428.2 Cl. 24	Does the counter have at the wheelchair accessible section, a leg clearance underneath at a height between 800 – 840mm for a min. length of 900mm.	Counter	TBA				
07.07	AS 1428.2- A5	Is the sink / basin accessible to people in wheelchairs (height 770 – 800mm).	Basin	TBA				
07.08	AS 1428.2- A5	Is the sink / basin accessible to people in wheelchairs (leg clearance height underneath 640-650mm) with appropriate unobstructed circulation space.	Basin	TBA				
07.09	AS 1428.2 Cl. 24	If there is a canteen / servery window does it have a wheelchair accessible section at a height between 830 – 870mm with a leg clearance underneath at a height of 800 – 840mm for a min. length of 900mm.	Canteen Window				NA	
07.10	AS 1428.2 Cl. 29	Are the operative components of any vending machine, for pre-packaged food and drink, accessible and between 700 – 1200mm high.	Vending Machine				NA	
07.11	AS 1428.2 Cl. 27.2	If seating is available, is it at a height of 450 – 520mm with armrests located at a height between 220 – 300mm above the seat and backs.	Seating	TBA				
07.12		If tea and coffee facilities are provided (other than vending machine), are the highest operable components located at a height between 900 – 1100mm.	Tea / Coffee	TBA				

ROK092		08.00 Meeting Spaces						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
08.01	AS 1428.2 Cl. 26.2 (a)	If an inbuilt stage or podium is provided, is there ramp access (in addition to any step / stair).	Stage				NA	No stages defined at 50%
08.02	APS – D3.7 (1) (2) (3)	If a sound amplification system is installed / inbuilt, is there a hearing augmentation system that covers 80% of the total enclosed space if an induction loop is inbuilt, or 95% if a receiver system is in use.	Sound Amplification = Hearing Augmentation	TBA				Sound amplification not defined at 60% Review
08.03	APS – D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, (excluding letter 'T') indicate the area where an assistive listening system is operational and the area covered.	Signage	TBA				Signage not defined at 60% Review
08.04	APS – D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, (excluding letter 'T') indicate which type of system is in place.	Signage	TBA				Signage not defined at 60% Review
08.05	APS – D3.7 (1) (2) (3)	If receivers are being used, does the signage indicate where the receivers can be obtained.	Signage	TBA				Signage not defined at 60% Review
08.06	AS 1428.1 Cl. 4.1	Is there a level, slip resistant floor surface.	Slip Resistance	TBA				Slip Resistance not defined at 60% Review
08.07	APS – 2.2 (4) / AS 1428.1 Cl. 3	Is there adequate circulation space between all furniture and fittings.	Circulation Space	TBA				Some issues with circulation space - Refer to markups
Universal Accessibility Options: not mandatory								
08.08		Is there appropriate lighting to the area.	Lighting	TBA				Lighting not defined at 60% Review
08.09		Is there clear, concise signage, incorporating Braille and tactile components that identifies all elements e.g. toilet, emergency exits.	Signage	TBA				Signage not defined at 60% Review
08.10		Is there sufficient level circulation space provided for a person using a wheelchair to sit at a meeting table in various locations.	Circulation Space	TBA				Some issues with circulation space - Refer to markups
08.11	AS 1428.2 Cl. 27.2	Is there some seating available which is 450 – 520mm high with armrests provided at a height of 220 – 300mm above the seat and a back.	Seating	TBA				Furniture specification not detailed at 60% Review
08.12	AS 1428.2 Cl. 26.2	Are boundaries of any stage or podium defined by barriers or an appropriate contrast to the floor surface, (colour and texture)	Stage				NA	Multiple Meeting Room Fiouts are not defined at 60% Review
08.13	AS 1428.2 Cl. 26.2 (b) / 6.3	Are all stage / podium controls able to be operated by a person when seated	Stage				NA	Multiple Meeting Room Fiouts are not defined at 60% Review
08.14	AS 1428.5 - 3	Is hearing augmentation available in meeting rooms (seating 5 or more participants)	Hearing Augmentation	TBA				Sound amplification not defined at 60% Review

R0K092		09.00 Hearing Augmentation						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
09.01	APS – D3.7 (1) (2) (3)	If a sound amplification system is installed / inbuilt is there a hearing augmentation system that covers 80% of the total enclosed space if an induction loop is inbuilt, or 95% if a receiver system in use.	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.02	APS – D3.7 (1) (2) (3)	Is hearing augmentation available at any screened / enclosed reception area / ticket or tellers cash booth (that has an inbuilt amplification system).	Screened Booth				NA	No Screened booth designed.
09.02	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Signage	TBA				Signage not defined at 60% Review
09.03	APS – D3.6 (b) (ii) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2.2	Does signage, including the international symbol of deafness, indicate which type of system is in place.	Signage	TBA				Signage not defined at 60% Review
09.04	APS D3.6 (b) (iii)	If receivers are being used, does the signage indicate where the receivers can be obtained.	Signage	TBA				Signage not defined at 60% Review
09.05	APS – D3.7 (4)	If a screen or scoreboard is capable of displaying public announcements, is it capable of supplementing any public address system (other than a system used for emergency warning purposes only).	Signage	TBA				Signage not defined at 60% Review
09.06	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl 5.2.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Signage	TBA				Signage not defined at 60% Review
Universal Accessibility Options: not mandatory								
09.07	AS 1428.5 - 3	Is hearing augmentation available in meeting rooms (seating 5 or more participants).	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.08	AS 1428.5 - 3	Is hearing augmentation available in any lift to assist with communication in an emergency.	Sound Amplification = Hearing Augmentation	TBA				Sound Amplification / Hearing Augmentation not defined at 60% Review
09.09		Is appropriate seating with backs and armrests available that provides good lines of sight for lip reading.	Seating lines of sight	TBA				Tiered seating not defined at 60% Review
09.10		Are there acoustic design elements to reduce noise e.g. rubber tips on furniture legs, soft furnishings, low pile carpet, double glazing, quiet equipment etc.	Acoustic Design Elements	TBA				Finishes not defined at 60% Review
09.11	AS 1428.5 - 3	Are there visible alarms at any security checkpoint.	Alarms	TBA				Security not defined at 60% Review
09.12		Are there visible emergency alarms throughout the building.	Alarms	TBA				Security not defined at 60% Review
09.13		Is there effective lighting for lip reading and sign language interpreters.	Lighting	TBA				Luminance not defined at 60% Review

ROK092	10.00 Contrasts							
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
10.01	AS 1428.1 Cl. 10.1	Doorways / frames / walls etc	Door Contrast	TBA				Finishes not defined at 60% Review
10.02	AS 1428.1 Cl. 3.6	Glass doors (solid, non-transparent contrasting strip across full width of glass and side partitions)	Glass Doors	TBA				Door Material not defined at 60% Review
10.03	APS – D3.8 1 (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Ramps (TGSIs at top and bottom - as required)	Ramp TGSI	TBA				TGSI detail not defined at 60% Review
10.04	APS – D4.5	Signs	Signage	TBA				Signage not defined at 60% Review
10.05	APS – D3.8 1 (a) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Stairs (TGSIs at top and bottom – as required)	Stair TGSI	TBA				Stair detail not defined at 60% Review
10.06	AS 1428.1 Cl. 8.1 (f) (g)	Stair nosing strips	Stair Detailing	TBA				Stair detail not defined at 60% Review
10.07	AS 1428.1 – 2021 Cl. 12.2.3 (e)	Toilet seats and cisterns	Sanitary Ware	TBA				Sanitary ware not defined at 60% Review

ROK092		11.00 Floor / Ground Surfaces						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
11.01	AS 1428.1 Cl. 4.1	Is the ground / floor surface firm and level (e.g. with no sharp transitions at abutting surfaces).	Firm Level Surface	TBA				Floor Finishes not defined at 60% Review
11.02	AS 1428.1 Cl. 4.1	Is the floor / ground surface slip resistant (in wet and dry conditions) allowing traction for a person using a wheelchair and people with ambulant or sensory disability.	Slip Resistant	TBA				Floor Finishes not defined at 60% Review
11.03	AS 1428.1 Cl 4.3	If carpeted, is it short pile (<11mm and backing <4mm) and securely attached to the floor surface.	Carpet	TBA				Floor Finishes not defined at 60% Review
11.04	AS 1428.1 Cl 4.5	If timber decking boards are installed and are no greater than 150mm wide, is there a maximum 6mm gap between boards.	Timber Decking	TBA				Floor Finishes not defined at 60% Review
11.05	AS 1428.1 Cl 4.5	If timber decking boards are installed that are over 150mm wide, is there a maximum gap of 10mm between boards, and if the gap is over 8mm do the boards run transverse to the direction of travel	Timber Decking	TBA				Floor Finishes not defined at 60% Review
11.06	AS 1428.1 Cl 4.5	If timber decking boards are installed, are adjacent boards level with a maximum vertical 3mm tolerance	Timber Decking	TBA				Floor Finishes not defined at 60% Review
Universal Accessibility Options: not mandatory								
11.07		Does the floor / ground surface have effective contrasts to walls and doors / doorframes	Contrast					Floor and Wall Finishes not defined at 60% Review.

ROK092		12.00 Emergency Egress / Evacuation						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Universal Accessibility Options: not mandatory								
12.01		Is there an accessible (e.g. appropriate door handle, clear door opening width, opening force) emergency exit in addition to the main entry	Accessible Emergency Exit	TBA				Emergency Door Material, Hardware, Width etc not defined at 60% Review
12.02		Is there clear, visible, accessible signage on emergency exits	Signage for Exit	TBA				Signage not defined at 60% Review
12.03		Is there a continuous accessible path of travel from the building to any nominated assembly area (e.g. firm path, no steps, stairs, well lit)	CAPT to Assemeby	TBA				Emergency Alarms not defined at 60% Review
12.04		Are audible emergency alarms provided in the building	Alarms	TBA				Emergency Alarms not defined at 60% Review
12.05		Are visible emergency alarms provided in the building	Alarms	TBA				Refuge place not defined at 60% Review
12.06		Are there places of refuge provided for people with mobility difficulties on levels above the main entrance level	Refuge on Level 1	TBA				Refuge place not defined at 60% Review
12.07		Are audible security alarms provided at any security checkpoints	Alarms	TBA				Security Alarms not defined at 60% Review
12.08		Are visible security alarms provided at any security checkpoints	Alarms	TBA				Security Alarms not defined at 60% Review
12.09		Are any fire hoses and extinguishers located at 700 – 1200mm high	Fire Extinguishers	TBA				Fire Strategy not defined at 60% Review
12.10		Is the emergency management plan located at an accessible height in a public area in an accessible format (e.g. large print, tactile, Braille)	Emergency Management Plan	TBA				Emergency Management Plan not defined at 60% Review
12.11		Is there an accessible (e.g. appropriate door handle, clear door opening width, opening force) emergency exit in addition to the main entry	Emergency Exit	TBA				Emergency Exit not defined at 60% Review
12.12		Is there clear, visible, accessible signage on emergency exits	Accessible Emergency Exit Signage	TBA				Emergency Exit not defined at 60% Review

ROK092 13.00 Accessible Car Parking								
Number	Standard	Item	Item	TBD	Y	N	NA	Action
Mandatory Items								
13.01	Note not required to be designated if 5 or less under APS) APS table D3.5, DP8	Check APS Table - appropriate numbers of designated accessible parking bays for people with disabilities provided.	Number of Parks	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.02	AS / NZS 2890.6 Cl. 2.4	Designated accessible bay/s (DAPB) have min. overhead clearance of 2500mm	Overhead Clearance	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.03	AS / NZS 2890.6 Cl. 2.4	Is there an overhead clearance a min. of 2200mm at the car park entry	Overhead Clearance at Entry	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.04	AS / NZS 2890.6 Cl. 3.1	Is the DAPB noted on the ground with the international symbol of access (white symbol between 800 – 1000mm high within a blue rectangle not more than1200 x 1200mm) located in the centre of the space between 500 – 600mm from the entry point	Symbol of Access	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.05	AS / NZS 2890.6 Cl. 3.2	Is the DAPB (dedicated) space delineated by yellow slip resistant lines (unbroken 80 – 100mm wide all sides – except	Yellow lines	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
		any side delineated by a kerb, barrier, wall)	Walkway lines	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.06	AS / NZS 2890.6 Cl. 3.2	Is any walkway within or partly within a shared area marked with yellow slip resistant lines (unbroken longitudinal lines on both sides – excepting any side delineated by a kerb, barrier, wall)	Parallel DAPB	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.07	AS / NZS 2890.6 Cl. 2.2.2	If the DAPB is parallel (to the roadway / parking aisle), is it a min. width of 3200mm and 7800mm long with an appropriate 1600mm wide x 7800mm long connecting pathway (pathway can be above grade of bay).	Angled DAPB	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.08	AS / NZS 2890.6 Cl. 2.2.1, Cl.3.2 b) 11)	If the DAPB is angled (to the roadway / parking aisle), is it 2400mm wide and 5400mm long, with an adjoining shared pathway a min of 2400mm wide x 5400 (plus 2400 x 2400 at front or rear) (must be at grade of parking bay). Is the shared area marked with diagonal stripes 150 to 200 mm wide with spaces 200 mm to 300 mm between stripes. The stripes shall be at an angle of 45 ±10 degrees to the side of the space.	Bollard	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.09	AS / NZS 2890.6 Cl. 2.2.1(e)	Is a bollard provided within the shared area (central in space – set back from the end of the parking module 750 – 850mm)	Level Ground, Firm Surface, Crossfall	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.10	AS / NZS 2890.6 Cl. 2.3	Is the DAPB on level ground, with a firm surface and free of loose material. Crossfall (not more 1:40 in any direction or 1:33 if bitumen / outside)	Kerb	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.11	AS / NZS 2890.6 Cl. 2.2.2 / 2.5	If kerbs exist, at a parallel parking bay, is there an appropriate kerb ramp (at front or rear end) provided from the DAPB (Note: pathway may require an increase in width to accommodate kerb ramp)	Slip Resistant Kerb	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.12	AS 1428.1 Cl. 4.1 and 7.7.3	Do existing kerb ramp/s at parking bay, have a slip resistant surface	Kerb Ramps	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.13	AS 1428.1 Cl. 7.2.2	Are the existing kerb ramp/s at DAPB, a max. length of 1520mm and maximum rise of 190mm with a slope / gradient where the ratio is not greater than 1:8	Kerb Ramp width	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.14	AS 1428.1 Cl. 7.7	Do existing kerb ramp/s at DAPB, have a min. width of 1000mm	Kerb Ramp Landing	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.15	AS 1428.1 Cl. 7.7	Do existing kerb ramp/s have an appropriate landing at the top and bottom of the ramp (Note: consider change of direction)	Kerb Ramp transition	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.16	AS 1428.1 Cl. 7	Do the existing kerb ramp/s at DAPB, have a smooth transition between the road and pathway (max. diff. 5mm with rounded edge)	TGSI	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
Universal Accessibility Options: not mandatory								

ROK09213.00 Accessible Car Parking								
Number	Standard	Item	Item	TBD	Y	N	NA	Action
13.18	AS / NZS 2890.6 – A3	Is the DAPB clearly visible with elevated signs with blue international access symbol		TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.19		Are the DAPBs adjacent to, or as near as possible, to the principal pedestrian entry of the building or facility		TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.20	AS 1428.2 Cl. 19	Is the area for the DAPBs etc well-lit and is the lighting even		TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.21	AS / NZS 2890.6 – A3	Are direction signs to DAPB provided, if DAPB sign not visible from car park entry		TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
13.22	AS 1428.4.1 Cl. 3.1 (c) (i)	Are there appropriate directional TGSIs on any pathway adjacent to a DAPB, where a kerb ramp is at a mid-block section or not on a direct path of travel		TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review

ROK092		14.00 Kerb Ramps						
Number	Standard	Item	Item	TBD	Y	N	NA	Action
Mandatory Items								
14.01	AS 1428.1. Cl. 4	If the pathway on the accessway crosses any vehicle traffic areas, (e.g. parking lot, internal road) is it free from any changes in level (e.g. kerbs, steps etc.).	Pathway level changes	TBA				Civil drawings not detailed at 60% Review
14.02	AS 1428.1. Cl. 4 / 7.7.3	Is the ground surface on the kerb ramp slip resistant.	Slip Resistant	TBA				Civil drawings not detailed at 60% Review
14.03	AS / NZS 2890.6 - Cl. 2.2.2 / 2.5	If the kerb ramps are inserted into the pathway, has the pathway width been extended to accommodate the kerb ramp.	Kerb ramps	TBA				Civil drawings not detailed at 60% Review
14.04	AS 1428.1. Cl. 7.7.1	If there is an opposing kerb ramp / pedestrian refuge / median, are the centre lines of the kerb ramps aligned.	Opposing Kerb Ramp	TBA				Civil drawings not detailed at 60% Review
14.05	AS 1428.1. Cl. 7.7.2	Do the kerb ramps on the accessway, have a max. rise of 190mm, length of 1520mm and do they have a slope / gradient where the ratio is not greater than 1:8.	Kerb ramp gradient	TBA				Civil drawings not detailed at 60% Review
14.06	AS 1428.1. Cl. 3.3	Are the openings of the kerb ramps a min. of 1000mm wide.	Openings min 1000mm	TBA				Civil drawings not detailed at 60% Review
14.07	AS 1428.1. Cl. 7.7.2	Do the kerb ramps, on the pathway to the PPE, have a smooth transition between the road and the pathway (max. diff. 5mm with rounded or bevelled edge).	Smooth Transition	TBA				Civil drawings not detailed at 60% Review
14.08	AS 1428.1. Cl. 7.7.2	Do the kerb ramps have an appropriate side profile i.e. splayed or tapered 45°.	Side Profile	TBA				Civil drawings not detailed at 60% Review
14.09	AS 1428.1. Cl. 7.7.2	Is the angle between the ramp surface and the lower surface (i.e. base of kerb) provided at an angle of 166°.	Angle	TBA				Civil drawings not detailed at 60% Review
14.10	AS 1428.1. Cl. 7.8.3	Do kerb ramps on the pathway have a landing of 1200mm min in length at the top and bottom of the ramp (following direction of travel).	Kerb Ramp Landing	TBA				Civil drawings not detailed at 60% Review
14.11	AS 1428.1. Cl. 7.8.3	Do kerb ramps on the pathway have a landing of 1500mm x 2000mm at any change of direction (T junction).	Kerb Ramp Landing	TBA				Civil drawings not detailed at 60% Review
14.12	AS 1428.1. Cl. 7.8.3	Do kerb ramps on the pathway have a landing of 1500mm x 1500mm at any single change of direction	Kerb Ramp Landing	TBA				Civil drawings not detailed at 60% Review
Universal Accessibility Options: not mandatory								
14.13		Are there any TGSIs (hazard) indicators installed at kerb ramps on the accessway (width x 600 – 800mm, setback 300mm ± 10mm)	TGSI	TBA				Civil drawings not detailed at 60% Review

ROK092		15.00 Landscaping						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Universal Accessibility Options: not mandatory								
15.01		Are pathways free from plant species that develop overhanging foliage, and / or leaves or drop seed pods, berries, leaf and bark litter	Foilage				NA	Existing Audit Requirement only
15.02		Are there landscape designs, materials, plants, etc., that contribute to pedestrian safety	Safety in Design	TBA				
15.03		Are any plantings used to provide orientation or direction cues for people with vision impairment e.g. distinctive scents, sounds, appearance or texture	Planting				NA	Existing Audit Requirement only
15.04		Are any planter boxes appropriately located clear of any pathway	Planting		Y			
15.05		Are any dense plantings maintained to provide a clear line of sight	Planting				NA	Existing Audit Requirement only

ROK092 16.00 Pathways (Accessways)								
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
16.01	APS - D3.2	Does an accessible pathway lead users from the designated accessible parking bay to the building entrance.	Accessible Pathway	TBA				Accessible Car Parking associated with Building ROK092 not included on drawings at 60% Review
16.02	APS - D3.2	Does an accessible pathway lead users from the allotment boundary to the building entrance.	Accessible Pathway		Y			
16.03	APS - D3.2	Does an accessible pathway lead users from any adjoining building required to be accessible (if linked by a pedestrian pathway).	Accessible Pathway	TBA				Not detailed at 60% Review
16.04	AS 1428.1 Cl. 4.2	If there is an abutment of surfaces on the pathway, are they no greater than 3mm if the abutment is vertical, or 5mm if a bevelled edge.	Accessible Pathway	TBA				Not detailed at 60% Review
16.05	AS 1428.1 Cl. 4.2 Figure 7(A)	If raked joint pavers are used, is the abutment of surfaces appropriate.	Pavers	TBA				Not detailed at 60% Review
16.06	AS 1428.1 Cl. 3.3	Are all accessways a min. width of 1000mm.	Accessway 1000mm		Y			
16.07	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.4	Do accessways provide a passing space where a direct line of sight is not available to the end of the walkway (max. 20m intervals) (min. 1800mm wide x 2000mm long).	Passing Space	TBA				Not detailed at 60% Review
16.08	APS – D3.3 (c) (d) (e) / AS 1428.1 Cl. 3.5	Do accessways provide a turning space near the end of the walkway where it is not possible to continue (within 2m of end).	Turning Space	TBA				Not detailed at 60% Review
16.09	AS 1428.1 Cl. 3.5	If a change of direction is required, is there appropriate circulation space provided along the accessway for the angle of the turn.	Circulation Space		Y			
16.10	AS 1428.1 Cl. 3.2	Does the full length of the pathway have overhead clearance of 2000mm (1980mm allowed at doorway).	Overhead Clearance		Y			
16.11	AS 1428.1 Cl. 4.1	Does the pathway have a slip-resistant surface with a texture that is traversable by a wheelchair or a person with ambulant or sensory disability.	Slip Resistance	TBA				Not detailed at 60% Review
16.12	AS 1428.1 Cl. 4.1	If a grate is installed on the accessway, are circular openings not greater than 13mm in diameter; or where slotted openings are in use are they not greater than 13mm width and 150mm long and oriented so that the long dimension is transverse to the direction of travel. If linear opening is less than 8mm wide – Where linear openings are less than 8mm wide, orientation is optional.	Grate	TBA				Not detailed at 60% Review
16.13	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3 / 2.5	Are appropriately installed TGSIs provided at existing defined pedestrian crossing point/s with a level transition over a vehi.ular traffic way on the pathway (width x 600 – 800mm, setback 300mm ± 10mm)	TGSI	TBA				Not detailed at 60% Review
16.14	AS 1428.4.1 Cl. 2.2 / 2.3 / 2.5	Are appropriate installed TGSIs provided at existing defined vehicle drop off areas, with blended kerbs and a level transition, if provided on the pathway (width x 600 – 800mm, setback 300mm ± 10mm)	TGSI	TBA				Not detailed at 60% Review
16.15	AS 1428.1 Cl. 10.4	If there is a gate on the pathway, does it have handles and locks inside and outside that can be operated by one hand and are located at an accessible height (900 – 1100mm grasped or turned, 900 – 1200mm if pushed, 900 – 1250mm if touched)	Gate	TBA				Not detailed at 60% Review
16.16	APS – DP1 AS 1428.1 Cl. 7.1	Is there appropriate circulation space and a level landing at the entrance / childproof gate/s.	Circulation Space	TBA				Not detailed at 60% Review
16.17	AS 1428.1 Cl 7.2	Is the floor or ground surface abutting the sides of the accessway, firm and level and of a different material to that of the accessway, at the same level as the accessway and extend horizontally for a min of 600mm (unless there is a kerb, a wall, fence, a balustrade or similar barrier).	Floor Surface	TBA				Not detailed at 60% Review
16.18	AS148.2 Cl 7.2	Are appropriate landings provided on accessways (walkways).		TBA			N	See Markup of Landscape - Issue with Ramp
Universal Accessibility Options: not mandatory								
16.19	AS 1428.2 Cl. 27.1 (b)	Do objects on the accessway, such as seats, tables, drinking fountains, bins etc have a luminance contrast (intensity of light reflected) of not less than 0.3 (30%) to background or surrounding surfaces.	Luminance Contrast	TBA				Need to determine existing conditions for accessibility in ROK-032
16.20		Are the edges of the pathways in colour contrast to their background (e.g. colour strip or grass on same ground surface)	Contrast against edge	TBA				Need to determine existing conditions for accessibility in ROK-032
16.21	AS 1428.2 Cl. 27.1 (a)	Is seating at a height between 450 – 520mm with armrests between 220 – 300mm above the seat with a back provided along the pathway (min. every 60m) (set back a min. of 500mm).	Seating on pathway	TBA				Need to determine existing conditions for accessibility in ROK-032
16.22		Is there uniform appropriate lighting of the pathways for nighttime use.	Lighting	TBA				Need to determine existing conditions for accessibility in ROK-032
16.23	AS 1428.4.1 Cl. 3.2 / 3.3	Are warning TGSIs (hazard) provided at changes in direction of directional indicators on the pathway.	TGSI	TBA				Need to determine existing conditions for accessibility in ROK-032
16.24		If there is a childproof gate, does it have an accessible doorbell or intercom system, located at a height between 900 – 1200mm, which can be heard from inside the premises	Childproof Gate	TBA			NA	
16.25		If the entrance / childproof gate is located within a continual height fence, is it highlighted to assist recognition by a child or a person with vision impairment	Childproof Gage	TBA			NA	

R0K092		17.00 Stairs						
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
17.01	APS – 3.3 (f) 4.4 / D3.1 / D3.2 / D3.3 / E3.6	Is there an accessible alternative route close to the stairs (e.g. ramp, lift) (where required – see Concessions in Premises Standards)	Accessible Alternative Route close to stairs		Y			Ramp Adjacent
17.02	AS 1428.1 Cl. 8.1 (a) (b) / 9	If the stairs abut an internal corridor / external boundary, are they setback to allow a min. of one tread width plus 300mm internally / min. 900mm externally	Setback		Y			Not abutting internal corridor - check boundary
17.03	APS – D3.8 1 (a) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Are there appropriate TGSIs (hazard – extending the width of path, luminance, depth) at the top and bottom of the stairs.	TGSI	TBA				TGSI existing or proposed not defined at 60% Review
17.04	AS 1428.1 Cl. 11 / AS 1428.4.1 Cl. 2.3 / 2.4	If a non enclosed landing is provided on the stairs, are TGSIs installed as required.	TGSI	TBA				TGSI existing or proposed not defined at 60% Review
17.05	AS 1428.4.1 – Cl. 2.4	If the distance of the landing is 3000mm or more to the nearest nosing edge, are the warning indicators spread over a distance of 600 – 800mm.	TGSI	TBA				TGSI existing or proposed not defined at 60% Review
17.06	AS 1428.1 Cl. 4.1	Do the stairs have a slip resistant surface.	Slip Resistance	TBA				Floor finish not defined at 60% Review
17.07	AS 1428.1 Cl. 8.1 (c)	Are all of the step risers enclosed and of opaque construction.	Step Risers	TBA				Step risers not defined at 60% Review
17.08	AS 1428.1 Cl. 8.1 (f) (g)	Do front edges of stairs nosing have a single strip of continuous colour not less than 50mm and not more than 75mm with a min. 30% luminance contrast (full width of path of travel) (can be set back 15mm) (must not project beyond the face of the riser and not extend more than 10mm down the riser when provided with a contrast and not set back from nosing).	Nosing Strips	TBA				Nosing Strips not defined at 60% Review
17.09	AS 1428.1 Cl. 11.1 (d)	Are the stair nosings level with the face of the riser (riser may be vertical or max. splay backward up to 25mm)	Nosing Strips	TBA				Nosing Strips not defined at 60% Review
17.10	AS 1428.1 Cl. 8.1 (e)	Are the profile of the nosings provided with a sharp transition; rounded up to 5mm radius or chamfered up to 5mm x 5mm.	Nosing	TBA				Profile of Nosing not defined at 60% Review
17.11	APS – D3.8 (3) / 1428.4.1 Cl. 2.2 / 2.3 / 2.4	On a continuous flight of stairs (within an aged care facility), is there a domed button 4 - 5mm high x 10 - 12mm diameter if handrails are not continuous on stair flights and around landings. (on top 150mm from end of rail),					NA	Not an Aged Care Facility
17.12	AS 1428.1 Cl. 8.2	Are appropriate handrails provided on two sides of the stairs (Note: if a balustrade is required at a height greater than the handrail, both shall be provided).	Handrail	TBA				Handrails not defined at 60% Review
17.13	AS 1428.1 Cl. 8.2 / 9 (j)	Are handrails continuous throughout the stair flight, and where practicable on landings.	Handrail	TBA				Handrails not defined at 60% Review
17.14	AS 1428.1 Cl. 8.2 (d) (e) (f)	Do the handrails extend at least one tread width plus 300mm past the edge of the bottom step, and a min of 300mm at the top step (Note: refer AS requirement at intermediate landings).	Handrail	TBA				Handrails not defined at 60% Review
17.15	AS 1428.1 Cl. 8 / 9 (h) (i)	Do the handrails have a min. clearance of 50mm from an adjacent wall and min. 600mm clearance above.	Handrail	TBA				Handrails not defined at 60% Review
17.16	AS 1428.1 Cl. 8 / 9 (i)	Are handrails constructed and fixed, ensuring no obstruction to the passage of the hand along the entire handrail.	Handrail	TBA				Handrails not defined at 60% Review
17.17	AS 1428.1 Cl. 9 (d) (e)	Is the handrail height consistent at a measurement between 865 – 1000mm above the stair nosing (throughout the stairs and on any landing) Construction tolerance of 10mm allowable and Height of handrail may vary at stairway handrail extension or where handrail transitions between flights or to a balustrade).	Handrail	TBA				Handrails not defined at 60% Review
17.18	AS 1428.1 Cl. 9 (b)	Do the handrails have a circular diameter of 30 – 52mm for a min. of 270°.	Handrail	TBA				Handrails not defined at 60% Review
17.19	AS 1428.1 Cl. 8.2 (c)	Do the handrails follow the angle of the nosings.	Handrail	TBA				Handrails not defined at 60% Review
17.20	AS 1428.1 Cl. 9 (c)	Are exposed edges and corners of handrails provided with a radius of not less than 5mm.	Handrail	TBA				Handrails not defined at 60% Review
17.21	AS 1428.1 Cl. 8. 2 (b)	Is there a min. clearance of 1000mm between handrails.	Handrail	TBA				Handrails not defined at 60% Review
17.22	AS 1428.1 Cl. 9 (g)	Are the handrails securely fixed, with ends returned to a side wall / post or turned through 180°.	Handrail	TBA				Handrails not defined at 60% Review
17.23	AS 1428.1 Cl. 9 (a)	Do the handrails (and balustrades) sit outside of required circulation spaces.	Handrail	TBA				Handrails not defined at 60% Review
Universal Accessibility Options: not mandatory								
17.24		Are the tread heights between 150 – 165mm high AS 1428.2 – Cl. 13.2	Tread Heights	TBA				Tread Heights not defined at 60% Review
17.25		Are the treads a min. of 275 – 300mm deep AS 1428.2 – Cl. 13.2	Tread depth	TBA				Tread Depths not defined at 60% Review
17.26		Is there appropriate, uniform lighting of the stairs for night time use	Lighting	TBA				Lighting not defined at 60% Review
17.27		Are the handrails of non-reflective material and a contrasting colour to the background	Handrail Materials	TBA				Handrails not defined at 60% Review

ROK092	18.00 Tactile Ground Surface Indicators							
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
18.01	AS 1428.4.1 Cl. 2.5	Are there appropriate hazard tactile ground surface indicators (TGSIs) prior to a hazard (e.g. roadway) i.e. (width x 600 – 800mm, setback 300mm ± 10mm).	Appropriate TGSI	TBA				TGSIs not defined at 60% Review
18.02	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3 / 2.5	Are appropriately installed TGSIs provided at existing defined pedestrian crossing point/s with a level transition over a vehicular traffic way on the pathway(width x 600 – 800mm setback 300mm ± 10mm).	Pedestrian Crossing TGSI	TBA				TGSIs not defined at 60% Review
18.03	AS 1428.4.1 Cl. 2.2 / 2.3 / 2.5	Are appropriate installed TGSIs provided at existing defined vehicle drop off areas, with blended kerbs and a level transition, if provided on the pathway (width x 600 – 800mm setback 300mm ± 10mm).	Vehicle dropoff TGSI	TBA				TGSIs not defined at 60% Review
18.04	APS – D3.8 1 (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Are there appropriate TGSIs (hazard – extending the width of path, luminance, depth) at the top and bottom of a ramp (as required).	Ramp TGSI	TBA				TGSIs not defined at 60% Review
18.06	AS 1428.1 Cl. 11 / AS 1428.4.1 Cl. 2.3 / 2.4	If a non enclosed landing is provided on the stairs, are TGSIs installed as appropriate.	Non-enclosed landing TGSI	TBA				TGSIs not defined at 60% Review
18.07	AS 1428.4.1 Cl. 2.4	If the distance of the landing is 3000mm or more to the nearest nosing edge, are the warning indicators spread over a distance of 600 – 800mm.	Landing TGSI	TBA				TGSIs not defined at 60% Review
18.08	APS – D3.8 / AS 1428.4.1 Cl. 2.6	If there is an overhead obstruction less than 2000mm (other than a doorway) are appropriate TGSIs installed (in the absence of any other barrier) (e.g. undercroft of stairs) (NOTE: an alternative type of barrier is preferred).	Overhead Obstruction TGSI	TBA				No Overhead Obstructions identified at 60% Review
18.09	AS 1428.4.1 Cl. 2.3.3 (b)	Are the warning indicators installed at right angles to path of travel on pathways.	Warning Indicators	TBA				Warning Indicators not defined at 60% Review
18.10	AS 1428.4.1 Cl. 2.3.3 (c) / 3.4 / 3.5	Are there warning indicators installed along edges of hazardous areas e.g. train platforms, wharves, level roadway crossing points etc.	Warning Indicators	TBA				Warning Indicators not defined at 60% Review
18.11	AS 1428.4.1 Cl. 2.2 / App. E	Are TGSIs installed with appropriate contrasts to background surfaces.	TGSI Contrast	TBA				TGSIs not defined at 60% Review
18.12	AS 1428.4.1 Cl. 2.3	Are the TGSIs installed to ensure no tripping hazard is produced.	No Tripping Hazards	TBA				TGSIs not defined at 60% Review
Universal Accessibility Options: not mandatory								
18.13	AS 1428.4.1 Cl. 3.1 (c) (i)	Are there appropriate directional TGSIs on any pathway adjacent where a kerb ramp is at a mid block section or not on a direct path of travel.	Directional TGSI	TBA				TGSIs not defined at 60% Review
18.14	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3	Are TGSIs provided at changes in direction on the pathway to the PPE.	Directional TGSI	TBA				TGSIs not defined at 60% Review
18.15	AS 1428.4.1 Cl. 2.1 / 2.2 / 2.3	Are warning TGSIs (hazard) provided at changes in direction of directional indicators on the pathway to the PPE.	Warning TGSI	TBA				TGSIs not defined at 60% Review
18.16		Are there any appropriate TGSIs (hazard) indicators prior to the existing kerb ramps on the pathway (width x 600 – 800mm, setback 300mm ± 10mm).	Kerb Ramps	TBA				TGSIs not defined at 60% Review
18.17	AS 1428.4.1 App. D	Are there directional indicators installed to provide direction to elements e.g. bus stops, kerb ramps, street furniture, toilets, train platforms, road crossings etc.	External Kerb Ramps	TBA				TGSIs not defined at 60% Review
18.18	AS 1428.4.1 App. A 3.1	Are TGSIs used with consistent application throughout an area.	TGSI	TBA				TGSIs not defined at 60% Review
18.19		Are the TGSIs well maintained.	TGSI	TBA				TGSIs not defined at 60% Review
18.20		Are the TGSIs used to promote pedestrian safety.	TGSI	TBA				TGSIs not defined at 60% Review

ROK092	19.00 Ramps							
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
19.01	APS – D3.11	If a vertical rise of more than 3.6m is provided through a series of connected ramps, is an alternative means of access provided.	Rise of more than 3.6 m				NA	Not a rise of 3.6m
19.02	AS 1428.1 Cl. 7.3	Do all ramps have a slope / gradient where the max. ratio is 1:14 (tolerance 3% provide no section is steeper than 1:14).	Gradient		Y			
19.03	AS 1428.1 Cl. 7.3	Do the 1:14 ramps have landings a min. of every nine metres or less at changes in directions.	Landings every 9m		Y			
19.04	AS 1428.1 Cl. 7.3	If the ramp abuts an internal corridor, is it set back a min of 400mm or, if it abuts an external boundary a min. of 900mm.	Corridor abut setback		Y			
19.05	APS – D3.11 (b)	If there are connected ramps / step ramps, are the landings free from any overlap.	Connected Ramps			N		See Markup in Appendix A
19.06	AS 1428.1 Cl. 7.8	Are landings 1200mm (where no change of direction required) in length or greater) (NOTE: sharp transitions are required between the planes of landings and ramps, refer AS for gradients).	Landing 1200mm - no direction change	TBA	Y			
19.07	AS 1428.1 Cl. 7.8	If the landing has a change of direction not exceeding 90°, is the landing a min. 1500mm, with the internal corner truncated for a min of 500mm in both directions.	Landing 1500mm - max 90 degree turn	TBA	Y			
19.08	AS 1428.1 Cl. 7.8	If the landing has a 180° turn, is the landing a min. of 1540mm deep with other required dimensions as per the Standard.	Landing 1540mm - 180 degree turn			N		See Markup in Appendix A
19.09	AS 1428.1 Cl. 7.8	If the landing is at a door, which is approached from the side, is there appropriate circulation space.	landing at door				NA	No landing at a door
19.10	AS 1428.1 Cl. 7.8	If the ramp is constructed with a change of direction, does the angle of approach create a 90° angle to the line of transition between the ramp surface and the landing surface.	angle of approach at 90 degree	TBA				Change in direction to be fixed and then this rechecked at 60% Review
19.11	AS 1428.1 Cl. 9	Do all ramps have an unobstructed width (in between handrails) a min. of 1000mm.	unobstructed width 1000mm	TBA				Existing ramp not detailed to answer this question at 60% Review
19.12	AS 1428.1 Cl. 7.3	Do any ramps (and landings as approp.) have kerbs on both sides with the top between 65 – 75mm, or higher than 150mm (see fig 18 AS).	Kerbs on both sides					Not detailed at 60% Review
19.13	AS 1428.1 Cl. 3	Does the full length of any ramp have min. overhead clearance of 2000mm.	Overhead Clearance		Y			
19.14	AS 1428.1 – Cl. 7.4	If ramps are curved, do they have a min. width of 1500mm and end with 1500mm long straight landings.	Curved Ramp				NA	Ramp not curved
19.15	AS 1428.1 Cl. 4.2	Is the ramp surface slip resistant with smooth transitions between different sections (i.e. abutment of surfaces).	TGSI	TBA				Not detailed at 60% Review
19.16	APS – D3.8 (1) (d) / 2 / AS 1428.4.1 Cl. 2.2 / 2.3 / 2.4	Are there appropriate TGSIs (hazard – extending the width of path, luminance, depth) at the top and bottom of the ramp (NOTE: refer to AS for differing requirements for landings).	TGSI	TBA				Not detailed at 60% Review
19.17	AS 1428.1 Cl. 7.3/9	Do all ramps have appropriate handrails on two sides (Note: if a balustrade is required at a height greater than the handrail, both shall be provided).	Ramp handrail	TBA				Not detailed at 60% Review
19.18	AS 1428.1 Cl. 9	Do the handrails have a circular diameter of 30 – 50mm for a min. of 270°.	Ramp handrail	TBA				Not detailed at 60% Review
19.19	AS 1428.1 Cl. 9	Are exposed edges (at ends) and corners of handrails provided with a radius of not less than 5mm.	Ramp handrail	TBA				Not detailed at 60% Review
19.20	AS 1428.1 Cl. 9	Is the handrail height consistent (measured at a height between 865 - 1000mm) throughout the ramp and any landing.	Ramp handrail	TBA				Not detailed at 60% Review
19.21	AS 1428.1 Cl. 9	Do the handrails have a min. clearance of 50mm from an adjacent wall and min. 600mm clearance above.	Ramp handrail	TBA				Not detailed at 60% Review
19.22	AS 1428.1 Cl. 7.3/9	Do the handrails extend a min. of 300mm past the ends of the ramp.	Ramp handrail	TBA				Not detailed at 60% Review
19.23	AS 1428.1 Cl. 9/9	Are handrails constructed and fixed, ensuring no obstruction to the passage of the hand along the entire handrail.	Ramp handrail	TBA				Not detailed at 60% Review
19.24	AS 1428.1 Cl. 9/9	Are handrails securely fixed, with ends returned to a side post / wall or downwards through 180°.	Ramp handrail	TBA				Not detailed at 60% Review
19.25	AS 1428.1 Cl. 9	Do the handrails (and balustrades) sit outside of required circulation spaces.	Ramp handrail	TBA				Not detailed at 60% Review
19.26	AS 1428.1 Cl. 7.6	If less than 1900mm in length, does the step ramp have a gradient a max. ratio of 1:10 and a max. rise 190mm.	Step Ramp				NA	No evidence of Step Ramp
19.27	AS 1428.1 Cl. 7.6.2	If a step ramp is installed and there is pedestrian cross traffic, do the edges of the step ramp have a 45° splay or a wall, fence, balustrade or suitable barrier or a kerb or where an open balustrade is provided, a kerb or kerb rail.	Step Ramp				NA	No evidence of Step Ramp
19.28	AS1428.1 Cl 7.6.1	If a step ramp is installed, is the top and bottom aligned at 90 degrees to the direction of travel and have sharp transitions at the top and bottom and at any tapered or splayed edges	Step Ramp				NA	No evidence of Step Ramp
19.29	AS 1428.1 Cl. 7.6/8	If the landing at the top and bottom of the step ramp follows the direction of travel, is it a min. of 1200mm long.	Step Ramp				NA	No evidence of Step Ramp
19.30	AS 1428.1 Cl. 7.6/8	If the landing at the top and bottom of the step ramp requires a change of direction, is it a min. of 1500mm.	Step Ramp				NA	No evidence of Step Ramp
19.31	AS 1428.1 Cl. 7.8 / 10	If the landing at the top and bottom of the step ramp is at a doorway, is the appropriate door circulation space provided.	Step Ramp				NA	No evidence of Step Ramp
19.32	AS 1428.1 Cl. 7.5	If there is a threshold ramp at the doorway, does it have sharp transitions at the top and bottom and be located not more than 20mm from door leaf it serves, not more than 280mm in length and a min. ratio of 1:8.	Threshold Ramp				NA	No evidence of Threshold Ramp
19.33	AS 1428.1 Cl. 7.5	If the threshold ramp does not abut a wall or kerb, are sides tapered or splayed (min. 45°).	Threshold Ramp				NA	No evidence of Threshold Ramp
Universal Accessibility Options: not mandatory								
19.34	AS 1428.2 Cl. 8.4.5	Do the edges of the ramps have colour contrast to their background.	Colour Contrast	TBA				Not detailed at 60% Review
19.35	AS 1428.2 Cl. 19	Is there appropriate uniform lighting of the ramp for night time use.	Luminance	TBA				Not detailed at 60% Review
19.36		Are the handrails of non-reflective material and a contrasting colour to the background.	Handrails	TBA				Not detailed at 60% Review

R0K092	20.00 Signage							
Number	Standard	Item	Item	TBA	Y	N	NA	Action
Mandatory Items								
20.01	APS – DP1 (b) / AS 1428.1 CL 5.1	Is appropriate signage available where directional decisions are made.	Directional Signage	TBA				Signage not defined at 60% Review
20.02	APS – D3.6 (e) / D4 / AS 1428.1 Cl. 5.1	If there is a non accessible entrance doorway, is there appropriate signage provided directing users to accessible entrance.	Non-Accessible Access Signage	TBA				Signage not defined at 60% Review
20.03	APS – D3.6 / D4 / AS 1428.1 Cl. 5.2	Where the symbol for access is used, does it comply with the international standard in style, colour and layout.	Symbol for Access	TBA				Signage not defined at 60% Review
20.04	APS – D3.6 (b) (i) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2	Does signage, including the international symbol of deafness, indicate the area where an assistive listening system is operational and the area covered.	Symbol for Deafness	TBA				Signage not defined at 60% Review
20.05	APS – D3.6 (b) (ii) / D4 / D3.7 (1) (2) (3) / AS 1428.1 Cl. 5.2	Does signage including the international symbol of deafness, indicate which type of system is in place.	Symbol for Deafness	TBA				Signage not defined at 60% Review
20.06	APS D3.6 (b) (iii)	If receivers are being used for hearing augmentation, does the signage indicate where the receivers can be obtained.	Hearing Augmentation Signage	TBA				Signage not defined at 60% Review
20.07	APS – D3.6 (b) / D4 / AS 1428.1 CL 5.1	Is raised tactile information provided on signs between 1200 – 1600mm.	Signage Raised Text	TBA				Signage not defined at 60% Review
20.08	APS – D4.5	Is there appropriate illumination of signage for day and night use (where required e.g. to maintain luminance).	Illumination	TBA				Signage not defined at 60% Review
20.09	APS – D3.6 (f) / D4	If there is a non-accessible toilet provided, is there signage available that directs users to an accessible toilet (where in different locations).	Signage to Accessible toilet at non-accessible toilet	TBA				Signage not defined at 60% Review
20.10	APS – D3.6 (c) / D4 / AS 1428.1 Cl 5.1	Does the signage indicate if the accessible toilet facility is suitable for left or right hand.	L or R Hand Accessible Facility	TBA				Signage not defined at 60% Review
20.11	APS – D4.3 (2); Title Case AS 1428.1 C 5.1	If available on the sign, is the text provided in Title Case.	Signage - Title Case	TBA				Signage not defined at 60% Review
20.12	APS-D3.6 (a) / AS 1428.1 Cl 5.1	Is there signage (incorporating raised text and Braille, and raised and visual symbols) installed identifying available sanitary facilities.	Signage to All Toilets	TBA				Signage not defined at 60% Review
20.13	APS – D3.6 (d) / AS 1428.1 Cl. 5.1	If there is an ambulant toilet, is appropriate signage installed at the airlock serving the area that contains the facilities identifying the facilities within.	Signage Ambulant Toilet	TBA				Signage not defined at 60% Review
20.14	APS – D3.6 (d) / AS 1428.1 Cl. 5.1	If there is an ambulant toilet, is there signage to identify the facility (Note: may be located on door if required).	Signage Ambulant Toilet	TBA				Signage not defined at 60% Review
Universal Accessibility Options: not mandatory								
20.15		Is signage (including tactile and Braille) located at the main building entry, both inside and out, giving directional and general information about buildings and facilities including services and access for people with disabilities.	Main Entry Signage	TBA				Signage not defined at 60% Review