

1.1.1 kinematic what to do next

What To Do Next

- Keep the current UR5 symbolic FK/Jacobian as the validated reference version.
- Wait until the final welding robot geometry and joint-axis directions are known.
- Define the final robot DH parameters inside `WeldingRobot.m`.
- Replace UR5-specific symbolic values, especially the hardcoded `alpha_clean`, with the welding robot's actual DH values.
- Re-run:
 - `symbolicFK.m`
 - `symbolicJacobian.m`
- Validate the final symbolic results against:
 - `controlFK.m`
 - `controlJacobian.m`
 - the Simulation/reference robot model

Goal:

Same kinematics code, new robot parameters
--

The algorithms should not need to be rewritten when moving from UR5 to the final welding robot.