

Motor Vehicle Accident Report

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00042	Policy	POL-74007757
Vehicle	2025 Mercedes-Benz GLC	VIN	JT08CR00UABYJ5XB0
Location	Johor Bahru	Date	2026-05-02
Weather	Rain	Road	Wet Asphalt

Incident Narrative

At approximately 17:48, the reporting driver stated the vehicle was travelling on an urban roadway in Johor Bahru. The collision resulted in a front-left impact. Responding personnel documented visible damage affecting Front bumper, Right door, Tail lamp. No injuries were reported in this synthetic example. The vehicle was drivable. Contributing factors noted: failure to yield, reduced visibility, and wet road conditions where applicable.

Damage Area	Severity	Recommendation
Tail lamp	Minor	Replace
Hood	Major	Inspect
Front bumper	Moderate	Inspect
Left fender	Moderate	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.