

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00020	Policy	POL-45224545
Vehicle	2024 Nissan X-Trail	VIN	JTL5W3YMJSC1MN7ES
Location	Ipoh	Date	2026-05-04
Weather	Cloudy	Road	Concrete

Coverage Assessment

The insured reported a flood exposure involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left headlamp, Left fender, Front bumper, Rear bumper. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 3 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 23 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 17,532.

Damage Area	Severity	Recommendation
Rear bumper	Moderate	Inspect
Left fender	Minor	Repair
Hood	Major	Repair
Front bumper	Major	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.