

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00025	Policy	POL-88415841
Vehicle	2020 Nissan X-Trail	VIN	JT08H59NZYNR47YH7
Location	Shah Alam	Date	2026-05-08
Weather	Cloudy	Road	Wet Asphalt

Coverage Assessment

The insured reported a front-left impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Tail lamp, Left fender, Rear bumper, Left headlamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 7 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 22 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 27,899.

Damage Area	Severity	Recommendation
Tail lamp	Major	Inspect
Left fender	Minor	Replace
Right door	Major	Replace
Rear bumper	Moderate	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.