

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00028	Policy	POL-20631042
Vehicle	2020 Honda Civic	VIN	JTFE7XNFJ3HXKG2VM
Location	Kuala Lumpur	Date	2026-05-18
Weather	Overcast	Road	Concrete

Coverage Assessment

The insured reported a right-side impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left fender, Front bumper, Right door, Left headlamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 6 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 26 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 27,282.

Damage Area	Severity	Recommendation
Hood	Major	Repair
Rear bumper	Major	Inspect
Left fender	Major	Repair
Tail lamp	Minor	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.