

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00032	Policy	POL-52436091
Vehicle	2022 Nissan X-Trail	VIN	JT3A1H4PV059TG5U0
Location	Seremban	Date	2026-05-23
Weather	Rain	Road	Urban Road

Coverage Assessment

The insured reported a flood exposure involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Rear bumper, Front bumper, Hood, Right door. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 6 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 24 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 14,202.

Damage Area	Severity	Recommendation
Left fender	Minor	Replace
Hood	Moderate	Inspect
Right door	Moderate	Repair
Left headlamp	Major	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.